




Precision German

5550 East La Palma Avenue
 Anaheim, CA 92807
 (714) 779-2082
 Info@precisiongermanperformance.com
 http://www.precisiongermanperformance.com

Invoice for RO #3821

Service Advisor: Kyle Deneau
 Date Created: 08/04/25 at 12:47 PM CDT
 Client: Hagerty Media
 Vehicle: 2008 Audi RS4 Base

<p>Hagerty Media</p> 	<p>2008 Audi RS4 Base 4.2L 8Cyl GAS BNS Naturally Aspirated VIN: WUADU78E38N901265 License: N/A Color: Blue Odometer In: 128101 / Out: 128101</p>	<p>RO # 3821 PO # - Time-In: 08/04/25 at 12:47 PM CDT Save Parts: No</p>
--	--	---

Client concerns:

- Post Purchase Inspection
- Reattach front fender liners

<p>1 - Check Engine/Drivetrain Malfunction Warning Light Tech:T Borden</p>		
<p>Labor:</p>	<p>Interrogate fault memory, follow test plan, and test related components to determine cause of warning light.</p>	<p>\$160.00</p>
<p>✓ Approved on 08/05/25 at 11:30 AM CDT</p>		<p>\$160.00</p>

<p>2 - Intake Manifold Tech:T Borden</p>		
<p>Labor:</p>	<p>Remove intake manifold to inspect intake valves for carbon build up, inspection/repair of volume adjustment flap linkage, make recommendations and necessary repairs while manifold is accessible. \$928.68 Remove carbon deposits from backside of intake valves \$337.70 Remove and replace faulty vacuum actuator for manifold flap system \$33.77 Remove and replace air oil separator while accessible \$33.77</p>	
<p>Parts:</p>	<p>Engine Intake Manifold Gasket 4 \$286.56 Fuel Injection Throttle Body Mounting Gasket 1 \$39.39 Media Blasting Media 0.2 \$22.09 Secondary Air Injection Solenoid 1 \$157.50 Oil Separator 1 \$197.80 Engine Oil Separator O-Ring (23.47 x 2.62 mm) 1 \$7.27</p>	
<p>✓ Approved on 08/12/25 at 01:59 PM CDT</p>		<p>Subtotal \$2,044.53 + est. Tax \$55.07 \$2,099.60</p>

<p>3 - Engine Mounts Tech:T Borden</p>		
<p>Labor:</p>	<p>Remove and replace worn/ruptured engine mounts, removing front suspension and sub-frame for access. \$1,097.53</p>	
<p>Part:</p>	<p>Engine Mount 2 \$881.76</p>	
<p>✓ Approved on 08/12/25 at 01:59 PM CDT</p>		<p>Subtotal \$1,979.29 + est. Tax \$68.34 \$2,047.63</p>

<p>4 - Manual Transmission Service Tech:T Borden</p>		
<p>Labor:</p>	<p>Drain and refill manual transmission with fresh fluid \$168.85</p>	
<p>Part:</p>	<p>Manual Transmission Fluid (1 Liter) 4 \$180.36</p>	
<p>✓ Approved on 08/12/25 at 01:59 PM CDT</p>		<p>Subtotal \$349.21 + est. Tax \$13.98 \$363.19</p>

5 - Differential Service			
Tech: T Borden			
Labor:	Drain and refill rear differential.		\$168.85
Parts:	Brake Cleaner - Brakleen Non-Chlorinated (14 oz. Aerosol Can)	1	\$19.49
	Gear Oil, MOTYLGEAR 75W85 1L, Full Synthetic	2	\$77.16
✓ Approved on 08/12/25 at 01:59 PM CDT		Subtotal \$265.50 + est. Tax \$7.49	\$272.99

6 - Oil Service			
Tech: T Borden			
Labor:	Change oil and filter, inspect vehicle, and top up fluids.		\$52.00
Parts:	5W40 SYNTHETIC OIL	10	\$94.50
	, Insert, w/ O-Ring Engine Oil Filter	1	\$39.44
✓ Approved on 08/12/25 at 01:59 PM CDT		Subtotal \$188.62 + est. Tax \$10.38	\$199.00

7 - Shift Lever Adjustment			
Tech: T Borden			
Labor:	Adjust shift lever to engage first gear properly, remove center console covers, shifter surround, and HVAC control unit for access.		\$211.06
✓ Approved on 08/12/25 at 01:59 PM CDT			\$211.06

8 - Remove & Replace Drive Belt (Accessory/Serpentine)			
Tech: T Borden			
Labor:	Remove & Replace Drive Belt (Accessory/Serpentine)		\$211.06
Part:	ContiTech, Multi-Rib Serpentine Belt Accessory Drive Belt	1	\$56.40
✓ Approved on 08/28/25 at 10:24 AM CDT		Subtotal \$267.46 + est. Tax \$4.37	\$271.83

9 - Alignment			
Tech: T Borden			
Sublet:	Adjust steering and suspension to factory alignment settings.		\$130.00
✓ Authorized on 08/12/25 at 01:59 PM CDT			\$130.00

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control.
 WARRANTY IS 24 MONTHS OR 24,000 MILES WHICH EVER OCCURS FIRST, UNLESS SPECIFIED OTHERWISE.

X _____

Total Repair Order & Signature:

Total Labor: \$3,403.27
Total Parts: \$2,059.72
Total Sublet: \$130.00
Total Fees: \$2.68
Subtotal: \$5,595.67
Taxes: \$159.63
Grand Total: \$5,755.30
BALANCE DUE: \$0.00

X

✓ PAID

Completed Transactions				
08/28/25	Hagerty Media	\$5,755.30	Credit Card Payment	