

Lindberg Automotive

20818 Rand Road

Deer Park, IL. 60047

Phone - 847-438-3600 Fax - 847-438-3644

Customer and Vehicle Report

Print Date: 10/07/2025

Vehicle: 1979 Pontiac - Firebird, 4.9L,V8 (301CI) VIN(W), ES51550

Average Daily Mileage: 32

Invoice: 053664, Posted On: 12/07/2024, SW: Doug , Lindberg

Odometer in: 940 Odometer Out: 948

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
Notes - AFTER CAR RUNNING FOR 5 TO 10 MINUTES CAR LOOSES IDLE. STARTS STALLING HARD TO START ----- TRANSMISSION LEAK -----									
-	TOWING					215.00	215.00		
-	A/T Oil Pan Gasket	TOS18662		Name No	1.00	25.07	25.07	21.06	
-	Automatic Transmission Fluid	D-1		Name No	5.50	4.00	22.00	5.96	
1.00	Remove shifter cable shaft. Clean shaft from rust & polish. Re install. install new seal. Drop transmission pan. Replace filter. Straighten pan.			Dennis Cooper	1.00	142.00	142.00		142.00
-	Selector shaft seal.	8792S		Name No	1.00	5.46	5.46	6.85	
-	Cleaner	74HV-A	Miscellaneous	Name No	4.00	5.75	23.00	4.04	
1.50	STALLING			Dennis Cooper	1.50	213.00	213.00		142.00
Try adjusting carburetor. Check timing. Car had 44 Degrees at idle. WAY TO MUCH. Pull distributor. Check advance on distributor machine. To much vacuum advance & no centrifugal advance. Weld up vacuum advance slot to stop advance at 10 Degrees. Replace advance springs on mechanical advance. Centrifugal advance starts at 1000 RPMS. Set timing at 700 RPMS to 12 Degrees BTDC. Vacuum hose to vacuum advance was put on different vacuum port.									
-	Distributor advance spring	928G		Name No	1.00	7.43	7.43		
-	Shop Supplies	SS	Miscellaneous	Name No	1.00	2.00	2.00	8.90	
Totals for Invoice:		Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
		84.96	570.00	68.40	586.56	7.50	0.00	6.80	600.86

Invoice: 053012, Posted On: 07/12/2024, SW: Doug , Lindberg

Odometer in: 0 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
------	-------------	----------	----------	------------	-----	------	------	-------	------

Customer and Vehicle Report

Print Date: 10/07/2025

Vehicle: 1979 Pontiac - Firebird, 4.9L,V8 (301CI) VIN(W), ES51550

Average Daily Mileage: 32

Invoice: 053012, Posted On: 07/12/2024, SW: Doug , Lindberg

Odometer in: 0 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	Notes - VALVE COVER GASKETS REPLACE --- NOISE WHEN BACKING UP --- UPPER CONTROL ARM BUSHINGS ---- INSTALL NEW WATER TEMP SENDER. CUT TO LENGTH YELLOW WIRE FOR SENSOR ----- REPLACE ALL FLUIDS ---- ENGINE MAY NEED TUNE UP.								
1.50	VALVE COVER GASKET - Remove & Replace - 305CID Eng Both - [Includes: Camshaft Covers on Over Head Cam Engines.]			Name No	1.50	213.00	213.00		142.00
-	Valve Cover Gasket Set	VS50005C		Name No	1.00	32.41	32.41	36.28	
-	Cleaner	74HV-A	Miscellaneous	Name No	3.00	5.75	17.25	4.04	
4.50	UPPER CONTROL ARM SHAFT BUSHING - Remove & Replace - Two Sides,Upper Bushings & ball joints. Boots torn apart. Sand blast around bushing holes. Clean ball joint mounting area from rust -			Name No	4.50	639.00	639.00		142.00
0.92	Front wheel alignment		Steering/Susp/Wheel Align	Name No	0.92	130.00	130.00		142.00
	Road test vehicle. Check all suspension and steering parts for wear. Check tire pressure and condition. Check riding height. Check caster and camber angles and adjust as required. Check and set toe-in as required. Center steering wheel.								
-	Transmission Mount Poly	3.1108G		Name No	1.00	67.88	67.88	80.08	
1.40	DRIVE TRAIN NOISE Rep[lace transmission mount. Install poly mount.			Name No	1.40	198.80	198.80		142.00
0.70	Replace Differential Fluid - Rear			Name No	0.70	99.40	99.40		142.00
-	75W90 SYNTHETIC GEAR LUBE	75W90	Maintenance	Name No	1.80	21.95	39.51		
-	Rislone Oil Supplement with Zinc	4405		Name No	1.00	12.16	12.16	12.16	
-	Wheel Lug Nut	611-097		Name No	4.00	6.42	25.68	5.11	
-	Front Upper Suspension Ball Joint	K5208		Name No	2.00	39.74	79.48	40.96	
-	Water temp sensor.	NVU-99320-04		Name No	1.00	35.60	35.60	35.60	
-	Reducer fitting	558334		Name No	1.00	6.88	6.88		
-	Centric Premium Brake Shoes	111.02450		Name No	1.00	52.44	52.44	69.72	
-	Premium Wheel Cylinder	134.63002		Name No	2.00	31.00	62.00	37.34	
3.70	REAR BRAKES			Name No	3.70	525.40	525.40		142.00

Customer and Vehicle Report

Print Date: 10/07/2025

Vehicle: 1979 Pontiac - Firebird, 4.9L,V8 (301CI) VIN(W), ES51550

Average Daily Mileage: 32

Invoice: 053012, Posted On: 07/12/2024, SW: Doug , Lindberg

Odometer in: 0 Odometer Out: 0

Time	Description	Part No.	Category	Technician	Qty	Sale	Extd	Price	Rate
	Remove & replace rear brake shoes & wheel cylinders. Replace missing parking brake Actuator rod. Cut right rear cable to have proper brake shoe adjustment. Includes flushing front brake system & rear.								
-	Cleaner	74HV-A	Miscellaneous	Name No	1.00	5.75	5.75	4.04	
-	Rear Brake Actuator Lever Strut Spring	18K1741		Name No	2.00	8.98	17.96	13.30	
-	Drum Brake Bar	21129		Name No	1.00	23.71	23.71	23.94	
-	UPS					14.88	14.88		
1.40	TEMPERATURE SENSOR Track down			Name No	1.40	198.80	198.80		142.00
	Temp sensor to work with customer gauges. Install new sensor & reducer fitting. Run wire & check operation.								
0.30	Change Motor Oil Lube Chassis		Oil Change	Name No	0.30	42.60	42.60		142.00
	Changed Motor Oil & Replaced Filter, Added Synthetic Motor Oil, Lube Chassis, Check all Fluid Levels. Tires were filled .								
-	Synthetic 5w30 GF-4	CQ930	Engine Mechanical Repair	Name No	5.00	6.50	32.50	4.00	
-	Oil Filter	PXL51040MP		Name No	1.00	4.00	4.00	4.18	
0.90	Pull one spark plug. Fuel fouled. Car has cam & eng work . Adjust carburator. Rerout for vacuum advance to be working at idle. Test drive.			Name No	0.90	127.80	127.80		142.00
-	Top Engine Cleaner	1052626	Maintenance	Name No	1.00	23.50	23.50	24.31	
Totals for Invoice:		Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
		538.71	2,189.68	219.09	2,509.30	7.50	7.50	43.70	2,568.00
Totals for Owner:		Parts	Labor	Discount	Subtotal	Haz Mat	Supplies	Tax	Total
		623.67	2,759.68	287.49	3,095.86	15.00	7.50	50.50	3,168.86