



**Hillyard Automotive LLC**  
 42750 Trade West Drive #110  
 Sterling, VA 20166  
 (703) 828-3900  
 hillyardautomotive@gmail.com  
 https://www.hillyardautomotive.com

**Invoice for RO #7123**  
 Service Advisor: mike hillyard  
 Posted Date: 05/07/25 at 03:52 PM EDT  
 Client:   
 Vehicle: 1985 Mazda RX-7 GS

	<b>1985 Mazda RX-7 GS 1.1L 2Cyl GAS Naturally Aspirated</b> VIN: JM1FB3316F0862559 License: PEPSRX7 Color: Red Odometer In: 86715 / Out: 86726	<b>RO # 7123</b> Time-In: 02/24/25 at 11:50 AM EST Save Parts: No
--	--	---

**Client concerns:**

- hard to start
- no choke
- runs rough since cats were gutted.

<b>1 - hard to start</b>			
Tech: B D			
Labor:	preliminary & full diagnosis including smoke test along with active testing .		\$660.00
Part:	2+2 Gum cutter	1	\$11.85
✓ Approved on 03/04/25 at 02:21 PM EST		Subtotal \$671.85 + est. Tax \$0.71	<b>\$672.56</b>

<b>2 - Tune up</b>			
Tech: L F			
Labor:	found oil in spark plug wires and coils. rec to replace spark plugs, wires, distributor cap, rotor.		\$495.00
Parts:	NGK Spark Plug BR8EQ-14 NGK	4	\$69.80
	NGK Ignition Wire Set ZE97A NGK	1	\$45.12
	API Distributor Cap	1	\$38.72
	aft dist rotor	1	\$17.42
	DEL Ignition Coil	2	\$120.58
✓ Approved on 03/11/25 at 08:41 PM EDT		Subtotal \$786.64 + est. Tax \$17.50	<b>\$804.14</b>

<b>3 - Fuel Filter</b>			
Tech: R D			
<b>Note:</b> Fuel hose at fuel filter are old and falling apart. Recommend replacing hoses and pump			
Labor:	Fuel hose replacement with filter. also lowered fuel tank and further diagnosis found clogged fuel lines. fuel screen ripped/broken and causing a clog when applying a load.		\$495.00
Parts:	Nicopp fuel line	1	\$35.23
	carquest fuel filter	1	\$11.23
	aft fuel filter	1	\$29.53
✓ Approved on 03/11/25 at 08:41 PM EDT		Subtotal \$570.99 + est. Tax \$4.56	<b>\$575.55</b>

<b>4 - Exhaust</b>			
Tech: L F			
<b>Note:</b> Exhaust hanger is broken			
Labor:	repair broken exhaust hanger.		\$165.00
✓ Approved on 03/11/25 at 08:41 PM EDT			<b>\$165.00</b>

<b>5 - Fuel pump &amp; lines</b>			
Tech: B D			
Labor:	Remove & Replace Fuel Pump		\$825.00
Parts:	mazda oem fuel pump assy	1	\$296.85
	napa fuel line	1	\$37.74
	advanced hose/fittings	1	\$42.70
✓ Approved on 04/09/25 at 11:32 AM EDT		Subtotal \$1,202.29 + est. Tax \$22.64	<b>\$1,224.93</b>

<b>6 - Carburetor Refresh</b>			
Tech: B D			
Labor:	found gaskets dry rotted and falling apart when carburetor came off. possible cause of vacuum leak. - gaskets fell apart when touched. cleaned jets installed new gaskets / carb rebuild kit.		\$264.00
Part:	aft rebuild kit / gaskets - included next day shipping	1	\$150.65
✓ Approved on 04/30/25 at 02:37 PM EDT		Subtotal \$414.65 + est. Tax \$9.04	<b>\$423.69</b>



<b>RO Fees</b>			
Fees:	shop supplies		\$89.95
	hazardous waste removal		\$27.99
	tire removal/ pick up		\$0.00
	Credit Card processing (if paid by credit card)		\$76.23
Subtotal			<b>\$194.17</b>

**Total Repair Order & Signature:**

Total Labor: \$2,904.00  
 Total Parts: \$907.42  
 Total Fees: \$194.17  
**Subtotal: \$4,005.59**  
 Taxes: \$54.45  
**Grand Total: \$4,060.04**  
**BALANCE DUE: \$0.00**

X

✓ PAID

<b>Completed Transactions</b>					
05/07/25		\$4,060.04	Credit Card Payment		Chip Visa 