

DAS Sport, LLC
 1 Cleveland Street
 Suite 1100
 Gordonsville, VA 22942



Client

Date	Invoice #	Terms
04/04/24	2024-2751	Net 10

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2463

Item Type	Qty	Description	Net	Amount
		VIN# AZ288-612		
		*** Engine Repair ***		
LM - Labor	1	Mechanical Labor: Assembly labor on 550 Spyder Engine - March 2024 (GIN#040124) (38.75 hrs)	3,875.00	3,875.00
SS	1	Supplies: Break In Oil	174.00	174.00
Parts	4	Spark Plug - 12mm	7.98	31.92
Sublet	1	Sublet Service: Shorten Case Studs to Fit	580.00	580.00
Sublet	1	Sublet Service: Check crankshaft after Inbound Shipping	275.50	275.50
Parts	1	Barrel Spacers .200th	302.90	302.90
Shipping	1	Shipping: Inbound Shipping, Duty, Customs	63.80	63.80
Shipping	1	Shipping: Duty and Taxes on First Shipment of Parts from CB Performance	460.26	460.26
Tax	1	VA Sales Tax 5.3%	26.97	26.97

Start Date	02/28/24	Invoice Amount	\$5,790.35
-------------------	----------	-----------------------	------------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.

DAS Sport, LLC

1 Cleveland Street
Suite 1100
Gordonsville, VA 22942



Client

Date	Invoice #	Terms
11/20/24	2024-3057	Net 10

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2568

Item Type	Qty	Description	Net	Amount
LM - Labor	12.5	VIN# AZ288-612 Hours Mechanical Labor: Check for Oil Leaks (Post Break in) - Remove oil pump drive gear cover, fabricate gasket, reassemble with sealant and gasket, torque hardware to spec - Remove oil pan cover, fabricate gasket, reinstall with sealant, torque to spec - Remove oil pressure sensor (for light), clean threads and reapply Teflon tape to threads - Oil level overflow line, remove and reroute, fabricate and install catch can and route overflow line through catch can - Change engine oil, replace Wix spin on filter - Road test and clean up oily residue from leaks for reinspection, all improved now - Seeps still slightly present at push rod tubes, cylinder head gaskets (Cylinder #1), valve cover typical sweat but do not leak, all these are ok at this time	0.00	0.00
BKCRC	6	Non-Flammable Contaminant Cleaning Solvent 20 fl oz	0.00	0.00
SS	1	Supplies: Hylamar, Gasket Maker, Teflon Tape	0.00	0.00
VAL20W50	5	Valvoline VR1 Race 20W50 Engine Oil (1 qt)	22.00	110.00
Parts	1	WIX 51515 Oil Filter	22.02	22.02
Parts	1	Catch Can Vent Tank	74.95	74.95
Parts	1	ORE#5476-259033 Fitting (785-416D)	23.36	23.36
LM - Labor	1.5	Hours Mechanical Labor: No Brake Lights, Check Turnsignals - Test connections, and check junction block - Diagnose faulty brake light switch - Determine not flasher equipped, but does change indication on engagement of turnsignal stalk, would need flasher inserted to make flashing operation	225.00	337.50

Start Date	02/28/24	Invoice Amount
-------------------	----------	-----------------------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.

DAS Sport, LLC
 1 Cleveland Street
 Suite 1100
 Gordonsville, VA 22942



Client

Date	Invoice #	Terms
11/20/24	2024-3057	Net 10

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2568

Item Type	Qty	Description	Net	Amount
Parts	1	Brake Light Switch ORE#5476-259103	44.10	44.10
		*** Return ***		
CTEK-56-353	-1	CTEK MULTI US 7002 12-Volt Battery Charger (previously on inv#2023-2384)	196.48	-196.48
		*** Transport ***		
Transport	1	JBT Transport: Blufon to Gordonsville (October 2024)	0.00	0.00
Transport	1	Evans Transport: Gordonsville to Blufon (November 2024)	0.00	0.00
Tax	1	VA Sales Tax 5.3%	4.13	4.13

Start Date	02/28/24	Invoice Amount	\$419.58
-------------------	----------	-----------------------	----------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.

DAS Sport, LLC

1 Cleveland Street
 Suite 1100
 Gordonsville, VA 22942



Client

Date	Invoice #	Terms
09/05/23	2023-2384	Due On Receipt

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2463

Item Type	Qty	Description	Net	Amount
LM - Labor	13.5	VIN# AZ288-612 *** General Service *** Hours Mechanical Labor: - Install Cteck Battery Maintainer, Secure leads on driver's frame rail - Reassemble battery hold down which was missing all nuts/bolts - Throttle linkage loose, carburetors are out of balance, verify with air flow tester, set idle mixture screws, re-synched all carbs - Drain and refill hot engine oil, refiull with Porsche Classic 20w50, replace WIX #51515R oil filter - Drain and refill gearbox with Swepco 201 Gear Oil - Brake moinsture content, maxced on tester, flush brake fluid with ATE200 - Tires are 2010 date codes, but no cracking and wearing evenly, ok for now - Engine and gearbox cleaned thoroughly to figure out where leaks are, appears extended sump plate is leaking, needs removal and new cork gasket - make new gasket for extended sump plate, install, not leaking, ok now - Clean and repack front wheel bearings, adjust to spec - Road test hot and cold, all ok at this time	165.00	2,227.50
Parts	1	51515R Wix Oil Filter ORE#5476-219922	38.00	38.00
Parts	4	20W50 Porsche Classic Engine Oil	15.75	63.00
CTEK-56-353	1	CTEK MULTI US 7002 12-Volt Battery Charger	196.48	196.48
SS	1	Supplies: Zip Ties, Hardware for Battery	12.00	12.00
WB	1	Red Wheel Bearing Grease, Solvent	18.00	18.00
SWE201	3	Swpeco 201 Gear Oil Liter	38.00	114.00

Start Date	06/29/23	Invoice Amount
-------------------	----------	-----------------------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.

DAS Sport, LLC

1 Cleveland Street
 Suite 1100
 Gordonsville, VA 22942



Client

Date	Invoice #	Terms
09/05/23	2023-2384	Due On Receipt

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2463

Item Type	Qty	Description	Net	Amount
ATE200	1	ATE Brake Fluid; SuperGold Dot 4, Type 200; 1 Liter Can	22.00	22.00
SS	1	Oil Disposal, Oil Filter Disposal	18.00	18.00
SS	1	Supplies: General Supply Purchase WUR#97777420	41.02	41.02
Fuel	1	Fuel Reimbursement: 10.24 Gallons Unleaded Fuel (OAS#063023)	44.04	44.04
Parts	1	Gasket Material	42.58	42.58
Tax	1	VA Sales Tax 5.3%	32.28	32.28
LM - Labor	7.5	*** Engine Removal *** Hours Mechanical Labor: Engine misfires and is noisy on road test, engine has damage to at least one cylinder from lean carb running condition (fuel was completely cut off when car arrived), remove engine for disassembly, diagnosis and repair	185.00	1,387.50

Start Date	06/29/23	Invoice Amount	\$4,256.40
-------------------	----------	-----------------------	------------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.

DAS Sport, LLC

1 Cleveland Street
 Suite 1100
 Gordonsville, VA 22942



Client

Date	Invoice #	Terms
12/15/23	2023-2454	Due On Receipt

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2463

Item Type	Qty	Description	Net	Amount
		VIN# AZ288-612		
		*** Engine Repair ***		
LM - Labor	12.5	Hours Mechanical Labor: Disassembly, measurement, parts ordering, prepare heads for 5-angle valve job work - Split case, disassemble, loosen connecting rods, inspect oil pump, sorting, bagging, and cleaning parts (GIN#011124)	185.00	2,312.50
Sublet	1	Sublet Service: 5-Angle Valve Job (GIN#011124)	960.00	960.00
SS	1	Supplies: General Supply	125.00	125.00
Parts	1	CB Performance Invoice #111523	4,270.87	4,270.87
Parts	1	CB Performance Invoice #111723	377.56	377.56
Parts	1	Wisco Piston & Cylinder Set (94mm/Stroker Crank) CB Performance Invoice	1,137.50	1,137.50
Shipping	1	Shipping: Inbound Freight, Duty, Broker, Tariff, Tracking (Motor to Barry in Kitchener ON Canada	288.00	288.00
Transport	1	Gingrich Transportation: VW Engine to Canada (Transport/Duty/Tariff/Broker Only)	1,010.30	1,010.30
Archival Work	1	Admin	250.00	250.00

Start Date	10/15/23	Invoice Amount	\$10,731.73
-------------------	----------	-----------------------	-------------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.

DAS Sport, LLC
 1 Cleveland Street
 Suite 1100
 Gordonsville, VA 22942



Client

Date	Invoice #	Terms
03/27/24	2024-2672	Due On Receipt

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2463

Item Type	Qty	Description	Net	Amount
		VIN# AZ288-612		
		*** Engine Repair ***		
LM - Labor	1	Mechanical Labor: Assembly labor on 550 Spyder Engine - January 2024 (GIN#011124)	1,887.00	1,887.00
LM - Labor	1	Mechanical Labor: Assembly labor on 550 Spyder Engine - February 2024 (GIN#020224)	1,017.50	1,017.50
SS	1	Supplies: General Supply	125.00	125.00
Parts	1	CB Performance Invoice #012424	381.94	381.94
Shipping	1	Shipping: Inbound	46.17	46.17

Start Date	02/28/24	Invoice Amount	\$3,457.61
-------------------	----------	-----------------------	------------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.

DAS Sport, LLC

1 Cleveland Street
 Suite 1100
 Gordonsville, VA 22942



Client

Date	Invoice #	Terms
08/31/24	2024-2829	Net 10

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2463

Item Type	Qty	Description	Net	Amount
		VIN# AZ288-612		
		*** Reinstall Engine ***		
LM - Labor	24	Hours Mechanical Labor: Install assembled engine, clean up accessories, and make ready to proper complete install	225.00	5,400.00
SS	1	Supplies: Loctite, Anti-seize, Solvent, Grease, Cleaners	125.00	125.00
SS	1	Supplies: Paint and Prep Supply	133.50	133.50
VAL20W50	5	Valvoline VR1 Race 20W50 Engine Oil (1 qt)	22.00	110.00
Parts	1	WIX 51515 Oil Filter	22.02	22.02
BKCRC	2	Non-Flammable Contaminant Cleaning Solvent 20 fl oz	15.84	31.68
SS	1	Supplies: Hot Water Tank Cleaning & Solution	120.00	120.00
		*** Sort Electrics ***		
LM - Labor	2.5	Hours Mechanical Labor: No oil pressure lights, alternator light on all the time - Diagnose and replace the defective oil pressure switch - Alternator not charging, replace alternator (911 Style 12v) with a good used unit - Recheck operation, all ok now	225.00	562.50
Used	1	Used Part: Alternator	250.00	250.00
70007	1	Oil Pressure Switch	17.70	17.70
		*** Upholstery ***		
LM - Labor	2.5	Hours Mechanical Labor: Final install recovered pieces	225.00	562.50
Sublet	1	Sublet Service: Cover Head Rest, Shoulder Rest with supplied materials (DAN#061224)	766.50	766.50
		*** Rolling Road Tune ***		
LM - Labor	8	Hours Mechanical Labor: Tune at Dyno	225.00	1,800.00

Start Date	02/28/24	Invoice Amount
-------------------	----------	-----------------------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.

DAS Sport, LLC

1 Cleveland Street
 Suite 1100
 Gordonsville, VA 22942



Client

Date	Invoice #	Terms
08/31/24	2024-2829	Net 10

Vehicle	AZ288-612		
VIN#	550 Spyder	Mileage	2463

Item Type	Qty	Description	Net	Amount
Dyno	1	- Remove carburetors, struggling with fuel volume on the right side, fixed carb linkages for throttle - Six times rejetted to get correct settings (venturi mates in the bowl was damaged) - 155 jetting with 200 air corrector - at WOT it is 12:1 AFR, idle 13.8 to 14 to 1 AFR - Replace (driver's side) carburetor, now has both 'newer' carbs (right replaced previously) - Starts and runs reliably - 106 RWHP, 116 foot lbs of torque at rear wheels Dynamometer Session - Measure Horsepower and Torque, Tune Engine, Tune Carbs, Set engine running specifications	2,150.00	2,150.00
Transport	1	*** Logistics *** JBT Transportation: Drop off Car at Blufton SC Warehouse (NO CHARGE) on 09/08/24	0.00	0.00
Transport	10.5	hrs JBT Transportation: Transport to Dyno - Split with another car	77.00	808.50
Fuel	1	Fuel Reimbursement: Tow Vehicle Diesel (1/2 the cost)	62.65	62.65
Fuel	1	Fuel Reimbursement: Tow Vehcile Diesel 1/2 the cost)	40.94	40.94
Transport	1	Journey Transportation: Retrieve 550 at Dyno to return to Gordonsville (Aug 21 2024)	870.00	870.00
Tax	1	VA Sales Tax 5.3%	40.51	40.51

Start Date	02/28/24	Invoice Amount	\$13,874.00
-------------------	----------	-----------------------	-------------

These products and services including all installation labor, are purchased "as is" without express or implied warranty of fitness or merchantability, they are all intended for use in properly sanctioned, off road, high performance, competitive and racing events. Such events are inherently dangerous and can result in serious injury or death despite the product's proper manufacture, installation and use. Proper installation, inspection and use by qualified persons are necessary and are solely the responsibility of the purchaser(s) and all successors. There is no warranty of any kind expressed or implied.



1715 N. Farmersville Blvd, Farmersville, CA 93223
 (800) 274-8337 - (559) 733-8222 - (559) 733-7967 (Fax)

INVOICE

Date: 11/03/2023 Order#: 213415

Order Comments:

QUOTE ONLY

Additional Information:

Your Salesperson Is Marianne (marianne@cbperformance.com)

Bill To: (Customer ID#136513)

Ship To:

Payment Method:

None

Shipping Method:

U.P.S. Ground

Code	Description	Qty	Price	Total
2242bcek	2242bcek Eagle Racing Camshafts **BCEK only**	1	\$134.95	\$134.95
1274	1274 CB Super Case - AS41 Magnesium Engine Case (specify size) [Bore Size:94mm Bore] [Case Savers:Accepts 8mm (default)] [Labor Options:No Labor]	1	\$1,399.95	\$1,399.95
2665	2665 H-Beam Super Race Rods - Chevy rod journal - 5.500" length - set of 4	1	\$312.95	\$312.95
1859	1859 Maxi 30 Full Flow Oil Pump with Black Anodized Billet Cover with 3/8" outlet (to '70)	1	\$70.95	\$70.95
1278	1278 CB High Performance Case Kit	1	\$46.95	\$46.95
1537	1537 28mm Ultralight Racing Lifters (set of 8)	1	\$178.95	\$178.95
1941	1941 Rear Main Seal - 13, 15, & 1600cc (Germany)	1	\$3.95	\$3.95
1804	1804 Main Bearings STD	1	\$39.95	\$39.95
2672	2672 Rod Bearings - Clevite - Chevy Journal - STD. (set of 4)	1	\$45.95	\$45.95
1399	1399 CB Performance Straight Cut Adjustable Cam Gears	1	\$109.95	\$109.95
1565	1565 Racing Push Rod Tubes (set of 8)	1	\$24.95	\$24.95
1628	1628 Chromoly Push Rods - blank end (.035")	1	\$93.95	\$93.95
1030	1030 True-Arc Wrist Pin Locks (set of 8)	1	\$5.95	\$5.95
1999	1999 Deflector Plates (8mm) fits 13, 15, & 1600cc (set of 2)	1	\$9.95	\$9.95
1904	1904 Engine Case Washer Set	1	\$6.95	\$6.95
1946	1946 Posi-Seal Cam Plug (for Grooved Cases)	1	\$4.95	\$4.95
2673	2673 Super Race Crank - 84mm Stroke - Chevy Journals	1	\$294.95	\$294.95
1360	1360 Racing Gland Nut with Washer	1	\$19.95	\$19.95

1229	1229 Chromoly Cylinder Head Studs - Dual Port (8mm x 1.25)	1	\$86.95	\$86.95
1849	1849 Racing Camshaft Bearing Set	1	\$23.95	\$23.95
1684	1684 CB Super Stock Rocker Arm - Complete Kit 1.1:1 Ratio (stock)	1	\$144.95	\$144.95
1362	1362 End Play Shim Kit	1	\$9.95	\$9.95
1908	1908 Engine Case Lock Nut Kit	1	\$7.95	\$7.95
1277	1277 Engine Case Bolts - 8x55 (set of 3)	1	\$3.95	\$3.95
1973	1973 Gasket Set - 13, 15, & 1600cc Dual & Single Port Engines (Germany)	1	\$20.95	\$20.95
1311	1311 Stage 1 - 1700lb. 200mm Kennedy Clutch	2	\$132.95	\$265.90
1078	1078 Piston Rings - 94mm Forged CIMA/MAHLE	1	\$25.95	\$25.95
LABOR-BALANCE	LABOR-BALANCE Balance Crank, Pressure Plate, Flywheel	1	\$150.00	\$150.00

Subtotal: \$3,546.60

Tax: \$0.00

Shipping & Handling: \$300.33

Grand Total: \$3,846.93

FREIGHT CLAIMS: ALL goods shall be considered to be delivered to the purchaser when they are placed in the hands of the carrier and consigned to the purchaser. All claims of loss, damage or destruction must be made by the purchaser to the carrier.

. . . . ALL SALES "AS-IS" - NO WARRANTY - NO REFUND

We value you as a customer and will make every effort to keep you happy. However, because we sell only highly specialized racing parts, we can make NO WARRANTY whatsoever. Consequently, all sales are on an "AS-IS" basis. These are automobile parts designed for specific uses in automobiles only. The parts may be dangerous and may cause injury if used for any other purpose, or otherwise misused. They may also be dangerous and may cause injury if modified, redesigned or altered before use. CB Performance Products will not assume any liability for and will not pay you for any injuries caused to you or others by any misuse, modification, redesign, or alteration of our products. These parts are not for use on public highways, off-road racing purposes only. CB Performance Products, Inc. will not be responsible for any incidental or consequential damage including direct or indirect labor, towing, lodging, garage, repair, medical or legal expense in any way attributable to the use of any item in this catalog or to the delay or inconvenience caused by the necessity of replacing or repairing any such item. **No Exchanges or refunds after (30) days of purchase. No Returns allowed unless authorized with a Return Authorization Number by CB Performance Products. *ALL RETURN AUTHORIZATION NUMBERS ARE VALID FOR 30 DAYS FROM THE DATE AUTHORIZED*** Authorized returns must be prepaid. COD shipments will not be accepted. ALL Returns are subject to a 20% restocking fee. Claims for shortages or wrong parts received must be made within 24 hours of receipt of goods. Attention: Some items may be subject to California's Proposition 65 Law, for more information see www.P65Warnings.ca.gov