



**GermanTech MotorWorks, LLC**

11250 Midway Drive  
 Louisville, KY 40299  
 (502) 493-4050  
 Service@GermanTechMW.com  
 https://www.germantechmotorworks.com

**Invoice for RO #39000**

Service Advisor: Brad Fieldhouse  
 Date Created: 07/14/23 at 03:53 PM EDT  
 Client:   
 Vehicle: 2008 Audi RS4 Cabriolet

	2008 Audi RS4 Cabriolet 4.2L 8Cyl GAS BNS	RO #39000
	Naturally Aspirated VIN: WUAYU48H48K800280 License: OKBIMR Color: Black Odometer In: 112111 / Out: N/A	Time-In: 07/14/23 at 03:53 PM EDT Save Parts: No

**Client concerns:**

- Clutch is stuck on the floor and will not build pressure.

<b>1 - Level 1 Diagnostics (*initial up to 1 hour)</b>		<b>TECH: K G</b>
<p><b>Note:</b> Confirmed that the clutch hydraulic system will not build pressure. Tech attempted to bleed the system with no success. Recommend replacing both the master and the slave cylinders at this time. There is a possibility that even after replacement of both pieces in the hydraulic system, vehicle may still need the clutch replaced as well. There are traces of clutch material around the edge of the inspection holes on the bell housing of the transmission.</p> <p>*Due to the nature of the concern, additional diagnosis or test plans may be required and will be requested in logical blocks of time. As always, if diagnosis concludes ahead of schedule, applicable credits can/will be applied.</p>		
Labor:	Any additional labor over 1 hour must be communicated with customer.	\$159.97
✓ Approved on 07/14/23 at 03:53 PM EDT		Subtotal \$159.97 + est. Tax \$9.60 <b>\$169.57</b>

<b>2 - Clutch Replacement with Flywheel &amp; Transmission Mount</b>		<b>TECH: K G</b>
<p><b>Note:</b> Confirmed that the clutch hydraulic system will not build pressure. Tech attempted to bleed the system with no success. Recommend replacing both the master and the slave cylinders at this time. There is a possibility that even after replacement of both pieces in the hydraulic system, vehicle may still need the clutch replaced as well. There are traces of clutch material around the edge of the inspection holes on the bell housing of the transmission.</p> <p>Clutch Replacement With LUK Pressure Plate, Clutch Disc, and Flywheel and Transmission Mount Replacement (2yr/24k Mile Warranty)        **Clutch replacement comes with a 2yr/24k mile warranty. Warranty only covers issues with defects in materials. Any issues that arise due to normal wear or signs of abuse are not covered.**</p> <p>Removed the exhaust and the drive shaft. Removed both axles from the transmission, lowered the subframe, and removed the transmission. With the subframe lowered, tech replaced the engine and transmission mounts. Once transmission was removed, tech found the crank position sensor had been broken by the clutch disc when it failed. Removed and replaced the broken sensor. Replaced the clutch line with a aftermarket braided stainless upgrade. Installed the new clutch and flywheel assembly and reassembled the vehicle. Tech test drove the vehicle and found all vehicle will now move through all gears. It was found that third gear has a slight grind as you are shifting into it. This is likely due to a failing synchro for third gear. To correct this, the transmission would need to be removed and rebuilt.</p>		
Labor:	Remove & Replace Clutch Assembly	\$2,594.55
	Clutch Fluid Flush	\$216.21
	Remove & Replace Flywheel	\$39.99
Parts:	DOT4 Brake Fluid 1L	1 \$25.95
	Clutch Kit	1 \$628.33
	Clutch Slave Cylinder	1 \$196.67
	Flywheel Bolt Set of 8	1 \$54.16
	Flywheel	1 \$1,752.86
	Exhaust Flange Nut Copper	6 \$185.40
	Stud	6 \$19.56
	Transmission Mount	1 \$303.33
	Release Bearing	1 \$141.40
	Bolt	2 \$13.54
	Crank Position Sensor	1 \$418.60
Discounts:	LUK Flywheel Discount	-\$902.87
	LUK Clutch Kit Discount	-\$125.00
	Release Bearing Discount	-\$50.00
✓ Approved on 07/27/23 at 12:20 PM EDT		Subtotal \$5,512.68 + est. Tax \$330.76 <b>\$5,843.44</b>

**3 - Driver's Inner CV Axle Boot****TECH: K G**

Note: Tech found the driver side Inner cv axle boot to be torn. Recommend replacing the inner cv boot at this time.

With transmission removed, tech removed and replaced the inner cv axle boot on the driver side.

Labor:	Remove & Replace Front CV Axle Boot (when performed with transmission removal)		\$79.99
Part:	CV Boot Kit	1	\$64.26

✓ Approved on 07/27/23 at 12:20 PM EDT

Subtotal \$144.25 + est. Tax \$8.66

**\$152.91****4 - Engine and Transmission Mount Replacement****TECH: K G**

Note: found the passenger side engine mount to be collapsed and leaking. recommend replacing both engine mounts and the transmission mount at this time.

Engine mounts were replaced during the clutch replacement.

Labor:	Labor (No additional labor with front subframe removed)		\$0.00
Part:	Engine Mount	2	\$783.34

✓ Approved on 08/08/23 at 09:09 AM EDT

Subtotal \$783.34 + est. Tax \$47.00

**\$830.34****5 - Heater Hose****TECH: K G**

Note: When removing the transmission, a heater hose connection was broken. Tech replaced the heater hose and vacuum filled the cooling system.

Parts:	Heater Hose	1	\$128.33
	Engine Coolant / Antifreeze VW / Audi G-013-A8J-1G w/DISTILLED WATER	1	\$46.19

✓ Approved on 08/08/23 at 10:48 AM EDT

Subtotal \$174.52 + est. Tax \$10.47

**\$184.99****RO Fees**

Fee:	Job Supplies / Consumables		\$59.97
------	----------------------------	--	---------

Subtotal

**\$59.97**

I hereby understand that all work listed on this repair order has been completed in full and payment shall be remitted in full at the time of vehicle delivery. I understand that any parts and labor disputes may be brought to management's attention and handled in an appropriate manner. I understand that all parts installed at GermanTech MotorWorks, LLC are warranted for 36 months or 40,000 miles for defects in material and workmanship; unless otherwise stated in writing; some parts only carry a 12 month / 12,000-mile warranty; some limited warranty parts only carry a parts warranty for 12 months. The replacement warranty will cover both parts and installation labor charges for the period of the parts warranty, unless otherwise stated in writing. Proper maintenance is required for warranty coverage. Installed vehicle batteries are covered for 24 months and unlimited mileage for full cost replacement and will be pro-rated for the remainder of a 60-month period from the date of install/purchase; batteries for low-mileage vehicles do require battery maintenance for full warranty coverage. There is no warranty on customer-supplied parts or Used parts; any claims therein must be handled directly with the supplier of said parts by the customer. All vehicles left over 3 days after repairs are completed can/will incur a \$45.00 per day storage fee; vehicles left beyond 3 days will incur a \$175 per day storage fee.

[ROADSIDE ASSISTANCE TOLL-FREE NUMBER 866.924-3668]

PLEASE READ BEFORE SIGNING: In the event that seller is required to institute litigation or any other procedures to enforce and collect the amount on the sales transaction, Owner hereby agrees to and shall pay all expenses and costs of any such collection proceedings, including sellers' attorney's fees and court costs.



**GermanTech MotorWorks, LLC**

11250 Midway Drive  
 Louisville, KY 40299  
 (502) 493-4050  
 Service@GermanTechMW.com  
 https://www.germantechmotorworks.com

**Invoice for RO #48155**

Service Advisor: Brad Fieldhouse  
 Posted Date: 04/11/25 at 11:30 AM EDT  
 Client   
 Vehicle: 2008 Audi RS4 Cabriolet

	<b>2008 Audi RS4 Cabriolet 4.2L 8Cyl GAS BNS Naturally Aspirated</b> VIN: WUAYU48H48K800280 License: OKBIMR Color: Black Odometer In: 114673 / Out: 114674	<b>RO # 48155</b> Time-In: 04/11/25 at 08:44 AM EDT Save Parts: No
--	--	--

**Client concerns:**

- Oil service and inspection
- Hearing a noise from the right side when braking. Like a rotational squeaking like something is dragging. Hard to tell if it is front or rear. Heard best with the top down or windows down against a wall or a building. Customer would like to ride with the tech to make sure they hear it. Advise on diagnosis needed
- Would like Brian to take a look at the hood and quote a repaint.
- New exhaust was installed recently, want to make sure that it looks ok and does not need any adjustments. Not hearing any issues, just want a quick visual when the car is on the lift for the oil service

<b>1 - Audi Oil Service (6+ Cylinder)-Full Synthetic Oil</b> Tech:SL <b>Note:</b> *GermanTech MotorWorks recommends a 5k mile oil service interval.*  Oil service performed. Tech removed and installed new oil filter. Tech drained oil and replaced drain plug seal. Drain plug torqued to spec per repair manual. Tech topped off oil and rechecked, tech found oil level within spec. Tech reset service reminders, installed new oil sticker and test drove vehicle. Tech rechecked and found vehicle operates as designed to at this time with no leaks.			
<i>Labor:</i>	Labor		\$40.00
<i>Parts:</i>	Audi Oil Drain Plug Crush Washer	1	\$1.56
	5w40 Leichtlauf High Tech LiquiMoly Full Synthetic Motor Oil - Specs: API SN/CF, ACEA A3-08/B3-08. OEM Approval: MB 229.5 and AMG. Porsche A40. BMW LL-01. VW 502.00 / 505.00. - 1000L/1L	10	\$105.00
	Oil Filter	1	\$36.67
✓ Approved on 04/11/25 at 08:47 AM EDT		Subtotal \$183.23 + est. Tax \$10.99	<b>\$194.22</b>

<b>2 - Caliper Bolt Repair (Customer Concern, Brake Noise)</b> Tech:SL <b>Note:</b> Tech found right rear lower caliper bolt missing. Tech has since removed both right rear calipers bolts and installed new bolts. All hardware torqued to spec per repair manual. Tech checked and verified left rear caliper bolts are torqued as well.  Tech installed new right rear caliper bolts and torqued to spec per repair manual.			
<i>Labor:</i>	Remove & Replace Caliper Bolts		\$183.97
✓ Approved on 04/11/25 at 10:10 AM EDT		Subtotal \$183.97 + est. Tax \$11.04	<b>\$195.01</b>

<b>3 - Exhaust Adjustment (Recommend Bluegrass Muffler)</b> <b>Note:</b> Mid pipe clamp loose and mangled. Other clamps appear to be leaking as well. See attached photos and video. Rear portion of exhaust touching rear support bars. At this time tech recommends to readjust alignment of exhaust and replace clamps. Recommend to get in touch with Bluegrass Muffler 502-245-0414			
✓ Approved on 04/11/25 at 11:00 AM EDT		0	<b>0</b>

<b>RO Fees</b>			
<i>Fee:</i>	Job Supplies / Consumables		\$23.87
		Subtotal	<b>\$23.87</b>

I hereby understand that all work listed on this repair order has been completed in full and payment shall be remitted in full at the time of vehicle delivery. I understand that any parts and labor disputes may be brought to management's attention and handled in an appropriate manner. I understand that all parts installed at GermanTech MotorWorks, LLC are warranted for 36 months or 40,000 miles for defects in material and workmanship (excludes wear and tear); unless otherwise stated in writing; some parts only carry a 12 month / 12,000-mile warranty; some limited warranty parts only carry a parts warranty for 12 months. The replacement warranty will cover both parts and installation labor charges for the period of the parts warranty, unless otherwise stated in writing. Proper maintenance is required for warranty coverage. Installed vehicle batteries are covered for 24 months and unlimited mileage for full cost replacement and will be pro-rated for the remainder of a 60-month period from the date of install/purchase; batteries for low-mileage vehicles do require battery maintenance for full warranty coverage. There is no warranty on customer-supplied parts or Used parts; any claims therein must be handled directly with the supplier of said parts by the customer. An express Mechanic's Lien (KY 376.270) is hereby acknowledged on the above vehicle to secure the amount of the repairs thereto. All vehicles left over 3 days after repairs are completed can/will incur a \$45.00 per day storage fee; vehicles left beyond 3 days will incur a \$175 per day storage fee. If GermanTech MotorWorks LLC is the merchant on your credit card transaction, you agree that GermanTech MotorWorks, LLC's services consist of facilitating the sale (maintenance and repair including supplied parts and materials), and once GermanTech MotorWorks, LLC provides said services, you agree not to dispute the credit card charge. As stated above, any disputes must be brought to management's attention and handled in an appropriate manner.

[ROADSIDE ASSISTANCE TOLL-FREE NUMBER (502) 255-2822 - Towing provided up to \$150.00]

PLEASE READ BEFORE SIGNING: In the event that seller is required to institute litigation or any other procedures to enforce and collect the amount on the sales transaction, Owner hereby agrees to and shall pay all expenses and costs of any such collection proceedings, including sellers' attorney's fees and court costs.

**Total Repair Order & Signature:**

Total Jobs: \$367.20  
 Total Fees: \$23.87  
**Subtotal: \$391.07**  
 Taxes: \$23.46  
**Grand Total: \$414.53**  
**BALANCE DUE: \$0.00**

X

✓ PAID

Completed Transactions						
04/11/25		\$414.53	Credit Card Payment	Discover**** 4579 Auth: 01126P	Contactless Discover AID:A00000015230100100000001	

**Declined Jobs:**

<b>1 - Right HPFP Replacement</b>			
Tech:S L			
<b>Note:</b> High pressure fuel pump on passenger bank is leaking. See attached photos. Tech recommends replacing high pressure pump at this time.			
Labor:	Remove & Replace Fuel Pump		\$285.62
Parts:	Fuel Pump Tappet	1	\$100.76
	Fuel Pump O-Ring	1	\$15.42
	Direct Injection Fuel Pump	1	\$861.52
<b>X Declined on 04/11/25 at 10:34 AM EDT</b>		Subtotal \$1,263.32 + est. Tax \$75.80	<b>\$1,339.12</b>
<b>2 - Drive Belt Replacement</b>			
Tech:S L			
<b>Note:</b> Drive belt shows cracks. Tech recommends replacing drive belt at this time.			
Labor:	Remove & Replace Drive Belt (Accessory/Serpentine)		\$777.04
Part:	Drive Belt	1	\$43.48
<b>X Declined on 04/11/25 at 10:34 AM EDT</b>		Subtotal \$820.52 + est. Tax \$49.23	<b>\$869.75</b>

**3 - Left Front Inner CV Boot Replacement**

Tech:S L

**Note:** Driver front inner cv boot appears to be starting to sling grease from cv boot. Tech recommends to monitor this condition for future repairs.

Labor:	Remove & Replace Front CV Joint Boot (One)		\$577.58
Part:	CV Boot Kit - Inner	1	\$74.48

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$652.06 + est. Tax \$39.12

**\$691.18****4 - Power Steering Fluid Leak (Clean & Recheck)**

Tech:S L

**Note:** Power steering leak appears to be present. Power steering pump and lines at pump show wetness.

Labor:	Engine Cleaning		\$91.99
Part:	Brake & Parts Cleaner	1	\$6.25

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$98.24 + est. Tax \$5.89

**\$104.13****5 - GT Filter, Engine Air (2yr/40k)**

Tech:S L

**Note:** 09/10/2013 79,935 - air filter replacement recommended with 40k miles. Tech would recommend replacing air filter due to age, next replacement would be at 119k miles.

Labor:	Remove & Replace Engine Air Filter Element		\$95.66
Part:	Air Filter - Special Order	1	\$50.74

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$146.40 + est. Tax \$8.78

**\$155.18****6 - GT Multi Bleed Port (Porsche, AMG, M, etc) Brake Fluid System Flush (2yrs or 30k)**

Tech:S L

**Note:** No history per carfax. Recommended brake flush service every 2 years or 30k miles.

Labor:	Labor		\$224.91
Part:	DOT4 LV Brake Fluid 1L	1	\$25.95

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$250.86 + est. Tax \$15.05

**\$265.91****7 - GT Audi Rear Differential Fluid Service**

Tech:S L

**Note:** No history per carfax. Recommended rear differential service every 60k miles.

Labor:	Drain & Fill Rear Diff		\$137.98
Part:	Gear Oil GEAR 300 LS 75W90 1L	1	\$52.56


**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$190.54 + est. Tax \$11.43

**\$201.97**



**GermanTech MotorWorks, LLC**  
 11250 Midway Drive  
 Louisville, KY 40299  
 (502) 493-4050  
 Service@GermanTechMW.com  
<https://www.germantechmotorworks.com>

**Invoice for RO #48155**  
 Service Advisor: Brad Fieldhouse  
 Posted Date: 04/11/25 at 11:30 AM EDT  
 Client:   
 Vehicle: 2008 Audi RS4 Cabriolet

	<b>2008 Audi RS4 Cabriolet 4.2L 8Cyl GAS BNS Naturally Aspirated</b> VIN: WUAYU48H48K800280 License: OKBIMR Color: Black Odometer In: 114673 / Out: 114674	<b>RO # 48155</b> Time-In: 04/11/25 at 08:44 AM EDT Save Parts: No
---	--	--

**Client concerns:**

- Oil service and inspection
- Hearing a noise from the right side when braking. Like a rotational squeaking like something is dragging. Hard to tell if it is front or rear. Heard best with the top down or windows down against a wall or a building. Customer would like to ride with the tech to make sure they hear it. Advise on diagnosis needed
- Would like Brian to take a look at the hood and quote a repaint.
- New exhaust was installed recently, want to make sure that it looks ok and does not need any adjustments. Not hearing any issues, just want a quick visual when the car is on the lift for the oil service

<b>1 - Audi Oil Service (6+ Cylinder)-Full Synthetic Oil</b> Tech:SL <b>Note:</b> *GermanTech MotorWorks recommends a 5k mile oil service interval.*  Oil service performed. Tech removed and installed new oil filter. Tech drained oil and replaced drain plug seal. Drain plug torqued to spec per repair manual. Tech topped off oil and rechecked, tech found oil level within spec. Tech reset service reminders, installed new oil sticker and test drove vehicle. Tech rechecked and found vehicle operates as designed to at this time with no leaks.			
<i>Labor:</i>	Labor		\$40.00
<i>Parts:</i>	Audi Oil Drain Plug Crush Washer	1	\$1.56
	5w40 Leichtlauf High Tech LiquiMoly Full Synthetic Motor Oil - Specs: API SN/CF, ACEA A3-08/B3-08. OEM Approval: MB 229.5 and AMG. Porsche A40. BMW LL-01. VW 502.00 / 505.00. - 1000L/1L	10	\$105.00
	Oil Filter	1	\$36.67
✓ Approved on 04/11/25 at 08:47 AM EDT		<i>Subtotal \$183.23 + est. Tax \$10.99</i>	<b>\$194.22</b>

<b>2 - Caliper Bolt Repair (Customer Concern, Brake Noise)</b> Tech:SL <b>Note:</b> Tech found right rear lower caliper bolt missing. Tech has since removed both right rear calipers bolts and installed new bolts. All hardware torqued to spec per repair manual. Tech checked and verified left rear caliper bolts are torqued as well.  Tech installed new right rear caliper bolts and torqued to spec per repair manual.			
<i>Labor:</i>	Remove & Replace Caliper Bolts		\$183.97
✓ Approved on 04/11/25 at 10:10 AM EDT		<i>Subtotal \$183.97 + est. Tax \$11.04</i>	<b>\$195.01</b>

<b>3 - Exhaust Adjustment (Recommend Bluegrass Muffler)</b> <b>Note:</b> Mid pipe clamp loose and mangled. Other clamps appear to be leaking as well. See attached photos and video. Rear portion of exhaust touching rear support bars. At this time tech recommends to readjust alignment of exhaust and replace clamps. Recommend to get in touch with Bluegrass Muffler 502-245-0414			
✓ Approved on 04/11/25 at 11:00 AM EDT		0	0

<b>RO Fees</b>			
<i>Fee:</i>	Job Supplies / Consumables		\$23.87
		<i>Subtotal</i>	<b>\$23.87</b>

I hereby understand that all work listed on this repair order has been completed in full and payment shall be remitted in full at the time of vehicle delivery. I understand that any parts and labor disputes may be brought to management's attention and handled in an appropriate manner. I understand that all parts installed at GermanTech MotorWorks, LLC are warranted for 36 months or 40,000 miles for defects in material and workmanship (excludes wear and tear); unless otherwise stated in writing; some parts only carry a 12 month / 12,000-mile warranty; some limited warranty parts only carry a parts warranty for 12 months. The replacement warranty will cover both parts and installation labor charges for the period of the parts warranty, unless otherwise stated in writing. Proper maintenance is required for warranty coverage. Installed vehicle batteries are covered for 24 months and unlimited mileage for full cost replacement and will be pro-rated for the remainder of a 60-month period from the date of install/purchase; batteries for low-mileage vehicles do require battery maintenance for full warranty coverage. There is no warranty on customer-supplied parts or Used parts; any claims therein must be handled directly with the supplier of said parts by the customer. An express Mechanic's Lien (KY 376.270) is hereby acknowledged on the above vehicle to secure the amount of the repairs thereto. All vehicles left over 3 days after repairs are completed can/will incur a \$45.00 per day storage fee; vehicles left beyond 3 days will incur a \$175 per day storage fee. If GermanTech MotorWorks LLC is the merchant on your credit card transaction, you agree that GermanTech MotorWorks, LLC's services consist of facilitating the sale (maintenance and repair including supplied parts and materials), and once GermanTech MotorWorks, LLC provides said services, you agree not to dispute the credit card charge. As stated above, any disputes must be brought to management's attention and handled in an appropriate manner.

[ROADSIDE ASSISTANCE TOLL-FREE NUMBER (502) 255-2822 - Towing provided up to \$150.00]

PLEASE READ BEFORE SIGNING: In the event that seller is required to institute litigation or any other procedures to enforce and collect the amount on the sales transaction, Owner hereby agrees to and shall pay all expenses and costs of any such collection proceedings, including sellers' attorney's fees and court costs.

**Total Repair Order & Signature:**

Total Jobs:	\$367.20
Total Fees:	\$23.87
<b>Subtotal:</b>	<b>\$391.07</b>
Taxes:	\$23.46
<b>Grand Total:</b>	<b>\$414.53</b>
<b>BALANCE DUE:</b>	<b>\$0.00</b>

X ✓ PAID

Completed Transactions					
04/11/25		\$414.53	Credit Card Payment	Discover**** 4579 Auth: 01126P	Contactless Discover AID:A00000015230100100000001

**Declined Jobs:**

1 - Right HPFP Replacement			
Tech: S L			
<b>Note:</b> High pressure fuel pump on passenger bank is leaking. See attached photos. Tech recommends replacing high pressure pump at this time.			
<i>Labor:</i>	Remove & Replace Fuel Pump		\$285.62
<i>Parts:</i>	Fuel Pump Tappet	1	\$100.76
	Fuel Pump O-Ring	1	\$15.42
	Direct Injection Fuel Pump	1	\$861.52
<b>X Declined on 04/11/25 at 10:34 AM EDT</b>			<i>Subtotal \$1,263.32 + est. Tax \$75.80</i> <b>\$1,339.12</b>

2 - Drive Belt Replacement			
Tech: S L			
<b>Note:</b> Drive belt shows cracks. Tech recommends replacing drive belt at this time.			
<i>Labor:</i>	Remove & Replace Drive Belt (Accessory/Serpentine)		\$777.04
<i>Part:</i>	Drive Belt	1	\$43.48
<b>X Declined on 04/11/25 at 10:34 AM EDT</b>			<i>Subtotal \$820.52 + est. Tax \$49.23</i> <b>\$869.75</b>

**3 - Left Front Inner CV Boot Replacement**

Tech:S L

**Note:** Driver front inner cv boot appears to be starting to sling grease from cv boot. Tech recommends to monitor this condition for future repairs.

Labor:	Remove & Replace Front CV Joint Boot (One)		\$577.58
Part:	CV Boot Kit - Inner	1	\$74.48

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$652.06 + est. Tax \$39.12

**\$691.18****4 - Power Steering Fluid Leak (Clean & Recheck)**

Tech:S L

**Note:** Power steering leak appears to be present. Power steering pump and lines at pump show wetness.

Labor:	Engine Cleaning		\$91.99
Part:	Brake & Parts Cleaner	1	\$6.25

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$98.24 + est. Tax \$5.89

**\$104.13****5 - GT Filter, Engine Air (2yr/40k)**

Tech:S L

**Note:** 09/10/2013 79,935 - air filter replacement recommended with 40k miles. Tech would recommend replacing air filter due to age, next replacement would be at 119k miles.

Labor:	Remove & Replace Engine Air Filter Element		\$95.66
Part:	Air Filter - Special Order	1	\$50.74

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$146.40 + est. Tax \$8.78

**\$155.18****6 - GT Multi Bleed Port (Porsche, AMG, M, etc) Brake Fluid System Flush (2yrs or 30k)**

Tech:S L

**Note:** No history per carfax. Recommended brake flush service every 2 years or 30k miles.

Labor:	Labor		\$224.91
Part:	DOT4 LV Brake Fluid 1L	1	\$25.95

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$250.86 + est. Tax \$15.05

**\$265.91****7 - GT Audi Rear Differential Fluid Service**

Tech:S L


**Note:** No history per carfax. Recommended rear differential service every 60k miles.

Labor:	Drain & Fill Rear Diff		\$137.98
Part:	Gear Oil GEAR 300 LS 75W90 1L	1	\$52.56

**X Declined on 04/11/25 at 10:34 AM EDT**

Subtotal \$190.54 + est. Tax \$11.43

**\$201.97**



YEAR: 2008  
 MAKE/MODEL: AUDI RS4 QUATTRO  
 VIN: WUAYU48H48K800280  
 ENGINE: 4.2L V8 F DOHC 32V  
 TRANS/DRIVE: 6 SPD MANUAL M/AWD  
 LICENSE/STATE: /IN  
 MILES IN/MILES OUT: 113200/113235

In: 11/30/2023 Out: 3/26/2024 Source: NONE Email [REDACTED]

**VEHICLE ISSUE #1: 3RD GEAR REBUILD**

PART: 0A2311283-RS4FUL	JHM 0A3 REBUILD KIT JHM-PERFORMANCE 3-PIECE SYNCHRONIZER RINGS (6) - OEM, UPDATED 1-2 SHIFT COLLAR OR SYNCHRO HUB - OEM, UPDATED 2ND GEAR - OEM INPUT SHAFT SEAL - OEM INPUT SHAFT SEAL C-CLIP - OEM INP	1 @ \$2,550.98	\$2,550.98	NEW
PART: LIQUIMOLY 75W90	75W90 SYNTHETIC GEAR OIL	5 @ \$33.06	\$165.30	NEW
PART: 070907601A	CRANKSHAFT POSITION SENSOR	1 @ \$99.97	\$99.97	NEW
LABOR: PRICE, B	TRANSMISSION R&R	7.2 @ \$180.00	\$1,296.00	LABOR
LABOR: PRICE, B	TRANSMISSION INTERNAL REBUILD; ALL SYNCHROS AND SEALS, COLLARS, JHM-PERFORMANCE 3-PIECE SYNCHRONIZER RINGS (6) - OEM, UPDATED 1-2 SHIFT COLLAR OR SYNCHRO HUB - OEM, UPDATED 2ND GEAR - OEM INPUT SHAFT	9 @ \$180.00	\$1,620.00	LABOR

**VEHICLE ISSUE #2: CONTROL ARMS**

PART: 19006-08065212	MEYLE OE COMPLETE CONTROL ARM KIT	1 @ \$617.34	\$617.34	NEW
LABOR: PRICE, B	UPPER CONTROL ARM, R&R, A4, S4, RS4, BOTH SIDES	2.9 @ \$180.00	\$522.00	LABOR
LABOR: PRICE, B	LOWER CONTROL ARM, R&R, A4, S4, RS4, BOTH SIDES	3 @ \$180.00	\$540.00	LABOR

**VEHICLE ISSUE #3: FUEL LEVEL SENSOR AND CLUTCH SWITCH**

PART: 7H0 927 189	OE CLUTCH PEDAL SWITCH	1 @ \$57.50	\$57.50	NEW
PART: 8E0201317R	FUEL TANK SENDER ASSEMBLY	1 @ \$391.66	\$391.66	NEW
LABOR: PRICE, B	CLUTCH SWITCH, R&R, A4, S4, RS4	0.9 @ \$180.00	\$162.00	LABOR
LABOR: PRICE, C	FUEL LEVEL SENDER, R&I, IN TANK, RS4	1.3 @ \$180.00	\$234.00	LABOR

**VEHICLE ISSUE #4: EXHAUST**

LABOR: PRICE, B	FULL CUSTOM STAINLESS EXHAUST	15 @ \$180.00	\$2,500.00	LABOR
-----------------	-------------------------------	---------------	------------	-------


**VEHICLE ISSUE #5: FIX SOFT TOP**

PART: 8H0-959-613 A	AUDI CONVERTIBLE TOP SENSOR	1 @ \$136.49	\$136.49	NEW
PART: 8H0959727B5PR	CONVERTIBLE TOP CONTROL SWITCH	1 @ \$119.99	\$119.99	NEW
PART: CONVERTIBLE TOP	B6/B7 CABRIOLET CONVERTIBLE TOP PUMP, MOTOR, RELAY	1 @ \$360.00	\$360.00	NEW

Recommended Repairs:  Warranty. For a period beginning on the date that Renn Sport Performance ("RSP") notifies the customer identified above that the repairs described above are complete and continuing for the lesser of 30 days or 500 miles from the mileage reading as of such notice, RSP will repair free of charge defects in materials used or its workmanship related to the services described above, provided that all such repairs must be completed by RSP at its facilities. This does not include towing charges, ANY performance modification's, or customer supplied parts. This warranty shall be void in the event that there is any damage resulting from the negligent or intentional acts of the customer or any third party.	Labor/Jobs	\$6,962.00
	Parts	\$4,950.88
	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$11,912.88
	Tax @ 7%	\$346.56
	Total	\$12,259.44
	Payments	\$7,000.00
	Balance	\$5,259.44

By signing below, the customer acknowledges and agrees that: (1) RSP is authorized to perform the services described above, including the use of any necessary materials; (2) the customer shall remit payment for parts plus half labor upon reception of vehicle and remit remaining payment immediately upon RSP's completion of the services described above; (3) replaced parts may be requested by customer for return immediately upon completion of the services described above; (4) parts removed during the performance of the services described above are subject to proper disposal; (5) RSP and its employees are authorized to operate the vehicle described above for the purposes of testing, inspection or delivery at customer's sole risk; (6) RSP shall have the right to a mechanic's lien on the vehicle described above

X \_\_\_\_\_ Date 3/26/2024



YEAR: 2008  
 MAKE/MODEL: AUDI RS4 QUATTRO  
 VIN: WUAYU48H48K800280  
 ENGINE: 4.2L V8 F DOHC 32V  
 TRANS/DRIVE: 6 SPD MANUAL M/AWD  
 LICENSE/STATE: /IN  
 MILES IN/MILES OUT: 113200/113235

PUMP,MOTOR,REL  
 AY

PART: B6/B7 CABRIOLET CONVERTIBLE TOP PUMP, MOTOR, RELAY 1 @ \$360.00 \$360.00 NEW  
 CONVERTIBLE TOP  
 PUMP,MOTOR,REL  
 AY

PART: PNT-CHF11S HYDRAULIC FLUID (CHF-11 POWER STEERING FLUID) 1 @ \$49.99 \$49.99 NEW

**VEHICLE ISSUE #6: OIL AND FILTER CHANGE, CABIN AIR FILTER**

PART: 3734 CABIN AIR FILTER 1 @ \$41.66 \$41.66 NEW

LABOR: CARMER, 10 QT LIQUI MOLY OIL CHANGE 1.3889 @ \$180.00 \$250.00 LABOR

**LABOR DISCOUNT - \$162.00  
 YOUR TOTAL SAVINGS TODAY - \$162.00**

Payment Rec'd	VENMO	Date : 11/30/2023	\$2,700.00
Payment Rec'd	PAYPAL	Date : 11/30/2023	\$800.00
Payment Rec'd	VENMO	Date : 12/10/2023	\$1,500.00
Payment Rec'd	Visa REF # square	Date : 1/15/2024	\$2,000.00
12/11/2023 09:53 - CUSTOMER	QUOTE VEHICLE ISSUE GOT APPROVED		
12/11/2023 09:53 -	AN EMAIL WAS SENT TO THE SHOP INDICATING A CUSTOMER CLICKED TO APPROVE A REPAIR ORDER BUT DID NOT SIGN THE RO AT 12-11-2023 09:53:11		
12/11/2023 09:53 - SHOP BOSS	A REMOTE SIGNATURE WAS RECEIVED AT 12-11-2023 09:53:46		
12/11/2023 09:53 - SHOP BOSS	THE RO WAS APPROVED AND AN EMAIL WAS SENT TO THE SHOP REGARDING THE REMOTE SIGNATURE THAT WAS RECEIVED AT 12-11-2023 09:53:46		
1/8/2024 16:16 - JOEL MYERS	SENT VIA TEXT MESSAGE: FROM RENN SPORT PERFORMANCE LLC AT 3174699650: INFORMATION UPDATE ON YOUR VEHICLE REPAIR. HTTPS://SBPT.IO/XJIL3		
1/8/2024 16:16 - JOEL MYERS	AN TEXT MESSAGE UPDATE WAS SENT TO 6092845774 FOR RO#1479		
1/8/2024 16:16 - JOEL MYERS	AN EMAIL UPDATE WAS SENT TO SHANE.M.REYNOLDS@GMAIL.COM FOR RO#1479		
1/9/2024 08:31 - JOEL MYERS	SENT VIA TEXT MESSAGE: FROM RENN SPORT PERFORMANCE LLC AT 3174699650: INFORMATION UPDATE ON YOUR VEHICLE REPAIR. HTTPS://SBPT.IO/UW18V		
1/9/2024 08:31 - JOEL MYERS	AN TEXT MESSAGE UPDATE WAS SENT TO 6092845774 FOR RO#1479		

Recommended Repairs:  Warranty. For a period beginning on the date that Renn Sport Performance ("RSP") notifies the customer identified above that the repairs described above are complete and continuing for the lesser of 30 days or 500 miles from the mileage reading as of such notice, RSP will repair free of charge defects in materials used or its workmanship related to the services described above, provided that all such repairs must be completed by RSP at its facilities. This does not include towing charges, ANY performance modification's, or customer supplied parts. This warranty shall be void in the event that there is any damage resulting from the negligent or intentional acts of the customer or any third party.	Labor/Jobs	\$6,962.00
	Parts	\$4,950.88
	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$11,912.88
	Tax @ 7%	\$346.56
	Total	\$12,259.44
	Payments	\$7,000.00
	Balance	\$5,259.44

By signing below, the customer acknowledges and agrees that: (1) RSP is authorized to perform the services described above, including the use of any necessary materials; (2) the customer shall remit payment for parts plus half labor upon reception of vehicle and remit remaining payment immediately upon RSP's completion of the services described above; (3) replaced parts may be requested by customer for return immediately upon completion of the services described above; (4) parts removed during the performance of the services described above are subject to proper disposal; (5) RSP and its employees are authorized to operate the vehicle described above for the purposes of testing, inspection or delivery at customer's sole risk; (6) RSP shall have the right to a mechanic's lien on the vehicle described above to secure full a ment as

X \_\_\_\_\_ Date 3/26/2024



YEAR: 2008 TRANS/DRIVE: 6 SPD MANUAL M/AWD  
 MAKE/MODEL: AUDI RS4 QUATTRO LICENSE/STATE: /IN  
 VIN: WUAYU48H48K800280 MILES IN/MILES OUT: 113200/113235  
 ENGINE: 4.2L V8 F DOHC 32V

1/9/2024 08:31 - JOEL MYERS	AN EMAIL UPDATE WAS SENT TO SHANE.M.REYNOLDS@GMAIL.COM FOR RO#1479
1/9/2024 08:33 - CUSTOMER	FUEL LEVEL SENSOR AND CLUTCH SWITCH VEHICLE ISSUE GOT APPROVED
1/9/2024 08:33 - CUSTOMER	EXHAUST VEHICLE ISSUE GOT APPROVED
1/9/2024 08:41 - JOEL MYERS	SENT VIA TEXT MESSAGE: FROM RENN SPORT PERFORMANCE LLC AT 3174699650: INFORMATION UPDATE ON YOUR VEHICLE REPAIR. HTTPS://SBPT.IO/LOSW7
1/9/2024 08:41 - JOEL MYERS	AN TEXT MESSAGE UPDATE WAS SENT TO 6092845774 FOR RO#1479
1/9/2024 08:41 - JOEL MYERS	AN EMAIL UPDATE WAS SENT TO SHANE.M.REYNOLDS@GMAIL.COM FOR RO#1479
1/9/2024 09:28 - CUSTOMER	CONTROL ARMS VEHICLE ISSUE GOT APPROVED
1/9/2024 09:29 -	AN EMAIL WAS SENT TO THE SHOP INDICATING A CUSTOMER CLICKED TO APPROVE A REPAIR ORDER BUT DID NOT SIGN THE RO AT 01-09-2024 09:29:08
1/9/2024 09:30 - SHOP BOSS	A REMOTE SIGNATURE WAS RECEIVED AT 01-09-2024 09:30:03
1/9/2024 09:30 - SHOP BOSS	THE RO WAS APPROVED AND AN EMAIL WAS SENT TO THE SHOP REGARDING THE REMOTE SIGNATURE THAT WAS RECEIVED AT 01-09-2024 09:30:03
1/9/2024 13:37 - JOEL MYERS	SENT VIA TEXT MESSAGE: FROM RENN SPORT PERFORMANCE LLC AT 3174699650: INFORMATION UPDATE ON YOUR VEHICLE REPAIR. HTTPS://SBPT.IO/Y9VK5
1/9/2024 13:37 - JOEL MYERS	AN TEXT MESSAGE UPDATE WAS SENT TO 6092845774 FOR RO#1479
1/9/2024 13:37 - JOEL MYERS	AN EMAIL UPDATE WAS SENT TO SHANE.M.REYNOLDS@GMAIL.COM FOR RO#1479
3/26/2024 15:30 - CUSTOMER	OIL AND FILTER CHANGE, CABIN AIR FILTER VEHICLE ISSUE GOT APPROVED
3/26/2024 15:31 - CUSTOMER	FIX SOFT TOP VEHICLE ISSUE GOT APPROVED
3/26/2024 15:31 -	AN EMAIL WAS SENT TO THE SHOP INDICATING A CUSTOMER CLICKED TO APPROVE A REPAIR ORDER BUT DID NOT SIGN THE RO AT 03-26-2024 15:31:46

Recommended Repairs:  Warranty. For a period beginning on the date that Renn Sport Performance ("RSP") notifies the customer identified above that the repairs described above are complete and continuing for the lesser of 30 days or 500 miles from the mileage reading as of such notice, RSP will repair free of charge defects in materials used or its workmanship related to the services described above, provided that all such repairs must be completed by RSP at its facilities. This does not include towing charges, ANY performance modification's, or customer supplied parts. This warranty shall be void in the event that there is any damage resulting from the negligent or intentional acts of the customer or any third party.	Labor/Jobs	\$6,962.00
	Parts	\$4,950.88
	Sublet	\$0.00
	Total Fees	\$0.00
	Subtotal	\$11,912.88
	Tax @ 7%	\$346.56
	Total	\$12,259.44
	Payments	\$7,000.00
	Balance	\$5,259.44

By signing below, the customer acknowledges and agrees that: (1) RSP is authorized to perform the services described above, including the use of any necessary materials; (2) the customer shall remit payment for parts plus half labor upon reception of vehicle and remit remaining payment immediately upon RSP's completion of the services described above; (3) replaced parts may be requested by customer for return immediately upon completion of the services described above; (4) parts removed during the performance of the services described above are subject to proper disposal; (5) RSP and its employees are authorized to operate the vehicle described above for the purposes of testing, inspection or delivery at customer's sole risk; (6) RSP shall have the right to a mechanic's lien on the vehicle described above

X  Date 3/26/2024



Home:  
Mobile:  
Work:  
Email:

Dec 9, 2021 10:55 AM  
YMMS: 2008 Audi RS 4  
Engine: 4.2L Eng  
License:  
VIN: WUAYU48H48K800280  
Odometer: 110339

TYPE	DESCRIPTION	PART #	QTY	PRICE	RATE	HOURS	LINE TOTAL
Labor	BRAKE SHOES &/OR PADS - Remove & Replace - [Includes: Clean, lube and/or replace Brake Hardware as necessary. Adjust Brakes (where applicable). Includes: Repack Wheel Bearings (where applicable). DOES NOT include refinishing.] All	-	-	-	\$160.00	2.5	\$400.00
Parts	BRAKE SHOES &/OR PADS Front HAWK	8E0 698 151 H	1.0	\$299.99	-	-	\$299.99
Parts	DISC ROTOR Each,Front	8E0 615 301 AB	2.0	\$750.00	-	-	\$1,500.00
Parts	BRAKE SHOES &/OR PADS REAR PAGID		1.0	\$59.99	-	-	\$59.99
Labor	SHOCK &/OR STRUT ASSEMBLY - Remove & Install or Remove & Replace - [DOES NOT include disassemble or alignment.] Both - [Includes: Drain and refill Hydraulic Oil. Includes: Bleed System.]	-	-	-	\$160.00	3.5	\$560.00
Parts	SHOCK &/OR STRUT ASSEMBLY Each	8E0 412 019 B	2.0	\$250.00	-	-	\$500.00
Parts	HYDRAULIC FLUID		1.0	\$20.00	-	-	\$20.00
Parts	TURNING REAR ROTORS		1.0	\$60.00	-	-	\$60.00
Parts	MOUNT AND BALANCE		1.0	\$90.00	-	-	\$90.00
Labor	15% OFF THE ROTORS AND DRC FILLING LABOR FREE	-	-	-	\$160.00	0.0	\$0.00
Labor	DRC FILLING HAD TO PAY GUY FROM AUDI	-	-	-	\$160.00	1.6	\$256.00
Labor	CALIPER PAINT	-	-	-	\$160.00	1.5	\$240.00
Parts	WIPER BLADES		1.0	\$45.99	-	-	\$45.99
Parts	POWDER COATING WHEELS		1.0	\$600.00	-	-	\$600.00
Labor Discount	RETURNING CUSTOMER						10.00%

Labor:	\$1,456.00
Parts:	\$3,175.97
Shop Supplies:	\$0.00
Hazardous Materials:	\$0.00
Labor Discount:	\$145.80
Labor Taxes:	\$0.00
Parts Taxes:	\$222.32
<b>TOTAL:</b>	<b>\$4,708.69</b>

Customer Signature: \_\_\_\_\_



-2000 oct 15

2000 oct 19

768.69

608.69