

## **1995 M3 Repair / Replacement List**

(Omitting routine maintenance/wear items)

<b><u>DATE</u></b>	<b><u>MILES</u></b>	<b><u>ACTIVITY</u></b>
09/27/2004	66,416	Replace rear shock towers (both sides)
11/02/2004		Ultimate mats and rubber mats from Bavarian Autosport.
04/04/2005	70,360	New metal impeller water pump and thermostat.
05/02/2005		Replace all brake pads and brake sensor wires.
07/06/2005		Replaced alternator and air conditioner belts.
03/29/2006		New Bilstein struts and shocks, together with new shock tower mounts and mount reinforcements. Install Bavarian Autosport high performance ignition coils.
06/06/2006		Repair crack and alignment of spare wheel.
07/05/2006		Upgrade to stainless steel brake line kit on all wheels.
08/23/2006		Replace stock plastic headlight units with euro glass headlight kit. Also replace both side yellow turn signals with clear turn signal.
10/30/2006		Replace valve cover gasket and power steering lines.
04/07/2007		Replace clutch arm bushings and install transmission mount enforcer.
04/10/2008	90,023	Replace under hood shocks and thermostat cover.
10/16/2008		Install new driver's door trim panel, to replace original warped panel.
10/24/2009		Switch stock shift knob for Tuner Motorsport "shorty" weighted knob.
11/06/2009	95,682	Install new fuel lines and fuel level sending unit.
08/06/2010	98,192	Replace water pump and accompanying belts.
08/15/2013	105,586	Replace transmission interlock seal.
09/01/2015	106,221	Replace valve cover gasket, ignition coils and misc. molding strips.
04/06/2018		Interior headliner replaced.
07/29/2020		Installed stainless front steel skid plate to replace original plastic.
07/17/2021		Rebuild "computer" screen to replace all pixels.
08/18/2021	115,895	Replace clutch slave cylinder.
05/22/2022		Replace under hood insulation panel.
11/15/2022		Installed new Toyo Proxes Sport tires.
07/22/2024		Replace valve cover gasket.