

2016 VW Golf GTI Autobahn Performance Package (German-Spec Clubsport Coverion)

VIN 3VW547AU9GM033488
 Color Deep Black Pearl
 Engine 2.0L I4 TSI DOHC 16V
 Transmission 6-Speed Manual
 Production Date 11/19/2015
 Delivery Date 1/26/2016

MAINTENANCE RECORDS

DATE	MILES	KM	SHOP	NOTES
01/25/16	2	3	Camelback VW - Phoenix, AZ	VEHICLE PURCHASED
01/30/16	293	472	-	Installed OEM LED license plate light housings. Recoded the following modules: 17-Instruments (disabled seatbelt warning); 09-Cent. Elect. (disabled DRL turn signal wink, added DRL option in MIB, set fog lights as Coming/Leaving Home, enabled fob convenience opening and closing and KESSY convenience closing, Leuchte channel for license plate lights voltage updated for OEM LED lights).
02/02/16	374	602	-	
02/16/16	549	884	Goodspeed Performance - Scottsdale, AZ	APR ECU Upgrade - 91 octane mapping, stage 1 v1.2.
03/12/16	1,013	1,630	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, installed new drain plug.
03/17/16	1,241	1,997	-	Installed OEM power folding heated mirrors with puddle lights, as per ETKA and recoded modules 42 and 52; enabled passenger mirror dip feature in module 52.
03/19/16	1,241	1,997	-	Installed OEM LED taillights and adapter harness, RoW headlight switch with rear fog option; recoded the following: taillight Leuchte channels, enabled rear fog icon in instrument cluster, disabled front side markers, enabled Single Sided Parking Lights, recoded ABS module to enable option to turn ECS off completely as in Golf R/Clubsport models factory coding.
03/31/16	1,784	2,871	-	Added manufacturer recommended complete fuel system cleaner to fuel tank (Valvoline).
04/13/16	3,762	6,054	-	Installed RoW GTI OEM rear leather headrests with red stitching.
04/25/16	4,013	6,458	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, installed new drain plug.
11/29/16	6,315	10,163	-	Recoded the following in 09-Cent. Elect: enabled refuel quantity in MFD, enabled fob lock/unlock feature with car running.
12/06/16	6,317	10,166	-	Installed new RS 3 spark plugs (06K-905-601-M).
12/07/16	6,739	10,845	Euro Code - Torrance, CA	Tinted windows with Llumar AT 35 GN SR HPR film (perferct match to OEM green tint found in Touaregs and all european models as an option); best tint shop carrying Llumar based on VVVortex tint forum.
12/11/16	6,928	11,150	-	Added manufacturer recommended complete fuel system cleaner to fuel tank (Valvoline).
12/16/16	7,248	11,664	-	Installed OEM auto-dimming rearview mirror as per ETKA.
02/05/17	7,433	11,962	-	Installed OEM alarm siren as per ETKA (Euro-spec locking chirp) and coded module 09-Cent. Elect. using VCDS.
02/22/17	7,447	11,985	-	Installed OEM rear footwell lights following Audi A3 diagrams.
04/18/17	7,957	12,806	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, installed new drain plug; topped off coolant (G 013A8J1G) and DOT 4 brake fluid (B 000 750 M2).
11/08/17	8,801	14,164	-	Installed Clubsport 19" OEM Brescia rims with Michelin Pilot Sport 4S performance tires; recoded module 17-Instruments to adjust speed reading for new wheel size. Rims delivered to and tires purchased, mounted and balanced at Discount Tire on Camelback, Phoenix.
03/16/18	9,740	15,675	-	Installed ECS Tuning spacer flush kit for 19" Brescia/Pretoria wheels (10mm front and 17.5mm rear).
03/17/18	9,781	15,741	VW North Scottsdale - Phoenix, AZ	Installed GTI Clubsport/Audi TTS clutch (new OEM clutch disc, new OEM pressure plate & new OEM throwout bearing).
03/18/18	10,096	16,248	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, installed new drain plug.
03/19/18	10,232	16,467	-	Installed LED door warning lights w/puddle lights on front doors.
03/20/18	10,316	16,602	-	Recoded module 32-Lock Electronics, acoustic measure channel for Differential Locks (Controller 0CQ-907-554.CLB) to increased traction as in stock coding on GTI Clubsport.
03/21/18	11,604	18,675	-	Installed OEM auto-dimming mirror w/HomeLink as per ETKA.
03/22/18	12,907	20,772	Goodspeed Performance - Scottsdale, AZ	Installed APR downpipe, flashed APR ECU Upgrade (91 octane mapping, stage 2, exhaust crackle).
03/23/18	13,979	22,497	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, installed new drain plug.
03/24/18	14,008	22,544	-	Added complete fuel system cleaner to fuel tank (Techron Concentrate).
03/25/18	14,113	22,713	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, replaced drain plug.
03/26/18	14,181	22,822	-	Installed RS 3 ignition coils (06H-905-110-L) and RS 3 spark plugs (06K-905-601-M).

03/27/18	14,416	23,200	Goodspeed Performance - Scottsdale, AZ	Installed IS38 turbocharger, APR intercooler for MQB, APR silicone boost hoses, APR pendulum mount and subframe mount insert; topped off coolant (G A013 774 1G DSP), performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, replaced drain plug.
03/28/18	14,418	23,203	Goodspeed Performance - Scottsdale, AZ	APR ECU Upgrade - 91 octane mapping, stage 3 v2.0.2 (IS38 APR DP, FWD, High Torque, Manual, Exhaust Crackle).
03/29/18	14,772	23,773	-	Installed new AGM battery (000 915 105 CC); coded module for AGM OEM battery.
03/30/18	14,982	24,111	-	Adjusted engine idle speed using VCDS (New value 50 RPM).
10/08/20	15,254	24,549	Goodspeed Performance - Scottsdale, AZ	Fixed APR downpipe exhaust leak between downpipe coupling and resonator.
03/08/21	15,875	25,548	-	Added manufacturer recommended complete fuel system cleaner to fuel tank (Valvoline) during road trip.
01/10/22	17,120	27,552	-	Added fuel system cleaner to fuel tank (Techron) during road trip.
02/21/22	17,621	28,358	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, installed new drain plug; checked engine air filter.
08/29/22	21,552	34,684	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, replaced drain plug.
09/29/22	25,129	40,441	-	Added fuel system cleaner to fuel tank during road trip
10/07/22	25,435	40,934	-	Performed tire rotation service; replaced front left (driver side) tire due to nail near sidewall.
11/13/22	25,946	41,756	-	Added fuel system cleaner to fuel tank during cross-country road trip (Techron).
01/09/23	26,386	42,464	-	Added fuel system cleaner to fuel tank during cross-country road trip (Techron).
01/23/23	26,629	42,855	-	Added fuel system cleaner to fuel tank during cross-country road trip (Techron).
01/27/23	26,728	43,014	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, replaced drain plug.
07/24/23	27,459	44,191	Rickenbaugh Collision Repair - Denver, CO	Rear hatch was replaced with new OEM unit and professionally painted to match OEM finish; a minor cosmetic dent located below the VW emblem occurred during professional transport via a multi-level auto carrier from Kanas to Colorado.
10/30/23	28,239	45,446	Emich Volkswagen - Denver, CO	Rerouted and reinstalled European tailgate light wiring harness per manufacture specification; replaced damaged wiring and associated electrical connectors; replaced all retention clips for the rear hatch interior trim.
02/20/24	28,703	46,193	Bluewater Performance - Denver, CO	Removed APR downpipe, reinstalled OEM downpipe and auxiliary parts; reflashed ECU with 91 octane APR tune for IS38 OEM downpipe.
03/16/24	28,741	46,254	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, replaced drain plug.
09/16/25	28,876	46,471	Discount Tire - Denver, CO	Installed and balanced four new Michelin Pilot Sport 4S tires (235/35 R19 91Y); comes with 30,000 mile warranty; invoice #5577735.
09/25/25	28,885	46,486	Colorado Detail - Denver, CO	Full professional detailing service completed, including complete exterior paint decontamination and buffing process across entire body.
10/25/25	28,931	46,560	-	Performed synthetic engine oil (Mobile 1 0W-40) and OEM filter service, replaced drain plug.