



Z Car Guy Cincinnati
 1416 Ledlie St
 Cincinnati, Oh 45225
 (513) 546-1086
 zcarguycin@gmail.com
 g.co/kgs/frsaJYP

Estimate #165

Created: 06/18/2025 at 3:21PM
 Payment Term: On Receipt
 Service Writer: Paul Krimmer

ZCGC ZCGC
 mlowney@hagerty.com

1972 Datsun 240 Z (Red)
 VIN: HLS30137706
 Mileage: 751,515 mi

Engine compression and leak down test.			
Compression and leak down test performed. Valve cover gasket replaced.			
Description	Price	QTY	Subtotal
Labor: Compression test. # 1 125 lbs, # 2 130 lbs, # 3 130 lbs, # 4 130 lbs, # 5 130 lbs, # 6 130 lbs.			\$0.00
Labor: Cylinder leak down test : # 1 16 %, # 2 17 %, # 3 14 %, #4 10 %, # 5 15 %, # 6 12 %.			\$0.00
Part: Adjust valves to factory specs.		1	\$0.00
Part: Replaced valve cover gasket with new aftermarket.		1	\$0.00
Part: New aftermarket valve cover gasket.		1	\$0.00
	Shop Supplies (13.7%): \$0.00		Total: \$0.00

Engine and transmission removal / reinstallation . Engine bay refinish.			
Below tasks have been completed . New clutch kit installed with resurfaced fly wheel , rear main oil seal , Engine bay refinished . All components are operating as should.			
Description	Price	QTY	Subtotal
Labor: Remove / reinstall engine.			\$0.00
Labor: Replaced clutch kit, clutch slave cylinder and hose, Engine rear main oil seal, resurface fly wheel,			\$0.00
Labor: Media blast, seal, refinish in base / clear entire engine bay.			\$0.00
	Shop Supplies (13.7%): \$0.00		Total: \$0.00

Engine cooling system.			
Below tasks have been completed. Cooling hoses have been replaced with aftermarket new, new antifreeze installed. System operating as should.			
Description	Price	QTY	Subtotal
Labor: Replaced all cooling hoses (including to and from heater core).			\$0.00
	Shop Supplies (13.7%): \$0.00		Total: \$0.00

Engine ignition tune up.			
Below tasks have been completed. Ignition parts listed below have been replaced with aftermarket new. System operating as should.			
Description	Price	QTY	Subtotal
Labor: Replaced : points, condenser, rotary button, cap, wires, spark plugs.			\$0.00
Labor: New : points, condenser, rotary button, cap , wires and plugs.			\$0.00
	Shop Supplies (13.7%): \$0.00		Total: \$0.00



Z Car Guy Cincinnati
 1416 Ledlie St
 Cincinnati, Oh 45225
 (513) 546-1086
 zcarguycin@gmail.com
 g.co/kgs/frsaJYP

Estimate #165

Created: 06/18/2025 at 3:21PM
 Payment Term: On Receipt
 Service Writer: Paul Krimmer

Fluids refresh .			
Description	Price	QTY	Subtotal
All tasks have been completed. Fluids replaced. Systems operating as should.			
Labor: Replaced : engine oil and filter, engine coolant, brake and clutch fluids, transmission and differential.			\$0.00
Part: New fluids.		1	\$0.00
Shop Supplies (13.7%): \$0.00			Total: \$0.00

Brake repair.			
Description	Price	QTY	Subtotal
All tasks completed. All parts listed below have been replaced with new aftermarket. Systems operating as should.			
Labor: Replaced : brake master cylinder, front calipers, rear wheel cylinders, pads and shoes, rear spring kits, Turn rotors and drums, bleed system.			\$0.00
Shop Supplies (13.7%): \$0.00			Total: \$0.00

Fuel system reconditioning / repair.			
Description	Price	QTY	Subtotal
Below tasks completed. New aftermarket parts installed : carb rebuild kits, fuel pump. System operating as should.			
Labor: Remove / flush / test fuel tank . Replace mechanical fuel pump. Flush lines .			\$0.00
Labor: Rebuild original carburetors.			\$0.00
Part: New aftermarket mechanical fuel pump.		1	\$0.00
Shop Supplies (13.7%): \$0.00			Total: \$0.00

Steering and suspension inspection and repair.			
Description	Price	QTY	Subtotal
Below tasks completed. All parts listed below have been replaced with new aftermarket. Systems operating ashoul with exception of : ***Car needs new strut cartridges and possibly springs***			
Labor: Inspect inner / outer tie rod ends, control arm bushings, compression rod bushings, Lower ball joints. All 4 struts (fluid leaks), then test action on test drive			\$0.00
Labor: Replace (steering rack components) Inner and outer tie rod ends ,rack boots and rack mounting bushings.			\$0.00
Labor: Replace lower front ball joints (boots missing and loose) compression rod bushings and sleeves, (dry rotted rubber) Front Sway bar links and mount bushings (dry rotted rubber)			\$0.00
Part: New Inner and outer tie rod ends . Right and left		1	\$0.00
Part: New Steering rack boots and ties.		2	\$0.00
Part: New Lower ball joint right and left		2	\$0.00
Part: New Compression rod bushings right and left		2	\$0.00



Z Car Guy Cincinnati
 1416 Ledlie St
 Cincinnati, Oh 45225
 (513) 546-1086
 zcarguycin@gmail.com
 g.co/kgs/frsaJYP

Estimate #165
 Created: 06/18/2025 at 3:21PM
 Payment Term: On Receipt
 Service Writer: Paul Krimmer

Steering and suspension inspection and repair.		
Part: Compression rod sleeves right and left	2	\$0.00
Part: New sway bar links and mount bushings right and left.	1	\$0.00
Shop Supplies (13.7%): \$0.00		Total: \$0.00

Tires replacement.			
Below tasks completed. Systems operating as should. Tires replaced . edTire date stamp : 21st week of 2024. Brand and size : Advanta 185/65/R14.			
Description	Price	QTY	Subtotal
Labor: Replacde all 4 tires. Mount and ballance. Align front end.			\$0.00
Part: Untitled part		1	\$0.00
Part: 4 new Advanta 185/65/R14 tires.		1	\$0.00
Shop Supplies (13.7%): \$0.00			Total: \$0.00

Test all electrical systems.	
All systems operating as should at this time.	
Description	Subtotal
Labor: Tested : all dash controls, interior and exterior lighting. All controls and options with the exception of the radio (missing).	\$0.00
Shop Supplies (13.7%): \$0.00	
Total: \$0.00	

Please note a current Insurance policy reflecting the value of the vehicle to its owner must be provided prior to repair initiation. Billing invoice in increments via e mail link must be paid with in a 7 day period via PayPal or another agreed method for repairs to continue. Any unpaid repair after the 7 day period will accrue a \$25.00 a day storage fee. Estimates provided are an approximation of timing and charges to you for the services requested. They are based on the anticipated work to be done. It is possible for unexpected complications to cause some deviation from the original quote. You hereby authorize the repair work described in this estimate to be done along with the procurement of the necessary material(s), including permission to operate the vehicle for on-road testing or inspection. If any additional repairs are required, we will prepare a revised work order providing the cost of additional parts and labor and total revised cost.

This shop charges a 3% credit card processing fee.

Labor	\$0.00
Parts	\$0.00
Subtotal	\$0.00
Tax	\$0.00
Grand Total	\$0.00
Paid to Date	(\$0.00)
REMAINING BALANCE	\$0.00

All parts are new unless specified otherwise.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts.

You agree that we are not responsible for loss or damage to your vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, or any other cause(s) beyond our control. We are not responsible for any delays caused by unavailability of parts or delays in delivery of parts by the supplier or transporter. You have the right to know before authorizing any additional repairs what those repairs will be and what they will cost. If required repairs exceed the authorized estimated amount, we must obtain your approval to perform the repairs. We will keep you informed and perform only repairs authorized by you.

Signature _____