




DEDICATED TO THE PROFESSIONAL  
 Store 3817, 245 WEST Ocotillo Avenue,  
 Chandler, AZ 85248 (480) 982-4865

Invoice	3817-319924
Sale Type	CHG. CARD SALE
Date	04/06/2022 7:53 AM
Ship Via	
PO Number	67 CAMARO SS

Bill To:



Counter #	Customer Account	Ordered By	Special Instructions
459570	2470298		

Qty	Line	Item Number	Description	Warr	Unit	Tax	List	Net	Extended
1	SSB	24PRMJ	BATTERY	2Y	EA	Y	271.17	122.79	122.79
		24PRMJ	Core Charge		EA	Y		22.00	22.00
		24PRMJ	Core Exchange		EA	Y		-22.00	-22.00

1 Item

Call 866-830-4351 for Super Start National Warranty Information.

Buy \$100 in Trico Raininguard wiper blades, get a Trico wiper rack free!

Chip Used: Y A00000025010801 0000008000 E800 06560103A0A002 Verified By Not Verified REF #: 963923384329 AUTH CD: 823737



Sub-Total 122.79  
 Sales Tax 9.58  
**Total 132.37**  
 AMEX #7004 132.37

WWW.FIRSTCALLONLINE.COM

Please visit [www.firstcallonline.com/warranty](http://www.firstcallonline.com/warranty) for warranty details

1/1

WE APPRECIATE YOUR BUSINESS!

Remit To: PO BOX 9464, SPRINGFIELD, MO 65801-9464

K-1961 CAMARO

SUPERSTITION SPECIALTY CARS LLC  
 7931 E PECOS RD SUITE 149  
 MESA, AZ 85212 US  
 6022004362  
 ssc\_fast@yahoo.com  
 www.sscfast.com



BILL TO \_\_\_\_\_ SHIP TO \_\_\_\_\_

INVOICE # 3659  
 DATE 03/20/2025  
 DUE DATE 03/20/2025  
 TERMS Due on receipt

YEAR, MAKE, MODEL ENGINE SIZE/ MILEAGE  
 1967 Chevrolet Camaro SS 327/49,421

ACTIVITY	QTY	RATE	AMOUNT
<b>CC Service Fee</b> 3.9% On All Credit Card Purchases. ACH/Bank transfer, check or cash removes this charge.	0	57.46	0.00
<b>Notes</b> * Minimum Diagnostic/ Labor charge of \$210.00 per hour * Additional Diagnostic charge, parts, labor, fluids, shipping & handling fees may be required to diagnose and or complete this project * All Parts and labor are estimated until project completion *** Indicates additional parts/labor required not reflected on original estimate/invoice.	1	0.00	0.00
<b>Diagnostic Check</b> First hour to diagnose issue * If more time is needed, we will call to get authorization before we continue* : Weak hood springs. : Check cooling system : Check fluids : General inspection : Road test	1	210.00	210.00
<b>Labor</b> Install new hood springs.	1.50	210.00	315.00
<b>Hood Spring</b> VA-FAR-63C16789	2	35.98	71.96T
<b>Labor</b> Pressure test cooling system.(OK) Check timing and dwell.(OK) Tighten oil pan bolts, trans pan bolts and valve cover bolts. Repaired RR outer brake light. (Ground issue) Replace plate light bulb. Adjust neutral safety/reverse light switch under dash. Adjust tire pressures.	4	210.00	840.00
<b>Bulb</b> NP-67	1	2.97	2.97T
<b>Labor</b>	3	210.00	630.00

All SSC work comes with a 3 month or 3,000 mile warranty on parts and labor supplied by SSC. SSC will not warranty any customer supplied part or labor used for customer supplied part. \*All sales are Final on B&W Trailer Hitch products, as well as Tires and Wheels and any warranty issues must go through the manufacturer only\*

SUPERSTITION SPECIALTY CARS LLC  
 7931 E PECOS RD SUITE 149  
 MESA, AZ 85212 US  
 6022004362  
 ssc\_fast@yahoo.com  
 www.sscfast.com



**BILL TO** [REDACTED] **SHIP TO** [REDACTED]

**INVOICE #** 3659  
**DATE** 03/20/2025  
**DUE DATE** 03/20/2025  
**TERMS** Due on receipt

**YEAR, MAKE, MODEL** 1967 Chevrolet Camaro SS  
**ENGINE SIZE/ MILEAGE** 327/49,421

ACTIVITY	QTY	RATE	AMOUNT
<b>CC Service Fee</b> 3.9% On All Credit Card Purchases. ACH/Bank transfer, check or cash removes this charge.	0	57.46	0.00
<b>Notes</b> * Minimum Diagnostic/ Labor charge of \$210.00 per hour * Additional Diagnostic charge, parts, labor, fluids, shipping and handling fees may be required to diagnose and or complete this project. * All Parts and labor are estimated until project complete. *** Indicates additional parts/labor required not included on original estimate/invoice.	1	0.00	0.00
<b>Diagnostic Check</b> First hour to diagnose issue * If more time is needed, we will call to get authorization before we continue* : Weak hood springs. : Check cooling system : Check fluids : General inspection : Road test	1	210.00	210.00
<b>Labor</b> Install new hood springs.	1.50	210.00	315.00
<b>Hood Spring</b> VA-FAR-63C16789	2	35.98	71.96T
<b>Labor</b> Pressure test cooling system.(OK) Check timing and dwell.(OK) Tighten oil pan bolts, trans pan bolts and valve cover bolts. Repaired RR outer brake light. (Ground issue) Replace plate light bulb. Adjust neutral safety/reverse light switch under dash. Adjust tire pressures.	4	210.00	840.00
<b>Bulb</b> NP-67	1	2.97	2.97T
<b>Labor</b>	3	210.00	630.00

All SSC work comes with a 3 month or 3,000 mile warranty on parts and labor supplied by SSC. SSC will not warranty any customer supplied part or labor used for customer supplied part. \*All sales are Final on B&W Trailer Hitch products, as well as Tires and Wheels and any warranty issues must go through the manufacturer only\*

ACTIVITY	QTY	RATE	AMOUNT
Replace rear axle seals and pinion seal. Reseal rear cover and fill.	1	46.95	46.95T
<b>Pinion Seal</b> NP-15315	2	13.23	26.46T
<b>Axle Seal</b> NP-13992	2	14.95	29.90T
<b>80W/90W Gear Oil</b>	1	25.00	25.00T
<b>Shop Fee</b>			

<b>SUBTOTAL</b>	2,198.24
<b>TAX</b>	16.87
<b>TOTAL</b>	2,215.11
<b>PAYMENT</b>	2,215.11
<b>BALANCE DUE</b>	<b>\$0.00</b>

Pay invoice

All SSC work comes with a 3 month or 3,000 mile warranty on parts and labor supplied by SSC. SSC will not warranty any customer supplied part or labor used for customer supplied part. \*All sales are Final on B&W Trailer Hitch products, as well as Tires and Wheels and any warranty issues must go through the manufacturer only\*