



Italian Auto Parts, Inc.  
 2370 John Glenn Dr  
 Atlanta, Ga 30341  
 678-637-5103

# Invoice

Date	Invoice #
10/27/2023	143173

Fax #	914-829-9018
-------	--------------

**PAID**  
 11/02/2023

Bill To

Robert Poulton  
 [Redacted]  
 [Redacted]  
 [Redacted]  
 Canada

Shipped With **DHL # 7670038036**

Item	Description	Qty	Rate	Amount
10075100	Alfa Romeo GTV6 Alfetta Windshield Gasket With Groove Chrome Insert	1	313.00	313.00
ARGTV6101	Alfa Romeo Alfetta GTV GTV6 Windshield OEM	1	810.00	810.00
SH	Product Rate - Est. US Shipping Cost		160.00	160.00
S&H	Shipping and Handling		300.00	300.00
Note	Robert Poulton 2359 Royal Windsor Drive Unit 25 Mississauga, Ontario, L5J1K7 Canada T: 9053305281		0.00	0.00
Note	Mrfiat.com Order Number:100031779  TransactionID: 3DJ11612HP657911S Transaction ID:  3E491581B7633240J		0.00	0.00

<b>Total</b>	<b>USD 1,583.00</b>
--------------	---------------------

Return Policy:  
<http://mrfiat.com/return-policy>

**Very Important!**  
**Inspect all items upon receipt!**

**Interior fan only works on speeds 1 and 2 but not 3**

Remove and Replace components as required to access and install materials, and/or perform needed service. Air Conditioning repairs which include replacement materials will normally require an additional service to evacuate and recharge system refrigerant and oil. Retest and verify repair as required. Perform final road test where applicable.

Removed switch and discovered the high speed wire was disconnected and being used as a jumper for two red wires. Disconnected and reattached the high speed wire which solved the problem. The two red wires were tied together and tucked away behind the switch.

Labor	2.1 Hour	\$155.00 / Hour	\$325.50 H
		<b>Sub</b>	<b>\$325.50</b>

**Evacuate and Recharge R134A Air Conditioning System**

Connect AC equipment, evacuate system of contaminates, verify system pressures, refrigerant levels and cooling vent temperature. Charge AC system, install proper refrigerant and oil capacity. Leak test AC system. Refrigerant leak detection dye may be added to system.

Labor - recover gasses from car.	0.6 Hour	\$155.00 / Hour	\$93.00 H
Evacuate & Recharge A/C System	1 Unit	\$46.95 / Unit	\$46.95 H
		<b>Sub</b>	<b>\$139.95</b>

**Air Conditioner General Service**

Remove and Replace components as required to access and install materials, and/or perform needed service. Air Conditioning repairs which include replacement materials will normally require an additional service to evacuate and recharge system refrigerant and oil. Retest and verify repair as required. Perform final road test where applicable.

Found System Empty	2.8 Hour	\$155.00 / Hour	\$434.00 H
Found High side Schrader valve faulty, replaced same			
Determine factory AC Charge			
Best possible info allowed me to come up with 32 Oz or 900 Grams			
Hence I charged the system with 11oz aka 311 grams of Red Tek charged			
RED TEK 12A A/C Refridgerant per ounce	11 Ounce	\$8.99 / Ounce	\$98.89 H
Labor- Barry to reinstall the lower crank pulley for the a/c system.	3.1 Hours	\$155.00 / Hours	\$480.50 H
only 1 bolt out of 3 holding the system together.			
		<b>Sub</b>	<b>\$1,013.39</b>

**Replace Rad Fan**

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor- remove radiator	8.4 Hour	\$155.00 / Hour	\$1,302.00 H
-remove old weak fans			
-install and fabriacte mounting points for new performance fans			
-found thermostat housing pourous and requiries replacement. NO LONGER AVAILABLE			
-repaired housing and installed back on vehicle.			
-reinstall radiator and fluids			
-pressure checked system and no leaks.			
-install electronic fan switch and wiring.			
High Performance Rad Fan	2 Unit	\$299.27 / Unit	\$598.54 H
Auxiliary Fan Switch	1 Unit	\$12.87 / Unit	\$12.87 H
2 Pin 92-87c Degree			
Radiator Clean, Test and Repair. Chemically cleaned radiator	1 Unit	\$207.15 / Unit	\$207.15 H
Electric Fan Switch	1 Unit	\$241.17 / Unit	\$241.17 H
Universal Green Coolant/Antifreeze per Liter	5 Litre	\$15.08 / Litre	\$75.40 H
		<b>Sub</b>	<b>\$2,437.13</b>

**Diagnose Transmission Concern**

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

Labor	14.2 Hour	\$155.00 / Hour	\$2,201.00 H
Shipping of clutch to Manufacturer	1 Unit	\$115.00 / Unit	\$115.00 H
Clutch Rebuild	1 Unit	\$278.57 / Unit	\$278.57 H

**Preferred Method of Payment: Visa / Mastercard / Debit / Email Transfer to accounting@ea.works**

Labor drain and replace Transmission fluid Repair where shifter rod is colliding with Exhaust Lubricate balance of shifter	1.2 Hour	\$155.00 / Hour	\$186.00 H
MTL- Manual Transaxle Lubricant MTF94	3 Unit	\$30.64 / Unit	\$91.92 EH
		<b>Sub</b>	<b>\$277.92</b>

#### Transaxle Assembly

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labour to drain and refill Transaxle	0.8 Hour	\$155.00 / Hour	\$124.00 H
Manual Transmission and Transfer Case Fluid	2 Unit	\$19.08 / Unit	\$38.16 H
		<b>Sub</b>	<b>\$162.16</b>

#### Air Conditioner General Service

Remove and Replace components as required to access and install materials, and/or perform needed service. Air Conditioning repairs which include replacement materials will normally require an additional service to evacuate and recharge system refrigerant and oil. Retest and verify repair as required. Perform final road test where applicable.

Labor check for AC function -Found no Freon in system, and Low Pressure switch inoperative, check and test system for leaks, repair low side valve, and connections at Compressor -Evac and recharge system, AC now works, however spit the main Pulley half at Crank -Repair Crank Pulley, and Jump LP switch, AC now functioning	3.9 Hour	\$155.00 / Hour	\$604.50 H
		<b>Sub</b>	<b>\$604.50</b>

#### Evacuate and Recharge Redtek Air Conditioning System

Connect AC equipment, evacuate system of contaminates, verify system pressures, refrigerant levels and cooling vent temperature. Charge AC system, install proper refrigerant and oil capacity. Leak test AC system. Refrigerant leak detection dye may be added to system.

Labor	0.6 Hour	\$155.00 / Hour	\$93.00 H
Evacuate & Recharge A/C System	1 Unit	\$46.95 / Unit	\$46.95 H
RED TEK 12A A/C Refridgerant per ounce	26 Ounce	\$8.99 / Ounce	\$233.74 H
		<b>Sub</b>	<b>\$373.69</b>

#### Radiator Cap

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor	0.3 Hour	\$155.00 / Hour	\$46.50 H
Radiator Cap	1 Unit	\$12.00 / Unit	\$12.00 H
		<b>Sub</b>	<b>\$58.50</b>

#### Door Mirror

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor Repair Door Mirror Mount Remove Mirror and rebuild, install new Base spring Used a Base Spring from 944 Porsche Reinstall Mirror Adjust and test	1.5 Hour	\$155.00 / Hour	\$232.50 H
		<b>Sub</b>	<b>\$232.50</b>

#### Alignment, Four Wheel

Inspect steering and suspension system components. Connect alignment equipment to verify and adjust front and rear wheel alignment settings for caster, camber, and toe in/out settings, thrust angle where applicable and center steering wheel. Some vehicles may require installation of alignment shims at additional charges. Adjust to meet manufacturers' specifications. Perform final road test where applicable.

Labour	1.2 Hour		\$186.00 H
Wheel Alignment Machine			\$63.95 H
Labor to repair Lower shield Mounts	0.6 Hours	\$155.00 / Hours	\$93.00 H
		<b>Sub</b>	<b>\$342.95</b>

Preferred Method of Payment: Visa / Mastercard / Debit / Email Transfer to [accounting@ea.works](mailto:accounting@ea.works)



**EA WORKS**

Carville PO Box 20044

Concord, Ontario, Canada L4K 0C8

Phone: 905.660.1884 // Fax: 905.660.1526

info@engineeredautomotive.com // www.ea.works

**Invoice**

Bill To: [Redacted]  
[Redacted] L4K 0C8  
Canada

Plate ON TBA  
Description 1984 Alfa Romeo GTV-6 2.5 V6 2.5L 2492CC  
VIN ZARAA6698E1006405  
Odometer 75,722 In / 76,347 Out

[Redacted]  
[Redacted]  
Freddy [Redacted]  
[Redacted]@ea.works.com

Invoice # 6303  
Work Order # 10062  
Service Advisor Dave T  
Technician Billy S

Invoice Date 10/11/2018 5:57 PM  
Appointment 9/4/2018 10:07 AM  
Promised 9/4/2018 11:07 AM

**Service**

**General Notes**

- a. Radiator fan stopped working, Luca to fix in the AM
- b. Order upgrade fans first thing in AM, do we possibly have these
- c. Flush system with existing rad before sending out
- d. Pull Rad and send out for flush and test
- e. Evacuate AC, check manuals online for proper charge to determine amount of Red Tech
- i. Possibly pull condenser and send out for flush and test at same time
- f. Battery mount
- g. Price out rear shock for rear hatch
- h. Freddy Claims high fan was working, quickly investigate the wiring change Luca made and confirm fix
- i. Engine Noisy observation by Freddy is the Gear Train noise when Clutch is engaged, does this possibly have single mass flywheel, or is something letting to in there

**Customer reports that the engine seems noisy and would like the oil and all other fluid levels checked**

Initial diagnosis, testing and inspection of the specific vehicle system as required. Perform road test where applicable. Report test result(s), system fault(s), component(s) failure and required repair(s). Additional diagnosis and testing time may be required at additional charges.

fuel charges 10/04/18	1 Unit	\$37.93 / Unit	\$37.93 H
		<b>Sub</b>	<b>\$37.93</b>

**Drivers Door Wont Close Properly**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Labor - Billy replaced door strikers hardware	1.4 Hour	\$155.00 / Hour	\$217.00 H
-found door pillar window guide cracked.			
-repaired via spot weld			
-door seal too thick , new seal is now instock and install as necessary			
Door Seal Kit for Drivers Door	1 Unit	\$145.25 / Unit	\$145.25 H
		<b>Sub</b>	<b>\$362.25</b>

**Preferred Method of Payment: Visa / Mastercard / Debit / Email Transfer to accounting@ea.works**

**Additional Time/Charges Required if:**

Seized adjustment hardware and requires usage of heat to loosen.

**Fuel Receipt**

Description			
Fuel receipt	1 Unit	\$27.78 / Unit	\$27.78 H
		<b>Sub</b>	<b>\$27.78</b>

**Cooling System Boiled Over Check Over System and Fans**

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor check for overheat condition	1.4 Hour	\$155.00 / Hour	\$217.00 H
Found Second Rad Fan not operational , wired in to primary fan for now, until Thermostat switch is repaired			
		<b>Sub</b>	<b>\$217.00</b>

**Drivers Door Wont Close Properly**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Labor adjusted door, but found door had to close due to Hinges worn, readjusted door to compromise, Note , door closes better with window slightly down Requires New Hinges	0.8 Hour	\$155.00 / Hour	\$124.00 H
		<b>Sub</b>	<b>\$124.00</b>

---

Total Parts		\$1,589.92
Total Labor		\$2,676.50
Total Sublet		\$101.30
Total Before Taxes & Miscellaneous Charges		\$4,367.72
(E) Environmental Fee	\$5.00 Each	\$10.00 H
(H) Canadian Harmonized Sales Tax R128999950RT0001	13 %	\$569.11
<b>Grand Total</b>		<b>\$4,946.83</b>

DeGasperis, Freddy charged \$4,946.83 to Account - 1 - DeGasperis, Freddy - Net 30 Days

**Preferred Method of Payment: Visa / Mastercard / Debit / Email Transfer to accounting@ea.works**

**The EA Warranty**

We are so confident in our abilities, Engineered Automotive warrants its work for 3 years or 36,000kms. This warranty is unmatched in our industry. You won't find it at any other shops or even at local dealerships....and it's just one of many reasons why you should trust EA to service your vehicle.

Please retain this invoice to maintain your warranty.



**EA WORKS**

Carville PO Box 20044  
 Concord, Ontario, Canada L4K 0C8  
 Phone: 905.660.1884 // Fax: 905.660.1526  
 info@engineeredautomotive.com // www.ea.works

**Invoice**

Bill To: [Redacted]ddy  
 29 Floral Dr [Redacted]  
 [Redacted] SC5  
 Canada  
 [Redacted] 3  
 [Redacted]  
 [Redacted] 64  
 [Redacted] .com  
 [Redacted]  
 [Redacted] .com

Invoice # 6181  
 Work Order # 9972  
 Service Advisor Billy S  
 Technician Barry G

Plate ON TBA  
 Description 1984 Alfa Romeo GTV-6 2.5 V6 2.5L 2492CC  
 VIN ZARAA6698E1006405  
 Odometer 75,467

Invoice Date 9/3/2018 12:02 PM  
 Appointment 8/16/2018 3:05 PM  
 Promised 8/16/2018 4:05 PM

**Inspection**

**CVI Complete Vehicle Inspection**

Labor	3 Hour	\$155.00 / Hour	\$465.00 H
		<b>Sub</b>	<b>\$465.00</b>

**Service**

**EA Vehicle Recovery/Towing/Delivery From Montreal to Toronto**

VIP Towing service featuring our enclosed flatbed trailer.

Vehicle Hook-Up			\$150.00 H
Distance Travelled	585 Unit	\$1.75 / Unit	\$1,023.75 H
		<b>Sub</b>	<b>\$1,173.75</b>

**Complimentary Car Wash**

Each and every time you visit EA, you receive a complimentary hand-wash of your vehicle's exterior and vacuum of the driver compartment.

Detail Labor			\$0.00 H
		<b>Sub</b>	<b>\$0.00</b>

**Lube, Oil & Filter Service - Conventional Oil**

Drain and refill engine oil, change engine oil filter and lubricate chassis grease fittings and friction points as required. Check and top off fluid levels, additional charges may apply where fluids are required. Complete a complimentary visual vehicle inspection.

Labor	1 Hour	\$155.00 / Hour	\$155.00 H
Castrol - 20W50 Conventional Motor Oil (1 litre)	7 Liter	\$9.99 / Liter	\$69.93 EH
Bosch - Bosch Engine Oil Filter - Alfa Romeo GTV V6	1 Unit	\$9.52 / Unit	\$9.52 H
fuel charges	1 Unit	\$73.52 / Unit	\$73.52 H
		<b>Sub</b>	<b>\$307.97</b>

**Manual Transmission Fluid Exchange**

Remove existing fluid(s). Additional chemicals may be added to completely clean system contamination. Fill system fluid(s) to proper capacity with new fluid. Fluid additives and/or conditioners may be required. Leak test vehicle system. Perform final road test where applicable.

**Preferred Method of Payment: Visa / Mastercard / Debit / Email Transfer to accounting@ea.works**




**Georgica Services Ltd.**

139 Springs Fireplace Road  
 East Hampton, NY 11937  
 (631) 324-7707  
 office@georgicaservices.com  
 http://georgicaservices.com

**Invoice for RO #90219**

**Service Advisor:** Felipe Rivas  
**Date Created:** 11/01/24 at 12:36 PM EDT  
**Client:** Lee Gold  
**Vehicle:** 1984 Alfa Romeo GTV-6 2.5

Lee Gold none NY 	1984 Alfa Romeo GTV-6 2.5 2.5L 6Cyl GAS Naturally Aspirated VIN: ZARAA6698E1006405 License: N/A Color: N/A Odometer In: 77103 / Out: 77106	RO # 90219 Time-In: 11/01/24 at 12:36 PM EDT
---	---	---

**Client concerns:**

- Post Purchase Inspection
- finish up

<b>1 - Perform a courtesy Digital Vehicle Inspection (DVI)</b> Tech: MM		
Perform a multipoint Digital Vehicle Inspection (DVI). Found: *Drive belts are cracked - Recommend replacing belts *There are traces of oil leaks - Need to clean and add dye to engine oil *Sparkplug replacement is due by time and mileage - Recommend complete tune-up *Brake fluid tested high on water content - Recommend brake fluid exchange *Shock arm bushings coming apart - Recommend replacing shocks *Shocks very rusty *Rear axle boots torn - Recommend replacing axle boots *Front brake hoses losing elasticity - Recommend replacing brake hoses *Exhaust hanger bushings dry cracked - Recommend replacing exhaust hangers *Rear view mirror glass cracked *Headlights need to be aimed properly *Doors are out of adjustment, hard to close		
<b>Labor:</b>		\$440.54
✓ Approved on 11/02/24 at 10:08 AM EDT		Subtotal \$440.54 + est. Tax \$38.00 <b>\$478.54</b>

<b>2 - APPROVED WORK DEPOSIT</b> Tech: TG		
<b>Labor:</b>	As per our company policy, a 50% deposit on approved work is required before work can commence.	\$0.00
✓ Approved on 11/09/24 at 02:44 PM EST		0 0

<b>3 - Drive Belts</b> Tech: GN		
<b>Labor:</b>	Remove and replace vehicle drive belts	\$1,096.11
<b>Parts:</b>	A/C belt 1 \$54.38 \$54.38 Alt Belt 1 \$80.63 \$80.63	
✓ Approved on 11/09/24 at 02:44 PM EST		Subtotal \$1,231.12 + est. Tax \$106.18 <b>\$1,337.30</b>

<b>4 - Tune-up</b> Tech: GN		
<b>Labor:</b>	Remove and replace ignition tune up parts.	\$660.81
<b>Parts:</b>	ign wire 1 \$444.44 \$444.44 Dist Cap 1 \$102.94 \$102.94 Dist Rotor 1 \$83.33 \$83.33 Spark plugs 6 \$10.41 \$62.46 Air Filter 1 \$102.94 \$102.94 Fuel Filter 1 \$77.78 \$77.78	
✓ Approved on 11/09/24 at 02:44 PM EST		Subtotal \$1,534.70 + est. Tax \$132.37 <b>\$1,667.07</b>

<b>5 - BRAKE HOSE (FRONT AND REAR)</b>			
Tech:GN			
<b>Labor:</b>	Remove and replace the front and rear brake hoses		\$660.81
	Drain Brake fluid from reservoir, clean, refill with new fluid and bleed out brake system at all wheels.		\$262.23
<b>Parts:</b>	DOT 3/4	2	\$19.85 \$39.70
	PARTS CLEANER	1	\$10.69 \$10.69
	Front hoses	2	\$106.88 \$213.76
	Rear hoses	1	\$96.00 \$96.00
✓ Approved on 11/09/24 at 02:44 PM EST			Subtotal \$1,283.19 + est. Tax \$110.68 <b>\$1,393.87</b>

<b>6 - Rear Axle</b>			
Tech:GN			
<b>Labor:</b>	Remove and replace rear axle boots		\$923.04
<b>Parts:</b>	Axle Boots	4	\$112.50 \$450.00
	CLEANER/SOLVENT	1	\$8.50 \$8.50
✓ Approved on 11/09/24 at 02:44 PM EST			Subtotal \$1,381.54 + est. Tax \$119.16 <b>\$1,500.70</b>

<b>7 - NOTE TO THE CUSTOMER</b>			
Tech:T G			
<b>Labor:</b>	Due to the nature of the type of work we do and the age and condition of some vehicles, we wish to inform you that the above estimate is based on "things going well". If we encounter unexpected, unusual circumstances or problems , extra labor and materials costs may need to be added to the above quoted price. If substantial, we will stop the work and review the added costs with you before proceeding. Thank you for your understanding.		\$0.00
✓ Approved on 11/09/24 at 02:44 PM EST			0 0

<b>8 - Parts not in the original estimate</b>			
Tech:GN			
<b>Labor:</b>	Axle bearing R&R		\$660.81
<b>Parts:</b>	Axle bearing	2	\$300.00 \$600.00
	Axle Bearing Lock Ring	1	\$180.00 \$180.00
	Axle Bearing Lock Ring	1	\$180.00 \$180.00
✓ Approved on 12/11/24 at 12:09 PM EST			Subtotal \$1,620.81 + est. Tax \$139.79 <b>\$1,760.60</b>

**Total Repair Order & Signature:**

**PAID**

X

Total Labor:	\$4,704.35
Total Parts:	\$2,787.55
Total Fees:	\$0.00
<b>Subtotal:</b>	<b>\$7,491.90</b>
Taxes:	\$646.18
<b>Grand Total:</b>	<b>\$8,138.08</b>
<b>BALANCE DUE:</b>	<b>\$5,038.08</b>

