



**3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353**

Invoice

Date	Invoice #
6/10/2024	JF7400

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
2019 Dodge Challenger SRT Hellcat Redeye 2C3CDZL92KH639967 Grey

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in 8242 1. CEL is on 2. Low Tire light is on 3. Center screen is missing Part #68396538AH from Repair Link ANTI THEFT CODE 8956 4. Dash trim is broken 5. Inspect the car for any other damage	1	0.00	0.00
Repair Labor	INITIAL INSPECTION Challenger Test drove the car. On the test drive discovered pull to the left. Brought car in the shop and lifted for inspection. Found bent right side inner tie rod end. Needs oil service, display and Red Eye Key. Once these are remedied further inspection and diagnosis can be performed. It also needs a set of tires.	1	146.00	146.00
Repair Labor	OIL SERVICE Drained the oil and replaced the filter. Refilled with oil. Checked and adjusted fluids as needed. Inspected the car for other needs. None found. Checked the oil level, level is good.	1.2	146.00	175.20
Parts	WP Mopar Oil Filter 4884899AC list \$11.00	1	10.30	10.30T
Parts	WP Motul Motor Oil 0w40 quart 3374650250694	7	15.44	108.08T

	Subtotal
	Sales Tax (0.0%)
	Total
	Payments/Credits
	Balance Due



**3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353**

Invoice

Date	Invoice #
6/10/2024	JF7400

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
2019 Dodge Challenger SRT Hellcat Redeye 2C3CDZL92KH639967 Grey

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	PASSENGER INNER TIE ROD END Removed and replaced the passenger inner tie rod end.	1.4	146.00	204.40
Parts	OR Inner Tie Rod End EV800963 list \$74.56	1	61.76	61.76T
Sublet	4 Wheel Alignment Hellcat	1	139.95	139.95
Repair Labor	CENTER SCREEN Installed the replacement infotainment screen. Would not power up. Had to run power diagnostic and inspection. Found missing fuses. Installed fuses. Screen now powers up with security. Called and got security. Entered the code and screen is fully functional at this time. Repaired dash trim and reinstalled.	2.5	146.00	365.00
Parts	LKQ Center Display Screen. 68396538AC	1	585.00	585.00T
Shop Supplies	Shop Supplies	1	35.00	35.00
Sublet	REDEYE KEY AND SECURE GATEWAY DIAGNOSTIC AND REPLACEMENT Vaden Dodge Repaired wiring. Replaced the Secure Gateway Module and the RF hub. Programmed the Redeye key. The car is fully functional now	1	2,417.10	2,417.10
Parts	VD Red Eye Key Fob 68394205AA list \$204.00	1	199.00	199.00T
Parts	VD Key blank 68200221AA list \$61.20	1	61.20	61.20T
	VEHICLE DETAIL			

	Subtotal
	Sales Tax (0.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
 Savannah, GA 31405
 (912) 417-4353

Invoice

Date	Invoice #
6/10/2024	JF7400

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
2019 Dodge Challenger SRT Hellcat Redeye 2C3CDZL92KH639967 Grey

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Sublet	Detailed inside and outside. COMPLETE TICKET	1	299.00	299.00

	Subtotal	\$4,806.99
	Sales Tax (0.0%)	\$0.00
	Total	\$4,806.99
	Payments/Credits	\$0.00
	Balance Due	\$4,806.99