

1960 CADILAC CONVERTIBLE SERIES 62 – PURCHASE MARCH 2024

WORK COMPLETED BY DJL AND VINNIE – 3/ /2024

---

WORK COMPLETED BY DJL AND VINNIE – 3/13/2024

**New Parts:**

Go to personal residence and start the car.

---

WORK COMPLETED BY DJL AND VINNIE – 3/14/2024

Restoration labor

**New Parts: Miscellaneous repair materials**

Take Dan Home, change master cylinder, glue rubber on left door, work on hood molding.

---

WORK COMPLETED by DJL & VINNIE – 3/15/2024

**MAINTENANCE LABOR**

Remove V emblem from hood, epoxy and install stud. Remove spark plugs, set gap at 35. Number 6 plug is oil fouled. Install front license plate, car on lift and inspect for leaks. Nonvisible. Put 2 3/8 SS bolts and washers on front inner fender (note one bolt is stripped on fender) Glue piece of vinyl behind front driver's seat, remove left front visor.

**PARTS:** \$12.00

**LABOR:** \$330.00

---

WORK COMPLETED by DJL & VINNIE - 3/16/2024

**MAINTENANCE LABOR**

**NEW PARTS: None needed**

Dash board repair, install sun visor, secure left door panel at bottom, change battery, pick up Dan

**LABOR:** \$150.00

---

WORK COMPLETED by DJL & VINNIE - 3/27/2024

Take car to shop and attempt to repair seat motors, move seats, remove cable, and move seats as far back as possible, make appointment to install electric fuel pump.

**PARTS:** \$25.00

1960 CADILAC CONVERTIBLE SERIES 62 – PURCHASE MARCH 2024

LABOR: 175.00

---

WORK COMPLETED by DJL & VINNIE - 3/28/2024

Pick up car from shop and return to garage. Change oil, Valvoline, oil filter, air filter not (is now) available.

PARTS: \$165.00  
LABOR: \$139.00  
TOTAL INVOICE TO DATE: \$1374.00

---

WORK COMPLETED by DJL & VINNIE - 3/29 /2024

PARTS:

NAPA – 2 fan belts & 2 radiator hoses \$111.62, exhaust gasket \$49.47, air cleaner \$52.23, anti freeze \$60.

LABOR:

Remove left hand door panel, drill and screw molding in door. 4 hrs at \$55 = \$220. Clean and polish xxx, clean out inside door, glue carpet under dash, reinstall kickplate under dash, screw in in place. Reinstall door molding on right door, screw into door, adjust hood and hood opening, install XX XX nut.

---

WORK COMPLETED by DJL & VINNIE - 4/4 /2024

PARTS:

LABOR: Change generator and power steering belts, change upper and lower radiator hoses, new stainless steel clamps, change antifreeze, pick up/deliver Dan home

TOTAL INVOICE TO DATE: \$641.00

---

WORK COMPLETED by DJL & VINNIE - 4/7 /2024 & 4/8/2024

PARTS:

LABOR: worked on computer for parts. \$25.00

Worked on computer for parts.

---

WORK COMPLETED by DJL & VINNIE - 4/9/2024

PARTS:

LABOR: Return Dan Home, tape off chrome on fender, sand inside of fender edge, paint three coats of red. \$25.00

---

1960 CADILAC CONVERTIBLE SERIES 62 – PURCHASE MARCH 2024

WORK COMPLETED by DJL & VINNIE - 4/10/2024

PARTS: Picked up battery charger

\$85.00

LABOR: House Call: Install new battery charger at Dan's garage on 1966 Lincoln, mount device on concrete wall. Deliver car to Auto mechanic for electric fuel pump installation.

---

WORK COMPLETED by DJL & VINNIE - 4/11/2024

PARTS and Labor: New electric fuel pump, new exhaust gaskets on right side of engine manifold down pipe. Install two metal gas filters. Campbells Garage. \$550.00

Put Stop Leak in Power steering, installed heat shield on fuel line to carb. \$50.00

TOTAL..... \$785.00

---

WORK COMPLETED by DJL & VINNIE - 4/11/2024 4/16/2024

PARTS and Labor: \$3 plus \$15

Add Marvel Mystery Oil to gas. Research on computer and phone calls.

---

WORK COMPLETED by DJL & VINNIE - 4/18/2024

Deliver Caddy to alignment shop, needs lower ball joints and idler arm, return to shop. \$50.00

Touch up paint on doors, channels, hood, tighten front grill  
@ \$25 p/hr, a bargain! \$50.00

---

WORK COMPLETED BY Keith Campbell & VINNIE – 4/24/2024

Deliver car to Vinnie ball joint and idler arm replacement/repair. \$570.41

---

WORK COMPLETED BY DJL & VINNIE – 4/26/2024

Install weather strip, right and left doors. Touch up paint on rocker panels, door jams, ash tray, lighter, glove box, R & R bulb in driver door, \$135.00

Parts:

Windshield & door rubber \$210.00

Starter solenoid for Lincoln \$42.00

Air Filter \$40.00

Ball joints \$215.00

**1960 CADILAC CONVERTIBLE SERIES 62 – PURCHASE MARCH 2024**

|              |          |
|--------------|----------|
| Idler Arm    | \$155.00 |
| Trans filter | \$85.00  |
| Trans basket | \$45.00  |

---

**WORK COMPLETED BY DJL & VINNIE – 5/06/2024**

Began at 0900. Remove distributor, install Par tronix electric ignitor system, install distributor, set timing and adjust carburetor. Drain and remove transmission oil pan, clean out debris, scrape off bad gasket, install transmission filter, reinstall oil pan, install new gasket on drain plug. Fill transmission with 10 quarts of transmission oil. Take out the speedometer, install gasket and tighten. Run car and check for leaks. Check put brake light switch. Finished at 1400. Labor \_ hours @ \$55 = \$275.00

|        |  |          |
|--------|--|----------|
| Parts: | Transmission fluid ten quarts                            | \$62.00  |
|        | Transmission Filter                                      | \$85.00  |
|        | Transmission Gasket                                      | \$60.00  |
|        | Drain Gasket, brass                                      | \$ 5.00  |
|        | Sub-total  | \$212.00 |
|        | Par-Tronix system, coil, ignitor, distributor cap, rotor | \$225.00 |

---

**WORK COMPLETED BY DJL & VINNIE – 5/10/2024**

Car was out of gas even though gas gauge indicated ¼ tank. \$70.00

---

**WORK COMPLETED BY DJL & VINNIE – 5/13/2024**

Drained 1 pint fluid from transmission, checked for leaks. Steering box has small leak, drained unit and refilled with stop leak. Tightened front bumper and grill. Checked proper tire pressure. Took choke apart and cleaned carbon deposits. Found chock was set in disabled position and will adjust tomorrow. Advise to put Sta-Bill gas treatment in with Rec 90 when not driving. \$203.00

---

**WORK COMPLETED BY DJL & VINNIE – 5/14/2024**

Adjusted chock, best way recommended to start cold engine is, key on and allow pump to run for a few seconds, pump pedal two times, and start car as usual. After starting, keep pedal engaged until engine runs for a minute or so. Choke is in bad condition and need to make a decision on what and how to repair. Probably, rebuild the carburetor!

Appears front main seal leaking and the seal to steering box is leaking as well. Both could be a big job!  
\$82.00

---

1960 CADILAC CONVERTIBLE SERIES 62 – PURCHASE MARCH 2024

WORK COMPLETED BY VINNIE & DJL - 5/21/2024

Drive Dan home from the shop, put Cadillac on lift and inspect for transmission leaks. Tighten bolts on trans pan. Tighten drain plug. Perhaps not tightening properly.

5/22/2024 – Inspect underneath car, still has engine oil leak by front of engine, small trans leak near plug area. Took car for a 20 minute test ride. Let car sit to look for leaks. No major leaks. Kept car overnight to check for hard starting.

5/23/2024 – Started car first thing in morning and remained hard to start. Started after three tries. Brought car to Cambell to check carburetor for leaks. Campbell confirmed that the oil leak is possibly the front seal, but the front of engine is not accessible and not able to go further as it is very expensive. Reset timing on engine to account for the addition of Per Tronic ignition. Brought my car back to the shop and left overnight to cold start the next morning.

Labor - \$75.00

5/24/2024 – Car started much better first thing in the morning. Explained to Dan about starting procedures, explained that drain plug was still leaking and that I will replace if I can find a new one.

Labor 3 Days - \$100.00

WORK COMPLETED BY [REDACTED] & DJL 6/24/2024

Find rattles, order suspension component for rear, repair left inner front fender from hitting, install missing bump stops in both ash tray, drain transmission, replace drain gasket, remove speedometer cable and install missing o ring, top off transmission, check choke operation, install missing gasket, adjust choke. Run engine, choke is not getting hot, replace choke with electric, run new wire and loom from fuse box to choke, install inline fuse, adjust choke.

Labor: 10.4 Hr. \$120

\$1,2148

Parts:

Rear control arm bushings, rear ball joint, choke coil

\$538.12

Repair material

\$12.00

TOTAL W/CHARGES AND TAX

\$2,092.21

# Don Caddy

Air Cleaner

upper & Lower Radiator Belts

door rubber -

order air cleaner or fine spray

3/29 Go to Napa order parts, at Home 17 hr on computer 25-

3/30 P/A parts Napa

5<sup>00</sup>

~~25~~  
101 40

4/02 P.U. exhaust gasket NAPA

4/03 P.U. Anti Freeze, bring car into shop & bring 60<sup>00</sup>

Don Home

25<sup>00</sup>

10-2 Remove left door Panel - drill & screw molding on door 4hr 220<sup>00</sup>

clean & polish hardware - clear out inside of door of debris

glue carpet under dash - reinstall knee plate under dash & screw it in.

Re installed door molding on right door, screw into door  
adjust Hood or Hood opening & install 5/8 Jeds nut.

7/04 8<sup>30</sup> 11<sup>30</sup> Change kerata & Powersteering Belts, Change upper & Lower Radiator Hoses, New 5/8 Clamps Screws & Hardware 15<sup>00</sup>

Change Anti Freeze - Clamps 13<sup>00</sup>

P/A Don & bring to Shop

PL  
4/4/24

641<sup>00</sup>

+



Innie Cashion  
FL  
+1 (203) 627-5057

VIN:  
Vehicle: 1960 Cadillac  
Series 62 6.4L,  
V8, Des 06X, USA  
License:  
Odometer: 28,621 Miles  
Customer  
Notes:

Invoice: 003043  
Created: 04/12/2024 9:34 AM  
Printed: 04/12/2024 9:34 AM  
Technician(s): Keith  
Written by:

Fuel pump

| Number | Type  | Part#/Op Code | Description  | Quantity | Unit Price  | Total Cost           |
|--------|-------|---------------|--------------|----------|-------------|----------------------|
| 1      | Part  |               | Pump         | 1.00     | \$ 98.00    | \$ 98.00             |
| 2      | Part  |               | Filter       | 1.00     | \$ 8.00     | \$ 8.00              |
| 3      | Labor |               | Install pump | 2.5000   | \$ 130.0000 | \$ 325.00            |
|        |       |               |              |          |             | Job Total: \$ 431.00 |

Exhaust gasket

| Number | Type  | Part#/Op Code | Description | Quantity | Unit Price  | Total Cost          |
|--------|-------|---------------|-------------|----------|-------------|---------------------|
| 1      | Labor |               |             | 0.5000   | \$ 130.0000 | \$ 65.00            |
|        |       |               |             |          |             | Job Total: \$ 65.00 |

Total Labor Time: 3.0000 Hours      Total Jobs Cost: \$ 496.00

|                                     |                  |
|-------------------------------------|------------------|
| Parts                               | \$ 106.00        |
| Labor                               | \$ 390.00        |
| Tax                                 | \$ 33.21         |
| Shop Supplies & Hazardous Materials | \$ 14.88         |
| <b>Grand Total</b>                  | <b>\$ 544.09</b> |
| Balance Due                         | \$ 544.09        |

I have received the above goods and/or services. If this is a credit card purchase, I agree to pay and comply with my cardholder agreement with the issuer. Warranty is 12 months / 12000 miles on parts and labor.

A finance charge of 1.5%/mo (18% annual rate) will be charged on all past due accounts. All parts are new unless otherwise specified. Re-check torque after the first 50 to 100 miles of service.

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

7-7 on Computer for Battery Minder 3  
 4-8 on Computer 25<sup>00</sup>  
 4-9 Return Dan Home, Tape off chrome on R/F fender, Sand ~~85~~  
 inside of fender & Paint 3 Coats of Red 25<sup>00</sup>  
 10 Pick up Battery Charger 85<sup>00</sup>  
 4/10 House Call: Drive to Dan home, install Noco Battery  
 Charger/maintainer on 66 Continental. Drill 2 holes in  
 concrete wall & mount device. Inspect working (OK) 50<sup>00</sup>  
 4/10 Bring car to mechanic to install fleet fuel Pump  
 4/11 P.U. Car from Shop - installed Elect Fuel Pump -  
 disconnected old pump, installed gasket on R/S of Exhaust  
 down pipe. installed 2 - metal gas filters, 550<sup>00</sup>  
 Put stop leads in Power Steering, installed heat wrap  
 on Fuel line to Carb 50<sup>00</sup>  
785<sup>00</sup>  
- 20<sup>00</sup>  
765<sup>00</sup>

XXX

P.C.  
 4/15/26

[Redacted]  
Campbell Automotive  
2815 SE Garden St  
Stuart, FL 34997  
Phone: (772) 236-0663  
MV# 94535  
campbell34957@gmail.com

Vinnie Cashin  
FL  
+1 (203) 627-5057

VIN:  
Vehicle: 1960 Cadillac  
Series 62 6.4L, V8,  
Des 06X, USA  
License:  
Odometer:  
Customer  
Notes:

Invoice: 003107  
Created: 04/25/2024 4:09 PM  
Printed: 04/25/2024 4:09 PM  
Technician(s): Keith  
Written by:

Ball Joints

| Number | Type  | Part#/Op Code |
|--------|-------|---------------|
| 1      | Labor |               |

| Description                       | Quantity | Unit Price  | Total Cost |
|-----------------------------------|----------|-------------|------------|
| R&R Lower ball joints & Idler arm | 4.0000   | \$ 130.0000 | \$ 520.00  |
|                                   |          | Job Total:  | \$ 520.00  |

Total Labor Time: 4.0000 Hours      Total Jobs Cost: \$ 520.00

|                                     |                  |
|-------------------------------------|------------------|
| Parts                               | \$ 0.00          |
| Labor                               | \$ 520.00        |
| Tax                                 | \$ 34.81         |
| Shop Supplies & Hazardous Materials | \$ 15.60         |
| <b>Grand Total</b>                  | <b>\$ 570.41</b> |
| Balance Due                         | \$ 570.41        |

I have received the above goods and/or services. If this is a credit card purchase, I agree to pay and comply with my cardholder agreement with the issuer. Warranty is 12 months / 12000 miles on parts and labor.

A finance charge of 1.5%/mo (18% annual rate) will be charged on all past due accounts. All parts are new unless otherwise specified. Re-check torque after the first 50 to 100 miles of service.

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

pd  
4/24/24

XXX



# 1960 Caddy

- 4/11 Marvel Mystery oil in Gas 3<sup>00</sup>
- 4/16 Work on Computer + phone Calls 15<sup>00</sup>
- 4/18 at Shop 0645 Bring Caddy to alignment Shop.  
needs lower ball joints + Idle arm  
Return to shop 0900 50<sup>00</sup>  
Touch up paint on Doors, Channels, Hood, Tighten front  
Cull @ \$25 per hr. (barger) 50<sup>00</sup>
- 4/25 Bring car to Shop for replacement of ball joints +  
Idle arm. Repairs 571<sup>00</sup>
- 4/26 Pick up car return to shop 0830 3 hrs } 125<sup>00</sup>  
Install weatherstrip on L & R doors. Touch up paint on  
rock panels, door Jam, Paint Ash tray, Tighten floor legs  
R & L ball in drives door, Pub Ball at Parts Store \$10<sup>00</sup> 1/30 10<sup>00</sup>

824  
797

1621<sup>00</sup>

## Parts

- ✓ Windshield + Door Rubber 210<sup>00</sup>
- ✓ P/u Starter solenoid for General 47<sup>00</sup>
- ✓ Air filter 210<sup>00</sup> (working installed)
- ✓ Ball Joints 215<sup>00</sup>
- ✓ Idle arm 155
- ✓ Trans filter 85
- ✓ " " Gearbit 45

797<sup>00</sup>

4/24/24  
Paid

+

May 07/2024

Dan 1960 Cadillac

05/06/ Start 0900

Remove Distributor , install Par Tronix electric ignitor system, Install Distributor, set timing on engine, Adjust carburetor.

Drain and remove transmission oil pan, clean out debris, scrape off bad gasket, install transmission filter, reinstall oil pan, install new gasket on drain plug. Fill transmission with 10 quarts of Transmission. Take out speedometer install gasket and tighten. Run car check for leaks.

Check out brake light switch.

1400 finished.

Labor r hours @ 55.00 = 275.00

|       |                               |       |           |
|-------|-------------------------------|-------|-----------|
| Parts | Transmission fluid ten quarts | 62.00 |           |
|       | Transmission filter           | 85.00 |           |
|       | Trans gasket                  | 60.00 |           |
|       | Drain gasket , brass          | 5.00  |           |
|       |                               | ----- | \$ 212.00 |

Par Tronix system

Coil ,Ignitor , Distrabator cap, rotor 225.00

Total \$ 712.00

*Handwritten signature and date: PD / 5/8/24*

Dan Lundstrom 1960 Cadillac

05/10/2024 Dan called with complaint of car not starting. Road Service, Drove to house (from my side bed) to access the situation. Plugged in battery minder because battery was worn down.

Upon inspection I concluded that the car had no gas even though the fuel gauge showed 1/4 of a tank. Drove to the shop to pick up a five gallon of high test gas and brought to Dan house. Reinstalled the gas filter and primed carb.

After putting the gas into the car had Dan start engine and car started up, adjusted the idle on the carburetor.

Advised Dan to fill the car up with Rec 90 fuel.

5 gal Gas \$ 50.00  
20.00

05/13 Drive Dan home, home, Put car on lift drained 1 pint of fluid from transmission, checked for leaks. Still a little leak from the steering box (Power steering fluid) drained unit and re filled with stop leak. Tightened front bumper and grill ( grill on passenger side was close to headlight housing possible from a former collision) pushed grill back and inserted foam insert to stop rattle.

Checked tire pressure and adjusted to 28 lbs ( pressure was approximately 34 lbs.)

Took choke apart and cleaned out carbon deposits and inspect choke spring ( choke was set to the disabled position, will look at it in the morning and try to adjust)

Advised Dan to put Sta-Bil gas treatment in fuel tank because cars are not driven the regular.

Labor 3.5 hrs @ 55.00 = \$ 193.00

1- bottle of Sta-Bil gas treatment 10.00

05/14

Adjusted choke, best way to start cold engine is to turn on key, let pump run for a few seconds pump the pedal two times and start car. When engine starts keep the pedal down until engine runs for a minute then let go. Choke is in very bad condition a lot of carbon from the engine and frankly the carburetor needs to be rebuilt.

Looks like the front maine oil seal leaks , the seal to the steering box leaks, Both of these could be a big job.

Labor 1.5 hrs @ 55 = 82.00

TOTAL \$ 355.00

PD  
5/15/2024

05/21/24 drive Dan home from shop. Put Cadillac on lift inspect transmission leaks. Tighten bolts on trans pan, tighten drain plug, does not look like it is tightening properly. Leave car overnight at shop.

05/22/24 Inspect underneath car , still has engine oil leak by front of engine ( told Dan about this before) only one small trans leak near plug area.  
Took car for ride for 20 min and returned to shop. Let car sit to check for leaks. No major leaks.  
Kept car overnight to check for hard starting tomorrow.

05/23/24 Started car in AM still a little hard to start, after 3 time car started , brought car To Campbell auto to check carb and leaks. Campbell confirmed that engine oil leak is possibly front seal but front of engine is not excess able to go further , ( this would be very costly)  
reset timing on engine to account for the addition of Per Tronic ignition.  
Brought car back to shop to leave overnight to check cold start tomorrow. \$ 75.00  
Campbell

05/24/24 Start car when cold, starts much better. Explained to Don about starting procedures , explained to Don if drain plug on Trans pan is still leaking that I will have to replace plug.(if I can find one)  
Delivered car to don 1100, don brought me ba ck to shop. Labor 3 days      100.00

Total 175.00

05/21/24 drive Dan home from shop. Put Cadillac on lift inspect transmission leaks. Tighten bolts on trans pan, tighten drain plug, does not look like it is tightening properly. Leave car overnight at shop.

05/22/24 Inspect underneath car, still has engine oil leak by front of engine (told Dan about this before) only one small trans leak near plug area. Took car for ride for 20 min and returned to shop. Let car sit to check for leaks. No major leaks. Kept car overnight to check for hard starting tomorrow.

05/23/24 Started car in AM still a little hard to start, after 3 time car started, brought car To Campbell auto to check carb and leaks. Campbell confirmed that engine oil leak is possibly front seal but front of engine is not excess able to go further, (this would be very costly) reset timing on engine to account for the addition of Per Tronic ignition. Brought car back to shop to leave overnight to check cold start tomorrow. Campbell \$ 75.00

05/24/24 Start car when cold, starts much better. Explained to Don about starting procedures, explained to Don if drain plug on Trans pan is still leaking that I will have to replace plug.(if I can find one) Delivered car to don 1100, don brought me back to shop. Labor 3 days 100.00

Total 175.00

XXX

pch

**ROD SHOP INC. Auto Repair & Painting**  
**Stuart, FL. 34994**

**Invoice / RO 24-9868**

6/24/2024

*Performance Technology for Your Car!*

Voice Mail 772.287.3336 & 772.287.3350  
 customer.service@therodshop.com

Federal Tax ID: 65-0188762  
 Florida Reg: MV-2393

772-201-4667

dan@yourdeveloper.us

|                |              |
|----------------|--------------|
| Apt Date/Note  |              |
| Sched Due Date | 6/24/2024    |
| Terms / Ins    | Customer Pay |
| CL #           |              |
| PO #           |              |

| Vehicle Info  | VIN       | Color Ext. / Int. | License (St.)    | Miles In / Out |
|---|-----------|-------------------|------------------|----------------|
| 1960 CADILLAC 62  | 60F066375 | RED               | 2Q9 FL           | 28621          |
| Description   | Qty       | Price / Rate      | Amount           |                |
| Restoration Labor (RS) 06/20/24 TO 06/24/24<br>LOCATE RATTLES, ORDER SUSPENSION COMPONENTS FOR REAR,<br>REPAIR LEFT INNER FRONT FENDER FROM HITTING, INSTALL MISSING<br>BUMP STOPS ON BOTH ASH TRAYS, DRAIN TRANSMISSION, REPLACE<br>DRAIN GASKET, REMOVE SPEEDOMETER CABLE INSTALL MISSING O-RING,<br>TOP OFF TRANSMISSION, CHECK CHOKE OPERATION, INSTALL MISSING<br>GASKET, ADJUST CHOKE, RUN ENGINE, CHOKE IS NOT GETTING HOT,<br>REPLACE CHOKE WITH ELECTRIC, RUN NEW WIRE AND LOOM, FROM<br>FUSE BOX TO CHOKE, INSTALL INLINE FUSE, ADJUST CHOKE,<br>Total Labor<br>*****                           | 10.4      | 120.00            | 1,248.00T        | 1,248.00       |
| New Part (Non-OEM) REAR CONTROL ARM BUSHINGS, REAR BALL JOINT,<br>CHOKE COIL<br>Total Parts<br>*****  | 1         | 538.12            | 538.12T          | 538.12         |
| Repair Material<br>Total Materials<br>*****   | 1         | 121.50            | 121.50T          | 121.50         |
| Freight / Shipping / Handling / Postage   |           |                   |                  |                |
| # Disposal Fee Oil / Qt.  | 1         | 24.40             | 24.40T           |                |
| Shop Supplies   | 3         | 2.50              | 7.50T            |                |
| # Disposal Hazardous Waste  | 1         | 14.00             | 14.00T           |                |
| Total Misc. & Sublet (#, Represent costs & profits to the repair facility for waste disposal)<br>*****  | 1         | 11.00             | 11.00T           | 56.90          |
| Subtotal<br>*****   |           |                   |                  | 1,964.52       |
| PLEASE SEE YOUR AUTOMOBILE REPAIR AUTHORIZATION FORM<br>Terms due upon receipt. Absolutely no checks or credit cards without prior approval. Cash deposits are required on all new accounts. Warranty Disclaimer: The manufacturer's warranty, if any, constitutes the only warranty with respect to the sale of all goods and labor. Seller hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller does not authorize any person to grant any warranty or assume any liability by seller. |           |                   | Taxable Amount   | \$1,964.52     |
|   |           |                   | Sales Tax (6.5%) | \$127.69       |
|   |           |                   | Total            | \$2,092.21     |

24-9868

XXX

pd  
 6/24/24