

CRAVER PLACE WORKS



ETHAN RODE 602-655-3456

# Service Invoice

Date: November 5, 2019

Customer:

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
11/3/2019		31536

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task 4: Refurbish Driver's Side CV axle	<input type="checkbox"/>	1	\$60.00	\$60.00
CV Boot Kit	<input type="checkbox"/>	2	\$16.50	\$33.00
Labor Task 8: Clean up Relay and fuse compartment. Paint tray, disinfect compartment, install updated relay, fuse, and breaker kit	<input type="checkbox"/>	1.5	\$60.00	\$90.00
Relay and Fuse Kit	<input checked="" type="checkbox"/>	1	\$110.00	\$110.00
Fused Fan Fail link	<input type="checkbox"/>	1	\$10.00	\$10.00
Labor Task 15: With Engine Removed, Replace Engine and Trans Mounts	<input type="checkbox"/>	.5	\$60.00	\$30.00
Engine Mount Kit W/ Hardware	<input checked="" type="checkbox"/>	2	\$55.00	\$110.00
Transaxle Mount	<input checked="" type="checkbox"/>	2	\$56.00	\$112.00
Labor Task 17: Install Delrin Steering column bushing	<input type="checkbox"/>	1.5	\$60.00	\$90.00
Delrin Bushing Kit	<input type="checkbox"/>	1	\$22.00	\$22.00

Totals	
Labor	\$270.00
Parts	\$397.00
Shop Supplies	\$35.00
Shipping	
Grand Total	\$702.00

CRAVER PLACE WORKS



ETHAN RODE 602-655-3456

# Service Invoice

Date: November 21, 2019

**Customer:**

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
11/20/2019		31536

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task 1: R&R Engine and Transaxle. Drain and refill engine oil, and coolant. Remove Intake manifold, clean and paint engine valley. Replace heater pipe, and re-seal Y-pipe below intake manifold. Replace all engine bay vacuum hoses, Front and rear crankshaft seals, timing cover seal, intake manifold o-rings and gaskets. Degrease engine exterior	<input type="checkbox"/>	8	\$60.00	\$480.00
Reinz Engine Gasket Set	<input type="checkbox"/>	1	\$110.00	\$110.00
Updated Rear Crank Seal	<input type="checkbox"/>	1	\$16.00	\$16.00
Front Crank Seal Sleeve	<input type="checkbox"/>	1	\$16.50	\$16.50
Misc Hose	<input type="checkbox"/>	1	\$88.00	\$88.00
Heater Pipe	<input checked="" type="checkbox"/>	1	\$58.00	\$58.00
Oil Filter, Hastings LF493	<input checked="" type="checkbox"/>	1	\$6.25	\$6.25
Engine Oil, 10W30 Conventional	<input type="checkbox"/>	7	\$5.43	\$38.00
Antifreeze Coolant	<input type="checkbox"/>	1	\$32.00	\$32.00
Labor Task 9: Diagnose lighting issues. Replace bad harnesses for front indicator lamps. Replace tail lamp circuit boards. Repair damaged wiring in rear lighting harness	<input type="checkbox"/>	2	\$60.00	\$120.00
Front Indicator Lamp Harness	<input checked="" type="checkbox"/>	2	\$45.00	\$90.00
Tail lamp Circuit Board w/incandescent bulbs, Pair	<input checked="" type="checkbox"/>	1	\$135.00	\$135.00
Labor Task 14: With engine removed, Tune up. replace fuel injector lines, fuel supply line, and fuel return line with customer supplied parts.	<input type="checkbox"/>	1.5	\$60.00	\$90.00
Spark Plugs, Bosch HR6DS	<input type="checkbox"/>	6	\$6.33	\$38.00
Ignition Rotor	<input type="checkbox"/>	1	\$17.50	\$17.50
Ignition Distributor Cap	<input type="checkbox"/>	1	\$25.00	\$25.00
Fuel Filter	<input checked="" type="checkbox"/>	1	\$16.25	\$16.25

Labor Task 18:Lower Crankcase damaged. Replace with good used part. Clean mating surfaces, and install new oil pan gasket	<input type="checkbox"/>	3	\$60.00	\$180.00
Lower Crankcase, Good used	<input type="checkbox"/>	1	\$300.00	\$300.00
Oil Pan Gasket	<input type="checkbox"/>	1	\$31.00	\$31.00

<b>Totals</b>	
<b>Labor</b>	\$870.00
<b>Parts</b>	\$1,017.50
<b>Shop Supplies</b>	\$70.00
<b>Shipping</b>	\$69.00
<b>Grand Total</b>	\$2,026.50

CRAVER PLACE WORKS



ETHAN RODE 602-665-3456

# Service Invoice

Date: December 2, 2019

**Customer:**

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
11/25/19		

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task 2: With Engine Removed-Remove stock exhaust, and exhaust studs. Four (4) broken fasteners noted. Install Customer Supplied DMC Europe Exhaust	<input type="checkbox"/>	3	\$60.00	\$180.00
Exhaust Hardware	<input type="checkbox"/>	1	\$49.50	\$49.50
<i>***NOTE*** Exhaust System does not conform to Federally mandated emissions standards. No guarantee or warranty expressed or offered relative to the vehicle's fitness to pass emissions inspection</i>				
Labor Task 16: Remove headliners, prep for restoration. Install restored headliners	<input type="checkbox"/>	3	\$60.00	\$180.00
Outside Labor- Headliner re-cover	<input type="checkbox"/>	1	\$275.00	\$275.00
Misc Labor: Replace broken Thermal Vacuum Switch	<input type="checkbox"/>	0	\$60.00	\$0.00
Thermal Vacuum Switch	<input type="checkbox"/>	1	\$55.00	\$55.00

Totals	
<b>Labor</b>	\$360.00
<b>Parts</b>	\$379.50
<b>Shop Supplies</b>	\$45.00
<b>Shipping</b>	\$8.50
<b>Grand Total</b>	\$793.00

CRAVER PLACE WORKS



ETHAN RODE 602-655-3456

# Service Invoice

Date: December 16, 2019

Customer:

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
12/10/19		

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task 19: Replace original Brake Hoses With new SS-Braid Hoses. Drain, Refill brake fluid. Bleed Brakes	<input type="checkbox"/>	2.5	\$60.00	\$150.00
SS Braid brake hose set	<input checked="" type="checkbox"/>	1	\$122.00	\$122.00
Labor Task 20: Fuel System Repairs, Control Press. Regulator not working properly. Send CPR in for rebuild. Send FD in for bench testing. Install Rebuilt parts. Install six new fuel injectors W/ Seals	<input type="checkbox"/>	2	\$120.00	\$240.00
Outside Labor: Control Pressure Regulator rebuild	<input type="checkbox"/>	1	\$250.00	\$250.00
Fuel Injector Seal	<input type="checkbox"/>	6	\$4.16	\$25.00
Fuel Injector	<input checked="" type="checkbox"/>	6	\$50.00	\$300.00
***NOTE** Fuel Distributor Tests Good, no repairs made.	<input type="checkbox"/>			
	<input type="checkbox"/>			\$0.00
Labor Task 9: Replace Passenger Side power window regulator	<input type="checkbox"/>	3	\$60.00	\$180.00
P/S Power Window Regulator	<input type="checkbox"/>	1	\$205.00	\$205.00
Labor Task 22: Replace worn AT Governor Cable, and Front trunk cable	<input type="checkbox"/>	.25	\$60.00	\$15.00
AT Governor Cable	<input type="checkbox"/>	1	\$36.00	\$36.00
Front Trunk Cable (cable only)	<input type="checkbox"/>	1	\$11.00	\$11.00

Totals	
Labor	\$585.00
Parts	\$949.00
Shop Supplies	\$25.00
Shipping	\$42.00
Grand Total	\$1,601.00

CRAVER PLACE WORKS



ETHAN RODE 602-655-3456

# Service Invoice

Date: December 28, 2019

**Customer:**

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
12/23/19		

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task 12: Replace A/C System. Install new components. Update to R134a refrigerant. Evacuate system, Charge, add UV dye.	<input type="checkbox"/>	6.5	\$60.00	\$390.00
A/C Accumulator-Dryer	<input type="checkbox"/>	1	\$22.00	\$22.00
A/C Lo Pressure Switch	<input type="checkbox"/>	1	\$11.00	\$11.00
White Orifice Tube	<input type="checkbox"/>	1	\$22.00	\$22.00
Hose Assy: Compressor-Condenser, Split-style	<input type="checkbox"/>	1	\$138.00	\$138.00
Hose Assy: Compressor-Accumulator, Split-Style	<input type="checkbox"/>	1	\$154.00	\$154.00
Hose Assy: Condenser-Evaporator	<input type="checkbox"/>	1	\$80.00	\$80.00
Sanden HP7 Compressor	<input checked="" type="checkbox"/>	1	\$215.60	\$215.60
Labor task 21: A/C Evaporator leaks, oriface tube stuck. Replace evaporator, clean air box, replace sealing foam on air doors, rebuild MODE switch	<input type="checkbox"/>	6	\$60.00	\$360.00
Evaporator Core	<input checked="" type="checkbox"/>	1	\$190.00	\$190.00
Mode Swich Kit	<input type="checkbox"/>	1	\$49.00	\$49.00
Blower Motor Resistor	<input checked="" type="checkbox"/>	1	\$26.00	\$26.00
Labor: Replace cracked heater valve with updated part. Clean coolant from engine compartment. Refill coolant and bleed cooling system	<input type="checkbox"/>	1	\$60.00	\$60.00
Heater Valve, Ford-Style	<input checked="" type="checkbox"/>	1	\$22.00	\$22.00
Labor: Replace new Thermo-Time Switch, Install new wheel nuts and torque to spec	<input type="checkbox"/>	0	\$60.00	\$0.00
Thermo-Time Switch, New	<input checked="" type="checkbox"/>	1	\$71.00	\$71.00
Lugnut Set	<input type="checkbox"/>	1	\$67.00	\$67.00

Totals

<b>Labor</b>	\$810.00
<b>Parts</b>	\$1,067.60
<b>Shop Supplies</b>	\$130.00
<b>Shipping</b>	\$66.50
<b>Grand Total</b>	\$2,074.10

CRAVER PLACE WORKS



ETHAN RODE 602-655-3456

# Service Invoice

Date: February 1, 2020

**Customer:**

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
1/15/2020		31539

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task 23: Set mixture to optimize engine performance. Troubleshoot poor/high idle issue	<input type="checkbox"/>	2	\$60.00	\$120.00
Outside Labor: Set Mixture, measure exhaust gases	<input type="checkbox"/>	1	\$90.00	\$90.00
Idle Air Control Valve	<input checked="" type="checkbox"/>	1	\$75.00	\$75.00
Throttle Cable	<input type="checkbox"/>	1	\$25.00	\$25.00
Outside Labor, Task 24: Four Wheel Alignment	<input checked="" type="checkbox"/>	1	\$150.00	\$150.00
Labor Task 27: Troubleshoot Transmission no-shifting issue. Fix bad wiring in multi-switch connector	<input type="checkbox"/>	3	\$60.00	\$180.00
Transmission pan gasket	<input type="checkbox"/>	1	\$25.00	\$25.00
Labor Task 29: Install customer's Wide Side Stripe	<input type="checkbox"/>	2	\$60.00	\$120.00
Install new Group 78 Battery	<input type="checkbox"/>	0		\$0.00
Group 78 Battery	<input checked="" type="checkbox"/>	1	\$95.00	\$95.00

Totals	
Labor	\$420.00
Parts	\$460.00
Shop Supplies	\$55.00
Shipping	\$15.00
<b>Grand Total</b>	<b>\$950.00</b>

CRAVER PLACE WORKS



ETHAN RODE 602-665-3456

# Service Invoice

Date: February 13, 2020

**Customer:**

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
2/8/20		31560

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task 25: Replace bad cooling fan switch (Otterstat)	<input type="checkbox"/>	.75	\$60.00	\$45.00
Otterstat 95c	<input checked="" type="checkbox"/>	1	\$40.00	\$40.00
Labor task 26: Side view mirrors faded, Replace with updated mirrors	<input type="checkbox"/>	.5	\$60.00	\$30.00
Convex Mirror Set	<input type="checkbox"/>	1	\$81.00	\$81.00
Labor Task 31: Brake Rotors warped, Replace brake rotors on all four wheels, and install updated brake pads	<input type="checkbox"/>	3	\$60.00	\$180.00
Brake Rotor Set, Front	<input type="checkbox"/>	1	\$175.00	\$175.00
Brake Rotor Set, Rear	<input type="checkbox"/>	1	\$200.00	\$200.00
EBC Brake Pad Set, Front	<input type="checkbox"/>	1	\$50.00	\$50.00
EBC Brake Pad Set, Rear	<input type="checkbox"/>	1	\$55.00	\$55.00
Labor Task 32: Replace failed speedometer angle drive	<input type="checkbox"/>	1	\$60.00	\$60.00
EU Angle Drive	<input checked="" type="checkbox"/>	1	\$68.00	\$68.00

Totals	
Labor	\$315.00
Parts	\$669.00
Shop Supplies	\$35.00
Shipping	\$10.00
<b>Grand Total</b>	<b>\$1,029.00</b>

CRAVER PLACE WORKS



ETHAN RODE 602-665-3456

# Service Invoice

Date: February 23, 2020

**Customer:**

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
2/15/20		

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task 11: Adjust E-Brake handle and switch	<input type="checkbox"/>	.5	\$60.00	\$30.00
Labor Task 28: Interior freshen-up: repair bolster D/S interior qtr. panel, replace decals on window and lock switches, new door escutcheons	<input type="checkbox"/>	3	\$60.00	\$180.00
Decal set	<input type="checkbox"/>	1	\$15.00	\$15.00
Door Escutcheon	<input type="checkbox"/>	2	\$30.00	\$60.00
Labor Task 30: Restore operation of power lock system. Add keyless entry	<input type="checkbox"/>	3	\$60.00	\$180.00
Digital Door Lock Module	<input checked="" type="checkbox"/>	1	\$275.00	\$275.00
Keyless Entry Module	<input checked="" type="checkbox"/>	1	\$55.00	\$55.00
Updated Lock Actuators	<input checked="" type="checkbox"/>	1	\$75.00	\$75.00
Labor Task 33: Remove binnacle for restoration. Install restored part with LED Lighting	<input type="checkbox"/>	1.5	\$60.00	\$90.00
DG Grey Binnacle W/Exchange	<input type="checkbox"/>	1	\$585.00	\$585.00
Cluster/Console LED kit	<input type="checkbox"/>	1	\$80.00	\$80.00
Labor Task 34: Idle thermistor is bad, Replace with new part	<input type="checkbox"/>	2	\$60.00	\$120.00
Idle speed thermistor	<input checked="" type="checkbox"/>	1	\$40.00	\$40.00

Totals	
Labor	\$600.00
Parts	\$1,185.00
Shop Supplies	\$55.00
Shipping	\$135.00
<b>Grand Total</b>	<b>\$1,975.00</b>

CRAVER PLACE WORKS



ETHAN RODE 602-655-3456

# Service Invoice

Date: January 3, 2021

Customer:

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
	1/1/21	34518

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task: Replace driver side power window regulator. Replace damaged drop glass	<input type="checkbox"/>	4	\$60.00	\$240.00
Window Regulator, LH	<input checked="" type="checkbox"/>	1	\$230.00	\$230.00
Drop Glass, LH	<input type="checkbox"/>	1	\$170.00	\$170.00
Labor Task: Adjust P/S Door lock mechanism	<input type="checkbox"/>	1	\$60.00	\$60.00
Axle Flange O-ring	<input type="checkbox"/>	2	\$5.00	\$10.00
Final Drive Seal	<input type="checkbox"/>	3	\$25.00	\$75.00
Flange Pin	<input type="checkbox"/>	2	\$5.00	\$10.00
Axle Flange repair sleeve	<input type="checkbox"/>	2	\$35.00	\$70.00
Gear Oil	<input type="checkbox"/>	2	\$17.00	\$34.00

Totals	
Labor	\$300.00
Parts	\$599.00
Shop Supplies	\$40.00
Shipping	\$32.50
Grand Total	\$971.50

CRAVER PLACE WORKS



ETHAN RODE 602-655-3456

# Service Invoice

Date: March 2, 2021

**Customer:**

Year	Make	Model
1981	DeLorean	DMC-12
Date In	Date Out	Milage
	3/2/2021	

Description	Warranty	Unit Qty	Unit Price	Total
Labor Task: Transaxle leaks at gearcase seal, TQ Converter seal. Pull Engine/Trans. Complete full re-seal of Transaxle. Split cases, new gaskets, seals, o-rings. Transaxle operates normally, no service of internal components recommended at this time	<input checked="" type="checkbox"/>	9	\$60.00	\$540.00
Trans Overhaul Gasket Set	<input type="checkbox"/>	1	\$275.00	\$275.00
Torque Converter Repair Sleeve	<input type="checkbox"/>	1	\$67.50	\$67.50
A/T Dipstick Tube	<input type="checkbox"/>	1	\$95.00	\$95.00
Engine Oil Filter	<input type="checkbox"/>	1	\$10.00	\$10.00
Engine Oil 15W-40	<input type="checkbox"/>	7	\$5.50	\$38.50
Coolant, Green	<input type="checkbox"/>	2.5	\$13.00	\$32.50
Labor Task: Repair engine oil leaks	<input checked="" type="checkbox"/>	2.25	\$60.00	N/C
123 valve cover Gasket	<input type="checkbox"/>	1	\$21.00	\$21.00
Oil Pressure switch	<input type="checkbox"/>	1	\$31.00	\$31.00

Totals	
Labor	\$540.00
Parts	\$570.50
Shop Supplies	\$35.00
Shipping	\$20.00
<b>Grand Total</b>	<b>\$1,165.50</b>