

WEBER AUTOMOTIVE  
28820 LORAIN ROAD  
NORTH OLMSTED, OH 44070



**Weber Automotive, Inc.**  
*Complete Import and Domestic Auto Care*  
28820 Lorain Road  
North Olmsted, Ohio 44070  
(440) 734-1413  
service@weberautomotive.com ~  
www.weberautomotive.com

07/31/2025 10:59:43  
CREDIT CARD  
MC SALE

Card # XXXXXXXXXXXXX3017  
Chip Card: Mastercard  
AID: A000000001010  
SEQ #: 2  
Batch #: 43  
INVOICE  
Approval Code: 66148P  
Entry Method: Chip Read  
Mode: Issuer

Park Dr  
d, OH 44070

Plate OH BS76QZ  
Description 2002 Chevrolet Camaro Z28 V8 5.7L 350CID VI  
G  
VIN 2G1FP22G622148353  
Odometer 7,131 In / 7,132 Out

Invoice Date 7/31/2025 11:00 AM  
Appointment 7/21/2025 8:00 AM  
Promised 8/1/2025 5:30 PM

SALE AMOUNT \$2816.20

NOTICE: Do not jump start the vehicle.  
CUSTOMER COPY: Do not jump start the vehicle.

Sub \$0.00 \*ES  
Sub \$0.00

Inspection

**Multi-Point Vehicle Inspection**

Checked functionality of all exterior lights, wiper blades, horn, belts, and hoses. Inspected engine air filter for cleanliness. Measured tire tread depth in 3 locations. Inflated all tires to manufacturer recommended pressure. Looked for any readily apparent fluid leaks and/or obvious safety concerns. Provided inspection findings to client.

Labor

Sub \$0.00 \*ES  
Sub \$0.00

**Comprehensive Inspection - Has been sitting for 7 years would like the vehicle inspected**

Before making a major investment in a vehicle, it's important to know exactly what you're buying. That's why we offer a comprehensive inspection service for vehicles you haven't yet purchased. Our experienced technicians thoroughly examine key safety and performance systems — including the brakes, suspension, tires, steering, lights, and more — to help uncover any existing issues or signs of potential future problems. We go beyond a basic visual check. Using professional diagnostic tools and industry expertise, we provide a detailed assessment and honest feedback so you can make an informed decision with confidence. Whether you're buying from a dealership or a private seller, our inspection gives you valuable insight into the vehicle's true condition and helps protect you from unexpected repairs or costly surprises down the road. By bringing the vehicle to us before you buy, you gain peace of mind, negotiating power, and clarity — all of which make this small upfront investment a smart part of your car-buying journey.

Labor

Sub \$253.34 \*ES  
Sub \$253.34

Service

**E-Check/Vehicle Emissions Testing**

We perform thorough OBD-II system and gas cap inspections, along with all state-required tests following Ohio EPA-approved procedures. This comprehensive evaluation helps ensure your vehicle's emission control systems are functioning properly, promoting cleaner air and compliance with state regulations. After testing, we provide you with clear, written results so you can confidently meet inspection requirements. Early detection of potential issues through this service helps prevent costly repairs, improves fuel efficiency, and supports long-term vehicle reliability. Our E-Check testing delivers peace of mind, regulatory compliance, and environmental responsibility—offering real value for you and your community.

Labor

Sub \$0.00 \*ES  
Sub \$0.00

**Battery Installation**

We replaced the vehicle's battery to ensure reliable starting power and consistent electrical system performance. A healthy battery is essential for powering your engine, electronics, and safety features. An old or failing battery can cause unexpected breakdowns, leaving you stranded and disrupting your day. Our expert replacement uses a high-quality battery matched to your vehicle's specifications, restoring dependable performance and extending the life of your vehicle's electrical system. By addressing this proactively, we help prevent inconvenient failures, improve overall vehicle reliability, and give you peace of mind every time you start your engine.

ACDELCO PROFESSIONAL/GOLD - Battery	1 Unit	\$226.62 ES
Labor		\$104.71 *ES
	<b>Sub</b>	<b>\$331.33</b>

**Accessory Drive Belt(s) - Includes freight to get belts**

Replaced the accessory drive belt (serpentine belt) to ensure reliable operation of critical engine components, including the alternator, power steering pump, air conditioning compressor, and water pump (if applicable). Over time, belts can wear, crack, or stretch, risking failure that could lead to loss of power steering, battery charging, or engine overheating. Installing a new, high-quality belt restores proper tension and performance, helps prevent unexpected breakdowns, and extends the life of connected components. Verified proper belt routing and tension after installation for smooth, quiet, and dependable engine operation.

Belt	1 Unit	\$119.13 ES
Belt	1 Unit	\$142.18 ES
Labor		\$168.89 *ES
	<b>Sub</b>	<b>\$430.20</b>

**Manual Transmission Fluid Exchange**

Drained and replaced the fluid in the manual transmission to remove heat-degraded lubricant, metal particles, and contaminants that accumulate over time. If the transmission was not equipped with a drain plug, a fluid evacuator was used to ensure a complete removal of the old fluid. Inspected the drain plug and gasket (if applicable) for damage or wear and replaced as needed to prevent future leaks. Refilled the transmission with fresh, high-quality fluid that meets manufacturer specifications to ensure optimal gear lubrication and smooth shifting performance. This service helps reduce gear wear, quiets drivetrain noise, improves shifting, and extends the life of internal transmission components. A properly serviced manual transmission ensures reliability, enhances fuel efficiency, and protects your investment for the long haul.

Sunoco - High Performance Automatic Transmission Fluid	8 Quart	\$74.48 ES
Labor		\$168.89 *ES
	<b>Sub</b>	<b>\$243.37</b>

**Coolant System Fluid Exchange**

Performed a full cooling system fluid exchange to help maintain proper engine temperature, prevent overheating, and protect vital engine components from corrosion and premature wear. Removed necessary components to access the cooling system and connected a professional-grade coolant exchange machine to the appropriate service points (radiator hose, reservoir, etc.). Flushed the system thoroughly, replacing the entire coolant capacity with clean, long-life coolant designed for optimal protection and performance. Excess coolant was removed from the reservoir and refilled to the correct level. After removing the machine and reassembling components, we inspected the system for leaks (none found) and road tested the vehicle to verify proper operation. Final coolant level was checked and topped off as needed. Important Note: We recommend returning after a few days of regular driving to recheck the coolant level, as air pockets in the system may take time to fully purge. This ensures long-term cooling efficiency and system reliability.

Extended-Life Antifreeze/Coolant DEFENDAL GOLD DEX-COOL	12 Gallon	\$216.00 ES
Labor		\$135.11 *ES
	<b>Sub</b>	<b>\$351.11</b>

**Brake Fluid System Flush - DOT 4**

We performed a complete brake fluid exchange to ensure your vehicle's braking system operates safely and effectively. After removing the wheels to access the calipers, we opened the bleeder screws and connected a professional-grade brake fluid exchange machine. This allowed us to flush out old, moisture-contaminated fluid and push clean, high-quality DOT 4 brake fluid through the entire system—including the master cylinder, brake lines, ABS module, calipers, and valves. Fresh brake fluid maintains proper hydraulic pressure, helps prevent internal corrosion, and ensures consistent braking performance. After topping off the reservoir and confirming there were no leaks, we reinstalled and torqued all wheels to factory specifications. A final road test confirmed smooth, responsive braking. This essential service helps extend the life of your brake components, enhances safety, and provides greater confidence behind the wheel.

Soltec - HD Brake Fluid DOT 4 DOT-3	1 Unit	\$45.49 ES
Labor		\$118.22 *ES
	<b>Sub</b>	<b>\$163.71</b>

Fluid Serial # \_\_\_\_\_

**Annual Transmission Extension Housing Shaft Seal - Includes freight to get seal**

Removed necessary components to access the output shaft area of the automatic transmission. Carefully extracted the worn or leaking output shaft seal, taking care not to damage the surrounding transmission housing or shaft surface. Cleaned the seal mating surfaces and inspected the output shaft for wear or damage that could lead to future leaks. Installed a new, high-quality output shaft seal to manufacturer specifications, ensuring a precise fit to prevent fluid leaks and maintain proper lubrication of internal transmission components. Reassembled all removed parts and topped off the transmission fluid to correct level if needed. Performed a final inspection for leaks and road-tested the vehicle to verify proper transmission operation. This service helps prevent fluid loss, protects transmission internals from contamination and wear, and supports overall drivetrain reliability.

Extension Housing Shaft Seal	1 Unit	\$86.68 ES
Labor		\$270.22 *ES
	<b>Sub</b>	<b>\$356.90</b>

**Fuel Filter**

Replaced the fuel filter to ensure clean fuel delivery and protect the engine's fuel system from contaminants such as dirt, rust, and debris. A clogged or dirty fuel filter can restrict fuel flow, leading to poor engine performance, hesitation, reduced fuel efficiency, and potential damage to fuel injectors and pumps. By installing a high-quality, manufacturer-approved fuel filter, we restored optimal fuel flow and filtration, helping the engine run smoothly and efficiently. This service supports consistent power delivery, improves fuel economy, reduces emissions, and extends the life of critical fuel system components—providing reliable performance and peace of mind.

Fuel Filter	1 Unit	\$57.16 ES
Labor		\$104.71 *ES
	<b>Sub</b>	<b>\$161.87</b>

**Run Rite Fuel System Cleaning Service**

Performed a comprehensive fuel system cleaning designed to restore engine efficiency, performance, and longevity. We began by adding a premium fuel system cleaner to the fuel tank, which works to dissolve deposits within the fuel pump, fuel lines, fuel rail, and injectors—continuing to clean these components over several tank fill-ups for lasting benefits. Simultaneously, a specialized engine oil system treatment was added to the crankcase to break down carbon buildup on critical lubricated surfaces, helping improve engine health and reduce wear. To target intake system deposits, we carefully accessed the intake cleaning service port and applied a powerful deposit cleaner directly through the throttle body while running the engine at controlled RPMs. This process removes stubborn carbon buildup on the throttle plate and intake surfaces, improving airflow and throttle response. Following the cleaning, the engine was allowed to idle to stabilize, then road-tested to ensure optimal performance. This service revitalizes fuel delivery, enhances combustion efficiency, reduces emissions, and promotes smoother engine operation—delivering noticeable improvements in drivability and fuel economy. Please note: It's normal to observe some temporary tailpipe smoke as loosened deposits are expelled from the system after this service. This will clear after driving the vehicle under load for a short period, signaling a cleaner, healthier engine.

Run-Rite 3 Step Kit	1 Unit	\$40.85 ES
Labor		\$126.67 *ES
	<b>Sub</b>	<b>\$167.52</b>

**Lube, Oil & Filter Service - Blended Oil**

To ensure your vehicle's engine continues to perform at its best, we performed an oil change service. This included removing the undercar shielding as needed to access the oil drain plug and filter. We drained the old engine oil and inspected the drain plug gasket for any signs of wear or damage, replacing it if necessary to ensure a proper seal. The oil filter was removed and the system was allowed to drain fully before installing a new filter with a properly lubricated gasket. A new drain plug was then installed, and the engine was filled with the correct type and quantity of oil. The vehicle was started and allowed to idle while we checked carefully for any leaks—none were found. Where applicable, chassis grease fittings and other friction points were lubricated. We then reinstalled the undercar shielding. As a courtesy, we topped off the windshield washer fluid to help maintain visibility and added coolant if needed to preserve proper engine cooling function (note: additional charges may apply for coolant top-off). This service was completed with attention to detail to support the reliability and safety of your vehicle.

5W30 - Castrol - GTX Ultraclean Synthetic Blend 5W-30 Engine Oil	5 Quart	\$24.00 ES
Castrol - GTX Ultraclean Synthetic Blend 5W-30 Engine Oil	0.5 Quart	\$5.04 ES
PF46E - Engine Oil Filter	1 Unit	\$15.00 ES
Labor	0.62 Hour	\$25.95 *ES
Technician: Rafael Otero		
Top Off Washer Fluid		\$0.00 *ES
	<b>Sub</b>	<b>\$69.99</b>

Total Parts	\$1,052.63
Total Labor	\$1,476.71
Total Before Taxes & Miscellaneous Charges	\$2,529.34

(*) Shop Supplies*	\$40.31 S
(E) Environmental Charge	\$37.94 S
(S) State Sales Tax	8 % \$208.61
<b>Grand Total</b>	<b>\$2,816.20</b>