

Part Number	Product Description	Ship Type	Status	Quantity	Price	Extended Price
15880	1967-68 Camaro, Rear Body Panel, Standard to RS Conversion Panel; EDP Coated	Oversize-2	In-Stock	1	\$149.99 ea	\$149.99
6201	MSD Digital 6A Ignition Control without Rev Limiter	Standard Size	In-Stock	1	\$263.99 ea	\$263.99
2659001	Mallory V8 Tail Block Distributor	Standard Size	In-Stock	1	\$494.99 ea	\$494.99
P1074K	Pypes Dual Electric Cutout Set w/Y-Pipes (Dump Legs) For 2.5" Exhaust	Standard Size	In-Stock	1	\$523.99 set	\$523.99
15899	1967-74 Camaro / Firebird, 1968-73 Nova Magnaflo 3" Crossmember Back Dual Exhaust System	Oversize-2	In-Stock	1	\$955.99 set	\$955.99
D40401	1967-69 Camaro / Firebird; Mini Tubs; DSE	Oversize-1	In-Stock	1	\$394.99 pr	\$394.99

The item(s) listed below are temporarily out of stock. Please allow ample time for delivery.

1662692	1968 Camaro, Firebird; Complete Door Shell Assembly; Passenger Side; EDP Coated	Truck Freight	In-Stock**	1	\$329.99 ea	\$329.99
1662693	1968 Camaro, Firebird; Complete Door Shell Assembly; Drivers Side; EDP Coated	Truck Freight	Backorder	1	\$329.99 ea	\$329.99
153079	1968 Camaro, Firebird; Firewall Panel; Coupe; with AC; EDP Coating	Truck Freight	In-Stock**	1	\$269.99 ea	\$269.99
C9003	1967-69 Camaro, Firebird; Full Floor Pan Assembly; EDP Coated	Truck Freight	In-Stock**	1	\$269.99 ea	\$269.99
152849	1967-69 Camaro, Firebird; Complete Floor Pan; For Deep Tubs; with Weld-Thru™ Primer	Truck Freight	Backorder	1	\$549.99 ea	\$549.99
1662753	1968 Camaro; Front Fender; Standard; with Extension; LH	Truck Freight	In-Stock**	1	\$289.99 ea	\$289.99
1662752	1968 Camaro; Front Fender; Standard; with Extension; RH	Truck Freight	In-Stock**	1	\$289.99 ea	\$289.99
CFH2	1967-69 Camaro Z/28 Bolt-On Style 4" Outlaw Cowl Induction Fiberglass Hood	Truck Freight	In-Stock**	1	\$639.99 ea	\$639.99
7738673	1968 Camaro Complete Quarter Panel; Coupe; LH	Truck Freight	In-Stock**	1	\$319.99 ea	\$319.99
7738674	1968 Camaro Complete Quarter Panel; Coupe; RH	Truck Freight	In-Stock**	1	\$319.99 ea	\$319.99
*881398	1967-69 Camaro, Firebird; Complete Rocker Panel Set; Inner and Outer; Coupe; RH	Standard Size	Backorder	1	\$117.99 set	\$117.99

7585083	1967-69 Camaro, Firebird: Roof Panel Skin, Sheet Metal; EDP Coated	Truck Freight	Backorder	1	\$279.99 ea	\$279.99
C337	1968 Camaro, Firebird: Full Trunk Floor Pan; EDP Coated	Truck Freight	Backorder	1	\$339.99 ea	\$339.99
174019	LS7 Bright Finish Vintage Air Front Runner Drive Set (Power Steering Without Pump)	OverSize-1	Backorder	1	\$2763.99 set	\$2763.99
K8461060	1967-69 F-Body Stock Width FAB9™ Rearend Housing for g-Bar or g-Link Rear Suspension	OverSize-1	Backorder	1	\$1121.99 set	\$1121.99
K8461011	1967-69 F-Body with G-Link Suspension and Mini-tub FAB9™ Rearend Housing	OverSize-1	Backorder	1	\$1631.99 set	\$1631.99
D141933	1958-86 Slant-Edge Die-Cast Aluminum Valve Covers - Bowtie - Green w/ Milled Emblem	Standard Size	Backorder	2	\$258.99 pr	\$517.98
174060BCA	Chevrolet Big Block with Power Steering Bright Finish Vintage Air Front Runner Drive Set w/o Pump	OverSize-1	Backorder	1	\$2226.99 set	\$2226.99
H550497	Holley Terminator EFI 4-Barrel TBI Kit with Transmission Control - Polished Finish	Standard Size	Backorder	1	\$3211.99 set	\$3211.99
RH150080	ARH 2" Long Tube Headers w/ 3-1/2" Collectors - 1967-69 Camaro w/LS Swap & Detroit Speed Front End	Overweight-1	Backorder	1	\$1548.99 set	\$1548.99
					Subtotal:	\$20155.73

I agree with Classic Industries® Terms and Conditions. Shipping and handling does not include backorder items.

All returns are subject to a 25% restocking fee. All merchandise is nonreturnable after 30 days from date of invoice. Literature, CD's, video, printed materials, stencil kits and stripe kits are non-returnable. Gift certificate have no cash value and must be redeemed for merchandise only. Electrical parts, gauges, wiring harnesses switches, etc. are non-returnable. All special products require a 50% nonrefundable deposit and are non-returnable. There is no guarantee on moving parts such as engines, transmissions, rear ends, steering gears, water pumps, distributors, wiper motors, etc. If any product is modified, altered, painted, installed, or disassembled in any way without Classic Industries® expressed written permission, the item is non-returnable. Classic Industries® always recommends professional installation on all products. Any item which has been altered, painted, installed or deemed non-resalable by Classic Industries® will be returned to the customer at the customers expense. California orders are subject to tax on handling fees, COD fees and rush fees. This additional tax will be applied to invoice. Classic Industries® is not responsible or liable for labor fees associated with the installation, removal, modification or repair of any product purchased regardless of the circumstances.



[My Account](#) | [Contact Us](#) | [Sign up for our Newsletter](#)

Find by Keywords...

GO

CONTACT US: 704.662.3272

10 Products - USD \$10,741.63

MY CART



Detroit Speed QUADRAL...
\$3,795.95

1

\$3,795.95



Wilwood Superlite 6R 13...
\$1,744.99

1

\$1,744.99



Detroit Speed Mini Tubs ...
\$394.95

1

\$394.95



Roll Cage Kit - (1967-69 ...
\$722.95

1

\$722.95



Stainless Steel Narrowed ...
\$935.95

1

\$935.95



Wilwood Superlite 4R 12...
\$1,744.99

1

\$1,744.99



American Autowire Class...
\$719.00

1

\$719.00



Detroit Speed Subframe ...
\$214.95

1

\$214.95



Fender Brace Kit - (1967-...
\$208.95

1

\$208.95



MPI GT1 Steering Wheel ...
\$258.95

1

\$258.95

Subtotal **USD \$10,741.63**

MODIFY MY CART

PLACE ORDER



ALL FESLER PRODUCTS ARE MADE IN THE USA, SO UNLIKE OUR COMPETITION WE ARE NOT WAITING ON SHIPS TO BE UNLOADED...



SHOPPING CART

RECARO EXPERT M Shown in Black Vinyl (ea)



Recaro Material: Black Leather w/Black Artista Insert

What seat do you need?: Both

Do you need seat brackets?: 2 Seat Brackets

Do You Need Seat Sliders?: 2 Seat Sliders

Please tell us the year, make and model of your project.: 1968 camaro

QUANTITY

- 1 +

\$3,030.00

Billet Interior Door Handles



Billet Handle Options: Brushed

QUANTITY

- 2 +

\$1,098.00

1967-69 1st Gen Camaro Custom Steel Rear Seat



Rear Seat Options: Raw Foam Not Covered

QUANTITY

- 1 +

\$3,500.00

1967-69 1st Gen Camaro Steel Center Console



Center Console Options: Raw Console

4 Way Billet Window Switch Kit: 4 Way Billet Window

Switch Kit Polished

Pioneer Double Din DVD: No Thank You

QUANTITY

\$2,324.00

1967-69 1st Gen Camaro DOT Flush-Mount Trim Less Glass Kit



1967-69 Camaro Front and Rear glass kit: I want to buy front and rear glass

Add Door Glass:: 1968-69 Models

Add Vent Window Glass:: No

Add Rear Quarter Window Glass:: 1967-69 Models

QUANTITY

\$2,459.00

1967-69 1st Gen Camaro Door Panels



Door Panel Options: Raw Not Covered

Add Fesler Billet Interior Door Handles & Wire kit: No

Thank you

Add Fesler Billet Arm Rest: Brushed

Add Power Windows: Power Windows WITH SWITCHES

BLACK ANODIZED

Add Morel Virtus Nano Carbon 6.5 Speakers: No

Thank You

Door Felts: No Thank You

QUANTITY

\$3,225.00

SPECIAL INSTRUCTIONS FOR SELLER

YOUR FORM OF PAYMENT WILL ONLY BE AUTHORIZED AT THE TIME OF CHECKOUT. ONCE YOUR PRODUCT IS READY TO SHIP, A FINAL PAYMENT WILL BE PROCESSED. YOU MAY BE REQUIRED TO FILL OUT A DIGITAL AUTHORIZATION FORM IF YOUR ORDER IS OVER \$1,000 OR INTERNATIONAL.

\$15,636.00

Taxes and shipping calculated at checkout

[HOME](#)

[FESLER FLUSH MOUNTED D.O.T. GLASS](#)

[FESLER PROJECT VEHICLES](#)

[1955](#)

CHECK OUT

FOLLOW US



MAIN MENU

[Home](#)

[Fesler Flush Mounted D.O.T. Glass](#)

[Fesler Project Vehicles](#)

[1955-59 Chevy Truck Products](#)

[1967-69 1st Gen Camaro Products](#)

[1970-81 2nd Gen Camaro Products](#)

[1967-72 C-10 Products](#)

Donnie's Auto Care Center LLC

Invoice

1609 S. Van Buren
 Enid, OK73703
 580-237-9010
 donniesautocare@sbcglobal.net

Rates:
 Labor Rate: \$80
 Diagnostic Rate: \$80

Bill To



Invoice Information

Invoice Number: 131
 Customer ID: 90
 Form Name: New estimate for 1968 Chevrolet Camaro
 Vehicle: 1982 Chevrolet Camaro
 Date: May 05, 2015

Labor Operations

Issue/Service/Part	Unit \$	Ext. \$	Tax	Sub Total
--------------------	---------	---------	-----	-----------

Rebuild Camaro

Complete rebuild, Frame off , install engine transmission,fuel injection,wiring,Re-Do wiring Ron strickland Did, Complete install, on all parts, Including paddle shifter, gas tank guages, vintage air, radiator & support, Vintage air front engine assembly,

- Dart Pro 1 Alluminum 310 Heads Assembled
- Head Gaskets
- ARP Head Bolts
- Polished Intake
- Intake Gaskets
- Fast Fuel Injection With Update & Bigger Fuel Pump
- Radiator & Support & cooling Fan Assemblys
- Complete Wiring Harness
- Shifter Cable
- Transmission cable ends
- transmission Fluid
- Engine Oil
- Oil Filter
- Relay Assemblr
- 3.50 Gears
- Gear grease
- Posi-Trac Additive
- Front Seats
- Dart Pro 1 Alluminum 310 Heads Assembled
- Fuel Tank sender
- Complete Relay Parts Assembly
- Drive Shaft
- Transmission Mount
- 6 An Fittings
- Braided Steel Line 6AN
- 12 Quarts Transmission Fluid
- Trans Mission Lines & Fittings

\$75.00	\$142,500.00	\$0.00	\$142,500.00
\$4,000.00	\$4,000.00	\$334.00	\$4,334.00
\$220.00	\$220.00	\$18.37	\$238.37
\$149.00	\$149.00	\$12.44	\$161.44
\$395.00	\$395.00	\$32.98	\$427.98
\$29.00	\$29.00	\$2.42	\$31.42
\$3,000.00	\$3,000.00	\$250.50	\$3,250.50
\$3,500.00	\$3,500.00	\$292.25	\$3,792.25
\$1,795.00	\$1,795.00	\$149.88	\$1,944.88
\$219.00	\$219.00	\$18.29	\$237.29
\$49.00	\$49.00	\$4.09	\$53.09
\$60.00	\$60.00	\$5.01	\$65.01
\$77.00	\$77.00	\$6.43	\$83.43
\$11.00	\$11.00	\$0.92	\$11.92
\$19.95	\$19.95	\$1.67	\$21.62
\$395.00	\$395.00	\$32.98	\$427.98
\$60.00	\$60.00	\$5.01	\$65.01
\$14.95	\$14.95	\$1.25	\$16.20
\$1,100.00	\$1,100.00	\$91.85	\$1,191.85
\$4,000.00	\$4,000.00	\$334.00	\$4,334.00
\$897.00	\$897.00	\$74.90	\$971.90
\$89.00	\$89.00	\$7.43	\$96.43
\$895.00	\$895.00	\$74.73	\$969.73
\$395.00	\$395.00	\$32.98	\$427.98
\$39.95	\$39.95	\$3.34	\$43.29
\$196.00	\$196.00	\$16.37	\$212.37
\$149.00	\$149.00	\$12.44	\$161.44
\$84.00	\$84.00	\$7.01	\$91.01
\$149.00	\$149.00	\$12.44	\$161.44

Oil Pan 7 Quarts	\$349.00	\$349.00	\$29.14	\$378.14
Headers Coated	\$595.00	\$595.00	\$49.68	\$644.68
MSD Distributor	\$329.00	\$329.00	\$27.47	\$356.47
MSD Coil	\$89.00	\$89.00	\$7.43	\$96.43
MSD 6AL Control Box	\$329.00	\$329.00	\$27.47	\$356.47
1 Set Spark Plug Wires	\$96.00	\$96.00	\$8.02	\$104.02
8 Spark Plugs	\$80.00	\$80.00	\$6.68	\$86.68
Hydraulic Roller Cam	\$385.00	\$385.00	\$32.15	\$417.15
Hydraulic Roller Lifters	\$695.00	\$695.00	\$58.03	\$753.03
1 Set Roller Rocker Arms	\$395.00	\$395.00	\$32.98	\$427.98
1 Set Stud Girdles	\$425.00	\$425.00	\$35.49	\$460.49
1 Pair Valve Covers	\$395.00	\$395.00	\$32.98	\$427.98
Gasket Set	\$256.00	\$256.00	\$21.38	\$277.38
Timing Cover	\$200.00	\$200.00	\$16.70	\$216.70
Exhaust System	\$595.00	\$595.00	\$49.68	\$644.68
Fittings & Extra Parts	\$1,500.00	\$1,500.00	\$125.25	\$1,625.25
Top & Bottom Hoses	\$42.00	\$42.00	\$3.51	\$45.51
All A/C Hoses	\$329.00	\$329.00	\$27.47	\$356.47
All A/C Fittings	\$219.00	\$219.00	\$18.29	\$237.29
Anti-Freeze	\$22.00	\$22.00	\$1.84	\$23.84
Fittings For A/C	\$129.00	\$129.00	\$10.77	\$139.77
Freon	\$30.00	\$30.00	\$2.50	\$32.50
Heater Hoses	\$16.00	\$16.00	\$1.34	\$17.34
Stainless Bolts	\$220.00	\$220.00	\$18.37	\$238.37
Extra Parts Not Mentioned	\$1,500.00	\$1,500.00	\$125.25	\$1,625.25
Paid * 2,000.00	\$200.00	\$200.00	\$0.00	\$200.00
Paid 	\$750.00	\$750.00	\$0.00	\$750.00
Not To Mention I Know I Missed A Lot Of Parts Not Mentioned On This Invoice	\$80.00	\$0.00	\$0.00	\$0.00

Paid In Taxes To Work On Car \$8,700.00 To IRS

Note
Paid \$ 82,00.00 In Checks & Cash

Totals Summary		
Labor:	2000 hr	\$143,450.00
Diagnostic:	0 hr	\$0.00
Parts:	53	\$31,207.85
Sub Total:		\$174,657.85
Tax:		\$2,605.85
Total:		\$177,263.70

1 Year Parts & Labor Warranty

G AND L AUTO SERVICE
 4294 INTERSTATE DR
 Macon, GA. 31210
 Phone: 478-474-6444 Fax: 478-474-5565

INVOICE

4766

Org. Est. # 006303

INVOICE

Printed Date: 04/04/2024 Work Completed: 08/09/2023



1968 Chevrolet - Camaro - 454

Lic # :

Odometer In : 1

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Used engine M64 LS82	1.00	4,117.65	4,117.65	Starter Shims Starter shims, customer supplied shims	195.26
wiring kit N ECM CUR 1479	1.00	2,214.29	2,214.29	Traced wires down from transmission ECU wired to dash module Traced wires down from transmission ECU wired to dash module	260.34
TIMING CHAIN KIT 1 EA CLY/Engine Timing Chain Kit 9-420558	1.00	134.06	134.06	Trace wires to make speedometer work Checked lifter adjusters - old engine	260.34 65.09
Oil Pump 1 EA MLLNG 1 EA/Engine Oil Pump M365	1.00	289.47	289.47	Checked lifter adjusters and found noise in the bottom of the engine. Engine needs to be replaced - old engine	
WATER PUMP 77053	1.00	283.19	283.19	Battery drain Fuel gauge, turn signal, cruise control starter shims sometimes squeals when cranking	
starter 89426n	1.00	284.97	284.97	shocks adjust- siffer/higher alignment window motor weak check lifter adjustment	
compressor 6511585 GPD	1.00	319.95	319.95	speedometer not working constant power to transmission controller	
OXYGEN SENSOR 2344332	2.00	133.31	266.62	Remove the 454 and install the 6.2	1,952.55
MASS AIR FLOW SENSOR B31503267API	1.00	233.69	233.69	Remove old wiring and install LS wiring	3,500.00
0W20 SYNETHIC OIL 0W20	6.00	11.65	69.90	R&R oil and filter R&R oil and filter	28.00
OIL FILTER PH2840	1.00	5.83	5.83		
Shop Supplies			27.00		

Org. Estimate 5,257.25 Revisions 0.00 Current Estimate 5,257.25

Labor:	8,259.61
Parts:	8,246.62
SubTotal:	14,506.23
Tax:	659.73
Total:	15,165.96
Bal Due:	\$6,165.96 + 5300

Extras Not incl on receipt:

Cold Air intake + install - 300 + install 200
 Air gap intake manifold + EPS (Summit max EPS LS750) - 2000 + install 400
 Lead Brakes 8" Booster + Master cyl 400 + install 100
 Lead Brakes 4 wheel disc prop + rear adj valve - 350 + install 100
 All new brake lines (custom install front + rear) 250 + 1000 install

total parts: ~~3500~~ + 1900 = 5300 (est)
 B&B

Payments - Cash

Customer Number : 1879

Vehicle Received: 8/9/2023

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. There will be a additional storage fee of \$25.00/day for vehicles left after three days of completion.

est tot 120,465.96

Signature _____

Date _____

Visit us on the web: www.facebook.com/GLCompleteAuto

Email Address: HUGHESGREG@ATT.NET

G AND L AUTO SERVICE
 4294 INTERSTATE DR
 Macon, GA. 31210
 Phone: 478-474-6444 Fax: 478-474-5565

INVOICE

4786

Org. Est. # 006353

INVOICE

Printed Date: 04/04/2024

Work Completed: 08/09/2023

1968 Chevrolet - Camaro - 454

Lic # :

Odometer In : 1

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Used engine MDA LS62	1.00	4,117.65	4,117.65	Starter Shims Starter shims, customer supplied shims	195.26
wiring kit N ECM CUR 1479	1.00	2,214.29	2,214.29	Traced wires down from transmission ECU wired to dash module Traced wires down from transmission ECU wired to dash module	260.34
TIMING CHAIN KIT 1 EA CLY/Engine Timing Chain Kit 9-4205SB	1.00	134.06	134.06	Trace wires to make speedometer work	260.34
Oil Pump FEA MLLNG 1 EA/Engine Oil Pump 3410 M365823	1.00	289.47	289.47	Checked lifter adjusters - old engine Checked lifter adjusters and found noise in the bottom of the engine. Engine needs to be replaced. - old engine	65.09
WATER PUMP T7053	1.00	283.19	283.19	Battery drain Fuel gauge, turn signal, cruise control starter shims sometimes squeals when cranking	
starter 6942sn	1.00	284.97	284.97	shocks adjust- stiffer/higher alignment window motor weak check lifter adjustment	
compressor 6511565 GPD	1.00	319.95	319.95	speedometer not working constant power to transmission controller	
OXYGEN SENSOR 2344332	2.00	133.31	266.62	Remove the 454 and install the 6.2	1,952.55
MASS AIR FLOW SENSOR B31503257API	1.00	233.69	233.69	Remove old wiring and install LS wiring	3,500.00
0W20 SYNETHIC OIL 0W20	6.00	11.65	69.90	R&R oil and filter R&R oil and filter	26.03
OIL FILTER PH2840	1.00	5.83	5.83		
Shop Supplies			27.00		

Org. Estimate 5,257.25 Revisions 0.00 Current Estimate 5,257.25

Extras Not incl on receipt:

Cold Air intake + install - 300 + install 200
 Air gap intake manifold + EFI (Summit Max EFI LS750) - 2000 + install 400
 Lead Brakes 8" Booster + Master cyl 400 + install 100
 Lead Brakes 4 wheel disc prop + rear adj valve - 550 + install 100
 All new brake lines (custom install front + rear) 250 + 1000 install

[Payments - Cash - \$3,000.00, MasterCard - \$4,000.00, American Express - \$2,000.00]

total parts: ~~3500~~ + 1800 = 5300 (est.)

Labor:	6,259.61
Parts:	8,246.62
SubTotal:	14,506.23
Tax:	659.73
Total:	15,165.96
Bal Due:	\$6,165.96
	+ 5300

Vehicle Received: 8/9/2023

Customer Number : 1879

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. There will be a additional storage fee of \$25.00/day for vehicles left after three days of completion.

Signature _____ Date _____

est tot: 20,465.96

Visit us on the web: www.facebook.com/GLCompleteAuto

Email Address: HUGHESGREG@ATT.NET