

Aspen Import Auto

(303) 934-8679

"Rocky Mountain Fiat Rescue"

1707 West Baltic Place
Englewood, Colorado 80110



3-909-4953
mileage 019083
11/18/83
06753

Roger Schultz Shultz

QUAN.	PART NO. AND DESCRIPTION	PRICE	AMOUNT
1	cond FT dx	325.00	
	Manifold		
1	4 bolt manifold gasket	17.19	
1	8008 Cond Top due to		
1	Cond Top fit Box Cover	30.00	
			388.19

Notes: windows
New Rear window
New upper soft - do not
touch or lean top
until has sun baked
3 to 4 days
top maintenance
Box kit

NAME: Roger Schultz Shultz
ADDRESS: 1098 West 94th pl
Westminster Co 80023
YEAR: 80 MAKE & MODEL: spider SERIAL NO.: WRITTEN BY: Tom PHONE?:

TUNE UP MINOR OVERHAUL MAJOR OVERHAUL CHANGE OIL SPARK PLUGS

OPER. NO.	INSTRUCTION	AMOUNT
	ep manifold leak - partial	
	header & remove gaskets manifold	
	Install w/ new gskt - Bites But to seal	
	R&R manifold & sublet for machine	
	(warped) - attempt to install - will	5.00
	not fit - too much needed to cut -	
	Replace manifold w/ good used -	
	(Repair & leaking studs during)	
	Install Customers top	350.00
	w/ supplied cables	
	Sand & prep Top frame	80.00
	Recover front Top Box	
	Ch over & call of prob's	
	Research - AC 5 -	

Not responsible for loss by fire or theft or any other cause beyond our control.

I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purposes of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.

TOTAL PARTS
388.19

TOTAL LABOR	978.00
TOTAL PARTS	388.19
Environmental Charges	24.00
TAX	32.36
TOTAL	1422.55

Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

Research - AC 5 - unable to find kit
\$1472.55

3-909-4953

Aspen Import Auto

(303) 934-8679

"Rocky Mountain Fiat Repair"

1707 West Baltic Place
Englewood, Colorado 80800



018911

Mulroy 67078

Roger Shultz

QUAN.	PART NO. AND DESCRIPTION	PRICE	AMOUNT
1	20603 HEAT HOSE	15.53	
	Coolant	16.83	
			32.36

NAME: Roger Shultz
 ADDRESS: 1098 W 144th Pl, Westminster Co 80023
 YEAR: 81 MAKE & MODEL: Fiat 3000 2400 SERIAL NO.: 50-00175145 WRITTEN BY: Tom
 TUNE UP MINOR OVERHAUL MAJOR OVERHAUL CHANGE OIL SPARK PLUGS

OPER. NO.	INSTRUCTION	AMOUNT
	Coolant leak	
	pressure test system	
	hole - heater hose - squirting on of manifold flange	137.00
	Drain System - Remove Components for Access & Replace hose - top of Bump System OK Fan operation	

~~note~~
~~oil pan~~
~~Amatched Head~~
 12/1/88
 Deloit

TOTAL PARTS

Not responsible for loss by fire or theft or any other cause beyond our control.	TOTAL LABOR	137.00
I hereby authorize the above repair work to be done with the necessary material and grant permission to operate equipment for purposes of testing and inspection. An express mechanic's lien is acknowledged to secure the amount of repairs.	TOTAL PARTS	32.36
	Environmental Charges	14.00
	TAX	36.40
	TOTAL	187.00

Unless otherwise provided by law, the seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

x drop off

THE DEALER ALTERNATIVE INC.

1603 SHERMAN

COEUR D' ALENE, ID. 83814

Phone - 208-664-8583 Fax - 208-667-4847

INVOICE

25622

DATE 224217332994 TIME 08:09:10
05/16/2006 00556N

DEALER ALTERNATIVE
1603 E SHERMAN AVE
COEUR D ALENE, ID 83814
2086648583

WE ARE THE TOYOTA MASTERS!

Print Date : 05/15/2006

TRANS #005
AUTH #077207
AVS RESPONSE: Z = Zip Match
VISA ACCOUNT #
XXXXXXXXXXXX8477

SALE AMOUNT \$329.94

THANK YOU!
THANK YOU
COME AGAIN

CUSTOMER COPY

DG	1.00	1.10	1.10
OIL FILTER			
1189	1.00	32.21	32.21
FUEL FILTER			
3002	1.00	4.38	4.38
LIGHT BULB			
1156	1.00	0.67	0.67
FAN SENOR			
2011321	1.00	14.79	14.79
FUEL			
1	1.00	14.41	14.41
Shop Supplies		1.00	1.00

1981 Fiat - Spider

Lic #: K188968

Odometer In : 62413

Unit #: BLUE

Vin #:

Hat #:

Ref #:

Sale	Extended	Labor Description	Extended
		ALIGNMENT	65.00
2.25	9.00		
		CHECK BRAKE & TAIL LIGHTS , CHECK COOLANT , GETS HOT , CHECK BATTERY GOES DEAD	32.50
		BATTERY & CHARGING SYSTEM OK .018 DRAW , NORMAL REPLACE BRAKE LIGHT BUBLE	
		LUBE OIL FILTER	10.00
		CHANGE ENGINE OIL & OIL FILTER LUBE CHASSIS,CHECK TIRE PRESSURE CHECK & TOP OFF ANY FLUIDS CHECK BRAKE PERCENTAGE, CHECK AIR FILTER	
		CHECK & FILL BATTERY CHECK TEMPERATURE RATING OF COOLANT CHECK FOR ANY LEAKS (OIL,COOLANT ETC), TIGHTEN DRAIN PLUG..... RESET OIL LIGHT WERE APPLY	
		REPLACE FUEL FILTER	32.50
		TIRE ROTATE	10.00
		REPLACE COOLANT TEMP SENSOR FOR FAN	32.50
		REPLACE FRONT WHEEL BEARINGS	65.00
		Hazardous Materials	1.00
		**** Recommendations ****	
		4-20-04	
		RADAITOR SEEP(1)	
		PAN DENTED	
		CLUNK IN RIGHT FRONT POSSIBLE UPPER CONTROL ARM	
		6-6-02	
		OIL PAN GASKET LEAK(2) POSSIBLE REAR MAIN SEAL	
		HAS AFTER MARKET AIR HORNS NOT ABLE TO ADDRESS CUSTOMER COMPLAINT	

THE DEALER ALTERNATIVE INC.

1603 SHERMAN

COEUR D' ALENE, ID. 83814

Phone - 208-664-8583 Fax - 208-667-4847

WE ARE THE TOYOTA MASTERS!

INVOICE

28264

*Visa
7-3-07*

INVOICE

Print Date : 06/27/2007

1981 Fiat - Spider

2.0L, In-Line4, VIN (B)

Lic # : K18896E

Odometer In : 62743

Unit # : BLUE

Vin # :

Hat # :

Cust ID : 2812

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
CASTROL GTX 5W-30				LUBE OIL AND FILTER	10.00
OIL	5.00	2.97	14.85	REPLACE OIL & FILTER LUBE CHASSIS,	
OIL FILTER NAPA				CHECK TIRE PRESURE, CHECK AND TOP	
OFN	1.00	4.49	4.49	OFF FLUIDS, CHECK BRAKES , CHECK AIR	
Shop Supplies		0.39	0.39	FILTER, CHECK COOLANT TEMP &	
				CONDITION, CHECK FLUID LEAKS,	
				TIGHTEN DRAIN PLUG....., RESET	
				MAINTENCE LIGHT, UP DATE	
				RECOMENDATIONS.	
				CHECK BATTERY AND CHARGEING SYSTEM	32.50
				CHECK FOR DRAWS BATTERY KEEPS GOING	
				DEAD,	
				Hazardous Materials	0.85
				**** Recommendations ****	
				4-20-04	
				RADAITOR SEEP(1)	
				PAN DENTED	
				CLUNK IN RIGHT FRONT POSSIBLE UPPER	
				CONTROL ARM	
				6-6-02	
				OIL PAN GASKET LEAK(2) POSSIBLE REAR	
				MAIN SEAL	
				HAS AFTER MARKET AIR HORNS NOT	
				ABLE TO ADDRESS CUSTOMER	
				COMPLAINT	
				5-15-06 BRAKES FRONT 50% REAR LOK	
				NEW	
				FRONT TIRE FEATHERING	
				PINION SEAL SEEP , TRANSMISSION SEEP	

MUFFLERS & MORE

exhaust and brake specialist

TNT MUFFLERS & MORE
523 SHERMAN AVE
COEUR D'ALENE ID 83814
209-666-2591

523 E SHERMAN AVENUE
COEUR D'ALENE, ID 83814
(208)666-2591

Year Make. 1981 FIAT Spyder
Engine 0 L
License WALSH_001
MLG in/out 0000 /
Vin

DATE: 06/28/86 TIME: 10:19
SER#: 041500215665 TRN: 0001
S-A-L-E-S D-R-A-F-T

REF: 0002 BCH: 055
CD TYPE: VISA
TR TYPE: PR
INVT:
AMOUNT: \$95.85

ACCT: *****0477 EXP: ***
AP: 077459
NAME: JOANN MCINTOSH

CARDMEMBER ACKNOWLEDGES RECEIPT OF
GOODS AND/OR SERVICES IN THE AMOUNT OF
THE TOTAL SHOWN HEREON AND AGREES TO
PERFORM THE OBLIGATIONS SET FORTH BY THE
CARDMEMBER'S AGREEMENT WITH THE ISSUER
THANK YOU
THANK YOU FOR USING VISA

TOP COPY-MERCHANT BOTTOM COPY-CUSTOMER

INVOICE : 1005881

Ref:1005867 01:19PM

Page 1

HRS	PRICE	PARTS & LUBRICANTS	QTY	PRICE	TOTAL
1.00	35.00	resonator muffler RES4921	1.00	41.99	41.99
1.00	15.00				

D AMOUNT	All Parts Are New Unless Shown As (U) Used or (R) Rebuilt	Labor 50.00 Sublet 0.00	Parts & Lubricants 41.99
-----------------	---	----------------------------	--------------------------

This vehicle will be reassembled within 3 days of the date shown above if I do not authorize the recommended services.

HAZ. DISPOSAL SHOP	0.00
Gasoline	1.68
Sub Total	93.67
Sales Tax	2.18
Deposit	0.00
Disc. Applied	0.00

I acknowledge notice and oral approval of an increase in the original estimated price

Visa / VISA

X

ACCEPTANCE SIGNATURE

I accept the charges and terms of this agreement.

TOTAL	95.85
BALANCE DUE	0.00

THANK YOU FOR YOUR BUSINESS. WE ARE YOUR EXHAUST AND BRAKE SPECIALIST.

I authorize the above repairs and necessary materials. Your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or items left in it. I agree to pay reasonable storage on vehicle left more than 3 working days after notification that job is completed. Labor is guaranteed 90 days or 4000 miles whichever occurs first. All other guarantees are made by the manufacturer. Warrantee work based on this bill must be performed at this shop. All parts are new unless specified as (U) used or (R) rebuilt. REMOVED PARTS WILL BE DISPOSED OF UNLESS I INITIAL HERE _____.

FOREIGN AUTOMOTIVE SERVICE TEAM

6900 117TH ST.
BROOMFIELD, CO 80020
303 469-4828

Repair Order #0038543

Date : 11/4/2015

Page : 1

Center : 2

Customer : Address : City : Cell : Work :	Vehicle : 1981 FIAT 124 SPIDER COUPE License : 676 QGY Clr : VIN : Engine : 4-1995 2.0L DOHC Trans : Mileage : 65671 Prod :
--	---

Op	Tech	Description	Part Description	Reason for Replacement	Labor	Parts	Subtotal
Quan	Part Number					Price	
Service Requests: Drop Off; 3rd vehicle.. fuel tank area has a leak.. believes that it is a fuel hose.. LARGE KEY IS TO THE IGNITION/SMALL KEY IS TO THE DOOR AND TRUNK EG R/R FUEL LINE FROM TANK TO FILLER NECK.							
MANO	1.00	NBH 1057	FUEL FILLER NECK	PART FAILED	148.01	42.00	190.01
						42.00	

Payments:
MSTR CHARG VISA, \$201.70, on 11/04/15
CardNo: [*****9685], AuthorizationNo: [886091]

OK Bad	Recommendation	OK Bad	Recommendation	OK Bad	Recommendation
--------	----------------	--------	----------------	--------	----------------

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control.
WARRANTY IS 12 MONTH OR 12 THOUSAND MILES WHICH EVER OCCURS FIRST, UNLESS SPECIFIED
OTHERWISE! X _____

Labor :	\$148.01	
Parts :	\$42.00	
Sublet :	\$0.00	
Other Fees :	\$0.00	
Supply Chrg	\$7.60	
Subtotal :	\$197.61	
Sales Tax :	\$4.09	
Paid By :	Total :	\$201.70
MSTR CHARG VISA	Paid :	\$201.70
Pay Ref :	Due :	\$0.00

FIAT PARTS WAREHOUSE**OTP LLC**802 WOODRUFF ST
SAN ANGELO TEXAS 76905PHONE: 325-248-6706
FAX: Call for number
ORDERS: 800-736-6410
EMAIL: fiatparts@outlook.com**10632**

INVOICE NUMBER

Sold To:
Address: :
City:
State:
Country:
Zip Code:
TAX ID #:ACCOUNT #: 21779
ATTENTION:
TELEPHONE: (303) 909-4953
ORDER DATE: 12/10/2015
P.O. NUMBER: F
SHIPPED VIA: FEDEX HOME DELIVER
SALESMAN: 10

QTY	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
1	1903138	DOOR CHECK SPRING	\$24.80	\$24.80	\$24.80
2	4296412G	EMBLEM HOOD&TRUNK GOLD	\$26.50	\$26.50	\$53.00
2	4399250	REAR SHOCK ABSORBER	\$38.97	\$38.97	\$77.94
1	46620285	MIRROR- OUTER-LEFT	\$44.80	\$44.80	\$44.80
1	46620286	MIRROR- RIGHT HAND	\$44.80	\$44.80	\$44.80
1	7025	FIAT PARTS CATALOG	\$0.00	\$0.00	\$0.00

LEFT MIRROR COMING FROM ALTERNATE WAREHOUSE.PARTS: \$245.34
SHIPPING: \$14.94
SUBTOTAL \$260.28
TAX: \$0.00
TOTAL: \$260.28**PAGE:****AUTH:** 72096904

Please Note: All parts returned must be accompanied by this invoice. No returns on electrical or special order parts. Special order parts must be pre-paid. All returned parts are subject to a 20% restocking charge. No returns on manuals, or any publications. No returns after 30 days. No returns without prior authorization. Disclaimer of Warranties: Any warranties on the products sold hereby are those made by the manufacturer. The seller, OTP LLC expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose. OTP LLC neither assumes, nor authorizes any other person to assume for its liability in connection with sale of said products. OTP LLC is not responsible for any labor on the installation of said products.

aardvark international LLC

PO Box 509
Whittier, CA
90608


Sales Receipt

Date	Sale No.
01/12/16	7732

Sold To

Ship To

Authorization	Pay Method	Ship Date	Ship Via	Phone
477951 Y	VISA	01/12/16	UPS	303 909 4953

Item	Description	Quantity	Price Each	Amount
V5568	Baby Tornado R. Convex Vitaloni - Plastic Base OBJECTS IN MIRROR ARE CLOSER THAN THEY APPEAR	1	85.00	85.00T
UPS \$14.50	UPS Freight - Insured Out-of-state sale, exempt from sales tax		14.50 0.00%	14.50 0.00
				
Thank you for your business.			Total	\$99.50

FIAT PARTS WAREHOUSE

OTP LLC

802 WOODRUFF ST
SAN ANGELO TEXAS 76905

PHONE: 325-248-6706
FAX: Call for number
ORDERS: 800-736-6410
EMAIL: fiatparts@outlook.com

14999

INVOICE NUMBER

Sold To:
Address:
City:
State:
Country:
Zip Code:
TAX ID #:

ACCOUNT #: 21779
ATTENTION:
TELEPHONE: (303) 909-4953
ORDER DATE: 11/1/2018
P.O. NUMBER: F
SHIPPED VIA: FEDEX HOME DELIVER
SALESMAN: 10

QTY	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
2	1903082	TOP WIRE-SPIDER	\$10.40	\$10.40	\$20.80
1	5886744	TAN VINYL TOP - 79 ON	\$265.00	\$265.00	\$265.00

PARTS: \$285.80
SHIPPING: \$22.54
SUBTOTAL \$308.34
TAX: \$0.00
TOTAL: \$308.34

PAGE:

AUTH: 00948202

Please Note: All parts returned must be accompanied by this invoice. No returns on electrical or special order parts. Special order parts must be pre-paid. All returned parts are subject to a 20% restocking charge. No returns on manuals, or any publications. No returns after 30 days. No returns without prior authorization. Disclaimer of Warranties: Any warranties on the products sold hereby are those made by the manufacturer. The seller, OTP LLC expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose. OTP LLC neither assumes, nor authorizes any other person to assume for its liability in connection with sale of said products. OTP LLC is not responsible for any labor on the installation of said products.