mu verge: 69,730

VIN# IGNEVI8KIJF102383

1988 Chernolet K5 Blazer

Restoration Have All Receipts & Records
of All Work Pentonned (Restored by Atlant)
Rebuilt 350 Engine Automation)
FAST Fuel Injection
Result 70084 Transmission
Lift Kit

Dual Front Shocks Exton Locking Rear Differential

33× 12.50 BF Gooprich Tixes 15×10 Custom Aluminum Wheels

Beautiful Refinished Two Tone RED OVER

All New Interior

Rust Free GA Tak

Loades W/options

Must See Tek That Is Berry To Go Anywhere!

(770)946-8949 atlantaautoresto@bellsouth.net



Invoice

Date	Invoice #	
08/20/2013	1427	
Terms	Due Date	
Net 15	09/04/2013	

Bill To

Wayne Barber 7358 Southlake Pkwy Morrow, GA 30260

Amount Due	Enclosed
\$135.00	

Place deticate para trascentiación multiples payocare

Year	Make	Model
1988	Chevrolet	Blazer

Date	Account Summary	Amount
07/25/2013	Balance Forward	\$4,476.58
07/29/2013	Payment received	-4,476.58
	New charges (see details below)	135.00
	Total Amount Due	\$135.00

Activity	Quantity	Rate	Amount
 Pinstriped corner trim & pinstriped vehicle body. Seam sealed & undercoated inner fender well access panels. 	3	45.00	135.00
DATD			
	Total Of No	ew Charges	\$135.0
	Total A	mount Due	

(770)946-8949 atlantaautoresto@bellsouth.net



Net 15

08/09/2013

Bill To	
Wayne Barber 7358 Southlake Pkwy Morrow, GA 30260	

Amount Due	Enclosed
\$4,476.58	·

Please detacles piportion and acturn with your paynt

Year	Make	Model
1988	Chevrolet	K5 Blazer

Date	Account Summary	Amount
06/30/2013	Balance Forward	\$5,366.12
07/05/2013	Payment received	-5,366.12
	New charges (see details below)	4,476.58
	Total Amount Due	\$4,476.58
		, , , , , , , , , , , , , , , , , , , ,

Activity	Quantity	Rate	Amount
• Installed glass in tailgate. Installed hinges, springs, tracks, tailgate straps & spring hold down brackets. Greased tracks & regulators. Taped out, cleaned & polished. wheel well molding to be painted. Polished wheel well screws. Installed 3 of 4 wheel wells. Installed gas lid door & all components. Polished drivers door handle & lock & installed. Installed drivers side seat belt retainer & panel screws. Cleaned buffing compound from drivers door, front marker lights, antenna & sleeve. Finished cleaning buffing compound from entire truck. Wiped down inside. Polished & installed passenger & drivers side mirrors. Installed & polished passenger side lock & handle. Installed the last wheel well molding. Installed drivers side rear tail light socket & lens & installed passenger side rear socket holder. Primed & painted door strikers. Disassembled passenger side vent window. Removed the weatherstripping, glue & glass. Sanded all parts to be painted. Installed passenger side tail light lens & lens chrome trim. Started installing body chrome trim & noticed that we did not have all the parts. Polished door edge protector chrome molding on both sides. Sanded primer on grill trim. Buffed stainless steel on grill trim. Taped out & sealed grill trim. Disassembled drivers side vent window. Rebuilt/assembled drivers side vent window. Rebuilt/assembled drivers side vent window. Tightened up &	83	45.00	3,735.00
Continue to the next page			
	<u> </u>		

Activity	Qua		Amount
mocked up passenger side vent window. Repainted & reglued of vent window. Installed tailgate inner & outer seals & window g the body side molding, rear molding caps, weatherstripping obth rear chrome molding corners. Painted grill inserts. Installe moldings. Installed both door window channel weatherstripping window whiskers/felt, access plates for body side molding chrodrivers side door panels & hardware, trim on the inside of wind pieces & both front fender emblems. Polished & installed rear bumper filler & passenger side door panels & hardware. Finish windshield trim. Installed cowl screen & cowl. Installed 2 of 4 Repaired door strikes & adjusted doors. Polished & cleaned all grille & headlight surrounds. Assembled & installed front bumper tightened rear bumper. Installed tailgate access panel. Greased contact points. Installed tailgate chrome body molding. Sanded, prepped hood for paint. Cleaned old weatherstripping glue from Glued weatherstripping for cab. Polished both sill plates. Straigdings from tailgate sill plate. Sandblasted & painted wiper arms sealed & painted hood. Assembled wipers & installed. Cleaned rear fender emblems & installed. Cleaned & prepped rear top fo Sanded, buffed & polished hood. Sandblasted & painted hood. Taped out & painted underside of hood. Repaired gouges on reseam sealed hard top. Taped out, prepped, sealed & painted hood. Taped out & painted underside of hood. Repaired gouges on reseam sealed hard top. Installed all weatherstripping on shell top. In all hardware. Cleaned retainers & installed. Installed both real p & tailgate sill plate. Tightened up drivers side mirror. Cleaned/sapray off both door glass. Glued shell top old rubber. Cleaned & Ready for pickup. Kelley Glass Single Source LMC Truck Home Depot	both doors & d side g, drivers side ome corners, shield & trim comper & ed up door bumpers. chrome for eadlight g. Adjusted & & lubed all g, taped out & a top of cab. htened out g. Prepped, backing of or paint. atch & spring. ar of hard top. ed hood. stalled top & canel screws Scraped over & detailed car.	1 258.75 1 299.32 1 173.08 1 10.43	258.75 299.32 173.08 10.43
!		Total Amount Due	ψ-,-70.36
•		TOWN PERFEIT LAND	

BARBER AUTO REPAIR & AIR CONDITIONING

7358 SOUTHLAKE PKWY • MORROW, GA 30260 Phone 770-961-2300

Fax 770-961-8400

INVOICE	040778	
Date	11 Mar 2012	
Page	1	

INVOICE

Bill To

WAYNE BARBER, JR. 150 WILD AZALEA TRL.

HAMPTON, GA 30228

Ship To PH# 770-946-8541

Technician **Order Date Ship Date** Customer No. PO Number Our Order No. 11 Mar 2012 11 Mar 2012 000-**WBARBERJ** 040778-00 County Mileage Vehicle / Information Tag **Payment Terms** 1988 CHEVY K5 BLAZER W/ 5.7L CASH

Order	Ship	B/O	Item Number	Description	Unit Price	Ext Price			
8.00 6.00 1.00 1.00 1.00 5.00 6.00- 1.00- 1.00 1.00 1.00 1.00 1.00	8.00 6.00 1.00 1.00 1.00 5.00 6.00- 1.00 1.00 1.00 1.00 1.00	.00 .00 .00 .00 .00 .00 .00 .00 .00	CR43TS 03107 131-87-ACD 19244932-ACD 10409635 9442012 14029009 12345610 22794700 19210283 9420462 12550760 14081241 10456287 10110898 2691671456 BRAKECLEAN	A/C DELCO SPARK PLUG K5 5.7L EXHAUST MANIF BOLT K5 5.7L DELCO ENG THERMOSTAT K5 5.7L LARGE OIL SENSOR GM RADIATOR CAP GM EXHAUST BOLT GM EXHAUST MANIFOLD STUD GM MOTOR OIL 5W30 GMC YUKON TAG LIGHT LENS CVR GM PF-46 OIL FILTER K5 WATER NECK BOLT K5 BRASS TUBE FOR OIL SENDER K5 EXHAUST "U" SHAPE RETAINR K5 5.7L ENGINE KNOCK SENSOR K5 5.7L OIL DIP STICK TUBE K5 OEM DULI-COLOR RED PAINT BRAKE CLEANER	1.880 EA 5.500 EA 5.890 EA 31.690 EA 8.810 EA 2.150 EA 2.130 EA 2.130 EA 2.550 EA 24.140 EA 5.480 EA 42.710 EA 37.380 EA 6.990 EA 2.500 CAN	15.04 33.00 5.89 31.69 8.81 21.50 10.65 19.56- 2.55 24.14 54.80 42.71 37.38 6.99 2.50			
		TH	HANK YOU FOR YO	OUR BUSINESS!	Subtotal	252.32			
15% charg	e on returns.	Evacuation							
drier voids	compressor v	varranty. Ne	w compressor must be	rder parts. Failure to change receiver e warranted through manufacturer.	Freight Sales Tax	17.66			
A service c	harge of 1 1/2 past due bala	% per month ances. Past d	which equals 18% ar ue accounts will be pl	nnually may be assessed and accumu- aced on a cash or non-ship status.	Total	269.98			
	lated on all past due balances. Past due accounts will be placed on a cash or non-ship status. Customer								

(770)946-8949 atlantaautoresto@bellsouth.net



Invoice

Date	Jinetes#
06/30/2013	1361
Teurs	
Net 15	07/15/2013

Bill To

Wayne Barber 7358 Southlake Pkwy Morrow, GA 30260

Amount Due	Enclosed
\$5,366.12	

Please detach top portion and return with your payment

	Year	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Meke	and the second second
	1988	(Chevrolet	Blazer
Activity	a service de la compa	Quentity	Rate.	See 1
Started disassembling tail-gate/molding. Continued disassembling ca		95.5	45.00	4,297.50
painted. Removed front & rear bumpers. Pressure washed entire truc			!	
front & rear bumper housings & fender wells. Repaired dents & ding				1
damage. Repaired LH door striker mount. Started sanding exterior of	truck to prime.			
Removed molding glue & pin stripping. Sanded door jambs. Remove	ed top. Prepped			
truck for paint. Repaired small rust holes in RH rocker panel. Sanded				
paint. Finished sanding truck. Sandblasted tail gate hinges & spring				
taping out vehicle for primer. Prepped & primed main body & cowl				
primer & urethane surfacer. Polished grille inserts & sanded inner tri			:	
gas lid/door & tailgate center panel. Taped out grille insert. Block sa	nded main body.			
Repaired numerous dents in roof. Finished sanding tailgate & tailgat				•
epoxy primed & urethane primed main body & tailgate. Block sande	d tailgate. Final			
block sanded main body. Final sanded rocker panels & final primed	tailgate. Started			
taping out vehicle for paint. Final block sanded tailgate. Finished tap	ing out main			
body. Final sanded back side of tailgate. Prepped, cleaned & wiped				
tailgate, cowl panel, tailgate hinges, tailgate spring retainers, tailgate			1	
gas door. Epoxy sealed all of the above & painted lower color on bo				
tailgate. Taped out beige basecoat and applied red base coat to main				
hinges, gas door, cowl panel and tailgate access panel. Sanded main	body and			
buffed main body. Buffed and polished tailgate. Sandblasted brush	guard brackets.		: :	
Painted front & rear bumper brackets & openings & all 4 wheel well				
taped out tailgate chrome molding, latches & handle. Started assemb				
Installed weatherstripping on tailgate & chrome molding. Cleaned	buffing		1	
compound off tailgate. Removed tape from molding.				
Single Source		1	1,009.30	1,009.30
• Summit		ì	34.33	34.33
	:			
Continue to the next page				
!			1	

(770)946-8949 atlantaautoresto@bellsouth.net



Invoice

Date	
07/25/2013	1388
Footie:	
Net 15	08/09/2013

Wayne Barber 7358 Southlake Pkwy Morrow, GA 30260

Amount Due	Eivälosed
\$4,476.58	

Please detach top portion and return with your payment.

Year

07/05/2013 Payment received New charges (see details below) Total Amount Due Activity Cusnity Rate Amount		1988	1988 Chevrolet		K5 Blazer	
Installed glass in tailgate. Installed hinges, springs, tracks, tailgate straps & spring hold down brackets. Greased tracks & regulators. Taped out, cleaned & polished. wheel well molding to be painted. Polished wheel well screws. Installed 3 of 4 wheel wells. Installed gas lid door & all components. Polished drivers door handle & lock & installed. Installed drivers side seat belt retainer & panel screws. Cleaned buffing compound from drivers door, front marker lights, antenna & sleeve. Finished cleaning buffing compound from entire truck. Wiped down inside. Polished & installed passenger & drivers side mirrors. Installed & polished passenger side lock & handle. Installed the last wheel well molding. Installed drivers side rear tail light socket & lens & installed passenger side vent window. Removed the weatherstripping, glue & glass. Sanded all parts to be painted. Installed passenger side tail light lens & lens chrome trim. Started installing body chrome trim & noticed that we did not have all the parts. Polished door edge protector chrome molding on both sides. Sanded primer on grill trim. Buffed stainless steel on grill trim. Taped out & sealed grill trim. Disassembled drivers side vent window. Assembled & installed passenger side vent window. Rebuilt/assembled drivers side vent window. Tightened up & mocked up passenger side vent window. Repainted & reglued drivers side vent window.	06/30/2013	Balance Forward Payment received New charges (see details below)			\$5,366.1 -5,366.1 4,476.5 \$4,476.5	
	hold down wheel we lock & in buffing cocleaning linstalled particles. I glue & gliens chroall the partimer or trim. Discovent wind up passer	glass in tailgate. Installed hinges, springs, tracks, tailgate straps & spring in brackets. Greased tracks & regulators. Taped out, cleaned & polished. Ell molding to be painted. Polished wheel well screws. Installed 3 of 4 lls. Installed gas lid door & all components. Polished drivers door handle & stalled. Installed drivers side seat belt retainer & panel screws. Cleaned compound from drivers door, front marker lights, antenna & sleeve. Finished buffing compound from entire truck. Wiped down inside. Polished & passenger & drivers side mirrors. Installed & polished passenger side lock. Installed the last wheel well molding. Installed drivers side rear tail light lens & installed passenger side rear socket holder. Primed & painted door Disassembled passenger side vent window. Removed the weatherstripping, ass. Sanded all parts to be painted. Installed passenger side tail light lens & me trim. Started installing body chrome trim & noticed that we did not have its. Polished door edge protector chrome molding on both sides. Sanded in grill trim. Buffed stainless steel on grill trim. Taped out & sealed grill assembled drivers side vent window. Assembled & installed passenger side low. Rebuilt/assembled drivers side vent window. Tightened up & mocked neger side vent window. Repainted & reglued drivers side vent window.	83		3,735.00	

molding, rear molding caps, weatherstripping on both doors & both rear chrome molding corners. Painted grill inserts. Installed side moldings. Installed both door window channel weatherstripping, drivers side window whiskers/felt, access plates for body side molding chrome corners, drivers side door panels & hardware, trim on the inside of windshield & trim pieces & both front fender emblems. Polished & installed rear bumper & bumper filler & passenger side door panels & hardware. Finished up windshield trim. Installed cowl screen & cowl. Installed 2 of 4 door bumpers. Repaired door strikes & adjusted doors. Polished & cleaned all chrome for grille & headlight surrounds. Assembled & installed grille & headlight bezels. Polished & cleaned front bumper. Installed front bumper. Adjusted & tightened rear bumper. Installed tailgate access panel. Greased & lubed all contact points. Installed tailgate chrome body molding. Sanded, taped out & prepped hood for paint. Cleaned old weatherstripping glue from top of cab. Glued weatherstripping	Cariiv	Rate	Amende
for cab. Polished both sill plates. Straightened out dings from tailgate sill plate. Sandblasted & painted wiper arms. Prepped, sealed & painted hood. Assembled wipers & installed. Cleaned backing of rear fender emblems & installed. Cleaned & prepped rear top for paint. Sanded, buffed & polished hood. Sandblasted & painted hood latch & spring. Taped out & painted underside of hood. Repaired gouges on rear of hard top. Seam sealed hard top. Taped out, prepped, sealed & painted hard top. Installed cowl to hood weatherstripping & door bumpers. Installed hood. Untaped hard top. Installed all weatherstripping on shell top. Installed top & all hardware. Cleaned retainers & installed. Installed both real panel screws & tailgate sill plate. Tightened up drivers side mirror. Cleaned/Scraped over spray off both door glass. Glued shell top old rubber. Cleaned & detailed car. Ready for pickup. • Kelley Glass • Single Source • LMC Truck		258.75 299.32 173.08	258.75 299.32 173.08
• Home Depot		10.43	10.43
	Tabl Of	New Charges	\$4,476.58

ANDY'S MUFFLER

2178 SCENIC HWY
Snellville, GA. 30078
Phone - 770-972-8222 Fax - 770-972-7054

ESTIMATE#	
100434	

	C	T	IRA	πA	T	E	(1)	D	S		D	17	//	\boldsymbol{c}	F	C
┏.	. "		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-			J	Л		E	П	v		•	_	J

Estimate Date: 10/10/2012

BARBER AUTOMOTIVE BARBER, WAYNE

1988 Chevrolet Blazer V10

Lic#:

Odometer In: 0

Unit#: ViN#:

Cellular 770-833-4808 Cust Id: 19,279

Part Description / Number	Qty	Sale	Extended	Labor Description	Hours	Extended
DYNOMAX MUFFLER		-		INSTALL DUAL EXHAUST	2.00	190.00
FL	2.00	79.00	158.00			
ALUM TUBING						
RPM	4.00	39.00	156.00			
31212 ANGLE STAINLESS TIPS						
RPM	2.00	30.00	60.00			

Parts: \$ 374.00 Labor: \$ 190.00 \$ 0.00 Total: \$ 564.00

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. SMOG: I understand that I can have emission service and/or adjustments done elsewhere. I hereby waive this right.

TEAR DOWN ESTIMATE: I understand that my vehicle will be reassembled within a days of the date shown above if I choose not to

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within ____days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts ____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

SIGNATURE...... Date...... Time......

Drive Line Service of Atlanta 4652 B Jonesboro Road Forest Park Ga. 30297 404-361-0475 FAX 404-361-9111

Sold to : BARBER AUTO AIR INC

Account # 12300 Invoice # : 62631

Address : 7358 SOUTHLAKE PKWY MORROW, GA. 30260

Phone: 770-961-2300

Date : 09/26/13

SPECIALIZING IN REPAIR MODIFICATION AND BALANCING OF TRUCK, AUTOMOTIVE, AND INDUSTRIAL DRIVE LINES

PARTS - SHOP SERVICE - DYNAMIC BALANCING

Shipping :

Customers Purchase Order: Job No: Card No. 62623

QTY	PART NUMBER	PART NUMBER DESCRIPTION		NET	TOTAL
4.0	WTS	BALANCE WEIGHTS	1.00	1.00	4.00
1.0	1-0153	1310 U JOINT	21.90	13.52	13.52
2.0	2-3011	#3 Mech U Joint	27.93	17.24	34.48
3.0	IUJ	Install U-JOINT	12.00	12.00	36.00
1.0	N2-40-1701	SPLINE	69.55	47.04	47.04
1.0	N2-3-8021KX	1310 SLIP	98.24	66.42	66.42
1.0	ITB	Install Tube and Balance	80.00	80.00	80.00
26.0	2.75X.083	TUBE	1.49	1.29	33.54
1.0	CEB	Change End and Balance	70.00	70.00	70.00

BLAZER FRONT & REAR SHAFT FRONT REPLACE SLIP & SPL INE, REAR +1/2" 29 1/4" C TO C EXISTING

DIFFERENTIAL REPAIR & PARTS RING & PINION SETS, AXLES, BEARING KITS PARTS \$ 199.00 RESALE SALES TAX \$ 186.00 LABOR \$ 0.00 FREIGHT \$

MISC (HWF) \$ __

Paid by CHECK 4501

MF

TOTAL \$\$ 385.00

0.00

Signature

WARRANTEED FOR 180 DAYS

(WARRANTY and liability or any resulting damage of above repairs are limited to the amount on this Invoice.) Material returns are subject to a 15% Handling Fee. No refunds without this Invoice.



Service is our best part:

Store 9688 1289 SPUR HWY. 138 JONESBORO, GA 30236 Phone: (770) 210-0336 Questions or feedback? Contact the Commercial Customer Support Team

at 1-877-280-5965 or email us at service@advanceautoparts.com

Morrow, GA 30260 Phone: (770) 961-2300 **Account ID:** 968 Barber Auto Air USE 7358 Southlake Pkwy 9688580817

Payment

Permatex **Product Line**

81343

Description

Date: P.O. #: Register: Store/Unit#: Internet Order #: wayne 1/22/12

Salesperson: Delivery: Invoice/Trans: 9688202223255 William 8 1:15:59PM

ANTI SEIZE LUBRICANT 1 O 7160116 REPLACE OR REFUND AT MGR DISCRETIC Warranty Qty 6.63 List 3.79 Extended 3.79

-5.25



D2KBB1C2VF143Q1B6F

TOTAL INVOICE SUBTOTAL PAYMENT T1 Tax @ CHANGE 7.0000% Cash 4.06 0.27 3.79

Customer's signature below certifies that the tax free purchase items qualify for resale or other permitted tax or fee exemption. Customer will pay all taxes and government fees on taxable purchases, including interest and penalties if applicable. All cores need to be in the original box and in rebuildable condition to receive full core credit. Invoice required as proof of purchase for all returns.