

Hamilton Automotive Repair LLC

108 Fabers Way
Hamilton, MT. 59840
Phone: 406-375-7500 Fax: 406-363-4022
Quality from caring

REPAIR ORDER - INV

Scheduled : 07/02/2019 12:00 AM Print Da

1965 Ford - Mustang - 289 Ford V8
Lic # : 132439D - MT

VIN # : 5R07A170978
MFG Date : 7/2/2019
Current Odom : 95880

Last Service : No History

Labor Requested / Part Description	Part #	Qty	Parts	List
<i>Engine Oil Change and Inspection</i>				
Engine Oil Filter - - Engine: 4.7 V8 Engine VIN: A Fuel Delivery Type: CARB Fuel Delivery Subtype: 4BBL Engine Version: All - Engine: 4.7 V8 Engine VIN: C Fuel Delivery Type: CARB Fuel Delivery Subtype: 2BBL Engine Version: All	R85515MP	1.00		3.50
Conventional 10W-30 Motor Oil - CARQUEST All Seaso	CQ630	5.00		4.18
Bulb Replacement	Bulb	1.00		5.00
<i>Fuel Pump Replacement</i>				
Fuel Pump	M20001	1.00		59.92
Fuel Filter	86003	1.00		7.19
<i>Bent New Fuel Hoses from Fuel Pump to Carburetor - Old Lines Bent by hand and kinked</i>				
<i>Replace Front Wheel Bearings, Shoes and Brake Lines, Tum Drums.</i>				
Brake Hydraulic Hose Front - Front Brake Type: Drum Engine: 4.7 V8 - From 8/17/64	BHA49757	2.00		21.37
Conventional Brake Fluid - DOT 3 - CARQUEST Brake	DOT3	1.00		6.14
Drum Brake Shoe Front - 2.31 x 10 in. Brakes; Std	S154	1.00		30.49
Wheel Bearing and Race Set Front Outer - Taper Bearing Set Includes Cup and Cone, Drum Brakes, Heavy Duty Brakes	A2	2.00		20.56
Wheel Bearing and Race Set Front Inner - Taper Bearing Set Includes Cup and Cone, Drum Brakes, Heavy Duty Brakes	A6	2.00		24.47
Wheel Seal Front Inner - Drum Brakes, Heavy Duty Brakes	6815	2.00		11.00
<i>Machine Drums</i>				
<i>Replace Rear Wheel Cylinders, adjust Drums</i>				
Drum Brake Wheel Cylinder Rear Left - Front Brake Type: Drum Engine: 4.7 V8 - Bore: 29/32 In.	WCA28804	1.00		27.97
Drum Brake Wheel Cylinder Rear Right - Front Brake Type: Drum Engine: 4.7 V8 - Bore: 29/32 In.	WCA28805	1.00		27.97
<i>Replace Idler arm and set toe</i>				
Idler Arm	K8106	1.00		158.20
<i>Replace Rear Pinion Seal, Differential fluid and vent tube</i>				
Differential Pinion Seal Rear - Ford, 8" Ring Gear	8181NA	1.00		14.44
Differential Pinion Repair Sleeve Rear - Ford, 8" Ring Gear	99181	1.00		69.46
75W-90 Synthetic Gear Oil - CARQUEST Full Syntheti	685-32	2.00		15.49
<i>Install Mustang Emblem (involves removing grill)</i>				
<i>Install battery hold down conversion</i>				
CJ Pony Parts part BTCB Order 101650332	BTCB	1.00		13.98
CJ Pony Parts part BTC3K Order 101650332	BTC3K	1.00		17.98
<i>Shipping</i>				
<i>Shifter rebuild kit</i>				
Scott Drake Shifter Rebuild Kit With Bolts 4-Speed 1965-1968	C5ZZ-7208-AK	1.00		38.51

Hamilton Automotive Repair LLC

000983

108 Fabers Way
Hamilton, MT. 59840
Phone: 406-375-7500 Fax: 406-363-4022
Quality from caring

REPAIR ORDER - INV

Scheduled : 07/02/2019 12:00 AM

Print Date : 8/5/2019

1965 Ford - Mustang - 289 Ford V8
Lic # : 132439D - MT

VIN # : 5R07A170978
MFG Date : 7/2/2019
Current Odom : 95880

Elapsed : 0

Last Service : No History

Labor Requested / Part Description	Part #	Qty	Parts List	Extended
Shipping				13.95
Replace Power Valve in float bowl and Adjust Carburetor				114.00
Carburetor Power Valve - - Engine: 4.7 V8 - Holley[R]/Demon[R]/Quick Fuel[R] Power Valve; Single Stage, Standard Flow 6.5 in. Hg	12665	1.00	18.18	18.18
Shop Supplies				39.76

Previous Estimate Amount: 57.11, Additional Cost: 146.87, Revised Estimate: 203.98, Parts: \$59.92 Labor: \$79.96 Sublet: \$0.00 Taxes & Fees: