



**Valvoline**  
Instant Oil Change

**Service You Can See.  
Experts You Can Trust.**



Customer Rated  
**4.6** out of 5\*

\*Based on a survey of over 250,000 Valvoline Instant Oil Change customers annually

Invoice: 6506 1/3/25, 12:47 PM R

GUEST INFORMATION	VEHICLE INFORMATION	SERVICE CENTER INFORMATION
	VIN: JM1NA3512M0232563 GA xxx 1991 Mazda Miata SE, 4CYL 1.6L, MFI LAST VISIT MILEAGE: 0 CURRENT MILEAGE: 117,598	VALVOLINE INSTANT OIL CHANGE GO0034-Pooler Parkway MANAGER: Sandybell 2121 Pooler Parkway Pooler, GA 31322 912-200-9436

MAINTENANCE CHECKS	SERVICES PERFORMED																				
Lubrication Points Sealed Oil Drain Plug & Gasket Checked-OK Tire Pressure Checked-OK Front 30 Rear 30 Brake Fluid Level Checked-OK Power Steering Fluid Level Checked-OK 12V Battery Checked-OK Windshield Wash Fluid Level Added Coolant Reservoir Level Checked-OK Transmission Fluid Level Checked-OK Rear Differential Fluid Level Not Checked Front Differential Fluid Level Not Checked Transfer Case Fluid Level Not Checked Oil Service Indicator Light Reset	<table border="1"> <thead> <tr> <th>ITEM DESCRIPTION</th> <th>QTY</th> <th>UNIT</th> <th>AMOUNT(\$)</th> </tr> </thead> <tbody> <tr> <td><b>MaxLife Oil Change</b></td> <td></td> <td></td> <td><b>79.99</b></td> </tr> <tr> <td>    Valvoline 5W30 MaxLife Oil API SP</td> <td>3.60</td> <td>QT</td> <td></td> </tr> <tr> <td>    Valvoline Oil Filter VO106</td> <td>1.00</td> <td>EA</td> <td></td> </tr> <tr> <td><b>Discount (NANAR5F)</b></td> <td></td> <td></td> <td><b>-15.00</b></td> </tr> </tbody> </table>	ITEM DESCRIPTION	QTY	UNIT	AMOUNT(\$)	<b>MaxLife Oil Change</b>			<b>79.99</b>	Valvoline 5W30 MaxLife Oil API SP	3.60	QT		Valvoline Oil Filter VO106	1.00	EA		<b>Discount (NANAR5F)</b>			<b>-15.00</b>
ITEM DESCRIPTION	QTY	UNIT	AMOUNT(\$)																		
<b>MaxLife Oil Change</b>			<b>79.99</b>																		
Valvoline 5W30 MaxLife Oil API SP	3.60	QT																			
Valvoline Oil Filter VO106	1.00	EA																			
<b>Discount (NANAR5F)</b>			<b>-15.00</b>																		

**YOUR SERVICE TEAM:** CSR: Kaydence TOPSIDE: Baylee BOTTOMSIDE: Hope

**COMMENTS**  
Thank you for your business. Cars - we know'em, we love'em.  
THANK YOU FOR CHOOSING US  
HAVE A NICE DAY!  
VISIT OUR WEBSITE AT WWW.VIOC.COM  
ENGINE OIL LEAK NOTED  
TRANSMISSION FLUID LEAK NOTED

US DEBIT *4601, Card Entry: Chip Read, Mode: Issuer, CVM: Verified by PIN (Online), AID: A0000000980840	<b>Subtotal</b>	64.99
	<i>Parts Subtotal</i>	48.74
	<i>Labor Subtotal</i>	16.25
	<b>Tax</b>	3.41
	<b>Total</b>	68.40
<b>DEBIT</b> (*4601 AP=138315)		68.40
	<b>Change Due</b>	0.00

Sign(x) \_\_\_\_\_

Cardholder agrees to pay to issuer total charges per the agreement between the cardholder and issuer.

**SAVE \$\$ ON YOUR NEXT VISIT**

Go to [www.tellvalvoline.com](http://www.tellvalvoline.com)  
and tell us about your experience

Entry Code:0035 3071 5003 4506 5

Thank you for your business  
[www.vioc.com](http://www.vioc.com)



3908 Ogeechee Road  
 Savannah, GA 31405  
 (912) 417-4353

# Invoice

Date	Invoice #
6/17/2024	JF7471

Name / Address

Vehicle Info
1991 Mazda Miata JM1NA3512M0232563 green

P.O. No.	Tech	Tech 2
	David	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in 114545 1. Oil service and inspection use Mobil1 5w30 2. Window malfunction start with switches 3. AC diag 4. Brake fluid exchange 5. Install convertible top client provided 6. Mount and balance Michelins client provided 7. Alignment	1	0.00	0.00
Repair Labor	Spk to Mike at Down South - Quoted \$800 OIL SERVICE AND INSPECTION Drained the oil and replaced the filter. Refilled with Mobil one oil. Checked and adjusted fluids. Inspected the car for any other needs. Radiator is original and discolored, clutch slave cylinder is leaking Checked oil level, level is good.	1	106.00	106.00
Parts	WP Oil Filter 5011-637053 list \$12.50	1	8.58	8.58T
Parts	OR Mobil1 5w30 quart 1-5-30 list \$19.47	4	15.49	61.96T
Shop Supplies	Shop Supplies AIR CONDITIONING EVALUATION	1	35.00	35.00

	<b>Subtotal</b>
	<b>Sales Tax (7.0%)</b>
	<b>Total</b>
	<b>Payments/Credits</b>
	<b>Balance Due</b>



3908 Ogeechee Road  
 Savannah, GA 31405  
 (912) 417-4353

# Invoice

Date	Invoice #
6/17/2024	JF7471

Name / Address

Vehicle Info
1991 Mazda Miata JM1NA3512M0232563 green

P.O. No.	Tech	Tech 2
	David	

Item	Description	Qty	Rate	Total
Repair Labor	Evacuated the ac system and pulled vacuum. System held vacuum. It has been previously converted to R134A. Recharged the system and attempted to run system. System would not run. The compressor requires replacement and the drier.	0.7	106.00	74.20
Repair Labor	FRONT AND REAR BRAKE WORK Removed all of the wheels. Started at the front and unbolted the calipers. Removed the pads and rotors. Installed new pads and rotors. Seated pads to the rotors. Repeated the same procedure in the rear of the car. Performed the brake fluid exchange. Reinstalled wheels with new tires.	4	106.00	424.00
Parts	TPH Front Brake Rotor JBR543 list \$39.96	2	37.36	74.72T
Parts	TPH Powerstop Ceramic Brake Pads with Hardware 17-457 list \$71.99	1	45.99	45.99T
Parts	TPH Rear Brake Rotor JBR544 list \$34.61	2	33.29	66.58T
Parts	TPH Powerstop Ceramic Brake Pads with Hardware 17-458 list \$71.99	1	45.99	45.99T
TEXTAR DOT4	WP BF 4 1 DOT 4 Brake Fluid List 24.29 CAMSHAFT ANGLE SENSOR AND VALVE COVER GASKET REPLACEMENT	1	14.65	14.65T

	<b>Subtotal</b>
	<b>Sales Tax (7.0%)</b>
	<b>Total</b>
	<b>Payments/Credits</b>
	<b>Balance Due</b>



3908 Ogeechee Road  
Savannah, GA 31405  
(912) 417-4353

# Invoice

Date	Invoice #
6/17/2024	JF7471

Name / Address

Vehicle Info
1991 Mazda Miata JM1NA3512M0232563 green

P.O. No.	Tech	Tech 2
	David	

Item	Description	Qty	Rate	Total
Repair Labor	Removed all in the way of the valve cover. Removed the valve cover cleaned all mating surfaces. Removed the Camshaft angle sensor and installed the new sensor. Reinstalled the valve cover with new gasket.	1.5	106.00	159.00
Parts	OR Camshaft Angle Sensor 19-0236 list \$506.76	1	185.53	185.53T
Parts	OR Valve Cover Gasket VS50094R list \$47.44	1	35.95	35.95T
Repair Labor	CLUTCH HOSE, MASTER AND SLAVE CYLINDER REPLACEMENT Removed the clutch master cylinder and slave cylinder. Installed the new slave cylinder with new hose and installed the new clutch master cylinder. Filled and bled the system.	2.8	106.00	296.80
Parts	WP Luk Clutch Slave Cylinder LSC184 list \$154.26	1	64.31	64.31T
Parts	WP Luk Clutch Master Cylinder LMC320 list \$218.59	1	44.86	44.86T
Parts	OR Clutch Hose BH380177 list \$38.97	1	29.44	29.44T
Sublet	TIRE REPLACEMENT Mount and balance of four tires	1	174.99	174.99
Parts	Michelin tires supplied by client	4	0.00	0.00T
Tire Disposal Fee	Tire Disposal Fee	4	5.00	20.00
	BINNACLE REPLACEMENT			

	<b>Subtotal</b>
	<b>Sales Tax (7.0%)</b>
	<b>Total</b>
	<b>Payments/Credits</b>
	<b>Balance Due</b>



3908 Ogeechee Road  
Savannah, GA 31405  
(912) 417-4353

# Invoice

Date	Invoice #
6/17/2024	JF7471

Name / Address

Vehicle Info
1991 Mazda Miata JM1NA3512M0232563 green

P.O. No.	Tech	Tech 2
	David	

Item	Description	Qty	Rate	Total
Repair Labor	Removed steering column clamshell. Removed instrument pod binnacle and installed the new binnacle. Reinstalled the steering column clamshell.	1	106.00	106.00
Parts	Gauge binnacle supplied by client WINDOW REPAIR	1	0.00	0.00T
Repair Labor	Tested the window switches and repaired the switches. Switches function. Got the drivers window to move up and down. Passenger front will not move and required the door panel off and further diagnostic. Need to lubricate all of the window channels and mechanisms. Installed new window rollers on both windows. Finished reassembling the passenger window and door panel. Passenger window is fully functional. Proceeded to doe the same procedure on the drivers window. Drivers window functions as designed. Reinstalled the window switch in the center console.	3.9	106.00	413.40
Parts	JCLM Glass Roller NAXU-58-515 list \$6.89 RADIATOR AND AIR CONDITIONING COMPRESSOR REPLACEMENT	2	6.89	13.78T

	<b>Subtotal</b>
	<b>Sales Tax (7.0%)</b>
	<b>Total</b>
	<b>Payments/Credits</b>
	<b>Balance Due</b>

Some products above selected for the following vehicle(s)

---

Vehicle: **91 Mazda Miata**

**Note:**

As a complimentary service to you, the Tire Identification Codes for the tires you purchased have been automatically registered in accordance with Department of Transportation (DOT) requirements. [Read More](#)

**Payment Summary**

Item(s) Total: **\$844.12**

Sales Tax: **\$67.53**

State Fee (Required): **\$4.00**

**Order Total: \$915.65**

**Get on the Inside Track**

Sign up to receive our emails complete with promotions, product updates/recommendations, performance advice, tech tips and more.

*Your personal information is protected. View our [Privacy Pledge](#).*

[Get Our Emails](#)

**QUESTIONS?**

**Product & Shipping**

If you have questions about the products you have ordered, please call Guy (ext.4855) at 888-727-8092 or email [guy@tirerack.com](mailto:guy@tirerack.com).

If you have questions about order status or other customer service matters, please contact customer service at 888-981-3953 or email [custsvc@tirerack.com](mailto:custsvc@tirerack.com).

**Return/Refund Policy**

Please read our full return policy and follow the [return check list](#) to ensure your return is properly received if a return is necessary.

**Installation**

Want to see all installation options? See our complete list of independent [Recommended Installers in your area](#).