

Maintenance Record

| Vehicle | 1989 Alfa Romeo Spider Graduate | | VIN:ZARBA5640K1063115 |
|--|---------------------------------|----------|---|
| Description of Work Performed | | | Parts used |
| Date: | 8/6/2008 | Mileage: | 79478 |
| Head Rebuild | | | Group 2 Motorsports Seattle WA |
| Clutch master and Slave | | | |
| Seat Belt Replacement | | | |
| Rear Trailing arm bushings | | | |
| engine mounts | | | |
| brake caliper rebuild F&R | | | |
| Door handle and locks Left | | | |
| Date: | 3/9/2012 | Mileage: | 84439 |
| Reupholster L Seat and | | | Classic Interior Restorations Seattle WA |
| Black Vinyl | | | |
| Date: | 3/21/2013 | Mileage: | |
| Repair and refinish entire car | | | Bumper Medic LLC San Diego CA |
| Replace F bumper valance | | | |
| Replace R marker | | | |
| Replace emblems throughout | | | |
| Date: | 6/26/2013 | Mileage: | 84627 |
| Install new Catalytic Converter | | | Dualtone 4745 Mission Bay Dr San Diego CA |
| Date: | 2/6/2016 | Mileage: | |
| replace high pressure injector hose | | | 8mm hose |
| Replace Large FI seal | | | |
| Replace small FI seal | | | |
| Date: | 4/28/2016 | Mileage: | 85798 |
| Install combo switch assy | | | 60-555799 |
| Investigate oil leak- suspect front crank seal | | | |
| replace trunk spring bracket with used part and adjusted | | | |
| Date: | 11/24/2019 | Mileage: | |
| Install new battery | | | Oreilly SSB 24RPRML |
| Date: | 9/12/2020 | Mileage: | 86194 |
| Install new Valve cover gasket | | | 71-21366-30 |
| Date: | 7/2/2021 | Mileage: | 86214 |
| Oil Change | | | 20-50 GTX |
| safety inspection | | | |
| Date: | 9/27/2021 | Mileage: | 86266 |
| Replace upper and lower oil pan gaskets | | | gaskets |
| Replace Fan Blade | | | Fan Blade |
| Replace Rear Crankshaft Seal | | | Crankshaft seal |
| Replace Clutch and Pilot bushing | | | Clutch kit and pilot bushing |
| Date: | 11/22/2021 | Mileage: | 86399 |
| Replace Trans Gear Oil | | | 75-90 GL-5 1 QT |
| Gear Oil Additive | | | BG-325 |

Maintenance Record

| Ownership Change July 7, 2022 | | |
|--|----------------------------------|--|
| Date: 8/1/2023 | Mileage: 86400 TMU no odo | |
| replaced Fuel Pump and mounts | | Bosch pump; HPSI hose |
| replaced fuel lines with new hose and clamps | | HPSI hose;clamps |
| Replaced vapor recovery lines in trunk with HPSI silicone hose | | HPSI hose;clamps |
| Replaced vacuum hoses under hood with HPSI silicone hose | | HPSI hose;clamps |
| Performed rust repair in spare tire well | | |
| Replaced Brake hoses with new hoses; Flushed/bled brake hydraulics | | rockauto hoses |
| Installed new wheels and tires | | Tire Rack |
| Date: 12/9/2023 | Mileage: 86400 (TMU) | |
| Repaired License Plate and CHMSL lights in trunk lid | | none |
| Installed Cat Back Exhaust | | Ansa center; Centerline stinger; Ansa hangers |
| Date: 2/23/2024 | Mileage: 86400 (TMU) | |
| Replaced Alternator Fan Belt; AC fan belt missing | | rockauto belt |
| Repaired Front parking lights, turn signals and side markers | | none |
| Reattached Exhaust Pipe Flange | | none |
| Troubleshoot Cigarette Lighter not working; ran another circuit | | none |
| Temp repair to the Driver's Door map pocket | | none |
| Date: 2/24/2024 | Mileage: 86400 (TMU) | |
| Installed new radio; cleaned up faulty wiring | | Amzn radio; chassis wiring plugs |
| adjusted bypass idle speed screw | | none |
| Installed LED Headlights | | AMZN |
| Installed Coolant overflow bottle with new bracket | | Centerline |
| Installed Cocomats | | Cocomat |
| finished door trim - armrests and door map pocket | | none |
| Ran on Orange Blossom Tour - 25Feb-1Mar 2024 | | |
| Date: 1/9/2025 | Mileage: 86500 (TMU) | |
| Diagnosed no-start to Fuel Pump. Cleaned up ground connection and test drove car | | |
| Replaced foam under Rear Shelf with Sound Deadening and Foam | | |
| Diagnosed Alternator Light/Gauge Outage to fuse. Replaced fuse. | | |
| Date: 4/1/2025 | Mileage: 86500 (TMU) | |
| Replaced Speedo Cable | | Cable fm AW Imports |
| Repositioned Rear Exhaust | | NA |
| Date: 10/6/2025 | Mileage: 86581 (TMU) | |
| Replaced 3 rad hoses and front heater return hose | | Vick Autosport |
| replaced intake runner hoses | | Centerline |
| Replaced AC Compressor, belt and Recvr/Drier; Flushed, N2 test, Evac, recharge | | Comp and Drier - Amazon AC Belt is 17305 or 13AV0775 |
| back flushed Radiator and added new coolant | | |
| replaced distributor cap and rotor | | AW Italian |
| Recovered Right seat | | Vick Autosport/Tim Suddard |
| Replaced all 6 tie rod ends in steering | | USP Motorsports |
| replaced rear axle straps | | AW Italian |
| Wheel Alignment | | Mavis Tire Ponte Vedra |

Maintenance Record

| | | |
|--|-----------------------------|-------------------------------|
| Investigated Main Seal Leak. Determined cause as F Trans Seal. Drained and refilled trans with Lucas Trans Seal Repair | | |
| Date: 10/11/2025 | Mileage: 86598 (TMU) | |
| Installed new Optima AGM Battery - | | Amazon |
| Date: 1/18/2026 | Mileage: 86634 | |
| conducted smoke test of intake system; found and fixed slight leak at bypass hose | | hose clamp |
| cleaned primary coil wire | | |
| Date: 4/16/2026 | Mileage: 86814 | |
| Oil and Filter change | | Beck Arnley; Castrol GTX10-40 |
| Adjust Exhaust Mount at Rear | | |
| Inspect Fuel pump mounting - re-mounted to make quieter | | |