




## Power Evaluation Sheet

Jeff's Tuning and Performance, LLC | 3288 SW 74TH AVE Ste 104 OCALA, Florida 34474  
Generated: 7/28/2026 | Tested: 7/28/2026 12:33:21 Eastern Daylight Time

Make: FORD  
Model: MUSTANG  
Year: 2007  
Correction Factor: J1349 (1.04)

**MD**  
**MUSTANG**  
DYNAMOMETER



| Channel          | Average       | Peak          |
|------------------|---------------|---------------|
| Torque SAE       | 444.21 FT-LBS | 469.05 FT-LBS |
| HP SAE           | 376.69 HP     | 474.59 HP     |
| Crank Torque SAE | 544.01 FT-LBS | 575.21 FT-LBS |
| Crank HP SAE     | 461.13 HP     | 579.15 HP     |



VMP Performance  
170 South SR 415  
New Smyrna Beach FL 32168  
United States

## Packing Slip

Order Date 5/18/2021  
Order # SO029180  
Ship Date 5/18/2021  
Tracking # 787289245013  
787289246178  
Ship Via FedEx Home Delivery®  
PO #  
Terms

### Ship To

| Item Number   | Description                                                               | Options | Or... | Qty  | BO | Shi... |
|---------------|---------------------------------------------------------------------------|---------|-------|------|----|--------|
| VMP-SUC019    | VMP Dual Fan Triple Pass Heat Exchanger for 2007-2012 GT500               |         |       | 1    |    | 1      |
| AFC-100208    | VMP Dual Fan Triple Pass Heat Exchanger - boxed with hdw                  |         |       | 1    |    | 1      |
| VMP-ENC004    | VMP Dual-Fan Plug and Play Heat Exchanger Replacement Harness 07-12 GT500 |         |       | 1    |    | 1      |
| 1310-8D080-BA | GT500 Intercooler Reservoir 3x Capacity Tank                              |         |       | 1 Ea |    | 1      |
| VMP-SUA031    | VMP Ultimate Pulley Removal & Installation Tool                           |         |       | 1    |    | 1      |
| VMP-SUT004    | VMP Performance Mustang Belt Tensioner (07-14 GT500)                      |         |       | 1 Ea |    | 1      |
| VMP-25-10-P   | VMP 2.5" 3-4psi 'stock look' pulley fits stock GT500 blower               |         |       | 1 Ea |    | 1      |
| VMP-TJ67-G    | VMP Twin Jet 67mm throttle body for 07-14 GT500 & Supercharged 5.0L       |         |       | 1 Ea |    | 1      |

DICK'S MACKENZIE FORD  
4151 SE Tualatin Valley Hwy  
Hillsboro, OR 97123  
Phone# (503) 693-1133  
August 31, 2021 09:43:18

A0000000042203

CH LOC CODE: D61

RK: 002

# D616195452423

TR: XXXXXXXXXXXX9975

D: DEBIT

RY: Contactlcc

IT PURCHASE: 4866.76

ROVAL CODE: 927986

T: 0/00

N ID: 258876179

TC 9051919996BC86DC

I AGREE TO PAY THE ABOVE  
TOTAL AMOUNT ACCORDING  
TO CARD ISSUER AGREEMENT

SIGNATURE

THANK YOU  
CARDHOLDER COPY

**Dicks Ford**  
 BOX 340 - HILLSBORO, OR 97123  
 693-1133 - www.dicksautogroup.com



SERVICE DEPARTMENT HOURS  
 7:30 a.m. to 6:00 p.m.  
 Monday - Friday  
 8:00 a.m. - 4:00 p.m. - Saturday

|                               |                 |
|-------------------------------|-----------------|
| R/O Open Date                 | R/O Number      |
| 05/27/21                      | 6195452/2       |
| R/O Close Date                | Status          |
| 08/25/21                      | Pre-Invoice     |
| Mileage In                    | Mileage Out     |
| 11446                         | 11446           |
| Service Advisor / Tag #       |                 |
| BENITO MARTINEZ/1924          |                 |
| Vehicle Identification Number |                 |
| 1ZVHT88S975256274             |                 |
| Delivery Date                 | In-Service Date |
|                               |                 |
| Color                         | License Number  |


|      |      |         |                   |  |                               |                 |
|------|------|---------|-------------------|--|-------------------------------|-----------------|
|      |      |         | Work Phone        |  | BENITO MARTINEZ/1924          |                 |
|      |      |         |                   |  | Vehicle Identification Number |                 |
|      |      |         | Home Phone        |  | 1ZVHT88S975256274             |                 |
|      |      |         | 503-840-9842      |  | Delivery Date                 | In-Service Date |
| Year | Make | Model   | Body              |  | Color                         | License Number  |
| 2007 | FORD | MUSTANG | 2DR CPE SHELBY GT |  | RED                           |                 |

| DESCRIPTION OF SERVICE AND PARTS                                                                                                                                                                                                                                                                      |                      | AMOUNT           |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|------------------|
| Installed 3C3Z 4663 AA :SHIM - DRIVING PINION<br>installed all customer supplied parts. heat<br>exchanger, S/C pulley, ring and pinion, cold air<br>intake, throttle body and tune, replaced all<br>belts and test drove, all new components<br>operating properly at this time<br>Sub Total: 3731.18 | 1@61.05              | 61.05            |
| -----                                                                                                                                                                                                                                                                                                 |                      |                  |
| #3 * 49FOZ: CAMPAIGN<br>ADDED OPERATION<br>recall 19s01 air bag<br>Installed 5R3Z 63044A74 B :MODULE - AIR BAG<br>performed recall 19s01 per wsm, installed new<br>airbag inflator, new SN: 2L182M3UEKK. vehicle now<br>okay, release to customer                                                     | Qty: 1               | Warranty         |
| -----                                                                                                                                                                                                                                                                                                 |                      |                  |
| #4 * 23FOZMTTIR: MOUNT AND BALANCE TIRES<br>ADDED OPERATION<br>tires<br>Tech: Trevor Enquist (10L)<br>Installed 9004 68255 :285/40ZR18<br>Installed 9004 07793 :255/45ZR18<br>mounted and balanced new tires<br>Sub Total: 1108.00                                                                    | 2@261.00<br>2@233.00 | 522.00<br>466.00 |
|                                                                                                                                                                                                                                                                                                       |                      | 2920.00          |

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

|                       |         |
|-----------------------|---------|
| LABOR                 | 1919.18 |
| PARTS                 | .00     |
| DEDUCTIBLE            | .00     |
| SUBLET                | .00     |
| SHOP SUPPLIES         | .00     |
| HAZARDOUS MATERIALS   | 27.58   |
| SALES TAX OR TAX I.D. | .00     |
| SPECIAL ORDER DEPOSIT | .00     |
| DISCOUNTS             | 4866.76 |
| TOTAL DUE             |         |



NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

OR 97123  
cksautogroup.com

SERVICE DEPARTMENT HOURS  
7:30 a.m. to 6:00 p.m.  
Monday - Friday  
8:00 a.m. - 4:00 p.m. - Saturday

|                               |                 |
|-------------------------------|-----------------|
| R/O Open Date                 | R/O Number      |
| 05/27/21                      | 6195452/1       |
| R/O Close Date                | Status          |
| 08/25/21                      | Pre-Invoice     |
| Mileage In                    | Mileage Out     |
| 11446                         | 11446           |
| Service Advisor / Tag #       |                 |
| BENITO MARTINEZ/1924          |                 |
| Vehicle Identification Number |                 |
| 1ZVHT88S975256274             |                 |
| Delivery Date                 | In-Service Date |
|                               |                 |
| Color                         | License Number  |
| T RED                         |                 |

| DESCRIPTION OF SERVICE AND PARTS                        |  |  |  | AMOUNT  |
|---------------------------------------------------------|--|--|--|---------|
| #1 - Q99PX: QUICK LANE MULTIPOINT INSPECTION            |  |  |  |         |
| Performed inspection, see inspection sheet for results. |  |  |  |         |
| Sub Total: .00                                          |  |  |  |         |
| #2 - 09FOMAIN: MAINTENANCE                              |  |  |  |         |
| customer requested rear diff gear swap .                |  |  |  |         |
| check over suspension / feels to stiff ? adjust ?       |  |  |  |         |
| cold air intake to be installed . update pully          |  |  |  |         |
| for supercharger add a cooling fan for rad. tuner       |  |  |  |         |
| install also a mass air intake to be installed .        |  |  |  |         |
| Tech: Trevor Engist (10L)                               |  |  |  | 2800.00 |
| Installed 4060868 :BELT                                 |  |  |  | 66.52   |
| Installed XL 3 :ADDITIVE - OIL - FRICTION MODI          |  |  |  | 7.69    |
| Installed XY 75W140 QL :OIL - REAR AXLE                 |  |  |  | 123.24  |
| Installed B7A 8287 BA :CLAMP - HOSE                     |  |  |  | 19.25   |
| Installed 7R3Z 8620 A :V-BELT                           |  |  |  | 112.17  |
| Installed D9AZ 4067 AH :SHIM - DIFFERENTIAL DRIVIN      |  |  |  | 174.74  |
| Installed D9AZ 4067 AK :SHIM - DIFFERENTIAL DRIVIN      |  |  |  | 124.30  |
| Installed D9AZ 4067 AL :SHIM - DIFFERENTIAL DRIVIN      |  |  |  | 96.78   |
| Installed N806282 S437 :SCREW AND WASHER ASY            |  |  |  | 10.00   |
| Installed VC 7 B :ANTI-FREEZE                           |  |  |  | 19.76   |
| Installed 9L3Z 4630 A :BEARING ASY - DRIVING PINIO      |  |  |  | 39.15   |
| Installed BR3Z 4676 A :SEAL ASY - OIL                   |  |  |  | 18.67   |
| Installed B7A 4621 A :BEARING ASY - DRIVING PINION      |  |  |  | 29.47   |
| Installed B7A 4616 A :CUP                               |  |  |  | 19.63   |
| Installed D5AZ 4670 A :WASHER                           |  |  |  | 8.76    |

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs hereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

|                       |  |
|-----------------------|--|
| LABOR                 |  |
| PARTS                 |  |
| DEDUCTIBLE            |  |
| SUBLET                |  |
| SHOP SUPPLIES         |  |
| HAZARDOUS MATERIALS   |  |
| SALES TAX OR TAX I.D. |  |
| SPECIAL ORDER DEPOSIT |  |
| DISCOUNTS             |  |
| TOTAL DUE             |  |

DO NOT RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.