

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 3242		License	VIN	301979	Year	1965
		Make	Porsche	Model	911			
		Engine	#902119	Transmission				
In Mileage	1	Out		Fleet #			P.O. Number	
Prod Date	Turbo/Non	Color	Yellow	Body Style	Coupe	Ext. War.	Written By: KB	

Recommended Services

Date	Mileage	Description
6/7/2017		Oil change for break-in oil due within 1,000 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's European or approved shop. X: _____
6/7/2017		Second oil change for break-in oil due within 3,000 miles of engine rebuild to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's European or approved shop. X: _____
6/7/2017		Regular oil change intervals of 3,000 mi/12 mo, whichever comes first, must be maintained after first two break-in oil changes to keep warranty of 12 mo./12,000 mi. in effect. Oil changes must be performed by Beck's European or approved shop X _____

Labor Operations

Tech	Type	Description	Price
FB	Lab	R&R engine and transmission. Disassemble, inspect, replace worn parts as nec. Reassemble.	\$8,103.55
FB	Lab	Rebuild transmission. (Appears to have been rebuilt then run without oil.)	\$1,605.38
GJ	Lab	Install customer supplied gauges (odometer reads 1). Install missing ignition switch wiring. Replace wiring as nec.	\$872.69
zFL	Sub	Rebuild and restore Solex 40P1 carbs	\$7,500.00
zFL	Lab	Rebuild connecting rods	\$360.00
zFL	Lab	Balance crankshaft, conn rods, pistons, flywheel, and clutch.	\$220.00
zFL	Lab	Surface coatings, plating	\$900.00
zFL	Sub	Restore camshafts	\$950.00
zFL	Sub	Inspect, machine, and tumble case. Clean oil galleys. Restore case to std align bore specs. Oil bypass mod.	\$2,850.00
zFL	Sub	Rebuild cyl heads	\$1,650.00
FB	Lab	Clean, glassbead, and tumble alum housings	\$374.01
zFL	Lab	Restore ignition distributor	\$450.00
zFL	Lab	Rebuild/restore Pierburg fuel pump.	\$450.00
zFL	Sub	Restore and clean oil cooler.	\$450.00
FB	Lab	Restore alternator fan and housing.	\$400.00
FB	Lab	Cyl heads have been cut for late heads. Machine and install adapter spacers.	\$600.00
zFL	Sub	Dismount, mount and balance tires.	\$100.00
JL	Lab	R&R front brake and hub assm. R&R backing plates, replace front brake rotors, replace all front wheel bearings.	\$623.35
zFL	Sub	Powdercoat dust shields, caliper brackets	\$150.00
FB	Lab	Rebuild 4 brake calipers.	\$1,496.04
FB	Lab	Replace brake master cylinder.	\$187.01
FB	Lab	Replace all steel brake lines.	\$374.01
FB	Lab	Bleed brake system. "Exercise" pistons.	\$311.68
FB	Lab	R&R rear brake assm and hubs. R&R backing plates for powder coat. Replace rear wheel bearings as nec.	\$748.02
FB	Lab	Restore Nadella axles.	\$997.36
FB	Lab	Refinish heater valves. Replace hoses and control cables.	\$498.68
FB	Lab	Replace clutch cable.	\$62.34
FB	Lab	Replace front ball joints.	\$249.34
zFL	Lab	R&R, strip, clean, and refinish oil tank.	\$872.69
FB	Lab	Replace fuel tank and hoses. Replace fuel level sender.	\$498.68
FB	Lab	Replace battery.	\$62.34
FB	Lab	R&R parking brake handle assm. Replace handle.	\$249.34
FB	Lab	Remove stock front seats. Install customer supplied Recaro Rallye sport seats.	\$249.34
FB	Lab	Install customer supplied, restored rear relay board. Wire as nec.	\$498.68
zFL	Sub	Four Wheel Alignment. (Alignments have free recheck within 1 year; if adjustment is necessary will be done at a reduced rate. Does not carry traditional 12/12 warranty as alignments can be knocked out by hitting things such as potholes or curbs.)	\$195.00

Labor Total \$36,159.53

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive

Scottsdale, AZ 85260

480-556-6572

602-997-6572

www.beckseuropean.com

Customer		Acct: 3242		License	VIN	301979	Year	1965
				Make	Porsche	Model	911	
				Engine	#902119	Transmission		
In	Mileage	Out	Fleet #	P.O. Number				
	1							
Prod Date	Turbo/Non	Color	Yellow	Body Style	Coupe	Ext. War.	Written By: KB	

Parts		Status	Qty	Price Ea.	Total
90110590151	Valve Spring Set	N	12.00	\$22.00	\$264.00
90110390900	Pistons/cylinders (Mahle)	N	1.00	\$4,500.00	\$4,500.00
	Sparkplug wires	N	1.00	\$200.00	\$200.00
Cam oil lines	One pair braided steel cam oil lines	N	1.00	\$500.00	\$500.00
Eng oil lines	One set suction and return braided steel oil lines	N	1.00	\$1,100.00	\$1,100.00
90130090100	Early 901 Transmission Gasket Kit ('66 to '68)	N	1.00	\$85.00	\$85.00
	40 wt non detergent oil	N	11.00	\$5.00	\$55.00
90110720310	Oil Filter (Red Porsche Classic)	N	1.00	\$22.11	\$22.11
Gear Oil	Gear Oil (pints)	N	6.00	\$4.95	\$29.70
	Fasteners	N	1.00	\$60.00	\$60.00
	Norma Scavenge Line Clamp Kit/Hardware.	N	1.00	\$57.50	\$57.50
90110313101	Wrist Pin Bushing/Rod Bushing	N	6.00	\$6.50	\$39.00
90110090201	2.0 Engine gasket set (Viton)	N	1.00	\$390.00	\$390.00
90110317200	Connecting Rod Bolt	N	12.00	\$15.99	\$191.88
90110317300	Connecting Rod Nut	N	12.00	\$2.90	\$34.80
90110113803	Main Bearing (#8)	N	1.00	\$172.93	\$172.93
91110190100	Main bearing set, Std	N	1.00	\$195.92	\$195.92
90110512504	Timing Chain Sprocket	N	2.00	\$64.68	\$129.36
99310552900	Timing Chain	N	2.00	\$47.93	\$95.86
3000509001	Clutch Kit	N	1.00	\$595.00	\$595.00
91110590101	Mechanical Chain Tensioner Set	N	1.00	\$120.00	\$120.00
91110522205	Timing Guide Rail	N	1.00	\$57.57	\$57.57
91110522206	Timing Guide Rail	N	5.00	\$33.47	\$167.35
Solex intake manifold	Right side	N	1.00	\$1,000.00	\$1,000.00
990579052	Rocker shaft seal	N	24.00	\$3.50	\$84.00
Rocker arm	Set of forged early rocker arms	U	1.00	\$1,000.00	\$1,000.00
2nd gear assembly (Mainshaft)	GA (18:32)	U	1.00	\$790.00	\$790.00
3rd gear assembly	O (23:28)	U	1.00	\$400.00	\$400.00
4th gear assembly	U (26:25)	U	1.00	\$400.00	\$400.00
5th gear assembly	Y (28:23)	U	1.00	\$400.00	\$400.00
9990520160A	Pinion Shaft Bearing	N	1.00	\$318.52	\$318.52
99920147000	Needle Cage Bearing	N	5.00	\$64.17	\$320.85
99911001201	Pinion Shaft Bearing	N	1.00	\$416.67	\$416.67
99905900800	Carrier Bearing	N	2.00	\$29.70	\$59.40
99911000800	Main Shaft Bearing	N	1.00	\$201.17	\$201.17
99905302500	Main Shaft Bearing	N	1.00	\$294.21	\$294.21
91461349100	Rubber Boot	N	1.00	\$13.21	\$13.21
90174129100	Speedometer cable boot.	N	2.00	\$17.73	\$35.46
91142359301	Accelerator Rod Boot	N	2.00	\$17.58	\$35.16
90142429302	Shift Rod Boot	N	1.00	\$42.80	\$42.80
91137504300	Engine Mount	N	2.00	\$37.90	\$75.80
90415	Tire Valve Stem	N	4.00	\$3.18	\$12.72
91420189100	Gasket, oil sender	N	1.00	\$7.51	\$7.51
93010727201	Cap Seal	N	1.00	\$8.83	\$8.83
90110769301	Oil Tank Mount Washer	N	2.00	\$8.29	\$16.58
90110769200	Oil Tank Mount Washer	N	2.00	\$8.29	\$16.58
91142320503	Clutch Cable Clevis	N	1.00	\$21.80	\$21.80
90142340104	Clutch Cable	N	1.00	\$28.40	\$28.40
90142342102	Bowden Tube for clutch cable	N	1.00	\$16.53	\$16.53

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 3242		License	VIN	301979	Year	1965
				Make	Porsche	Model	911	
				Engine	#902119	Transmission		
In Mileage	1	Out	Fleet #	P.O. Number				
Prod Date	Turbo/Non	Color	Yellow	Body Style	Coupe	Ext. War.	Written By: KB	

Parts		Status	Qty	Price Ea.	Total
91442321100	Bushing	N	2.00	\$6.47	\$12.94
90142429202	Shift Boot	N	1.00	\$49.42	\$49.42
99961192020	Chassis Ground Strap	N	1.00	\$13.56	\$13.56
91121129700	Gasket, heat control box	N	2.00	\$4.94	\$9.88
90005203000	Wheel Bearing, Rear	N	2.00	\$17.96	\$35.92
99911308540	Wheel Bearing Seal, Rear Outer	N	2.00	\$8.31	\$16.62
99911304650	Wheel Bearing Seal, Rear Inner	N	2.00	\$9.00	\$18.00
90135296411	Caliper Repair Kit, Rear	N	2.00	\$14.98	\$29.96
90135196411	Caliper Repair Kit, Front	N	2.00	\$28.38	\$56.76
91121102210	Heat Exchanger	N	1.00	\$678.57	\$678.57
91121102160	Heat Exchanger	N	1.00	\$678.57	\$678.57
901355600/67	Brake Line Kit	N	1.00	\$190.91	\$190.91
91450431900	Grommet	N	2.00	\$4.06	\$8.12
90142470106	Heater Cable Wire	N	1.00	\$28.80	\$28.80
90142470401	Heater cable guide	N	2.00	\$22.07	\$44.14
99908500102	Barrel Nut	N	6.00	\$4.40	\$26.40
69535263101	Brake Hose	N	2.00	\$23.40	\$46.80
90135563202	Brake Hose	N	2.00	\$29.29	\$58.58
991758424	Shift Coupler Bushing Kit	N	1.00	\$10.00	\$10.00
91142455103	Parking Brake Cable	N	2.00	\$51.14	\$102.28
90135501101	Brake Master Cylinder	N	1.00	\$114.69	\$114.69
90135140111	Brake Disc	N	2.00	\$64.06	\$128.12
90134104700	Ball Joint	N	2.00	\$245.28	\$490.56
90161352120	Brake Light Switch	N	1.00	\$27.97	\$27.97
90135240110	Brake Disc	N	2.00	\$111.80	\$223.60
477405641	Wheel Bearing Seal	N	2.00	\$4.58	\$9.16
Wire harness	Ign switch/headlight switch wire harness	U	1.00	\$120.00	\$120.00
	Emergency Brake Handle	U	1.00	\$214.29	\$214.29
90133102600	Wheel Bearing	N	1.00	\$203.97	\$203.97
91434705700	Tie Rod Bushing	N	2.00	\$65.90	\$131.80
91134703101	Tie Rod	N	2.00	\$121.66	\$243.32
FH 5x2.5	Fuel Hose	N	2.00	\$13.00	\$26.00
90121119401	Hot air hose	N	2.00	\$25.46	\$50.92
99918200336	Lug Nut	N	20.00	\$11.70	\$234.00
91111102505	Muffler	N	1.00	\$586.67	\$586.67
90134116601	Rubber	N	2.00	\$26.51	\$53.02
90134116501	Rubber	N	2.00	\$28.43	\$56.86
99970412550	Seal Ring	N	2.00	\$8.10	\$16.20
99970412650	Seal Ring	N	2.00	\$4.14	\$8.28
90111115104	Muffler Support Bracket	N	1.00	\$45.00	\$45.00
95 Fuel Additive	Fuel Additive 95 (Unleaded)	N	8.00	\$7.49	\$59.92
Fuel tank	Flushed, cleaned, and refinished	R	1.00	\$950.00	\$950.00
90161204303	Instrument light wire harness	N	1.00	\$200.00	\$200.00
Dot 4	Castrol Dot 4 Brake Fluid	N	2.00	\$18.00	\$36.00
Solex fuel line	Duel fuel line over shroud	U	1.00	\$500.00	\$500.00
Brake caliper clips and pins	Brake pad spreader clips and pin set (4 calipers)	U	1.00	\$140.00	\$140.00
Silicone heater duct	Heater control valve hose	N	2.00	\$30.00	\$60.00
	Sealed Beam (Headlight)	N	2.00	\$16.58	\$33.16
64461334211	Hazard/Turn Signal Flasher Relay	N	1.00	\$63.31	\$63.31

BECK'S EUROPEAN

Beck's-An Independent Porsche

8225 East Butherus Drive
 Scottsdale, AZ 85260
 480-556-6572 602-997-6572
 www.beckseuropean.com

Customer		Acct: 3242		License	VIN	301979	Year	1965
				Make	Porsche	Model	911	
				Engine	#902119	Transmission		
In	Mileage	Out	Fleet #	P.O. Number				
1								
Prod Date	Turbo/Non	Color	Yellow	Body Style	Coupe	Ext. War.	Written By: KB	

Part Number		Part Description	Status	Qty	Price Ea.	Total
H6024		Sealed Beam	N	2.00	\$18.63	\$37.26
64461334211		Hazard/Turn Signal Flasher Relay	N	1.00	\$63.31	\$63.31
8040-1083		Porsche Twin LPG Shock Koni R 8040-1083 STD Adjust	N	2.00	\$160.00	\$320.00
		Rear App Rear fitment.				
91120151500		Fuel Filler Nick Sleeve	N	1.00	\$112.51	\$112.51
90142336900		Retaining Bracket	N	2.00	\$11.71	\$23.42
		911 Ignition Switch Bezel	N	1.00	\$83.43	\$83.43
361004		Strut Insert	N	2.00	\$87.42	\$174.84
6101074		Electric Fuel Pump	N	1.00	\$264.00	\$264.00
7992		Spark Plug	N	7.00	\$4.95	\$34.65
91160312000		Alternator (Valeo)	N	1.00	\$590.00	\$590.00
101792423		Pedal Bushing Set	N	1.00	\$20.94	\$20.94
90142336900		Retaining Bracket	N	1.00	\$11.71	\$11.71
90110895511		Air Filter	N	1.00	\$34.86	\$34.86
Parts Total						\$23,993.16

Pre-Pay		Payment	Total Tax	Taxable Parts \$23,993.16	From date of service - 12 mo./12,000 mi. warranty, whichever comes first, we will cover defects in workmanship to the vehicle in this facility only. Does not include racing products/services. Towing not included.	Date	1/23/2019
\$0.00	Cash	\$1,000.00	\$1,907.46	NonTax Parts \$0.00		RO #	10140
\$0.00	Check	\$9,000.00		Total Parts \$23,993.16		RO Total	\$62,060.15
	Chk #	190201935	Supplies	Labor \$22,314.53		Balance Due	\$37,060.15
\$0.00	Credit	\$15,000.00	Disposal	Sublet \$13,845.00			
	Type	Other	Environ.	NonTax Labor \$0.00			
	Expires			NonTax Sublet \$0.00			
\$0.00	Paid	\$25,000.00		Total Labor \$36,159.53		Signature or Initial	Date