

320 Commerce Ct.
Rocky Mt. N.C. 27803





dC Automotive
"Paradise for Porsche"


1-800-579-2410
(252)-977-1430

INVOICE # 28658	INVOICE DATE 06/20/2025	SALESMAN REX JOHNSTON	PRIORITY NORMAL	PAGE 1 OF 1
--------------------	----------------------------	--------------------------	--------------------	----------------

BILL TO:	SHIP TO:

SHIPPING DATE 06/27/2025	SHIP VIA Residential Ground	PACKAGES 1
SPECIAL INSTRUCTIONS		

ORD	SHIP	PART NO	DESCRIPTION	LIST PRICE	UNIT PRICE	LINE TOTAL
1	1	477827348F	Decklid Shock STABILUS Hatch strut (NEW - OEM) (114564) 	41.96	41.96	41.96
1	1	944 608 102 04	Fuel Pump Bosch , note this is a special order item, delivery estimate 1-2 weeks. Fuel Pump (NEW - OEM) (120881) 	140.96	140.96	140.96
1	1	928 110 253 06	Note this is a special order item, delivery estimate 1-2 weeks. Fuel filter (NEW - AFTERMARKET) (47303) 	30.96	30.96	30.96
2	2	944 511 351 01	Note this is a special order item, delivery estimate 1-2 weeks. Hood Shock, stabilus Decklid Shock, stabilus (NEW - AFTERMARKET) (46522) 	22.96	22.96	45.92

1	1	944 512 349 00	Note this is a special order item, delivery estimate 1-2 weeks. Hatch strut (NEW - AFTERMARKET) (46646) 	26.96	26.96	26.96
---	---	----------------	--	-------	-------	-------

<p>Our warranty/exchange policy is 30-90 days (unless otherwise previously agreed upon) EXCHANGE or STORE CREDIT only. We only issue refunds if we are unable to provide the part you need as a functional mechanical unit or in sufficiently good condition for cosmetic items. No longer needing an item, or obtaining a replacement elsewhere when we have one available is NOT a valid reason to request a refund. If an item is incorrect or non-functional or otherwise unsatisfactory, we will provide one that is or log the return as store credit. If we make a mistake we cover shipping, if the customer makes a mistake (ordering the wrong part number or wrong part completely) return and replacement shipping is the customers responsibility. We reserve the right to charge a restocking fee up to 15% of the order total on returns due to a customer mistake. Please be aware of this policy before placing your order and if you have any concerns or questions don't hesitate to ask. Our goal is to be fair and honest.</p>	PARTS TOTAL	286.76
	CREDITS	(0)
	SALES TAX	0.00
	TAX CREDITS	(0)
	FREIGHT	18.00
	SHIPPING CREDITS	(0)
TOTAL	304.76	

THANK YOU FOR YOUR BUSINESS
FOR QUESTIONS REGARDING THIS INVOICE PLEASE EMAIL rex@dcauto.com



RockAuto Order Confirmation

Order 316338398

Tuesday, July 15, 2025 10:28 AM Central Time

Ship To:

Bill To:



	<u>Part Number</u>	<u>Part Type</u>	<u>Price EA</u>	<u>Core EA</u>	<u>Quantity</u>	<u>Total</u>
1985 PORSCHE 944 2.5L L4						
GB REMANUFACTURING	83212101 (832-12101)	Fuel Injector Return and Rebuild Service Only	\$ 33.79	\$ 0.00	4	\$ 135.16
Shipping	Ground Advantage					\$ 23.96
Tax						\$ 14.72
Order Total						\$ 173.84
American Express						-\$ 173.84
Balance Due						\$ 0.00

To **CHECK ORDER STATUS, MAKE CHANGES, ARRANGE A RETURN** (including Cores) or **REPORT A PROBLEM**

visit <http://www.rockauto.com/orderstatus>

Please print this page as your receipt.

ALL THE PARTS YOUR CAR WILL EVER NEED



**Parts
Catalog**



**Help
Pages**



**Order Status
& Returns**

Please do not reply to this automated email. Its "noreply" address is unable to receive replies.