




[< Back to My Orders](#)

Customer #: N/A
Order #: 3001015616
Order Date: 8-6-25
Status: Complete

Items Ordered	Invoices & Shipments				
Description	Part #	Unit Price	Quantity	Subtotal	
THERMOSTAT, original type, bellowed	434-156	\$169.99	Ordered: 1 Shipped: 1	\$169.99	
GASKET, thermostat	C4985	\$1.49	Ordered: 1 Shipped: 1	\$1.49	
				Subtotal \$171.48	
				Shipping & Handling (Ground Saver) \$21.99	
				Tax (estimated) \$8.17	
				Total \$193.47	
				Store Credit \$0.00	






[< Back to My Orders](#)

Customer #: N/A
Order #: 3000812807
Order Date: 1-27-25
Status: Complete

Items Ordered	Invoices & Shipments
---------------	--

Description	Part #	Unit Price	Quantity	Subtotal
Rebuild Kit, Square Body Fuel Pump	EPK805	\$184.99	Ordered: 1 Shipped: 1	\$184.99

Subtotal \$184.99
Shipping & Handling (Ground Saver) \$21.99
Tax (estimated) \$8.74
Total \$206.98
Store Credit \$0.00



IL
17


IL
17



Its Alive Automotive
 11714 Saint Charles Rock Road
 Bridgeton, MO 63044
 (314) 710-6600
 vendor@itsaliveauto.com
 www.itsaliveauto.com

Invoice #2919

Created: 10/17/2025 at 10:01AM
Invoiced: 10/17/2025 at 3:50PM
Payment Term: On Receipt
Payment Due: 10/17/2025
Service Writer: Logan Moriarity



1966 Jaguar Mark II (Green, #c942)
 License Plate: AH04

Reinstall Distributor Properly

Description	HRS	Subtotal
Labor: Reinstall Distributor	1.1	\$165.00
Labor: Set Timing	0.87	\$130.50
Labor: Tune Carburetors	1.1	\$165.00
Shop Supplies (8%): \$36.84 Estimated Tax (8.99%): \$3.31		Total: \$500.65

Convenience Fee

A 3.5% convenience fee is added to all card transactions.

Description	Subtotal
Fee: Convenience Fee	\$17.50
Shop Supplies (8%): \$0.00	
Total: \$17.50	

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature

Labor	\$460.50
Subtotal	\$460.50
Shop Supplies	\$36.84
EPA	\$0.00
Fees	\$17.50
Tax	\$3.31
Grand Total	\$518.15
Paid to Date	(\$0.00)

REMAINING BALANCE \$518.15

Appointments

Michael K. / 1966 Jaguar Mark II


Fri 10/17/25 3:00 PM – 4:00 PM



Its Alive Automotive
 11714 Saint Charles Rock Road
 Bridgeton, MO 63044
 (314) 710-6600
 vendor@itsaliveauto.com
 www.itsaliveauto.com

Invoice #2546

Created: 04/08/2025 at 12:30PM
Invoiced: 06/05/2025 at 11:36AM
Payment Term: On Receipt
Payment Due: 06/05/2025
Service Writer: Thomas Brown



1966 Jaguar Mark II (Green, #c942)
 License Plate: AH04
 Mileage: 33,320 mi

Customer Comments

possible intake leak - Carbs wont idle down.

Multi-Point Inspection - NO CHARGE

Required on all in-coming cars

Description	HRS	Disc	Subtotal
Labor: MPI	1	100%	\$0.00
Discount (100%): (\$150.00)			Total: \$0.00

Carburetor - PAID 5/5/25 \$1,358.99

Customer states possible intake leak, carbs won't idle down

Description	HRS	Subtotal
Labor: Diagnose High Idle - Rear carb stuck open - correct	1	\$125.00
Labor: Remove carburetors, correct throttle shaft and flip butterfly valves to correct orientation. reinstall carbs and tune.	9	\$1,125.00
Shop Supplies (8%): \$100.00 Estimated Tax (8.99%): \$8.99		Total: \$1,358.99

Electrical - PAID 5/5/25 \$169.87

Description	HRS	Subtotal
Labor: Ignition Switch Intermittently losing power	1.25	\$156.25
Shop Supplies (8%): \$12.50 Estimated Tax (8.99%): \$1.12		Total: \$169.87

Brake Master Cylinder - PAID 5/5/25 \$845.08

Description	Price	QTY	HRS	Subtotal
Labor: R&R Brake Master Cylinder			3	\$375.00
Part: Brake Master Cylinder Part #: 11977	\$306.81	1		\$306.81
Part: Shipping	\$94.50	1		\$94.50
Shop Supplies (8%): \$30.00 Estimated Tax (8.99%): \$38.77				Total: \$845.08

Detail

Description	HRS	Subtotal
Labor: Buff/Polish	8	\$1,000.00
		Total: \$1,000.00



Its Alive Automotive
 11714 Saint Charles Rock Road
 Bridgeton, MO 63044
 (314) 710-6600
 vendor@itsaliveauto.com
 www.itsaliveauto.com

Invoice #2546

Created: 04/08/2025 at 12:30PM
Invoiced: 06/05/2025 at 11:36AM
Payment Term: On Receipt
Payment Due: 06/05/2025
Service Writer: Thomas Brown

Alternator Conversion				
Description	Price	QTY	HRS	Subtotal
Labor: Replace generator with alternator conversion - Repair wiring as necessary			5.8	\$725.00
Part: Alternator Conversion, Mk II	\$621.38	1		\$621.38
Part: Shipping	\$30.00	1		\$30.00
Shop Supplies (8%): \$58.00			Estimated Tax (8.99%): \$61.06	Total: \$1,495.44

V BELT				
Description	Price	QTY	Subtotal	
Part: Belt, Driving Fan Part #: C19523	\$50.30	1	\$50.30	
Part: Shipping	\$52.49	1	\$52.49	
Shop Supplies (8%): \$0.00			Estimated Tax (8.99%): \$9.24	Total: \$112.03

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Totals only include authorized services

Signature _____

Labor	\$3,656.25
Parts	\$1,155.48
Subtotal	\$4,811.73
Discount	\$150.00
Shop Supplies	\$200.50
Tax	\$119.18
Grand Total	\$4,981.41
Paid to Date	(\$2,373.94)
REMAINING BALANCE	\$2,607.47


Payments		
5/5/2025	Credit card ending in 2003	\$2,373.94
Total Payments		\$2,373.94



Its Alive Automotive
 11714 Saint Charles Rock Road
 Bridgeton, MO 63044
 (314) 710-6600
 vendor@itsaliveauto.com
 www.itsaliveauto.com

Invoice #2388

Created: 01/20/2025 at 9:10AM
Invoiced: 01/20/2025 at 4:03PM
Payment Term: On Receipt
Payment Due: 01/20/2025
Service Writer: David Uelk



1966 Jaguar Mark II (Green, #c942)
 License Plate: AH04

Mount and Balance 4 tires, no tubes.

Description	HRS	Subtotal
Labor: Mount and Balance 4 tires, no tubes. Check that wheels are true.	1	\$150.00
Part: Tire Inner Tube 15 inch inner tubes		\$174.80

Discount (10%): \$32.48 Tax (8.988%): \$14.14 **Total: \$306.46**

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Totals only include authorized services

Labor	\$150.00
Parts	\$174.80
Subtotal	\$324.80
Discount	\$32.48
Shop Supplies	\$0.00
EPA	\$0.00
Tax	\$14.14
Grand Total	\$306.46
Paid to Date	(\$306.46)

Signature

REMAINING BALANCE \$0.00

Payments

1/20/2025	Credit card ending in 2003	\$306.46
Total Payments		\$306.46

Declined

Carbs

Looking for 2" dual SUs with intake manifold.

Description	Subtotal
Labor: Untitled labor	\$0.00
Total: \$0.00	

MOSS MOTORS, LTD.
440 RUTHERFORD STREET
GOLETA, CA 93117

INVOICE 5-6523902

PAGE : 1
01/06/25
WH2
G-GRND

Customer No.: 8-563568
[Redacted]

SHIP TO:
[Redacted]

Customer Ref. :
Web Ref. :
Salesperson: AARON MCCRURY Ext:

Orig. Order	Qty Ship	B/O	Customer Ref.\Part No.	Shipped\Part No.	U O M	Description	Oversize Fee	Catalog Price	Unit Price	Extended
1	1			CAC9938	Each	BALL JOINT, UPPER		26.99	26.99	26.99

*** END OF ORDER ***

All Prices are in US Dollars

Subtotal: 26.99
Sales Tax: 1.14
Total: 28.13
XXXX-XXXX-XXXX-2003 CC Credit Card: -28.13



[< Back to My Orders](#)

Customer #: N/A
Order #: 3000794774
Order Date: 1-2-25
Status: Partially Shipped

Items Ordered	Invoices & Shipments				
Description	Part #	Unit Price	Quantity	Subtotal	
Mount, Engine or Gearbox, UNF, Multiple Jag, Austi	011-146	\$11.99	Ordered: 2 Shipped: 2	\$23.98	
Cylinder Head Breather Gasket	C2227	\$0.79	Ordered: 2 Shipped: 2	\$1.58	
BOOT, rack	C33417	\$6.99	Ordered: 2 Shipped: 2	\$13.98	
Tie Rod End, Imperial Threads	JLM9726	\$17.69	Ordered: 2 Shipped: 2	\$35.38	
Oil Filter, Paper	1526	\$4.79	Ordered: 1 Shipped: 1	\$4.79	
Spin-On Oil Filter Conversion Kit	37-2003	\$99.99	Ordered: 1	\$99.99	
Brake Fluid Level Switch	C23632	\$62.99	Ordered: 1 Shipped: 1	\$62.99	
Insulator Block, Carburetor to Manifold	696-000	\$6.99	Ordered: 2 Shipped: 2	\$13.98	

Subtotal \$1,317.49
Tax (estimated) \$47.71
Total \$253.83
Store Credit \$0.00

Description	Part #	Unit Price	Quantity	Subtotal
Mounting Gasket	C2363	\$1.99	Ordered: 4 Shipped: 4	\$7.96
Oil Pan Gasket, Pair	C19590	\$10.99	Ordered: 1 Shipped: 1	\$10.99
Intermotor Sports Coil, Non-Ballasted Ignition	143-201	\$44.99	Ordered: 1 Shipped: 1	\$44.99
Elbow Hose, Breather To Pipe	C18591	\$6.99	Ordered: 1 Shipped: 1	\$6.99
FLOAT, Nitrophyl, premium	370-015	\$12.99	Ordered: 2 Shipped: 2	\$25.98
BALL JOINT, lower	CAC9937	\$39.99	Ordered: 2 Shipped: 2	\$79.98
BALL JOINT, upper, sealed	CAC9938	\$26.99	Ordered: 1 Shipped: 1	\$26.99
Complete Polyurethane Front Bushing Kit, MK II Lat	37-6013	\$129.99	Ordered: 1 Shipped: 1	\$129.99
Complete Polyurethane Rear Bushing Kit, Mk II	37-6026	\$126.99	Ordered: 1 Shipped: 1	\$126.99
GAZ Shock, Front	GT3-2093	\$149.99	Ordered: 2 Shipped: 2	\$299.98
GAZ Shock, Rear	GT3-2094	\$149.99	Ordered: 2 Shipped: 2	\$299.98
			Subtotal	\$1,317.49
			Tax (estimated)	\$47.71
			Total	\$253.83
			Store Credit	\$0.00

SNG Group USA
 92 Londonderry Turnpike
 Manchester
 New Hampshire
 03104
 United States





FOR THE ROAD AHEAD

SALES INVOICE

Invoice No: **AD39633**
 Date: 06/30/2025
 Account No: KEY0003

Shipping: 2nd Day Air



Order Taken By: WEBSITE

Ord Qty	Inv Qty	Part Number	Description	Retail Price	Unit Price	Line Total
		Customer Order No				
2	2	P_SB200	Seat Belt Rear Statc	\$43.06	\$43.06	\$86.12
		WEB #537861				
Debit/Credit Card		\$86.12	Box Count: 1	Goods at Tax Rate 1		\$86.12
			Actual Wght: 2.84 lbs	Goods at Tax Rate 2		\$0.00
			Vol Weight: 3.78 lbs	Shipping & Handling		\$0.00
			Card: x2003	Rate 1 Tax 0.00%		\$0.00
				Rate 2 Tax 0.00%		\$0.00
Allocation Total		\$86.12		Invoice Total		\$86.12

This commercial arrangement incorporates SNG Group's sales contract and returns policy (which have been sent to you or are available for download from www.sngbarratt.com) (the "Conditions"). Unless you have objected in writing, by placing an order with us you agree that our Conditions apply. No terms sent to us by you (whether or not you say those terms apply) will supersede the Conditions.





SNG Barratt USA
 92 Londonderry Turnpike
 Manchester
 New Hampshire
 03104
 United States



Invoice No: **AD80576**
 Date: 11/17/2022
 Account No: KEY0003

Shipping: UPS Ground

Keeping Your Jaguar on the Road
www.sngbarratt.com



Order Taken By: WEBSITE

EORI No:

Ord Qty	Inv Qty	Part Number C/Order No	Description	Retail Price	Unit Price	Line Total
1	1	C33177X WEB #411913	Choke Otter Switch	\$130.66	\$130.66	\$130.66
2	2	CRK217X WEB #411913	Carb Rebuild Kit	\$93.51	\$88.83	\$177.66
1	1	SBS9306 WEB #411913	Spinner Removal Tool	\$24.48	\$22.03	\$22.03



Debit/Credit Card	\$330.35	Box Count:	1	Goods at Tax Rate 1	\$330.35
		Actual Wght:	2.7 Lbs	Goods at Tax Rate 2	\$0.00
		Vol Weight:	3.29 Lbs	Shipping & Handling	\$0.00
		Card: x2003	Auth: 283666	Rate 1 Tax 0.00%	\$0.00
Allocation Total	\$330.35			Rate 2 Tax 0.00%	\$0.00
				Invoice Total	\$330.35

This commercial arrangement incorporates SNG Barratt's sales contract and returns policy (which have been sent to you or are available for download from www.sngbarratt.com) (the "Conditions"). Unless you have objected in writing, by placing an order with us you agree that our Conditions apply. No terms sent to us by you (whether or not you say those terms apply) will supersede the Conditions.

MOSS MOTORS, LTD.
440 RUTHERFORD STREET
GOLETA, CA 93117

INVOICE 5-5974020

PAGE : 1
09/13/22
WH1
G-GRND



Customer Ref. :
Web Ref. : 100490956
Salesperson: SHADONNA MOSES Ext:

Orig. Order	Qty Ship	B/O	Customer Ref.\Part No.	Shipped\Part No.	U O M	Description	Oversize Fee	Catalog Price	Unit Price	Extended
1	1			981-174	Each	BRAKE SERVO, AFTERMARKET		209.99	209.99	209.99

*** END OF ORDER ***

All Prices are in US Dollars

Subtotal: 209.99

Total: 209.99

XXXX-XXXX-XXXX-2003 CC Credit Card: -209.99

This is a backorder shipment. Items shipped with this invoice were backordered on the original order referenced above.