

Item	Qty	Total Price	Date	Seller	Notes	Odometer	Total Spent:	Current Odomete Miles on Oil	
Rims + Tires	4	\$750.00	7/14/20	Friend	Rims are from a B6 A4 "ultrasport," tires are "like new" Bridgestone potenza pole positions		\$24,430.28	135,700	2,932
Brake Calipers	4	\$663.35	7/15/20	AutoGator through Ebay	Calipers from a 2002 Porsche 911 Carrera salvage title. Turns out the brakes were from a 996 Turbo and misadvertised... Only found this out after sand blasting and powder coating them...				
Caliper Repair Kit	4	\$195.94	7/25/20	FCP Euro	4 Total kits each with dustboots, seals, and bleed valves. 2 front kits, 2 rear kits.				
Oil Change	1	\$55.43	7/28/20	Oreilly's	6 quarts of mobile 1 5w30 with a mobil 1 oil filter. Only used 5 quarts of oil				
Stromung Exhaust	1	\$1,282.00	8/3/20	Stromung	Bought via phone call with Scott Taylor from Stromung. Optional Cat included.				
EFI Downpipe	1	\$637.34	8/3/20	EFI Express	Downpipe with "stromung" fitment. 6-8 week lead time.				
2Bennett Coilovers + Camber Plates	1	\$2,254.50	8/14/20	2Bennett	Coilover system requires custom work to be done on the top spring perch. Springs are 8" x 380lb in front and 7" x 400lb in rear. Koni shocks set to 75% stiff in the front, 85% stiff in the rear.				
Diagnosis of bad fuel pump	1	\$70.00	8/25/20	Autosport Werks	The car broke down, had it towed to ASW where they diagnosed a bad fuel pump. It was 1/2 hour labor				
Brake rotors - front	2	\$308.77	9/1/20	Apikol	StopTech Slotted 323x30mm rotors left and right at \$143/ea before tax				
Brake rotors - rear	2	\$237.51	9/1/20	Apikol	StopTech Slotted 300x22mm rotors left and right at \$110/ea before tax				
Brake brackets - front	2	\$258.02	9/1/20	Apikol	UrS, Boxster S Caliper and A8 rotor bracket (x2 brackets for left/right)				
Brake brackets - rear	2	\$258.02	9/1/20	Apikol	UrS w/ B7 S4 rotors (x2 brackets for left/right)				
Brake caliper mounting bolt - front	4	\$21.59	9/1/20	Apikol	M12 x 1.5 x 25mm Grade 10.9 brake caliper mounting bolt				
Brake caliper to carrier mounting bolt	4	\$21.59	9/1/20	Apikol	M12 x 1.5 x 72mm Bolts T55 torx grade 10.9				
Brake caliper mounting bolt - rear	4	\$21.59	9/1/20	Apikol	M12 x 1.5 x 56mm for Boxster S rear calipers				
Brake lines	2	\$172.74	9/1/20	Apikol	16" SS braided brake lines. DOT approved. M10 banjo to M10x1 inverted flare. All hardware included				
Walbro fuel pump	1	\$151.14	9/1/20	Apikol	Walbro 450lph E85 compatible fuel pump				
Walbro fuel pump adapter	1	\$96.10	9/1/20	Apikol	Bracket that interfaces fuel pump with the fuel pump housing				
Brake Pads	4	\$176.38	9/25/20	Apikol	Front and rear StopTech 996 brake pads. \$10.43 shipping				
ABS sensors	3	\$78.74	9/29/20	Ebay	Both front sensors and one rear sensor. Used on ebay. Coming from Alberta Canada.				
Front Axle Rebuilds	2	\$257.78	10/6/20	CVJ Axles	Had both front axles rebuilt. \$119/ea before tax.				
Brake caliper sandblasting	1	\$30.00	10/13/20	A1 Metal Stripping	All 4 porsche brake calipers sandblasted. Paper receipt				
Brake caliper stickers	6	\$9.83	10/12/20	Etsy	Old Audi logo stickers. 3x fronts at 3.5in wide, 3x rear at 3in wide.				
Downpipe gaskets	2	\$40.00	10/14/20	EFI Express	OE gasket for between the turbo and downpipe (\$20) and 3-hole wastegate gasket (\$12) + shipping				
Upright welding/new wheel bearings	2	\$514.39	10/21/20	Apikol	Wheel bearings were \$127.08/ea. 1 hour of labor for welding the upright collars, 1 hour of labor for pressing in new wheel bearings. Paper receipt				
Exhaust wrap	1	\$28.20	11/03/20	AutoZone	Titanium exhaust wrap for trying to abolish the rattle of the exhaust.				
Hose clamps	6	\$12.95	11/03/20	O'reilly's	Hose clamps for clamping the exhaust wrap onto the exhaust pipe.				

Exhaust gasket	2	\$20.94	11/05/20 Super Rupair	In taking out the midpipe of the exhaust to fix a rattle, I had to replace the gaskets. Could only find the gasket through Subaru. However, ended up using a gasket from Apikol that Dan paid for.	
Brake caliper stickers	6	\$10.08	11/6/20 Etsy	Old Audi logo stickers. 3x fronts at 3.5in wide, 3x rear at 3in wide. Second set so I could use the small stickers for all 4 brakes.	
Brake fluid	2	\$21.75	11/07/20 O'reilly's	2 quarts of dot 4 brake fluid Prestone brand.	
Alignment	1	\$200.00	11/10/20 AutosportWerks	Aligned to spec within stock.	
Boxster S Rear Calipers	2	\$345.47	11/12/20 Apikol	This was to replace the rear Turbo calipers that I was sold by mis-advertisement. Paper receipt.	
Headlight bulbs	2	\$52.99	11/14/20 O'reilly's	Front left headlight bulb went out so I replaced both to keep the colors the same. 9006 bulb.	
Sand blasting boxster s calipers	2	\$30.00	11/19/20 A1 Metal Stripping	Had the boxster s rear calipers sand blasted. Paper receipt.	
Rear wheel bearings	2	\$422.40	11/19/20 Apikol	\$103 for each wheel bearing. 1 hour labor for each bearing... they were quite tough to get out (apparently).	
Winter tires + install	4	\$866.13	12/03/2020 Big O Tires	225/45/18 Bridgestone Blizzak WS90s. \$178 per tire plus \$21 each for install onto the B6 A4 ultrasport rims.	
2nd Alignment	1	\$0.00	12/07/20 AutosportWerks	The front right tie rod nuts were loose after the 1st alignment. The front left tie rod end was tilted. I also had taken out and reinstalled the rear spindles.	
Wiper blades	2	\$79.58	12/13/20 Advance Auto Parts	Rain X silicone advantage wiper blades. 22". Washer fluid included in receipt.	
Window switches	4	\$27.21	12/17/20 Ebay	Window switches I believe for everywhere but the driver's panel.	
Drivers window switch/mirror set	1	\$38.10	1/22/21 Ebay	Set includes drivers window switch panel, mirror adjustment panel, memory seat panel, and wiring.	
Coil pack wiring harness	1	\$60.95	1/24/21 Ebay	Coil pack update harness to interface new ignition coils from a 1.8t/2.0t	
Igntion Coils	5	\$235.94	1/25/21 ECS Tuning	5 ignition coils for an audi 2.0t motor. Part number: 07K905715G. \$44.10/ea	
Transmission mounts	2	\$112.86	2/16/21 034 Motorsports	New "street density" transmission mounts. While doing new clutch/flywheel/trans updating the mounts as preventative maintenance.	
Clutch, flywheel, transmission, timing belt, waterpump, install big brakes, etc.	1	\$4,928.50	3/1/21 Apikol	Lots of stuff done. Reference receipt. Price includes parts and labor	
Wheel spacers, stud conversion	4	\$509.06	3/1/21 Apikol	H&R 10mm spacers front and rear. Lug stud/nut conversion. Price also includes a credit of \$105.59 for returning the 996 carrera 4s front brake pads that were not used with the front turbo calipers now on the car. However, there was a shipping and restocking fee for the pads which totaled \$26.59.	
Coolant temp sensor	1	\$53.15	3/3/21 Apikol	AAN ECT sensor. Think the temp sensor is reading higher than actual.	
Oil Change	1	\$47.87	3/3/21 O'reilly's	5qt of Castrol Edge 5w40 fully synthetic. Bosch filter. Oil change was done at 102,007 mi by me.	102,007
Hydraulic fluid	1	\$31.55	3/29/21 O'reilly's	1L of Pentosin CHF 11S. For topping off my leaking hydraulic fluid reservoir until I get around to replacing the whole system	
Front brake pads	4	\$143.51	5/4/21 Apikol	Stoptech street pads with vibration shims purchased through Apikol for the 996 turbo calipers. Price includes shipping.	

Oil Change	1	\$53.31	10/4/21 AutoZone	5qt of Mobil 1 5w30 full synthetic extended performance. STP Extended Life oil filter. Mileage: 108,208.	108,208
Alignment	1	\$375.00	1/12/22 Eurosport Racing	Alignment done by Jason at Eurosport Racing. Torqued camber plate nuts to 18 ft-lbs per request to torque more than specced value.	
Idle Control Valve	1	\$203.29	1/16/22 Ebay	NOS Bosch idle air control valve. PN: 0 280140 512. Attempting to fix idle surge issue. Did not work, but left new idle control valve in the car.	110,211
Vehicle Speed Sensor	1	\$29.73	2/9/22 RockAuto	Speedometer is stuck at 75mph. Hoping this sensor will fix the problem. Tested sensor with DMM and believe that is the issue. Did not solve.	
Rims	4	\$1,166.86	6/8/22 DriftWorks	Rota D154, 5x112, 18"x8.5", silver. Driftworks is based in the UK, had to import the rims.	113,060
Import fee for rims	1	\$37.80	7/6/22 FedEx	Import fee via FedEx for the rims.	
Camshaft Position Sensor	1	\$280.50	7/7/22 2Benett	Camshaft position sensor. Aftermarket sensor as you can't get OE anymore. This was manufactured by a company called EnzMan MotorSport (based in Germany). 2Bennett had one of their sensors on their shelf in CA, bought it from them. Hoping to fix check engine code 2113 (G40 Cam Position Sensor).	113,080
Tires	4	\$961.68	7/12/22 Firestone	4 new tires. Firestone Firehawk Indy 500 summer tires. 245/40/r18. Price includes mount and balance of tires on Rota D154 rims. Also includes road hazard protection for all 4 tires.	113,100
Oil Change	1	\$42.79	7/12/22 Advance Auto Parts	Cost for 5 quarts of Mobil 1 5W-30 High Mileage and a Mobil 1 oil filter. Receipt includes wheel chock purchase, but that is not included in the "Total Price" column.	113,190
Oil Drain Plug Washer	4	\$17.92	7/12/22 FCP Euro	Copper washers for oil drain plug. Audi part number: N0438541.	113,190
Lug bolts	20	\$96.80	7/28/22 Kixx Motorsport	H&R tapered lug bolts (M14x1.5 x 38mm). H&R bolts bought through Kixx Motorsport.	
Battery	1	\$173.33	10/20/22 Napa	New battery.	114,200
Starter	1	\$158.22	10/29/22 Oreilly's	Old starter died. Ultima R612429B was the replacement part. Starter costed \$139.99 + shipping, there was a \$22.00 core charge that was refunded when I turned in my old starter.	114,800
O2 Sensor	1	\$90.93	2/10/23 FCP Euro	Replacing O2 sensor to hopefully solve rough idle/running rich/misfires. Bosch PN: 0258003957	116,700
Spark plugs, ignition coil packs, valve cover gasket	5, 5, 1	\$165.91	2/16/23 FCP Euro	After replacing O2 sensor, checked ignition coils. Dirty with oil. Replacing VCG to stop oil leaking in, replacing coil packs and spark plugs.	116,920
PCV Valve	1	\$42.25	2/25/23 Napa	Removed intake one way bleeder valve and plugged/capped the hoses on either side of it. Installed new PCV valve (PN: 034129101B).	116,945
Fuel pressure regulator	1	\$64.69	3/26/23 FCP Euro	Installed fuel pressure regulator. Seems to have fixed issues!	117,500
Coolant Expansion Tank	1	\$73.57	3/30/23 EuropaParts	Coolant expansion tank upper nipple crumbled, leaking coolant. New one installed on 4/23/23.	118,127
Thermostat, coolant, power steering fluid, fuel filter crush washer	1	\$164.01	3/30/23 FCP Euro	Thermostat replaced with coolant expansion tank. Also included a coolant flush. Done on 4/23/23.	118,127
Oil change	1	\$56.39	4/22/23 Walmart, NAPA	Bought the oil at Walmart (Mobil 1 Extended Performance High Mileage 5W-30) and bought the filter at NAPA (NAPA Gold?). Oil change done with coolant flush on 4/23/23.	118,127

Diverter Valve	1	\$70.43	7/10/23 EuropaParts	Diverter valve replacement to solve turbo fluttering.	
Oil change + washer fluid	1	\$44.64	2/10/24 Advance Auto Parts	Mobil 1 high mileage 5W-30 oil. Mobil 1 M1205A filter.	123,240
After-run coolant pump and coolant	1, 3	\$131.46	4/3/24 FCP Euro	After run pump was leaking from one of the nipples. The thing exploded when I tried to tighten the hose clamp (while the engine was hot). New pump, new coolant.	
Camber plate	1	\$108.00	8/13/24 2Bennett	Noticed camber plate was cracked, likely from hitting a pothole. Replacement part.	126,308
Front Spring Mounting Plates	1	\$158.63	8/13/24 RiAuto.org	One of the studs that goes into the FR camber plate was bent. These spring mountint plates replace the stud. Got another stud, didn't have to install these plates.	n/a
Springs	4	\$421.00	9/16/24 2Bennett	7x500 springs all around. Full stiff on all dampers. Installed on 9/29/24.	126,860
Alignment	1	\$300.00	9/30/24 Northwest Frame & Alignment	4 wheel alignment (\$120) and labor to un-seize the front tie rods (\$180). No numbers were written down, but the guy said it's at 5/8 of a degree of negative camber all around.	126,860
Oil change	1	\$28.88	11/09/24 Advance Auto Parts	Oil change. Mobil 1 5W-30. Fram Titanium oil filter.	128,064
Rear diff fluid	1	\$40.64	11/09/24 AutoZone	2 quarts of 75W-90 gear oil. Actually purchased on 10/15, but installed with the oil change on 11/09. Drained and added 2 quarts.	128,064
Gauge faces	1	\$30.81	2/15/25 Ebay	Replacement paper gauge faces for the instrument cluster. Specifically for the speedometer.	
Trunk gas shocks	2	\$32.99	2/15/25 Amazon	Replacement gas shocks for the trunk. Installed on 3/24/25.	130,300
Gauge faces round 2	1	\$58.99	4/3/25 Whitegauges.net	Attempting to get the gauge face color that matches the stock insturment cluster. I believe white is the US model color, and light grey is the Canadian model color.	
Starter	1	\$975.00	11/15/2025 Modern Specalist	Ignition wasn't put in correct poistion, starter motor burned and was towed to Modern Spectalist (John is the guy who knows these cars the best in all of Colorado)	130,753
Power Steering O-Ring	1	\$270.00	1/6/2026 Modern Specalist	power steering leak, R&R O-Ring labor and supplies	131,401
Ignition and Starter	1	\$479.71	1/12/2026 Modern Specalist	Emission test center dmaged starter and ignition switch	131,498
Oil Change	1	\$182.18	3/10/2026 Modern Specalist	Changed oil and inspection	132,768