

FAIRLANE 500 2 DR CONVERTIBLE  
 SPRINGTIME YELLOW  
 BASE 289 2V V8 ENGINE  
 390 4V THUNDERBIRD SPECIAL 8  
 ACCENT STRIPE  
 ALL VINYL TRIM  
 BLACK POWER TOP  
 FOUR SPD MANUAL TRANSMISSION  
 ELECT CLOCK&COURTESY LIGHT GRP  
 7.75X14-4 PR WSW TIRES  
 AM RADIO  
 RIGHT HAND MIRROR  
 WHEN APPLICABLE PRICES INCLUDE 7%FET

\$ 2663	94
105	63
158	08
13	90
24	47
52	95
184	02
30	08
48	35
57	46
6	95

TRANSPORTATION CHARGES

71 95

TOTAL

\$ 3417 78

METHOD OF TRANSP.

BOLD TO:

PETERSBURG MTR CO INC

PETERSBURG  
 SHIP TO (IF OTHER THAN ABOVE)

VA 23803

VEHICLE SERIAL NUMBER

74362212696

FINAL ASSEMBLY POINT

LORAIN OHIO

## Ford Motor Company Lifeguard Design Safety Features standard on all 1967 Ford-built cars

- Dual Hydraulic Brake System with Warning Light
- Front and Rear Seat Belts
- Front Seat Belt Retractors
- Impact-Absorbing Steering Wheel with Deep-Padded Hub
- Padded Instrument Panel
- Padded Windshield Pillars
- Double-Yoke Safety Door Latches and Safety Hinges
- Outside Rearview Mirror
- Day/Night Inside Mirror with Shatter Resistant Flexible Backed Glass and Breakaway or Double Pivot Supports
- Windshield Washers
- Two-Speed or Variable-Speed Windshield Wipers
- Padded Sun Visors
- Thick Laminate Safety Plate Glass Windshield
- Turn Indicators with Lane-Changing Signal Feature
- Positive Door Lock Buttons
- Back-Up Lights
- 4-Way Emergency Flasher
- Front Seat Shoulder Harness Anchors
- Tire Safety Rim
- Folding Seat Back Latches (Wagons)
- Corrosion Resistant Brake Lines
- Safety-Designed Instrument Panel and Controls
- Uniform Shift Quadrant
- Reduced Glare Instrument Panel and Wiper Arms and Blades
- Energy Absorbing or Impact-Distributing Arm Rests



THIS LABEL IS AFFIXED PURSUANT TO FEDERAL AUTOMOBILE INFORMATION DISCLOSURE ACT. MANUFACTURER'S SUGGESTED RETAIL PRICE INCLUDES REIMBURSEMENT FOR FEDERAL EXCISE TAX AND SUGGESTED DEALER PREPARATION AND CONDITIONING CHARGE. GASOLINE, LICENSE AND TITLE FEES, STATE AND LOCAL TAXES AND DEALER INSTALLED OPTIONS AND ACCESSORIES ARE NOT INCLUDED.

FINANCE OCT 66 AAD 419C (PRINTED IN U.S.A.)

NOT FOR TITLE OR REGISTRATION

7836Z212696

WARRANTY NUMBER



MADE IN  
U.S.A.

*Ford*<sup>®</sup>

76B 8 4A 27F 25 1 5

BODY

COLOR

TRIM

DATE

D.S.O.

AXLE

TRANS.





## Proper Noise

2242 Dengler Street

Reading, PA 19606

610-775-3228

ed@propernoise.com

www.propernoise.com



## INVOICE

BILL TO

INVOICE # 1968

DATE 07/26/2021

DUE DATE 08/07/2021

TERMS Due on receipt

SERVICE/PARTS	HOURS/QUANTITY	RATE	AMOUNT
<b>Service 001</b> Charged the dead battery and test-drive the car. After inspection, researched and ordered all parts for the jobs required.	4	86.00	344.00T
<b>Service 002</b> Performed the complete inspection on the car.	4	86.00	344.00T
<b>Service 003</b> Inspect and paint the new radiator. Removed the old unit from the car.	3	86.00	258.00T
<b>Service 003</b> Installed the new radiator and refit the hoses. Filled the coolant and started the car. Test-drive to finish the evaluation. Clutch is slipping. Put car up and began removal of the transmission.	6	86.00	516.00T
<b>Service 003</b> Removed the starter, bellhousing, clutch, pressure plate, and flywheel. Cleaned up parts and sent the flywheel out for resurfacing.	5.50	86.00	473.00T
<b>Service 004</b> Assisted with removal of trans; started removing pedal assembly; found blown fuse for other electrical issues	2	86.00	172.00T
<b>Service 001</b> Removed the pedals for replacement	1	86.00	86.00T

CONV  
BODY

5/7

SERVICE/PARTS

	HOURS/QUANTITY	RATE	AMOUNT
of the mainshaft bushings.			
<b>Service 004</b> Replaced the fuse and worked through fixing gauge operation and other electrical gremlins. Drained the tank and inspected the float. Replaced it with a new brass unit. Refit to the tank and checked calibration. Bent arm to read accurately, then resealed the sender and refilled the tank. Replaced burnt out bulb under dash.	6	86.00	516.00T
<b>Service 004</b> Removed all clutch linkage for restoration of worn out pivots. Rebuilt and reinstalled the pedal assembly. Welded up blown out holes in levers and redrilled to nominal size. Resealed the transmission front and rear lip seals with new.	7.50	86.00	645.00T
<b>Service 004</b> Blasted and painted clutch fork and inspection plate. Cleaned all hardware for reinstallation. Installed the flywheel and midplate and torqued hardware.	4	86.00	344.00T
<b>Service 005</b> Repair, weld, machine clutch linkage. Fabricated one missing shifter button.	1.50	86.00	129.00T
<b>Service 003</b> Assisted with installation of transmission into the car, aligning and lifting everything into position. Refit the driveshaft and tightened down all mounts.	6	86.00	516.00T
<b>Service 004</b> Installed the rebuilt clutch Z-bar and supports. Fit the new clutch and pressure plate to the flywheel. Installed the bellhousing, starter, and refit the gearbox. Tested function on the stands, then lowered car down for testing.	7	86.00	602.00T
<b>Service 001</b> Installed the shifter with new springs and buttons. Test-drive on the road - all good. Replaced 2 bad bushings in the left/rear shock. Cleaned car for delivery.	2.50	86.00	215.00T
			Subtotal: 5,160.00
<b>Sales</b> AutoKrafters clutch replacement parts	1	338.44	338.44T
<b>Sales</b> Resurface flywheel (machine shop charge)	1	205.11	205.11T

FUEL TYPE: GASOLINE

132002200166

36721269

VEHICLE ID#

NV

SERVICE/PARTS

089093000

Multi Purpose Solvent

Sales

AutoKrafters clutch linkage rebuild parts

Sales

flywheel bolt kit

Sales

Eastwood Radiator Black

360-646

brass fuel tank float

AF-2000

Prestone Antifreeze, per gallon

Grease

wheel bearing and/or chassis lubrication

Sales

Aluminum Be Cool radiator

HAZMAT

disposal fee

DE1635

Duplicolor Engine Enamel, Semi-Gloss Black, can

Sales

Transmission Seal Kit

	HOURS/QUANTITY	RATE	AMOUNT
Multi Purpose Solvent	3	6.296	18.89T
AutoKrafters clutch linkage rebuild parts	1	149.31	149.31T
flywheel bolt kit	1	16.99	16.99T
Eastwood Radiator Black	1	14.99	14.99T
brass fuel tank float	1	12.99	12.99T
Prestone Antifreeze, per gallon	2	19.99	39.98T
wheel bearing and/or chassis lubrication	1	5.00	5.00T
Aluminum Be Cool radiator	1	476.86	476.86T
disposal fee	1	6.95	6.95T
Duplicolor Engine Enamel, Semi-Gloss Black, can	1	14.04	14.04T
Transmission Seal Kit	1	23.79	23.79T

Subtotal: 1,323.34

SUBTOTAL	6,483.34
TAX (6%)	389.00
TOTAL	6,872.34
BALANCE DUE	<b>\$6,872.34</b>