



mrfiat.com: New Order # 100022108

1 message

orders@mrfiat.com <orders@mrfiat.com>

Wed, Mar 3, 2021 at 5:13 PM



Thank you for your order from mrfiat.com. Once your package ships we will send an email with a link to track your order. If you have any questions about your order please contact us at info@mrfiat.com or call us at +1 678-637-5103 Monday - Friday, 10am - 7pm EST. If additional shipping is required to complete your order we will contact you.

Your order confirmation is below. Thank you again for your business.

Your Order #100022108 (placed on March 3, 2021 5:13:29 PM EST)

Billing Information:

Payment Method:

Credit Card

Credit Card Type:

American Express

Credit Card Number:

xxxx-1007

Payer Email:

swiftmotoring@gmail.com

Shipping Information:

Shipping Method:

Product Rate - Est. US Shipping Cost

Item

SKU


Qty

Subtotal

3/3/2021

Gmail - mrfiat.com: New Order # 100022108

Item	Sku	Qty	Subtotal
Fiat 500 N 1st Series Original Gearshift Knob	IN-500-126	1	\$33.00



Subtotal	\$33.00
Shipping & Handling	\$12.00
Grand Total	\$45.00

Thank you again, mrfiat.com



Order #100022133

Order Date: March 5, 2021

Shipping Address

Billing Address

Shipping Method

Product Rate - Est. US Shipping Cost

Payment Method

PayPal Express Checkout

Payer Email:

Items Ordered

Product Name

Fiat 500 F/L/R 600 D Wiper Blades Set

SKU	Price	Qty	Subtotal
WS-500-004	\$42.00	Ordered: 1	\$42.00

Fiat 500 L Door Opener Latch Cover

DR-500-016	\$4.00	Ordered: 2	\$8.00
------------	--------	------------	--------

Subtotal	\$50.00
Shipping & Handling	\$10.00
Grand Total	\$60.00



Euro Auto Service LLC
 11815 US Hwy 15 501 Unit C
 Aberdeen, NC 28315 US
 910-944-5751
 euroautonc@gmail.com

Invoice

BILL TO

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
2457	03/30/2021	\$0.00	04/29/2021	Net 30	

MAKE/MODEL/YEAR
 Fiat, 500, 1973

DATE	QTY	ACTIVITY	DESCRIPTION	RATE	AMOUNT
	1.75	Labor	Install driving lights and switch Repair front fender plate bracket Remove stereo wiring	130.00	227.50T

Thank you for your business. Happy motoring!

PAID

SUBTOTAL	227.50
TAX	15.93
TOTAL	243.43
PAYMENT	243.43
BALANCE DUE	\$0.00

TERMS: All amounts are due upon receipt of this invoice. Customer shall pay a late fee of \$25 and 1.5% per month on all amounts more than 30 days past due. A \$25 fee will be assessed to any check returned by the bank. Euro Auto Service LLC may take possession and or retain any of the Customer's property until all outstanding debts are paid in full.



Order #100023906

Order Date: August 27, 2021

Shipping Address

Billing Address

Shipping Method

Product Rate - Est. US Shipping Cost

Payment Method

PayPal Express Checkout

Payer Email:

Items Ordered

Product Name	SKU	Price	Qty	Subtotal
Fiat Abarth Scorpion Horn Button	SW-SW-001	\$36.00	Ordered: 1	\$36.00
Fiat 500 600 850 124 1100 Hub Adapter	SW-SW-015	\$74.00	Ordered: 1	\$74.00
Fiat 500 Abarth Oil Cap	AB-500-032	\$41.00	Ordered: 1	\$41.00
Fiat 500 600 Abarth Hood Hinge Set	AB-500-074	\$14.00	Ordered: 1	\$14.00
Fiat 500 Spare Tire Strap	LC-500-003	\$13.00	Ordered: 1	\$13.00
			Subtotal	\$178.00
			Shipping & Handling	\$10.00
			Grand Total	\$188.00

Close Window

ROY COOPER
GOVERNOR

STATE OF NORTH CAROLINA
DEPARTMENT OF TRANSPORTATION
DIVISION OF MOTOR VEHICLES
3152 MAIL SERVICE CENTER
RALEIGH NC 27697-3152

J. ERIC BOYETTE
SECRETARY

08/31/21

S7272083
905 TS
AGE: 03/03/2022

RE: LICENSE #: JCC8080 03-04-2021 03-31-2022
VEHICLE 1973 FIAT 2S
IDENT #: 110F6148776
TITLE #: 773231210638075
OWNER

DEAR SIR:

WE ACKNOWLEDGE RECEIPT OF YOUR NORTH CAROLINA TITLE APPLICATION (MVR-1) FOR THE ABOVE LISTED VEHICLE; HOWEVER, IT IS REQUIRED THAT THIS VEHICLE BE INSPECTED BY AN INSPECTOR WITH THE DIVISION OF MOTOR VEHICLES LICENSE AND THEFT BUREAU.

PLEASE CONTACT THE INSPECTOR IN YOUR AREA AT 521 S. SANDHILLS BLVD ABERDEEN NC 28315, OFFICE TELEPHONE NUMBER (910)944-3624, TO HAVE THE VEHICLE INSPECTED. ONCE COMPLETED, FURNISH THE DIVISION WITH A COPY OF THE REPORT.

PLEASE BE ADVISED, YOU WILL NOT RECEIVE YOUR TITLE OR BE ABLE TO RENEW YOUR REGISTRATION UNTIL THE INSPECTION IS COMPLETE. FAILURE TO PROVIDE THE INSPECTOR'S REPORT IN ONE YEAR WILL RESULT IN THE CANCELLATION OF YOUR REGISTRATION AND LICENSE PLATE.

SHOULD YOU HAVE FURTHER QUESTIONS REGARDING THIS TRANSACTION, YOU MAY CONTACT THE LICENSE AND THEFT BUREAU VEHICLE EXAMINATION UNIT AT (919)861-3143 OR WRITE TO THE NORTH CAROLINA DIVISION OF MOTOR VEHICLES, 3152 MAIL SERVICE CENTER DIVISION, RALEIGH, NORTH CAROLINA 27699-3152.

VEHICLE SERVICES
QUALITY ASSURANCE

CC:



Italian Auto Parts, Inc.

2370 John Glenn Dr
Atlanta, Ga 30341
678-637-5103

Invoice

Date	Invoice #
8/27/2021	119615

PAID
08/27/2021

Bill To

Fax #	
-------	--

Shipped With USPS # 9405511899561592957567

Item	Description	Qty	Rate	Amount
SWSW001	Fiat Abarth Scorpion Horn Button	1	36.00	36.00
P2501	Fiat 500 600 850 124 1100 Hub Adapter	1	74.00	74.00
AB500032	Fiat 500 Abarth Oil Cap	1	41.00	41.00
AB500074	Fiat 500 600 Abarth Hood Hinge Set	1	14.00	14.00
LC500003	Fiat 500 Spare Tire Strap	1	13.00	13.00
SH	Product Rate - Est. US Shipping Cost		10.00	10.00
Note			0.00	0.00
Note	T: Mrfiat.com Order Number:100023906 TransactionID: 28N49707UJ041140J		0.00	0.00

Total	USD 188.00
--------------	-------------------

Return Policy:
<http://mrfiat.com/return-policy>

Very Important!
Inspect all items upon receipt!



Italian Auto Parts, Inc.

2370 John Glenn Dr
Atlanta, Ga 30341
678-637-5103

Invoice

Date	Invoice #
10/15/2021	120899

PAID
10/15/2021

Bill To

Fax #	
-------	--

Shipped With fFEDEX # 285043953635

Item	Description	Qty	Rate	Amount
LC500008	Fiat 500 Front Trunk Rubber Bumper	10	1.00	10.00
LC500019	Fiat 500 Battery Bracket OEM	1	25.00	25.00
AB500003	Fiat 500 Wiper Pantograph	1	69.00	69.00
SH	Product Rate - Est. US Shipping Cost		12.00	12.00
Note			0.00	0.00
Note	Mrfiat.com Order Number:100024338		0.00	0.00
	TransactionID: 2M6837585P245682K			

Total	USD 116.00
--------------	-------------------

Return Policy:
<http://mrfiat.com/return-policy>

Very Important!
Inspect all items upon receipt!



Order #100024356

Order Date: October 17, 2021

Shipping Address

Billing Address

Shipping Method

Product Rate - Est. US Shipping Cost

Payment Method

Credit Card

Credit Card Type:

Visa

Credit Card Number:

xxxx-1950

Payer Email:

Items Ordered

Product Name	SKU	Price	Qty	Subtotal
Fiat 500 R 126 Slalom Sport Muffler	EX-500-042	\$240.00	Ordered: 1	\$240.00
Fiat 500 Strap for Rear Seat	IN-500-056	\$11.00	Ordered: 1	\$11.00
			Subtotal	\$251.00
			Shipping & Handling	\$35.00
			Grand Total	\$286.00

Close Window



Italian Auto Parts, Inc.

2370 John Glenn Dr
Atlanta, Ga 30341
678-637-5103

Invoice

Date	Invoice #
10/17/2021	120964

PAID
10/18/2021

Bill To

Fax #	
-------	--

Shipped With **FFEDEx # 285094386723**

Item	Description	Qty	Rate	Amount
EX500042	Fiat 500 R 126 Slalom Sport Muffler	1	240.00	240.00
IN500056	Fiat 500 Strap for Rear Seat	1	11.00	11.00
SH	Product Rate - Est. US Shipping Cost		35.00	35.00
Note			0.00	0.00
Note	Mrfiat.com Order Number:100024356		0.00	0.00

Total	USD 286.00
--------------	-------------------

Return Policy:

<http://mrfiat.com/return-policy>

Very Important!

Inspect all items upon receipt!



3908 Ogeechee Road
 Savannah, GA 31405
 (912) 417-4353

Invoice

Date	Invoice #
11/3/2021	JF4506

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
Fiat 500	John Jr.	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in 29578 NEEDS LIST 1. Fix Shifting - I have Front Shift Rod Bushing and Rear Lolipop - DONE 2. CAR RUNS LIKE SHIT - Full tune up - Spark plugs, Spark Plug Rubbers, Wires, Cap, Rotor, ??? Points and Con, needs Dist adv Springs, and isolators, Check and Set Timing and dwell - Check carb Operation - Accel Pump - and Fuel flow - New Fuel filter, - DONE 3. Install Front Racing Seat - See Joe for HOW TO - DONE 4. Install Hood Straps - Rivet on - DONE 5. Driving Lamps and Wiring - SEE JOE CHANGING ARRANGEMENT - DONE 6. Make Toggle Switch Panel - Under dash - all new noggles and for Ignition - DONE 7. Drivers Door Window Sucks - DONE 8 Full Fluid Service - DONE 9. Exhaust - Do this Last Open with no muffler - I have gaskets - DONE	1	0.00	0.00

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
11/3/2021	JF4506

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
Fiat 500	John Jr.	

Item	Description	Qty	Rate	Total
Repair Labor	38hrs total SHIFTER SHIFTER FLOPS AND HAS POOR TO NO SHIFT ENGAGEMENT - Remove both seats, Carpet, and Complete front center tunnel and rear access panel - remove complete shiter and rod - paint shift lever - found that all guide bushings gone shifter is a mess and filthy - remove take apart and clean and grease shifter - install shifter guide tube bushing and rear firewall bushing - had to make one - install shifter, rod and rear lolipop link asym new. Check operation on lift - all gears operate and reverse	4	122.00	488.00
Parts	COC 0004329757N Rubber Bushing for Gear Shift	1	6.25	6.25T
Parts	COC 0004111917N Shift Shaft Flex Joint	1	24.75	24.75T
Shipping	Shipping DRIVERS WINDOW	1	14.80	14.80

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
11/3/2021	JF4506

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
Fiat 500	John Jr.	

Item	Description	Qty	Rate	Total
Repair Labor	Remove door card and confirm operation and issue - window tracks missing all window felt and glass flopping around and also noticed lower window track off bottom of vent window frame missing - confirmed parts needed and correct part numbers - ordered window track and used porsche 911 window felt - Install all parts and glass back in door - lube window regulator.	2	122.00	244.00
Parts	POR-911-542-905-00 Window Track Felt	1	42.50	42.50T
Parts	MRFIT - FIAT 500 Window Guide Track Drivers Door NEW	1	65.00	65.00T
Shop Supplies	Shop Supplies	1	35.00	35.00
Repair Labor	RACING SEAT Racing Seat had tracks that did not match oe tracks - Used an old Porsche Seat base and mounting plate - Matched up mounting holes on Race Seat Tracks - Drilled holes thru floor thru center of body mounted tracks and secure seat to floor of car.	1.3	122.00	158.60
Parts	RACING SEAT PROVIDED BY CLIENT IGNITION SYSTEM	1	0.00	0.00T

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
11/3/2021	JF4506

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
Fiat 500	John Jr.	

Item	Description	Qty	Rate	Total
Repair Labor	Pulled distributor to repair sticking advance and replace adv springs (assumed issue) and install new points and cond - Found that counter weight studs completely loose and floping on spindle - spent hours trying to repair and finally gave up - needs new distributor - Replaced Spark plugs, Wire set, boots - Had joe order new distributor - Install new distributor - had to read about 123 set up and programming - put in stock advance curve into dist memory - installed new coil.	2.5	122.00	305.00
Parts	IAP CS500022 Fiat 500 N/D/F Spark Plug Cable Set	1	32.60	32.60T
Parts	IAP EI500009 Fiat 500 126 Spark Plug Rubber	2	5.00	10.00T
Parts	MRFT - Ignition 123 Electronic Ign dist w/OVERNIGHT SHIPPING	1	414.00	414.00T
Parts	OR NGK 6422 Copper Spark Plug List 6.59	2	5.89	11.78T
Parts	SSF 9220081083 Ignition Coil - BOSCH BLUE COIL LIGHTS - ELECTRICAL	1	67.42	67.42T
Repair Labor	DEISGN, FAB and Install - Front driving lights - FAB a 3 gang toggle switch panel under left side of dash - install 3 toggles for center and outer driving lights and Ignition - Wire all to car.	5	122.00	610.00

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
11/3/2021	JF4506

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
Fiat 500	John Jr.	

Item	Description	Qty	Rate	Total
Parts	MSC HARDWARE AND SUPPLIES HOME DEPOT - FOG LIGHT BUMPER BOLTS 4x	1	70.61	70.61T
Blue LED Rocker	12v 20A Blue LED Light Rocker Toggle	1	5.50	5.50T
Red LED Rocker	12v 20A Red LED Light Rocker Toggle	1	5.50	5.50T
Yellow LED Rocker	12v 20A Yellow LED Light Rocker Toggle	1	5.50	5.50T
Shop Supplies	Shop Supplies - Wiring and Connectors	1	35.00	35.00
Parts	Lights Provided by customer	1	0.00	0.00T
Repair Labor	FLUID SERVICE Change Engine Oil and Gear box - Found issues and discussed with client - Fill Plug was stuck Solid in transmission.	1.5	122.00	183.00
20W50	Total Racing 20W50 High Zinc Engine Oil	3	10.50	31.50T
Parts	80w90 Gear oil	1.25	9.50	11.88T
Repair Labor	INITIAL START AND TUNE Car runs - found that Carb has 2 issues - Running way to rich - leaking fuel - Timing good - Need to pull car FUEL SYSTEM	1	122.00	122.00

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
11/3/2021	JF4506

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
Fiat 500	John Jr.	

Item	Description	Qty	Rate	Total
Repair Labor	★ Remove Carb - Clean and Rebuild - had to remove 4x - found that choke barrel was allowing fuel to leak past butterfly and raw fuel going into intake - polish choke barrel and seat - leak fixed - set float level and mixture and idle speed	3.5	122.00	427.00
Parts	IAP FS500022 Fiat N/D/F/L Complete IMB 10 Carburetor Repair Kit - EXPENSIVE KIT YIKES	1	75.00	75.00T
Parts	Hengst Fuel Filter	1	7.00	7.00T
Repair Labor	STARTER REPAIR Starter was always HIT OR MISS - Solenoid on start was flopping around and found that 1 mounting bolt was missing - Clean up threads and install mounting bolt - now secure and works 100%	0.5	122.00	61.00
Repair Labor	EXHAUST RR Stock Muffler and Install Race exhaust provided by customer	1	122.00	122.00
Parts	IAP EX500033 Fiat 500 126 Reinforced Manifold Gasket Set	1	12.00	12.00T
Repair Labor	HOOD STRAPS Positon - Mark - drill and rivet rubber hood straps	1.25	122.00	152.50
Parts	Cust provided hood straps	1	0.00	0.00T

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
11/3/2021	JF4506

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
Fiat 500	John Jr.	

Item	Description	Qty	Rate	Total
Repair Labor	FINAL ROAD TEST AND TUNE Road Test car - Richen Idle Mixture for new exhaust - All Gears work - Transaxel very noisy - Got car up to 49mph -	0.5	122.00	61.00
Shipping	Shipping - SHIPPING FOR 1st BIG ORDER AFTER SEEING CAR	1	60.00	60.00
Parts	SPARE PARTS TO GO WITH CUSTOMER IAP EX5000032 Reinforced Muffler Exhaust Gasket Set	1	12.00	12.00T
Parts	IAP EI500008 Fiat 500 R 126 Distributor Cap	1	18.00	18.00T
Parts	IAP EI500004 Fiat 500 R Rotor Arm	1	10.00	10.00T
CTEK 5.0	CTEK (40-206) MXS 5.012v Fully Automatic 8 Step Charger	1	109.13	109.13T
	COMPLETE TICKET			

Subtotal	\$4,126.82
Sales Tax (7.0%)	\$73.35
Total	\$4,200.17
Payments/Credits	\$0.00
Balance Due	\$4,200.17



Italian Auto Parts, Inc.

2370 John Glenn Dr
Atlanta, Ga 30341
678-637-5103

Invoice

Date	Invoice #
6/19/2023	139384

Fax #	914-829-9018
-------	--------------

PAID
06/19/2023

Bill To

Shipped With

Item	Description	Qty	Rate	Amount
EX500025	Fiat 500 R Dual Pipes Sport Muffler	1	264.00	264.00
EX500032	Fiat 500 126 Reinforced Muffler Exhaust Gasket Set	1	18.00	18.00
AB500074	Fiat 500 600 Abarth Hood Hinge Set	1	14.00	14.00
S&H	Shipping and Handling 7FC940980V111612A		40.00	40.00

Total	USD 336.00
--------------	-------------------

Return Policy:

<http://mrfiat.com/return-policy>

Very Important!

Inspect all items upon receipt!



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
3/24/2023	JF6046

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in 29644	1	0.00	0.00
	1. Drivers window			
	2. Carburetor fuel leak			
Repair Labor	DRIVERS WINDOW REPAIR Fixed the window the regulator came out of the track. It does not have a stop so I drilled a hole and added a bolt to act as a stop to prevent it from falling out again. Put the door panel back together.	1	132.00	132.00
Repair Labor	FUEL LEAK Found that the float was bleeding into the air corrector and passing fuel through the main nozzle. Tweaked the float level to eliminate the carb from sucking fuel into the main while sitting. Drove the car, now all is good.	1	132.00	132.00
Repair Labor	MUFFLER WORK Removed the remaining factory exhaust bolts and replaced with longer ones that will hold a lock washer. Made an exhaust gasket for the rear pipe (fell out with the bolts). The problem with the exhaust is that it would not work with the bracket from the stock one, so it vibrates a lot. Hopefully this is all it needed. The client may want to check them periodically since there is no bracket.	0.5	132.00	66.00

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



Invoice

3908 Ogeechee Road
 Savannah, GA 31405
 (912) 417-4353

Date	Invoice #
3/24/2023	JF6046

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total										
Shop Supplies	Shop Supplies COMPLETE TICKET	1	25.00	25.00										
<table border="1"> <tr> <td>Subtotal</td> <td>\$355.00</td> </tr> <tr> <td>Sales Tax (7.0%)</td> <td>\$0.00</td> </tr> <tr> <td>Total</td> <td>\$355.00</td> </tr> <tr> <td>Payments/Credits</td> <td>-\$355.00</td> </tr> <tr> <td>Balance Due</td> <td>\$0.00</td> </tr> </table>				Subtotal	\$355.00	Sales Tax (7.0%)	\$0.00	Total	\$355.00	Payments/Credits	-\$355.00	Balance Due	\$0.00	
Subtotal	\$355.00													
Sales Tax (7.0%)	\$0.00													
Total	\$355.00													
Payments/Credits	-\$355.00													
Balance Due	\$0.00													



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
9/15/2023	JF6579

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
	TOM	

Item	Description	Qty	Rate	Total
Cust Issue	Mileage in	1	0.00	0.00
Repair Labor	1. Install exhaust EXHAUST INSTALLATION	1.8	146.00	262.80
Parts	Raised the body and lowered the engine to install the exhaust. Modified one of the brackets to fit around the new exhaust. Exhaust is installed. The car runs very poorly need to look into this. Exhaust and gaskets supplied by the client	1	0.00	0.00T
Repair Labor	ENGINE DRIVABILITY DIAGNOSTIC AND REPAIR Worked on tuning the engine and getting it running well. Made mixture adjustments. Needs more attention.	1.6	146.00	233.60
Parts	Performed fuel pump flow test. Found good flow. Spark plugs require replacement. Installed new plugs. Cylinder 2 is now firing but the engine still won't idle. Fiat OR NGK Spark Plug Copper 6422	2	8.73	17.46T

	Subtotal
	Sales Tax (7.0%)
	Total
	Payments/Credits
	Balance Due



3908 Ogeechee Road
Savannah, GA 31405
(912) 417-4353

Invoice

Date	Invoice #
9/15/2023	JF6579

Name / Address

Vehicle Info
Fiat 500 vin 110f6148776 red

P.O. No.	Tech	Tech 2
	TOM	

Item	Description	Qty	Rate	Total
Repair Labor	Checked the float level and it was good, blew out the main and idle jets again and put it back together. And now for some reason only the Fiat gods know, it runs like a beast again. Checked timing and spun it around the parking lot it revved out in 1st without any problem. Reinstalled the engine cover and final road test. After the test drive I parked it under the cabana and John noticed something leaking out of the front. Turns out the rubber master feed line had rubbed a hole in it. I replaced it with the last of the Porsche brake hose we had and added a grommet to the hole it runs through. Rinsed the underside off to get rid of the brake fluid; now its ready to leave.	1.7	146.00	248.20
Parts	Master cylinder brake fluid hose	1	15.64	15.64
Shop Supplies	Shop Supplies	1	15.00	15.00

Subtotal	\$792.70
Sales Tax (7.0%)	\$2.32
Total	\$795.02
Payments/Credits	-\$795.02
Balance Due	\$0.00