



3908 Ogeechee Road  
 Savannah, GA 31405  
 (912) 417-4353

# Invoice

Date	Invoice #
8/15/2023	JF6437

Name / Address

Vehicle Info
Ford Custom Hot Rod 8793A14 Metallic yellow

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	INITIAL START AND FUEL DRAIN AND OIL CHANGE AND BATTERY Use transfer pump to remove old fuel from tank and dispose - Remove bowls from carbs to clean out - changed engien oil and added 4 gallons of fuel - Started car and fuel flooding down carb barrels and leaking out of 2 exhaust pipes - Shut down car and prep for full carb overhauls. Also removed Drivers seat to access battery and change out - Will not hold charge	4.5	132.00	594.00
Parts	OR WIX oil filter 51060 List 22.02	1	13.50	13.50T
10W40	Total Classic 10W-40 Performance Engine Oil	5	8.50	42.50T
Parts	Hot Rod OR Super Start Battery 29NF list \$220.32 Ford Hot rod	1	166.50	166.50T
Repair Labor	CARB OVERHAUL and PLUGS Remove and rebuid Both Carbs - Complete Mess Inside from Sitting - Change 8 Spark Plugs	8	132.00	1,056.00
Parts	ATK Holley Carburetor Renew Kit HLY-37-119 Ford Hot Rod	2	49.75	99.50T
Shipping	Shipping	1	11.99	11.99
Parts	OR ACDelco Spark plug R45TS List 7.61 2ND START AND DIAG	8	6.29	50.32T

	<b>Subtotal</b>
	<b>Sales Tax (0.0%)</b>
	<b>Total</b>
	<b>Payments/Credits</b>
	<b>Balance Due</b>



3908 Ogeechee Road  
Savannah, GA 31405  
(912) 417-4353

# Invoice

Date	Invoice #
8/15/2023	JF6437

Name / Address

Vehicle Info
Ford Custom Hot Rod 8793A14 Metallic yellow

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
Repair Labor	Started Car and found that raw fuel still coming out of 2 exhaust pipes - Installed fuel pressure gauge and found that fuel pressure was 11 PSI from mechanical pump- Carbs can't handle - This was causing more flooding and also discovered that wires ends broken inside distributor cap - Needs new cap and wires and new fuel pump pulled down to correct psi. - Internal regulator not working. RR Fuel pump - Install new plug wires and cap - car now running correctly but out of tune and balance - Modify Carb cap to balance both carbs for air flow - check and adj timing - set idle mixtures - Test car in parking lot. 23	6.5	132.00	858.00
Parts	Hot Rod ATK Distributor Cap Black PNX-D650710	1	48.53	48.53T
Parts	Hot Rod ATK Spark Plug Wire Set PNX-828215HT	1	142.10	142.10T
Shipping	Shipping	1	11.99	11.99
Parts	Hot Rod ATK Carb Cover with shipping	1	54.55	54.55T
Parts	Hot Rod ATK Holley Fuel Pump HLY-12-835	1	113.00	113.00T
	<b>FLUID SERVICE AND INSPECTION</b>			
Repair Labor	Drain and Fill Coolant, Flush and bleed brake system , Change Transmission Fluid and top off Diff was 1/2 Qt low - RR fuel Filter under car	2.5	132.00	330.00
TEXTAR DOT4	WP BF 4 1 DOT 4 Brake Fluid List 24.29	1	18.65	18.65T

	<b>Subtotal</b>
	<b>Sales Tax (0.0%)</b>
	<b>Total</b>
	<b>Payments/Credits</b>
	<b>Balance Due</b>



3908 Ogeechee Road  
 Savannah, GA 31405  
 (912) 417-4353

# Invoice

Date	Invoice #
8/15/2023	JF6437

Name / Address

Vehicle Info
Ford Custom Hot Rod 8793A14 Metallic yellow

P.O. No.	Tech	Tech 2
	BRIAN	

Item	Description	Qty	Rate	Total
ANTIFREEZE	Green Antifreeze per Gallon	2	24.99	49.98T
Shop Supplies	Shop Supplies - Gear oil for Trans and Diff, MSC items	1	35.00	35.00
Fuel Charges	Fuel Charges	1	24.01	24.01
Repair Labor	DRIVERS DOOR POWER WINDOW Hot Rod Drivers window would not function - Removed the drivers door panel and trim. Found a bad connection at the contact switch. Loose wire. Lubricated the window tracks and adjusted the run channels so it will function more smoothly.	2	132.00	264.00
Sublet	MOVE CAR TO WAREHOUSE Hot Rod Towing from JFrazar to Brooklands	1	102.60	102.60
	COMPLETE TICKET EMAIL SENT 08/28			

	<b>Subtotal</b>	\$4,086.72
	<b>Sales Tax (0.0%)</b>	\$0.00
	<b>Total</b>	\$4,086.72
	<b>Payments/Credits</b>	\$0.00
	<b>Balance Due</b>	\$4,086.72