

19.09.2025



NAME: Rice cooker

BRAND: Tristar

Dear Customer.

There is a recall of the product on the Safety Gate portal (details here). The temperature of the pins (to be connected with a plug) of the appliance is too high. A user could suffer burns. Moreover, the product leaks water on the inside, which may lead to an electric shock for a user.

Please check the batch number T14691 on the product labelling and contact support@wolt.com to get a refund or Wolt credit if you have an affected product. If you have any further questions regarding the product, please contact our retail partners you've purchased the item from.

Homemate Mriehel customercare@homemate.com.mt \$\mathbb{L} + 35623262000

From our side, we have taken all necessary steps to make sure all the affected products are no longer available on our platform. If you have any questions or concerns, please don't hesitate to contact support@wolt.com. We are here for you!

Best regards,

Wolt Support