

LACK OF RESOURCES THE DIRTY DOZEN "We

- 1. LACK OF COMN
- COMPLACENCY 2.
- LACK OF KNOV 3.
- DISTRACTION 4.
- LACK OF TEAM 5.
- 6. FATIGUE
- LACK OF RESO
- 8. PRESSURE
- 9. LACK OF ASSE
- **10. STRESS**
- **11. LACK OF AWAF**
- **12. NORMS**

This refers to ALL AREAS of activity related to aviation



















NCY EXIT



to do."











CK OF RESOURCES UNTERMEASURES

nsure sufficient manpower.

rder & stock necessary tools, parts & quipment.

o not improvise or use incorrect parts, ools or equipment to expedite your work.

you cannot perform a task correctly, do ot proceed.

exemember the complexity of the system.

















