

ALEOS 4.18.1.002_6b9144

RELEASE NOTES

About ALEOS 4.18.1.002_6b9144

This release of ALEOS 4.18.1.002_6b9144 is for the AirLink[®] RV55. It is intended for customers of Case New Holland/Raven, and should not be used by other entities.

These release notes describe a bug fix and resolution details. For details about the previous release of ALEOS 4.18.1, see the [release notes](#).


Bug Fix

Services

Resolved an issue where the configured MSCI Server password no longer worked after upgrade to ALEOS 4.18.1.

The resolution adds a new ACEmanager setting and AT command to set the MSCI password for server-initiated communication.

To set the password, go to Services > ALMS > MSCI > HTTP Server Services Password or use AT*MSCISERVERPASSWD=<password>.



[-] MSCI	
AT Server URL	https://na.m2mop.net/devic
AT Auto Synchronize Configuration	Enable ▾
AT TLS Verify Peer Certificate	Disable ▾
AT HTTP Server Services	LAN Only ▾
HTTP Server Services Password	*****
Private AMM Certificate	Private AMM Certificate
Currently Installed AMM Certificate	
AMM Management Tunnel	Disable ▾

Note: Semtech recognizes that our customers deploy routers in a wide range of network environments with varying configurations. It is always good practice to install a new ALEOS release on a few trial routers to ensure that standard operation is maintained within your environment before deploying the new release across your fleet of AirLink routers. For more information, please see the application note [Testing AirLink Devices Before Deployment](#).