



# GNX G604.09.06kX Release Notes

## OVERVIEW

<b>DATE ISSUED:</b>	19-Nov-2021
<b>ISSUED BY:</b>	Sierra Wireless GNX Product Management
<b>PRODUCTS AFFECTED:</b>	All GNX-5P and GNX-6 Internal, External and Companion SKUs. This release does not apply to GNX-3 SKUs
<b>FOR DISTRIBUTION TO:</b>	All GNX Customers
<b>SUMMARY:</b>	<p>This release includes the features from G604.09.05 which are:</p> <ol style="list-style-type: none"><li>1. Set HL7688 modems to Data Centric for AT&amp;T 3G sunset</li><li>2. Fix GNX-5P ECM Status in the DIAG HOS command</li><li>3. Fix rewriting last odometer seed with PARAM_ODOMETER</li><li>4. Fix param ENGINE_SECONDS overlap on VALID_IB_CRC_DEL</li></ol> <p>This release includes the following new features:</p> <ol style="list-style-type: none"><li>1. Adds MIL + DTC to Activity Report column</li><li>2. Adds APN to support new Jasper SIM</li><li>3. Verified HL7650 Modem FW update to A1</li></ol> <p>Notes:</p> <ol style="list-style-type: none"><li>1. This version detects the new compatible Bluetooth module rolling into production in late 2021 per <a href="#">G604.09.03kX Firmware Release Announcement</a></li><li>2. All GNX devices operating on the A&amp;T network <b>MUST</b> upgrade to this release prior to February 2022, or your GNX-5 and GNX-6 HL7688 devices will fail to connect to the AT&amp;T LTE network</li><li>3. Note that an upgrade from GNX firmware release earlier than G604.08.09 <b>MUST</b> first upgrade to G604.08.09 first and then proceed to upgrade to G604.09.06kX</li><li>4. To ensure that there are no unintended consequences, we highly recommend testing the upgrade path in a limited capacity before performing this upgrade on a large population of devices. Consider rolling out the upgrade in increasing population sizes. e.g. considering testing 1 device then with 10 devices, then test with 100 devices, and then 1000 devices before upgrading the balance of your fleet</li><li>5. Release notes are on the <a href="#">Source</a></li></ol>



	<ol style="list-style-type: none"><li>6. This release is available from <a href="#">Source</a> and available for FOTA from the GNX server</li><li>7. This release will be introduced into the factory and all new devices shipped from the factory will ship with this release starting early 2022 or sooner</li><li>8. GNX support requests should be continued to be logged with <a href="mailto:support@sierrawireless.com">support@sierrawireless.com</a>. Support request response times may vary.</li></ol>
--	---

## PRODUCT SUPPORT

WHEN IS THIS UPDATE AVAILABLE:	The release is now available for download or over-the-air updates
--------------------------------	---

## CONTACT

SUPPORT:	<a href="mailto:support@sierrawireless.com">support@sierrawireless.com</a> <a href="https://source.sierrawireless.com/">https://source.sierrawireless.com/</a>
----------	---

## REVISION HISTORY

26-Oct-2021	Initial Release
26-Oct-2021	Revisions
26-Oct-2021	More revisions
05-Nov-2021	General Availability
19-Nov-2021	Bulletin published