

ALEOS 4.4.3 Release Notes

The ALEOS 4.4.3 release is for the AirLink LS300. Refer to the ALEOS Software Configuration User Guide for update instructions.

New Feature

WAN MTU

Added an ACEmanager configuration item for setting the maximum size of IP packet sent to the cellular network.

Bug Fixes

SIM PIN

Resolved a problem where AirLink LS300 was unable to register to mobile network if the SIM PIN was enabled

I/O

Resolved an intermittent problem where the digital/analog I/O, board temperature, or power input voltage incorrectly displayed zero in ACEmanager

GPS

Resolved an issue where the GPS location was not being updated when the fix was lost

Logging

Fixed an issue that could allow unauthenticated users to access device logs

Miscellaneous

Resolved an issue where some AirLink LS300 gateways became stalled after a soft reboot