



GNX-6 External Supply Constraints and End of Sale

OVERVIEW

DATE ISSUED:	February 15, 2021
ISSUED BY:	Sierra Wireless GNX Product Management
PRODUCTS AFFECTED:	All GNX-6 External Antenna SKUs including: 1104398 1104400 1104401 1104402 1104403 1104519 1104520
FOR DISTRIBUTION TO:	All GNX Customers
SUMMARY:	<p>GNX-6 External devices (all SKUs) use components that were affected by the Japanese crystal oscillator factory fire in 2020. Sierra has sufficient components to meet our forecasted 2021 demand. If you anticipate requiring more of these SKUs than you have currently on order or forecast, please contact your account manager to discuss options.</p> <p>In addition to the supply constraints, Sierra announces these SKUs will be End of Sale as of December 31 2021. Sierra will make efforts to meet demand throughout 2021 but with the supply issues there maybe constraints. Last Time Buy and Last Time Ship will be determined on a case-by-case basis based on available stock.</p> <p>Warranty and Support terms remain unaffected.</p>

CONTACT

SUPPORT:	support@sierrawireless.com https://source.sierrawireless.com/
-----------------	---

REVISION HISTORY

15-JAN-2021	Draft Release
15-FEB-2021	Initial Release