

>> | ALEOS 4.8.1 Release Notes

ALEOS 4.8.1 is for AirLink MP70, MP70E, RV50, RV50X, GX450 and ES450 gateways.

Bug Fixes

LAN

Corrected issue preventing IP Passthrough from working on the USB and Ethernet interfaces.

Security

Ensured that Trusted IP rules and Port Filtering rules are applied before Port Forwarding rules. Please note that Port Filtering rules now apply to traffic from trusted IPs.

Resolved CVE-2016-10229: Unsafe checksum calculation for UDP traffic.

WAN/Cellular

Fixed issue where Ethernet WAN port was incorrectly being bridged to the LAN for a short period after device boot.

Fixed continuous reboot of the radio when user APN is disabled by Verizon (MC7354).

Fixed issue where brief (~1second) cellular outages resulted in Network Link state being reported as Down for ~30 seconds.

Call Manager

ALEOS will now make no additional connection attempts if Verizon throttles RTT.