



AirLink OS 5.1.77 General Availability

OVERVIEW

DATE ISSUED:	10-Dec-2024
ISSUED BY:	Sierra Wireless Product Management
PRODUCTS AFFECTED:	AirLink [®] Operating System (OS) Routers: <ul style="list-style-type: none">• RX55, XR60, XR80, XR90
FOR DISTRIBUTION TO:	All AirLink OS Customers
RELEASE DETAILS:	<p>AirLink OS 5.1.77 is General Availability. This is a major release that supersedes AirLink OS 5.0 and delivers feature enhancements, bug fixes, and security updates.</p> <p>For the AirLink OS 5.1.77 release details, refer to the release notes available on The Source.</p> <p>This release is recommended for all AirLink OS routers.</p>



PRODUCT SUPPORT

WHEN IS THIS UPDATE AVAILABLE?	AirLink OS 5.1.77 will be available from ALMS and The Source on or before 10-Dec-2024.
---------------------------------------	--

CONTACT

SUPPORT:	<p>Ask for support here:</p> <ul style="list-style-type: none">• sierrawireless.com/support <p>Sign up to the Source for product resources and subscribe to product bulletins here:</p> <ul style="list-style-type: none">• sierrawireless.com/sso/signup <p>Sign up for Security Bulletins here:</p> <ul style="list-style-type: none">• sierrawireless.com/company/iot-device-security/security-bulletins
-----------------	--

REVISION HISTORY

10-Dec-2024	Initial Release
--------------------	-----------------