



# End of Sale Announcement: MG90 US

## OVERVIEW

<b>DATE ISSUED:</b>	Nov 1, 2018
<b>ISSUED BY:</b>	Sierra Wireless Enterprise Solutions Product Management
<b>PRODUCTS AFFECTED:</b>	MG90 LTE Router
<b>ORDER CODES AFFECTED:</b>	MG90 LTE Router - <b>US</b> variant
<b>FOR DISTRIBUTION TO:</b>	General Distribution
<b>SUMMARY:</b>	<p>Sierra Wireless announces the last time buy and last time ship date for the MG90 LTE (US variant) Router. This notice contains all relevant milestones and dates for the affected products.</p> <p>The AirLink® MG90 LTE-A and the latest LTE-A Pro variants remain in production. <a href="http://www.sierrawireless.com/mg90">www.sierrawireless.com/mg90</a></p>

## PRODUCTION MILESTONES

<b>AFFECTED MODELS:</b>	MG90 LTE ( <b>US</b> variant)
<b>LAST TIME BUY:</b>	<b>30-NOV-2018</b> The product cannot be ordered from Sierra Wireless after this date.
<b>LAST TIME SHIP:</b>	<b>30-DEC-2018</b> The last possible ship date that can be requested from Sierra Wireless.
<b>REASON:</b>	Technology obsolescence. Superseded by the FirstNet Ready™ MG90 LTE Advanced Pro.

<b>OTHER MODELS:</b>	MG90 LTE-A and MG90 LTE-A Pro ( <b>Single</b> and <b>Dual Radio</b> variants)
<b>STATUS:</b>	Remain in production

## PRODUCT SUPPORT AND MAINTENANCE

<b>ACTIVE SOFTWARE MAINTENANCE PHASE:</b>	<b>FROM 1-NOV-2018 TO 31-MAR-2019</b> During this phase, device software will be actively maintained. Software releases will contain bug fixes and security patches only, no new features will be deployed. Following Active Software Maintenance the products move to Critical Software Maintenance (see below).
---	---



<b>CRITICAL SOFTWARE MAINTENANCE PHASE:</b>	<p><b>FROM 1-APR-2019 TO 31-DEC-2020</b> During this phase, new device software will be released if a Critical software issue or security vulnerability is discovered.</p> <p>A software issue is deemed to be Critical if it causes the Sierra Wireless product or service to become systemically unavailable or unresponsive, and there is no available resolution or workaround.</p> <p>A security vulnerability is deemed to be Critical if it scores 9 or 10 on the Common Vulnerability Scoring System Version 3.0 (CVSSv3) as determined by Sierra Wireless.</p>
<b>END OF SOFTWARE MAINTENANCE:</b>	<b>31-DEC-2020</b> No new device software will be released after this date.

## CONTACT

<b>SALES:</b>	<p><a href="http://www.sierrawireless.com/sales">www.sierrawireless.com/sales</a></p> <p>1-877-687-7795</p>
<b>CUSTOMER SUPPORT:</b>	<a href="http://www.sierrawireless.com/support">www.sierrawireless.com/support</a>

## REVISION HISTORY

<b>NOV 1, 2018</b>	Rev1: Initial announcement
--------------------	----------------------------

## AFFECTED PART NUMBERS

PART No.	MODEL DESCRIPTION	SUGGESTED REPLACEMENT	PART No.
1103541	MG90 LTE, US, DC	MG90 LTE-A Pro, NA, DC MG90 LTE-A, NA, DC	1103981 1102695