

CAUTION

TABLE SAW

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Spreader and anti-kickback dogs are properly positioned and functional when cutting wood.
- Dust collection system, if provided, is connected and operational.
- Keep work area clean. Foreign materials may cause poor footing
- Use proper saw blade for material being cut.
- Inspect mounting flanges for damage and proper size.
- Replace dull, cracked, or excessively fouled saw blades or blades with broken teeth.
- Use push blocks/push sticks whenever possible.
- Follow manufacturer requirements for cutting ferrous and nonferrous metals.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.

Note: Immediately report all machinery malfunctions to management