

CAUTION

Disc Sander

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Do not mix incompatible dusts (steel and aluminum).
- Never start machine unless all guards are in place, properly designed and adjusted.
- Beware of moving machinery parts.
- Keep work area clean. Foreign materials may cause poor footing.
- Dust collection system, if provided, is connected and operational.
- Avoid contact with unused portion of abrasive disk or belt above and below work table.
- Use proper abrasive disk and/or belt for material being processed.
- Replace disks if abrasive surface has rips, tears, or worn areas.
- Do not wear gloves, jewelry, or loose clothing.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Ensure that operator is properly trained and has read owners operation manual.

Note: Immediately report all machinery malfunctions to management