

CAUTION

BENCH-MOUNTED HYRAULIC POWER PRESS

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Locate operational controls a safe distance from machine.
- Keep work area clean. Foreign materials may cause poor footing.
- Use hand-feeding tools whenever possible.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- De-energize and lockout machine before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.