

## HONDA CIVIC Si & TYPE-R FD1 & FD2 (2006~2011)



### STRUT BAR



Product	Area/Type	Part No.	MSRP (USD)	Major Spec
STRUT BAR	Front OS	329 540 A	\$200	Requires clutch reservoir relocation
	Rear OS	329 541 A	\$200	Replaces OEM bar

### POWER BRACE

PROGRESSIVE EQUIPMENT <sup>®</sup>



Product	Area/Type	Part No.	MSRP (USD)	Major Spec	Re
POWER BRACE	Front Member	329 492 FM	\$200		A
	Floor Front / Side	329 492 FS	\$400		B
	Floor Rear Side	329 492 RS	\$307	(Sedan models only) requires drilling	C
	Floor Center	329 492 C	\$307	Fitment on Sedan requires drilling	D
	Rear Lower Arm	329 492 RL	\$174		E
	Rear Bulk	329 492 RB	\$194	Carpet / panel trimming required	F
	Rear End	329 492 RE	\$194	Requires OEM bumper beam removal	G
	Seat Rail	329 492 SR	\$174	Driver & passenger set	H



**CARROSSER Co. Ltd**  
1664-1 Shinbo-cho Takasaki-shi  
Gunma-ken 370-0018 JAPAN  
Tel: (+81) 27-352-3578 • Fax: (+81) 27-352-1919  
<http://www.cusco.co.jp>  
[oversea@cusco.co.jp](mailto:oversea@cusco.co.jp)

**CUSCO USA Inc.**  
16631 Gemini Lane  
Huntington Beach, CA 92647 USA  
Tel: (714) 907-0033 • Fax: (714) 369-8142  
<http://www.cuscousainc.com>  
[info@cuscousainc.com](mailto:info@cuscousainc.com)

