

This list only contains POS terminal solutions that have been tested and verified by NETS ITverification since 01.01.2018. For any questions related to the solution validity, function, acceptance etc., please contact the Supplier/owner.

<i>Supplier /PSP</i>	<i>Manufa ctor</i>	<i>Model</i>	<i>Application</i>	<i>Pin Y/N</i>	<i>Note</i>
NETS A/S:					
ID-2659	Ingenico	iCT220E/ iCT220EG/ iWL220G	PSAM Telium2 2.2.2.5 (414-5002)	Y	
ID-2660	Ingenico	iCT220EG+iPP350, iCT250E+iPP350	PSAM Telium2 2.2.2.5 (414-5002)	Y	(1)
ID-2661	Ingenico	iCT250E/ iCT250EG/ iWL250G/ iWL250B/ iWL250	PSAM Telium2 2.2.2.5 (414-5002)	Y	
ID-2662	Ingenico	iPP350	PSAM Telium2 2.2.2.5 (414- 5002),Combridge	Y	(1)
ID-2698	Ingenico	iPP350	PSAM Telium2 2.2.2.5 (414-5002), SIL	Y	(1)
ID-2742	Ingenico	iPP350	PSAM Telium2, 3.0.0.8 (SIL)	Y	(1)
ID-2743	Ingenico	iPP350	PSAM Telium2, 3.0.0.8 (Combrigde)	Y	(1)
ID-2744	Ingenico	iCT250E/ iCT250EG/ iWL250G/ iWL250B/ iWL250	PSAM Telium2, 3.0.0.8	Y	
ID-2745	Ingenico	iCT220EG/iPP350, iCT250E/iPP350	PSAM Telium2, 3.0.0.8	Y	(1)
ID-2780	Ingenico	iPP350	PSAM Telium2, 3.1.0.7 (SIL)	Y	(1)
ID-2779	Ingenico	iPP350	PSAM Telium2, 3.1.0.7 (Combrigde)	Y	(1)
ID-2778	Ingenico	iCT250E/ iCT250EG/ iWL250G/ iWL250B/ iWL250	PSAM Telium2, 3.1.0.7	Y	
ID-2777	Ingenico	iCT220EG/iPP350, iCT250E/iPP350	PSAM Telium2, 3.1.0.7	Y	(1)
ID-2670	Ingenico	iWL286	SDI Nordic v.5.1	Y	
ID-2686	Ingenico	IUC180B+IUR250	Viking 6.12	N	
ID-2687	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.12	Y	
ID-2688	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/ IWL255G/IMP550/IMP627/IMP657	Viking 6.12	Y	(1)
ID-2689	Ingenico	IUC180B+IUR250	Viking 6.12	N	
ID-2690	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.12	Y	
ID-2691	Ingenico	IPP350/ICT220/ICT250/IWL220/ IWL250/IWL255G	Viking 6.12	Y	(1)
ID-2692	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250 /IWL255G/IMP550/IMP627/IMP657	Viking 6.12	Y	(1)

ID-2746	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250 /IWL255G/IMP550/IMP627/IMP657	Viking 6.23	Y	(1)
ID-2747	Ingenico	IPP350/ICT220/ICT250/IWL220/ IWL250/IWL255G	Viking 6.23	Y	(1)
ID-2748	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/ IWL255G/IMP550/IMP627/IMP657	Viking 6.23	Y	(1)
ID-2749	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.23	Y	
ID-2750	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.23	Y	
ID-2751	Ingenico	IUC180B+IUR250	Viking 6.23	Y	
ID-2752	Ingenico	IUC180B+IUR250	Viking 6.23	N	
ID-2776	Ingenico	Lane3000/Move3500/Desk3500	Viking7.0	Y	

ID-2825	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 6.4	Y	(1)
ID-2826	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL25 5G	Viking 6.4	Y	(1)
ID-2827	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 6.4	Y	(1)
ID-2828	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.4	Y	
ID-2829	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.4	Y	
ID-2830	Ingenico	IUC180B+IUR250	Viking 6.4	N	
ID-2831	Ingenico	IUC180B+IUR250	Viking 6.4	N	
ID-2788	Ingenico	Lane3000/Move3500/Desk3500	Viking7.0	Y	
ID-2864	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 6.5	Y	(1)
ID-2865	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 6.5	Y	(1)
ID-2866	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.5	Y	
ID-2867	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL25 5G	Viking 6.5	Y	(1)
ID-2868	Ingenico	IUC180B+IUR250	Viking 6.5	N	
ID-2869	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 6.5	Y	(1)
ID-2870	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 6.5	Y	(1)
ID-2871	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.5	Y	
ID-2872	Ingenico	IUC180B+IUR250	Viking 6.5	N	
ID-2893	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0	Y	(1)
ID-2894	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL25 5G	Viking 8.0	Y	(1)
ID-2895	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0	Y	
ID-2896	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0	Y	(1)
ID-2897	Ingenico	IUC150 + IUR250 + IUP250	Viking 8.0	Y	
ID-2898	Ingenico	IUC180B+IUR250	Viking 8.0	N	

ID-2899	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0	Y	(1)
ID-2900	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0	Y	
ID-2901	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0	Y	(1)
ID-2902	Ingenico	IUC150 + IUR250 + IUP250	Viking 8.0	Y	
ID-2903	Ingenico	IUC180B+IUR250	Viking 8.0	N	
ID-2943	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.3	Y	(1)
ID-2944	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL25 5G	Viking 8.0.3	Y	(1)
ID-2945	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0.3	Y	
ID-2946	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.3	Y	(1)
ID-2947	Ingenico	IUC150 + IUR250 + IUP250	Viking 8.0.3	Y	
ID-2948	Ingenico	IUC180B+IUR250	Viking 8.0.3	N	
ID-2949	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.3	Y	(1)
ID-2950	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0.3	Y	
ID-2951	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.3	Y	(1)
ID-2952	Ingenico	IUC150 + IUR250 + IUP250	Viking 8.0.3	Y	
ID-2953	Ingenico	IUC180B+IUR250	Viking 8.0.3	N	
ID-2995	Ingenico	IUC180B+IUR250	Viking 8.0.6	N	
ID-2994	Ingenico	IUC150B + IUR250 + IUP250	Viking 8.0.6	Y	
ID-2993	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.6	Y	(1)

ID-2992	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0.6	Y	
ID-2991	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL22	Viking 8.0.6	Y	(1)
ID-2990	Ingenico	IUC180B+IUR25	Viking 8.0.6		
ID-2989	Ingenico	IUC150B + IUR250 + IUP250	Viking 8.0.6	Y	
ID-2988	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.6	Y	(1)
ID-2987	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0.6	Y	
ID-2986	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL25 5G	Viking 8.0.6	Y	(1)
ID-2985	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.6	Y	(1)
ID-3048	Ingenico	IUC150B + IUR250 + IUP250	Viking 8.0.8	Y	
ID-3067	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220 - Ver. Viking 8.2.0	Viking 8.2.0	Y	(1)
ID-3082	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.2.5	Y	
ID-3060	Ingenico	Self 4000	Viking 8.3.0	Y	
ID-3096	Ingenico	Self 4000	Viking 1.01.0	Y	

ID-3095	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 1.01.0	Y	
ID-3117	Ingenico	Self 4000	Viking 2.0	Y	
ID-3116	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 2.0	Y	
ID-3146	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.2.6	Y	
ID-3148	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 2.001	Y	
ID-3149	Ingenico	Self 4000	Viking 2.001	Y	
ID-3156	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 2.01	Y	
ID-3157	Ingenico	Self 4000	Viking 2.01	Y	
ID-3160	Ingenico	Lane3000/Lane5000	Viking 8.0	Y	
ID-3167	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 2.02	Y	
ID-3168	Ingenico	Self/4000	Viking 2.02	Y	
ID-3205	Iphone	Iphone X	My payment app 8.0.0	Y	
ID-3093	Ingenico	Lane3000/Lane5000	Onepa 7.0	Y	
ID-3118	Ingenico	Lane3000/Lane5000	Onepa 7.1	Y	
ID-3142	Ingenico	Lane3000/Lane5000	Onepa 7.1 Build 02	Y	
ID-3152	Ingenico	Self 4000	OnePA 8.0	Y	
ID-3199	Ingenico	Self 2000	OnePA 8.2	Y	
ID-3200	Ingenico	Lane3000/Lane5000	OnePA 8.2	Y	
Verifone:					
ID-3041	Verifone	P400, V400c	Engage GPA v1.1.01	Y	
N/A	Verifone	Vx680, Vx690, Vx820 and Vx520c	Version 3.7.31	y	
N/A	Atos	Yomani XR/ML, Yomani 1	Version 3.7.31	y	
N/A	Verifone	T650C, T650P, CM5P, CM5, P400+T650C, M424, M440, P630	Android GPA 3.30.3	y	
N/A	Verifone	V400M, P400, M400, V400C, E285, X10	Cobra 3.3.9	Y	
ID-3132	Verifone	P400, V400c	Engage GPA v1.2.01	Y	(3)
ID-3169	Verifone	V400m/P630/V660p/P400/M400/V400c/e285	Cobra 4.0.0.0	Y	
ID-3170	Verifone	P630/V660P	Android GPA 5.343	Y	
ID-3188	Verifone	UX700	Android GPA 5.340	Y	
Verifone Norway:					
ID-2640	Verifone	Vx680, Vx690, Vx820, Vx520c	paypoint 5.15	Y	

ID-2641	Atos	Yomani XR/ML, Yomani 1	paypoint 5.15	Y	
ID-2642	Atos	Xenteo Eco	paypoint 5.15	Y	
ID-2684	Atos	Xenteo ECO	5.15	Y	
ID-2905	Verifone	Vx680, Vx690, Vx820 and Vx520c	paypoint 5.15	Y	
Verifone Finland:					
ID-2910	Wordline	Verifone II	Yomani 4.0	Y	

Bambora:					
ID-2598	Ingenico	ICT250/IPP350/IWL250	SP900-201 v2	Y	
ID-2736	Ingenico	Desk5000/Move5000/Lane3000 link2500	Bambora POS 1.0	Y	
ID-3123	Ingenico	DX8000/RX5000/EX8000	Samport AX 1.0.0	Y	
N&TS					
ID-2540	Ingenico	ICT250, IPP350, IWL250	V. P2PE-Micro2, 1.0 01.68B	Y	
Circle K:					
ID-2643	Gilbarco	SPOT M7/M4	NC3 1.7.358	Y	
ID-2634	Atos	YOMANI II/ML	Statoil 17.04.06	Y	
ID-2836	Gilbarco	SPOTM7	N3 1.7.794	Y	
ID-2837	Atos	Yomani ML	Statoil 19.26.06	Y	
ID-2964	Yomani	Yomani ML	Statoil 21.02.02	y	
ID-3111	Gilbarco	SPOT M4	GVR NC3 1.9.852.0	Y	
ID-3112	Gilbarco	SPOT M7	GVR NC3 1.9.852.0	Y	
ID-3113	Atos	Yomani ML	Statoil 21.02.22	Y	
ID-3190	Yomani	RX5000, RX7000	circlek-app-main Version: 00.01.00	Y	
RetailInMotion:					
ID-2650	Datecs	Bluepad 500	Datecs bluepad 500 V. 2.4.39.45	y	
Adyen:					
ID-2718	Verifone	P400/V400M/V400c/M400/V200C/E285	EVO v. 1.36	y	
ID-2719	Verifone	Vx820/Vx690/Vx680/Vx675/e355/e315	VOS v. 1.31	y	
ID-3122	Verifone	P400Plus/P200/V200c/V205c/V200t/V210/e235/V240m/e280/e285/P400/V400c/V400m/M400/M424/M440	Adyen v1 V1_96	Y	(3)
ID-3144	Castles	AMS1/S1F2/S1U2/S1E2/S1E2	Adyen v1 V1_96	Y	(3)
Dover:					
ID-2714		Crypto VGA	V. 2.x	y	
ID-2832	Verifone	P400	52.06	y	

WestPay:					
ID-2470	XAC	8006, 103	West Transaction Engine v1.22	y	
ID-2723	XAC	xCL_AP-10 / xCL_AT-100	West Payment Application 2.0.0	y	
Altapay:					
ID-2655	Pax	S920	CB2 V. 1.0	y	
ID-2672	Ingenico	ICT250	CB2 V. 1.72W	y	
ID-2700	Pax	A920	A 1.0.1	y	
Ingenico:					
ID-2812	Ingenico	Move5000	Axis cross-border EU 2.2	y	
3C Payment/Planet:					
ID-3091	PAX	IM30	Integra 1.0	Y	
ID-2935	Pax	Pax A920, Pax A930, A30, A35, A50, A77, A80, A920, A920Pro and IM30	IntegraTE 1.0	Y	
Logos Design A/S					
ID-2683	Verifone	UX100 + 300 + 400	UXL 2.0	y	
ID-2971	Verifone	UX100 + 300 + 400	UXL 2.0	y	
ID-3071	Verifone	Valina	Wilma 1.6.0	y	
Payex					
ID-2769	Ingenico	IWL250	PayEx Nordic Payment 1.0.2260	Y	
ID-2720	Ingenico	IUR250+IUP250+IUC150	PayEx Nordic Payment v1.0.2220	Y	
ID-3127	Pax	A30, A35, 920 Pro	Payex 1.2.x	Y	
TietoEvry					
ID-3086	Wincor nixdorf	Cineo 2550	Multivendor MV 22.3.0	Y	
Euronet 360 Finance Limited					
ID-3058	NCR	Selfserv 6628	EFTS 3.4	Y	
Multipay Global solutions					
N/A	Pax	A920	Carte 3.4.38	Y	
N/A	Pax	Q30	Prolin 3.2.22	Y	
Viva Wallet					
ID-3076	Ciontek	CS50	Version 5.5.0	Y	

ID-3173	Sunmi	P2Lite	T6810 V5.19.2(10545)	Y	
ID-3184	Pax	A935	V. 5.19.11	Y	
Softpay Aps					
ID-3105	Softpay	Softpay TTP	Version 2.2.0	Y	
Loomis Digital solutions AB:					
ID-3145	Pax	Pax A920 PRO, A30, A35, A50, A60, A77, A80, A800, A910, A920, A920Mini, A930	POSitive 1.00.36.5870	Y	
ID-3189	Pax	Pax A920 PRO, A30, A35, A50, A60, A77, A80, A800, A910, A920, A920Mini, A930	POSitive 1.00.36.5950	Y	
ID-3191	Pax	IM 30 POSitive 1.00.36.5960	Y	ID-3191	
Diebold Nixdorf					
ID-3133		CS2040	Proflex 4.3	Y	
Hamag A/S					
ID-3134	Cryptera	INT3520	PS 001	Y	
S5					
ID-3135	Pax	A920, A920 Pro, A35	Carte A1.2.1.1	Y	
MarketPay					
ID-3158	Pax	A35, A920Pro, A99, A8900, A50, A50S, A77, A8500	PayOnSite 2.0.2	Y	
Surfboard					
ID-3201	Iphone	Iphone X	CheckoutX 1.1.5	Y	

Notes:

- 1) iPP350 firmware must be minimum 2.2.1.7
- 2) Time limited approval, waiver granted until 31-12-2024
- 3) Time limited approval, waiver granted until 30-06-2024