


# Release Notes

## OnePA Payment Terminals



Production Version 5.0.2 | March 2021

SMURR Originated	ALMAN Checked	TPUOL Approved	Issued for Use Remarks
---------------------	------------------	-------------------	---------------------------

# Table of Contents

Section	Page
<b>1. INTRODUCTION</b> .....	<b>4</b>
<b>2. NEW FEATURES</b> .....	<b>5</b>
2.1 Release Highlights .....	5
<b>3. FIXED BUGS</b> .....	<b>5</b>

# Acronyms

The following acronyms are used throughout this document:

Acronym	Description
BAXI	BBS ActiveX Interface
ECR	Electronic Cash Register
TCP	Transmission Control Protocol
TLS	Transport Layer Security

## 1. INTRODUCTION

The purpose of this release is to introduce bug fixes. The production release version is 5.0.2.

For information or questions regarding this release, please contact your local Pre-Sales teams or Account Manager. For further information on the terminal range, please consult the user guides/quick guides on the Nets website.

The information contained in this document is confidential and only aimed at the intended recipient. The information shall not be used, published or redistributed without the prior, written consent of Nets A/S.

This release is for:

- › Lane/5000, Lane/3000
- › All markets (NO/SE/FI/DK/PL)
- › BAXI Ethernet integrated (Lane/5000, Lane/3000)

## 2. NEW FEATURES

### 2.1 *Release Highlights*

The following updates were made in this release:

- › Hotfixes

## 3. FIXED BUGS

The following incidents were resolved:

- › The sending logic for ECR communication (to avoid sending multiple messages without receiving a reply).
- › The receiving logic for ECR communication (to accept receiving multiple TCP payloads in a single message).
- › Avoiding download after every reboot in a production terminal.
- › After receiving timeout, the terminal would fail to connect to the correct TLS socket.
- › Terminal crashing when BAXI Agent service was closed.
- › Last financial result fix was not working as expected.