

Frigidaire Side-by-Side Refrigerators with Slim Ice Buckets Recall Feb. 8, 2024



Feb. 8: Frigidaire is recalling about 383,240 side-by-side refrigerators that contain an ice bucket part that can break, causing plastic pieces to fall into the ice bucket. If dispensed out of the ice bucket, these pieces pose choking and laceration hazards.

Product(s) affected: Frigidaire Side by Side Refrigerators with Slim Ice Buckets manufactured between 2015 and 2019 and sold online on Frigidaire.com and at Lowe's, Home Depot, and other retailers nationwide from Nov. 2015 - Sept. 2019. The recall applies to the following model numbers:

DGHK2355TF, DGHX2655TF, FFSC2323TS, FGSC2335TD, FGSC2335TF, FGSS2635TD, FGSS2635TE, FGSS2635TF, FGSS2635TP, FPSC2277RF, FPSC2278UF, FPSS2677RF, LFSC2324VF, LGHK2336TD, LGHK2336TF, LGHX2636TD, and LGHX2636TF

You can find the model and serial # of your Frigidaire refrigerator inside on the right side above the top shelf.

What to do if you have the product(s): Stop using the ice maker and contact Electrolux Group at (888) 377-7563, 8:30 a.m. to 8 p.m. ET Monday - Friday, for a free replacement part. You can

also email IceBucketRecall@electrolux.com or visit www.icebucketrecall.com or www.frigidaire.com for more information.