

ENGINEERING BULLETIN

Subject: PRESTIGE PA Series Obsolete Components Date: 5/8/20

Triangle Tube carried out a supply chain assessment in 2019 to ensure the long term availability of a number of components utilized in our boilers recognizing that replacement parts would be required throughout their expected lifetime.

In order to ensure continuity of supply, several changes to the components were required including the ignition components on the Prestige PA Series. Parts have been re-sourced and as a consequence when either an igniter or control module must be replaced on a Prestige PA Series boiler, these will be replaced with a kit containing the re-sourced components.

Prestige models built with these updated components will have a serial number beginning with PB. The replacement update kit includes a PB decal to affix over the PA serial number prefix on the rating label to readily identify units which have the replacement update kit installed.

In order to minimize inconvenience to our customers, the replacement update kit cost will be kept to a minimum for a time period of 24 months from release of this bulletin after which time the costs will increase to the nominal amount.

Model	Obsolete		Replacement Update Kit		
	Control Module	Igniter	Low Altitude	High Altitude	
			(Below 5,000')	(Above 5,000')	
Prestige PA80	PARKIT80	PARKIT16	PARKIT141	PARKIT151	
Prestige PA110 / Exc.	PARKIT81	PARKIT16	PARKIT142	PARKIT152	
Prestige PA155	PARKIT82	PARKIT56	PARKIT143	PARKIT153	
Prestige PA175	PARKIT83	PARKIT56	PARKIT144	PARKIT154	
Prestige PA250	PARKIT84	PARKIT56	PARKIT145	PARKIT155	
Prestige PA299 V2*	PARKIT97	PARKIT16	PARKIT146	PARKIT156	
Prestige PA399 V2*	PARKIT98	PARKIT16	PARKIT147	PARKIT157	
Prestige PA299 V1*	PARKIT97	PARKIT16	PARKIT148	PARKIT158	
Prestige PA399 V1*	PARKIT98	PARKIT16	PARKIT149	PARKIT159	

^{*} PA299 & PA399 Versions – V1 models were built with a one piece blower and venturi but some may have been updated to V2. V2 models beginning with serial number PA117000 were built with separate blower and venturi. See PRESTIGE Service Parts Kit Engineering Bulletin (10/24/18) for more information.

Triangle Tube - 1240 Forest Parkway, Suite 100 - West Deptford, NJ 08066 Tel: 856 228 8881 - Fax: 856 228 3584 - e-mail: info@triangletube.com



In the event that individual parts are required after installing a replacement update kit, reference the table below for replacement part numbers.

Component Part Numbers of Replacement Update Kit

Model	Control Module	Control Module	Igniter	Spark	Ignition
	Low Altitude	High Altitude		Generator	Cable
	(Below 5,000')	(Above 5,000')			
Prestige PA80	PARKIT111**	PARKIT121**	PARKIT130	PARKIT133	PARKIT134
Prestige PA110 / Exc.	PARKIT112**	PARKIT122**	PARKIT130	PARKIT133	PARKIT134
Prestige PA155	PARKIT113**	PARKIT123**	PARKIT131	PARKIT133	PARKIT134
Prestige PA175	PARKIT114**	PARKIT124**	PARKIT131	PARKIT133	PARKIT134
Prestige PA250	PARKIT115**	PARKIT125**	PARKIT131	PARKIT133	PARKIT134
Prestige PA299 V2*	PARKIT116**	PARKIT126**	PARKIT132	PARKIT133	PARKIT134
Prestige PA399 V2*	PARKIT117**	PARKIT127**	PARKIT132	PARKIT133	PARKIT134
Prestige PA299 V1*	PARKIT118**	PARKIT128**	PARKIT132	PARKIT133	PARKIT134
Prestige PA399 V1*	PARKIT119**	PARKIT129**	PARKIT132	PARKIT133	PARKIT134

^{*} PA299 & PA399 Versions – V1 models were built with a one piece blower and venturi but some may have been updated to V2. V2 models beginning with serial number PA117000 were built with separate blower and venturi. See PRESTIGE Service Parts Kit Engineering Bulletin (10/24/18) for more information.

Please contact technical support at (856) 228-8881 x575 with any questions regarding this issue.

^{**} Universal Control Module (PARKIT102) can be substituted for specific model control module if display software version is at least 4.03 and rating plate states the appliance code.