



Excavator Inspection Checklist

15 Mar 2024 / Reid Tromp

Complete

Score	9 / 11 (81.82%)	Flagged items	1	Actions	1
Site conducted	Marked as 'my site is not listed here'				
Conducted on	15 Mar 2024 08:20 PST				
Prepared by	Reid Tromp				
Location	1401 Wall Ave, Ogden, Utah				
Excavator ID No.	20194877				

Flagged items & Actions

1 flagged, 1 action

Flagged items

1 flagged, 1 action

Engine and Cooling System

No humming or vibration when you start the engine?

No

very minimal humming heard

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 15 Mar 2024 12:00 PST | Created by: SafetyCulture Staff

very minimal humming heard

Call Gary from the maintenance team for additional checks

Other actions

0 actions

No cracks, welds, or signs of damage on the frame?

No

prominent scratches found



Photo 1

No wear and misalignment in boom, arm, and bucket?

Yes

Hydraulic System

2 / 2 (100%)

Hydraulic fluid level within the recommended range?

Yes

No any leaks or damages to hoses, fittings, and cylinders?

Yes

Engine and Cooling System

1 flagged, 1 action, 2 / 3 (66.67%)

Engine oil level within the recommended range?

Yes

No humming or vibration when you start the engine?

No

very minimal humming heard

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 15 Mar 2024 12:00 PST | Created by: SafetyCulture Staff

very minimal humming heard

Call Gary from the maintenance team for additional checks

No leaks or wear in the radiator, hoses, or belts?

Yes

Electrical System

2 / 2 (100%)

Working lights, gauges, and switches?

Yes

No damaged wiring or loose connection?

Yes

Undercarriage

2 / 2 (100%)

Proper tracks tension?

Yes

No wears in rollers, idlers, and sprockets?

Yes

Sign-Off

Name

Reid Tromp

Reid Tromp
14 May 2024 08:28 PST

Media summary



Photo 1