

1970 MG MGB Mk II

2dr Roadster . 4-cyl. 1798cc/92hp 2x1bbl SU

#1 Concours condition

\$34,500

▼ -3.1%

#2 Excellent condition

\$21,100

▲ +0.5%

#3 Good condition


\$9,800*

▼ -2%

#4 Fair condition

\$4,500

▼ -2.2%



NOTE: The chart displays price changes for the last year.

Model description

Triumph-dominated British Leyland started to exert its influence on the 1970 MGB, even as it promoted Giovanni Michelotti's Triumph TR6 roadster, brilliantly face-lifted from the dated TR5/TR250.

First thing to go from the MGB was the classic vertical barred grille, replaced by a recessed grille with a chrome surround and new colored central badge. The aluminum hood was now steel but the hood center hood molding remained, though the badge was no longer below it. The rear bumper was split with the license plate between the halves – an experiment which lasted only one year. U.S. cars had rubber inserts in the overriders.

Inside, the three-spoked steering wheel was smaller and new woven vinyl reclining seats replaced leather surfaces. U.S. cars had headrests, which would be extended to other markets later and the choke was now a "T" lever. MGB Mk II color schemes all featured black vinyl seating without contrasting piping, and all had black top, boot cover and tonneau.

Sales continued to increase with 20,072 MGB roadsters finding buyers for the model year. As usual most (15,998) came to the U.S. with 4157 at the end of 1969 and 11,841 in the spring and summer of 1970. The UK bought 2410 roadsters. MGB GT sales didn't have quite the same disparity, with 11,380 GTs sold and 6601 coming to the U.S. compared to 3611 sold in the UK.

Some new colors were introduced. Available MGB colors included Black (special order), Antelope Beige, Bermuda Blue, Blue Royale, Dark British Racing Green, Flame Red, Bronze Yellow, Pale Primrose Yellow and Glacier White. Grampian Gray, Sandy Beige and Metallic Golden Beige and Riviera Silver Blue were discontinued and Antelope Beige and Bermuda Blue were GT-only colors. This was the last year for Dark British Racing Green. Mk II color schemes featured black seating without contrasting piping, and all had black top, boot cover and tonneau.

*Please note: All prices shown here are based on various data sources, as detailed in [About Our Prices](#). For all Hagerty clients: The values shown do not imply coverage in this amount. In the event of a claim, the Guaranteed Value(s)® on your policy declarations page is the amount your vehicle(s) is covered for, even if the value displayed here is different. If you would like to discuss your policy, please call us at 877-922-3391.

Body styles

2dr Roadster

Engine types

4-cyl. 1798cc/92hp 2x1bbl SU

1970-1974 MG MGB stats

Highest sale	Lowest sale	Most recent sale	Sales
\$88,521	\$624	\$6,510	767

Vehicle's condition classification**#1. Concours**

#1 vehicles are the best in the world. Imagine the best vehicle, in the right colors, driving onto the lawn at the finest concours. Perfectly clean, the vehicle has been groomed down to the tire treads. Painted and chromed surfaces are mirror-like. Dust and dirt are banned, and materials used are correct and superbly fitted.

#2. Excellent

#2 vehicles could win a local or regional show. They might even be former #1 vehicles that have been driven or have aged. Seasoned observers will have to look closely for flaws but will be able to find some. The paint, chrome, glass and finishes will all appear as excellent. The vehicle drives as a new vehicle of its era would.

#3. Good

#3 vehicles drive and run well but are not used for daily transportation. The casual passerby will not find any visual flaws, but these vehicles might have some incorrect parts. #3 vehicles could possess some, but not all, of the issues of a #4 vehicle, but they will be balanced by other factors such as fresh paint or a new, correct interior.

#4. Fair

#4 vehicles are daily drivers, with flaws visible to the naked eye. The chrome might have pitting, the windshield might be chipped and perhaps the body has a minor dent. Imperfect paintwork, split seams or a cracked dash might be present. No major parts are missing, but there might be non-stock additions. A #4 vehicle can also be a deteriorated restoration.