Labor: \$0.00

Labor: \$431.83

174.44

BAR #: ARD00186820

22681 Granite Way Laguna Hills, CA 92653 Phone: 949-770-2421 FAX: 949-770-2726 200008177 Order Date 07/29/14 09:49 am Closed/Paid: 08/05/14 08:12 am

Competent Motorsport

895 Dove St. Ste 300

NEWPORT BEACH, CA 92660

03 PORSCHE 996 Turbo black

Invoice No.

113093 Mi.Last in 1/6/2021 Lic: 6DMS514/CA 6Cyl 3.6 Eng Quotes

1 07/29/14 09:56am 0.00 Competent Motors in person.

Job01 Vehicle inspection

Inspect vehicle, compile list of required repairs

Job Subtotal: \$0.00 Status: Completed

Job02 Check Wheel Bearings

Replace right front wheel bearing

999-053-054-05 Wheel bearing-S 102.00 102.00 1.0@ 102.00 =\$

Job Subtotal: \$533.83 Status: Completed

Job03 Check Air conditioning

Labor: \$370.14

Recommend replace Receiver Drier

944-573-143-01 Receiver drier-S 1.0@ 73.24 =\$ 73.24 999-707-434-41 11.20 A/C O ring-N 4.0@ 2.80 =\$ R134AFREON FREON-N 30.00 =\$ 90.00 3.0@

Job Subtotal: \$544.58

Status: Completed

Job04 996 - Oil service Labor: \$154.38

Oil and filter change, vehicle inspection.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) \_

Order Date 07/29/14 09:49 am Closed/Paid: 08/05/14 08:12 am

BAR #: ARD00186820 22681 Granite Way Laguna Hills, CA 92653 Phone: 949-770-2421 FAX: 949-770-2726

Invoice No. 200008177

Job04 996 - Oil service

996-107-225-53 5W-40 04632227	oil filter OX128/1D-N syntec-N 22 x 27 Sealing Ring-N	1.0 @ 9.0 @ 1.0 @	19.73 =\$ 12.55 =\$ 2.70 =\$	19.73 112.95 2.70	135.38	
Status: Completed			Job Subtotal: \$289.76			
Job05 Check Brake Pads		Labor: \$123.38				
Replace front brake	pads and sensors					

996-351-949-12

Brake pads front-N 1.0 @ 298.38 =\$ 996-612-365-00 Sensor brake pad-N 2.0@

298.38 21.15 =\$ 42.30

340.68

Job Subtotal: \$464.06

Status: Completed

Recommendations: Recommend trans service

Brakes: Front 90% - Rear 95%

Payments to VISION motorsports inc.	Cost Summary	
Status: Closed Work Order Payments: \$1,896.43 1 08/05/14 1896.43 Visa	Labor Parts Haz Waste Subtotal Tax Total Payments Bal Due	1079.73 752.50 4.00 1836.23 60.20 \$1896.43 1896.43 0.00

Thank you for choosing VISION motorsports inc.

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.