



34th Street Garage


2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

Invoice for RO #7154

Posted Date: 01/26/09 at 05:00 AM MST

Client: CARLA KOTILA

Vehicle: 1991 Honda CRX Base



1991 Honda CRX Base 1.5L 4Cyl GAS D15B2
Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 131655 / Out: 131655

RO # 7154
Save Parts: No

1 - Shop Supplies

Part: Shop Supplies

✓ Approved on 01/26/09 at 05:00 AM MST

\$6.75

2 - Comment: CRANKS - NO START

✓ Approved on 01/26/09 at 05:00 AM MST

0

0

3 - INCLUDES REPLACING OIL FILTER AND UP TO

✓ Approved on 01/26/09 at 05:00 AM MST

0

0

4 - Lube, Oil & Filter

Labor: Lube, Oil & Filter

✓ Approved on 01/26/09 at 05:00 AM MST

\$34.95

5 - OIL FILTER DISPOSAL FEE

✓ Approved on 01/26/09 at 05:00 AM MST

0

0

6 - Oil Filter

Part: Oil Filter

✓ Approved on 01/26/09 at 05:00 AM MST

0

0

7 - Bulk Oil

Part: Bulk Oil

✓ Approved on 01/26/09 at 05:00 AM MST

0

0

8 - SAFETY INSPECTION

✓ Approved on 01/26/09 at 05:00 AM MST

0

0

9 - REMOVE & REPLACE ELECTRONIC IGNITION CONTROL UNIT

Labor: REMOVE & REPLACE ELECTRONIC IGNITION CONTROL UNIT

✓ Approved on 01/26/09 at 05:00 AM MST

\$64.00

10 - 5 QTS OF ENGINE OIL.

✓ Approved on 01/26/09 at 05:00 AM MST

0

0

11 - SCOPE CHECK FOR NO START

Labor: SCOPE CHECK FOR NO START

✓ Approved on 01/26/09 at 05:00 AM MST

\$80.00

12 - IGN CONTROL MOD/UNIT

Part: IGN CONTROL MOD/UNIT

✓ Approved on 01/26/09 at 05:00 AM MST

\$210.11

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____

Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

X _____

Total Jobs:	\$395.81
Total Fees:	\$0.00
Subtotal:	\$395.81
Taxes:	\$36.16
Grand Total:	\$432.97
BALANCE DUE:	\$0.00

✓ PAID




34th Street Garage
2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

Invoice for RO #20908

Posted Date: 06/13/16 at 07:00 AM MDT

Client: CARLA KOTILA

Vehicle: 1991 Honda CRX Base



1991 Honda CRX Base 1.5L 4Cyl GAS D15B2
Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 161638 / Out: 161638

RO # 20908
Save Parts: No

1 - Engine Mount-Front

Part: Engine Mount-Front

✓ Approved on 06/13/16 at 07:00 AM MDT

\$32.35

2 - Synthetic Blend Motor Oil

Part: Synthetic Blend Motor Oil

✓ Approved on 06/13/16 at 07:00 AM MDT

\$24.95

3 - TRANSMISSION FLUID 10W30

Part: TRANSMISSION FLUID 10W30

✓ Approved on 06/13/16 at 07:00 AM MDT

\$19.50

4 - Clutch Kit

Part: Clutch Kit

✓ Approved on 06/13/16 at 07:00 AM MDT

\$284.70

5 CLUTCH AND FLYWHEEL (STD TRANS) - Remove & Replace - FWD - [Includes: R&I Transaxle and Clutch.] PLUS REMOVE AND REPLACE TROW OUT RETAINER SPRING AND FRONT MOUNT

Labor: CLUTCH AND FLYWHEEL (STD TRANS) - Remove & Replace - FWD - [Includes: R&I Transaxle and Clutch.] PLUS REMOVE AND REPLACE TROW OUT RETAINER SPRING AND FRONT MOUNT

✓ Approved on 06/13/16 at 07:00 AM MDT

\$690.00

6 - Lube, oil, and filter

Labor: Lubricate and check chassis. Change oil and oil filter. Check air filter and breather filter. Check all fluid levels and tire pressures. Preform basic safety inspection. Road test vehicle.

✓ Approved on 06/13/16 at 07:00 AM MDT

0

0

7 - Flywheel

Part: Flywheel

✓ Approved on 06/13/16 at 07:00 AM MDT

\$123.08

8 - Rel. Brg. Retain. Spring

Part: Rel. Brg. Retain. Spring

✓ Approved on 06/13/16 at 07:00 AM MDT

\$13.94

9 - OIL FILTER

Part: OIL FILTER

✓ Approved on 06/13/16 at 07:00 AM MDT

\$15.00

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____

Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

X _____

Total Jobs:	\$1,203.52
Total Fees:	\$0.00
Subtotal:	\$1,203.52
Taxes:	\$118.50
Grand Total:	\$1,352.83
BALANCE DUE:	\$0.00

✓ PAID




34th Street Garage

2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

Invoice for RO #37297

Service Advisor: KAI BAERD
Posted Date: 01/09/23 at 06:02 PM MST
Client: CARLA KOTILA
Vehicle: 1991 Honda CRX Base



1991 Honda CRX Base 1.5L 4Cyl GAS D15B2
Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 177638 / Out: 177638

RO # 37297
Time-In: 01/05/23 at 04:02 PM MST
Save Parts: No

Client Concerns

lof, b2b waiting in village. CHECK SEAT BELT OPERATION

DRIFTS TO THE LEFT

1 - FULL SERVICE OIL CHANGE 5W30 BLEND

Tech: A HYATT

Note: FULL SERVICE OIL CHANGE INCLUDES:
REPLACE ENGINE OIL WITH SYNTHETIC BLEND ENGINE OIL (UP TO 5QTS)
REPLACE OIL FILTER
LUBRICATE CHASSIS
VEHICLE INSPECTION
INSPECT FLUIDS

Labor: FULL SERVICE OIL CHANGE 5W30 BLEND
Parts: 5W30 MOTOR OIL
OE HONDA FILTER

✓ Approved on 01/06/23 at 09:06 AM MST

Subtotal \$55.16 + est. Tax \$5.65

\$60.81

2 - BUMPER TO BUMPER INSPECTION

Tech: A HYATT

Note: BRAKE INSPECTION NOTES:
FRONT: BRAKE PAD LIFE ___60%, BRAKE ROTOR SIZE ___OK___,
REAR: BRAKE PAD/SHOE LIFE ___50%, BRAKE DRUM SIZE ___OK___,
BRAKE FLUID CONDITION ___NEEDS FLUSH___, BRAKE CALIPERS ___OK___, WHEEL CYLINDERS ___LEAKING - NEEDS REPLACEMENT___
ABS: NO
FRONT ROTORS VENTED: YES
ELECTRONIC PARKING BRAKE: NO
TIRE SIZE: P 175/70R13_ LOAD RANGE ___82_ SPEED RATING ___T___

Labor: BUMPER TO BUMPER INSPECTION

✓ Approved on 01/06/23 at 09:06 AM MST

Subtotal \$59.95 + est. Tax \$6.14

\$66.09

3 - WHEEL CYLINDERS - REPLACE

Tech: A HYATT

Note: REMOVE AND REPLACE BOTH BRAKE DRUM WHEEL CYLINDERS. TEST DRIVE AND VERIFY CORRECT OPERATION
(WILL REQUIRE A BRAKE SYSTEM FLUSH WITH WHEEL CYLINDER REPLACEMENT)

Labor: WHEEL CYLINDERS - REPLACE
Parts: BRAKE CLEAN
Drum Brake Wheel Cylinder
Drum Brake Wheel Cylinder

✓ Approved on 01/06/23 at 03:16 PM MST

Subtotal \$431.23 + est. Tax \$44.20

\$475.43

4 - BRAKE HOSE, FRONT and REAR - REPLACE

Tech: A HYATT

Note: INCLUDES REPLACING FRONT BRAKE FLEX HOSE AND BLEEDING AIR FROM SYSTEM. ROAD-TEST VEHICLE / VERIFY REPAIR

Labor: BRAKE HOSE, FRONT and REAR - REPLACE
Parts: Brake Hydraulic Hoses
Brake Hydraulic Hoses
Brake Hydraulic Hoses

✓ Approved on 01/06/23 at 03:16 PM MST

Subtotal \$434.04 + est. Tax \$44.49

\$478.53

5 - BRAKE SYSTEM FLUSH DOT3

Tech: A HYATT

Note: INCLUDES FLUSHING OLD BRAKE FLUID FROM BRAKE SYSTEM AND REPLACING WITH VEHICLE SPECIFIED BRAKE FLUID.

Labor: BRAKE SYSTEM FLUSH DOT3
Parts: DOT3 SYN BRAKE FLUID
PARTS CLEANER

✓ Approved on 01/06/23 at 03:16 PM MST

Subtotal \$132.98 + est. Tax \$13.63

\$146.61**6 - LIGHT BULB - REPLACE**

Tech: A HYATT

Note:
REPLACE BURNED OUT LIGHT BULB(S)

Labor: LIGHT BULB - REPLACE
Part: LIGHT BULB

✓ Approved on 01/06/23 at 03:16 PM MST

Subtotal \$26.49 + est. Tax \$2.72

\$29.21**7 - REVERSE LIGHT BULB(S) - REPLACE**

Tech: A HYATT

Labor: REVERSE LIGHT BULB(S) - REPLACE
Part: BULB

✓ Approved on 01/06/23 at 03:17 PM MST

Subtotal \$27.98 + est. Tax \$2.87

\$30.85**RO Fees**

Fees: SHOP SUPPLIES \$40.87
ENVIROMENTAL \$5.00

Subtotal

\$45.87

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____
Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

Total Jobs: \$1,167.83
Total Fees: \$45.87
Discounts: -\$20.00
Subtotal: \$1,193.70
Taxes: \$122.35
Grand Total: \$1,316.05
BALANCE DUE: \$0.00

X

✓ PAID

Payment History					Payment Signature
01/09/23	CARLA KOTILA	\$1,316.05	Credit Card Payment	Mastercard****	Mastercard

Declined Jobs:

1 - FUEL INJECTION SERVICE		
✗ Declined on 01/06/23 at 03:16 PM MST	Subtotal \$250.89 + est. Tax \$25.72	\$276.61
2 - STRUT, FRONT - REPLACE		
Note: REMOVE AND REPLACE FRONT SHOCK ABSORBERS OR STRUTS. UPON REMOVAL, INSPECT MOUNTS / BUSHINGS FOR WEAR, REPLACE AS NECESSARY. ROAD-TEST VEHICLE. (INCLUDES TIME TO TRANSFER NECESSARY PARTS)		
✗ Declined on 01/06/23 at 03:16 PM MST	Subtotal \$918.98 + est. Tax \$94.20	\$1,013.18
3 - STRUT, REAR - REPLACE		
Note: REMOVE AND REPLACE REAR SHOCK ABSORBERS OR STRUTS. UPON REMOVAL, INSPECT MOUNTS/BUSHINGS FOR WEAR, REPLACE AS NECESSARY. ROAD-TEST VEHICLE. (INCLUDES TIME TO TRANSFER NECESSARY PARTS)		
✗ Declined on 01/06/23 at 03:16 PM MST	Subtotal \$829.72 + est. Tax \$85.05	\$914.77
4 - ALIGNMENT		
Note: SET VEHICLE TO SPEC'S		
✗ Declined on 01/06/23 at 03:16 PM MST	Subtotal \$179.95 + est. Tax \$18.44	\$198.39



34th Street Garage

2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com


Invoice for RO #39062

Service Advisor: Dylan Heckett

Posted Date: 07/20/23 at 01:19 PM MDT

Client: CARLA KOTILA

Vehicle: 1991 Honda CRX Base



1991 Honda CRX Base 1.5L 4Cyl GAS D15B2
Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 177852 / Out: 177852

RO # 39062
Time-In: 07/12/23 at 02:22 PM MDT
Promised Time-Out: 07/14/23 at 06:00 PM MDT
Save Parts: No

Client Concerns

BRAKE PEDAL DROPS TO FLOOR WHILE STOPPED - INTERMITTENTLY

1 - BRAKE INSPECTION & DIAGNOSE

Tech: G WALLACE

Note: BRAKE PEDAL DROPS TO FLOOR WHILE STOPPED - INTERMITTENTLY

FRONT: BRAKE PAD LIFE ___6___MM/%, BRAKE ROTOR SIZE ___GOOD FOR NOW REPLACE WHEN TIME TO DO PADS___,

REAR: BRAKE SHOE LIFE ___4___MM/%, /DRUM SIZE_GOOD

BRAKE FLUID CONDITION___GOOD___%, BRAKE CALIPERS___GOOD___, WHEEL CYLINDERS___GOOD___

ABS: NO

FRONT ROTORS VENTED: YES

REAR ROTORS VENTED: NO

ELECTRONIC PARKING BRAKE: NO

Labor: BRAKE INSPECTION

✓ Approved on 07/12/23 at 02:23 PM MDT

Subtotal \$100.00 + est. Tax \$10.25

\$110.25

2 - COURTESY INSPECTION

Tech: G WALLACE

Note: See Report

Labor: COURTESY INSPECTION

✓ Approved on 07/12/23 at 02:32 PM MDT

0

0

3 - BRAKE MASTER CYLINDER - REPLACE

Tech: G WALLACE

Note: REMOVE AND REPLACE BRAKE MASTER CYLINDER. INSPECT ASSOCIATED COMPONENTS, AND RE-ASSEMBLE.
BLEED SYSTEM OF AIR, ROAD-TEST VEHICLE/VERIFY REPAIR.

Labor: BRAKE MASTER CYLINDER - REPLACE

Parts: DOT3 SYN BRAKE FLUID

PARTS CLEANER

Brake Master Cylinder

✓ Approved on 07/19/23 at 05:36 PM MDT

Subtotal \$718.59 + est. Tax \$73.66

\$792.25

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____

Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

Total Jobs: \$818.59

Total Fees: \$0.00

Subtotal: **\$818.59**

Taxes: \$83.91

Grand Total: **\$902.50**

BALANCE DUE: **\$0.00**

X

✓ PAID

Payment History					Payment Signature
07/20/23	CARLA KOTILA	\$902.50	Credit Card Payment	Mastercard****	Mastercard



34th Street Garage

2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

RO #40799

Service Advisor: KAI BAERD

Posted Date: 01/16/24 at 04:45 PM MST

Client: CARLA KOTILA

Vehicle: 1991 Honda CRX Base

1991 Honda CRX Base 1.5L 4Cyl GAS D15B2 Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 178130 / Out: 178130

RO # 40799
Save Parts: No

Client Concerns

LOF - B2B - VEHICLE HAS A KILL SWITCH - SILVER TOGGLE SWITCH LEFT SIDE OF STEERING WHEEL UNDER THE DASHBOARD

Inspection Rating Key:

😊 Checked & Okay ⚠ Requires Attention Soon ✖ Requires Immediate Attention — Not Applicable

BUMPER TO BUMPER INSPECTION

TECH: GABRIEL WALLACE

😊 ⚠ ✖ — ROAD TEST

✅ ☐ ☐ ☐ ☐ NOISE Finding:

✅ ☐ ☐ ☐ ☐ VIBRATION Finding:

😊 ⚠ ✖ — WARNING / DASH LIGHTS

✅ ☐ ☐ ☐ ☐ CHECK ENGINE LIGHT Finding:

✅ ☐ ☐ ☐ ☐ ABS / TRACTION LIGHT Finding:

✅ ☐ ☐ ☐ ☐ AIR BAG LIGHT Finding:

✅ ☐ ☐ ☐ ☐ TPMS LIGHT Finding:

✅ ☐ ☐ ☐ ☐ MAINTENANCE LIGHT Finding:

😊 ⚠ ✖ — EXTERIOR LIGHTING

✅ ☐ ☐ ☐ ☐ HEADLIGHTS Finding:

✅ ☐ ☐ ☐ ☐ BRAKE LIGHTS Finding:

✅ ☐ ☐ ☐ ☐ TURN SIGNAL LIGHTS Finding:

✅ ☐ ☐ ☐ ☐ LICENSE PLATE LIGHTS Finding:

☐ ☐ ☒ ☐ REVERSE LIGHTS Finding: No reverse lights

☐ ☐ ☒ ☐ PARK / RUNNING LIGHTS Finding: driver rear side marker light out

😊 ⚠ ✖ — WINDSHIELD


✅ ☐ ☐ ☐ ☐ NOTES FOR OTHER GLASS Finding:

😊 ⚠ ✖ — UNDER HOOD FLUIDS

✅ ☐ ☐ ☐ ☐ ENGINE OIL Finding:

✅ ☐ ☐ ☐ ☐ BRAKE FLUID Finding:

☐ ☒ ☐ ☐	TRANSMISSION FLUID (IF EASILY ACCESSABLE)	Finding: Potential leak
☐ ☒ ☐ ☐	COOLANT / ANTIFREEZE	Finding: No history of coolant flush - DO WITH TIMING BELT
☐ ☐ ☐ ☒	POWER STEERING FLUID	Finding:
☺ ⚠ ✕ — BATTERY		
☒ ☐ ☐ ☐	BATTERY TEST / CORROSION	Finding:
☺ ⚠ ✕ — TUNE UP		
☒ ☐ ☐ ☐	SPARK PLUGS / WIRES (IF EASILY ACCESSIBLE)	Finding:
☐ ☒ ☐ ☐	FUEL SYSTEM SERVICE	Finding: in recs
☺ ⚠ ✕ — FILTERS		
☒ ☐ ☐ ☐	AIR FILTER	Finding:
☒ ☐ ☐ ☐	FUEL FILTER	Finding:
☒ ☐ ☐ ☐	CABIN FILTER (IF EASILY ACCESSIBLE)	Finding:
☺ ⚠ ✕ — BELTS & HOSES		
☒ ☐ ☐ ☐	DRIVE BELTS	Finding:
☒ ☐ ☐ ☐	COOLANT HOSES	Finding:
☐ ☐ ☒ ☐	TIMING BELT (IF EQUIPPED)	Finding: Timing belt ten years old. INTERFERANCE ENGINE
		
☺ ⚠ ✕ — BRAKES		
☒ ☐ ☐ ☐	FRONT PADS / ROTORS / CALIPERS / HOSES	Finding: Front brakes 5mm. OK FOR NOW
		
☒ ☐ ☐ ☐	REAR PADS / ROTORS / CALIPERS / HOSES	Finding:
☒ ☐ ☐ ☐	EMERGENCY / PARKING BRAKE	Finding:
☺ ⚠ ✕ — STEERING & SUSPENSION		

☐ ☒ ☐ ☐ STEERING CONDITION	Finding: Both outer tie rods are ripped and leaking grease. Recommend inner and outer tie rods, no history on either.
	
☒ ☐ ☐ ☐ SUSPENSION CONDITION	Finding:
☐ ☒ ☐ ☐ STRUTS / SHOCKS - FRONT	Finding: In recs
☐ ☐ ☒ ☐ STRUTS / SHOCKS - REAR	Finding: Rear struts leaking
	
☺ ⚠ ✖ — AXLES / BEARINGS	
☐ ☐ ☐ ☒ AXLES	Finding:
☒ ☐ ☐ ☐ CV AXLES	Finding:
☐ ☐ ☐ ☒ U-JOINTS	Finding:
☐ ☐ ☐ ☒ DRIVELINE	Finding:
☺ ⚠ ✖ — EXHAUST	
☒ ☐ ☐ ☐ MUFFLER	Finding:
☒ ☐ ☐ ☐ CATALYTIC CONVERTER	Finding:
☒ ☐ ☐ ☐ EXHAUST PIPE / TIPS	Finding:
☺ ⚠ ✖ — 4WD FLUIDS	
☐ ☐ ☐ ☒ FRONT DIFFERENTIAL (IF EASILY ACCESSIBLE)	Finding:
☐ ☐ ☐ ☒ REAR DIFFERENTIAL (IF EASILY ACCESSIBLE)	Finding:
☐ ☐ ☐ ☒ TRANSFER CASE FLUID (IF EASILY ACCESSIBLE)	Finding:
☺ ⚠ ✖ — LEAKS	
☐ ☒ ☐ ☐ FLUID LEAKS	Finding: Mutiple oil leaks under vehicle recommend oil dye.
	


— TIRES		
☒ ☐ ☐ ☐ FRONT LEFT	Finding:	
☒ ☐ ☐ ☐ FRONT RIGHT	Finding:	
☒ ☐ ☐ ☐ REAR LEFT	Finding:	
☒ ☐ ☐ ☐ REAR RIGHT	Finding:	
— NOTES		
☒ ☐ ☐ ☐ TECH NOTES	Finding:	
☐ ☒ ☐ ☐ BODY DAMAGE	Finding: passenger side roof seal coming up. vehicle smells like water. maybe leak elsewhere.	
☒ ☐ ☐ ☐ OTHER SERVICE / MAINTENANCE	Finding:	



34th Street Garage
2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

Invoice for RO #40799

Service Advisor: KAI BAERD
Posted Date: 01/16/24 at 04:45 PM MST
Client: CARLA KOTILA
Vehicle: 1991 Honda CRX Base



1991 Honda CRX Base 1.5L 4Cyl GAS D15B2
Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 178130 / Out: 178130

RO # 40799
Time-In: 01/10/24 at 07:07 PM MST
Save Parts: No

Client Concerns

LOF - B2B - VEHICLE HAS A KILL SWITCH - SILVER TOGGLE SWITCH LEFT SIDE OF STEERING WHEEL UNDER THE DASHBOARD

1 - FULL SERVICE OIL CHANGE - 5W30 SYNTHETIC BLEND

Tech: G WALLACE

Note: CHANGE ENGINE OIL WITH SYNTHETIC ENGINE OIL (UP TO 5 QUARTS)
REPLACE OIL FILTER
LUBRICATE CHASSIS (IF APPLICABLE)
INSPECT FLUIDS & TOP OFF IF NEEDED (SYNTHETIC FLUIDS EXTRA)
SET TIRE PRESSURE WITHIN SPECIFICATIONS

Labor: FULL SERVICE OIL CHANGE 5W30 BLEND
Parts: 5W30 MOTOR OIL
OE HONDA FILTER

✓ Approved on 01/10/24 at 07:08 PM MST

Subtotal \$79.95 + est. Tax \$8.19

\$88.14

2 - BUMPER TO BUMPER INSPECTION

Tech: G WALLACE

Note: SEE INSPECTION REPORT FOR FULL LIST OF COMPONENTS INSPECTED, SOME VEHICLES MAY NOT BE EQUIPPED WITH ALL OF THE ITEMS ON THIS LIST.

Labor: BUMPER TO BUMPER INSPECTION

✓ Approved on 01/10/24 at 07:08 PM MST

Subtotal \$59.95 + est. Tax \$6.14

\$66.09

3 - TIMING BELT / WATER PUMP - REPLACE

Tech: G WALLACE

Labor: TIMING BELT / WATER PUMP - REPLACE
Parts: PowerGrip Premium OE Timing Belt Component Kit W/Water Pump
EXTENDED LIFE - GREEN

✓ Approved on 01/11/24 at 01:49 PM MST

Subtotal \$924.81 + est. Tax \$94.79

\$1,019.60

4 - DIAGNOSE - OIL DYE TEST

Tech: G WALLACE

Note: INCLUDES ADDING TRACER OIL DYE TO AFFECTED SYSTEM AND INSPECTING WITH U.V. LIGHT TO PINPOINT SOURCE.

Labor: DIAGNOSE - OIL DYE TEST
Parts: UV OIL DYE
PARTS CLEANER

✓ Approved on 01/11/24 at 01:49 PM MST

Subtotal \$131.94 + est. Tax \$13.52

\$145.46

5 - FUEL INJECTION SERVICE

Tech: G WALLACE

Labor: FUEL INJECTION SERVICE
Parts: CLEAN MASS AIR FLOW SENSOR
MOTORVAC DETERGENT
FUEL

✓ Approved on 01/11/24 at 01:49 PM MST

Subtotal \$250.89 + est. Tax \$25.72

\$276.61

6 - PARK / RUNNING LIGHT BULB(S) - REPLACE - drivers side Tech: G WALLACE		
Labor:	PARK / RUNNING LIGHT BULB(S) - REPLACE	
Part:	BULB	
✓ Approved on 01/11/24 at 01:49 PM MST		Subtotal \$23.99 + est. Tax \$2.46 \$26.45

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____
Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

Total Jobs: \$1,471.53
Total Fees: \$0.00
Subtotal: \$1,471.53
Taxes: \$150.83
Grand Total: \$1,622.36
BALANCE DUE: \$0.00

X

✓ PAID

Payment History					Payment Signature
01/16/24	CARLA KOTILA	\$1,622.36	Credit Card Payment	Mastercard****	Mastercard

Declined Jobs:

1 - OIL DYE FOLLOW-UP Note: LOCATE LEAK(S) WITH ULTRA VIOLET LIGHT AND GLASSES (PAID FOR ON PREVIOUS RO) CUST HAS NOW DRIVEN MIN 100 MILES TO HELP CIRCULATE OIL DYE		
✗ Declined on 01/11/24 at 03:08 PM MST		0 0
2 - TIE-ROD END, INNER & OUTER- REPLACE Note: REMOVE AND REPLACE INNER TIE-ROD END(S). ROAD-TEST VEHICLE AND VERIFY REPAIR.		
✗ Declined on 01/11/24 at 01:49 PM MST		Subtotal \$706.40 + est. Tax \$72.41 \$778.81
3 - ALIGNMENT Note: SET VEHICLE TO SPEC'S		
✗ Declined on 01/11/24 at 01:49 PM MST		Subtotal \$179.95 + est. Tax \$18.44 \$198.39

4 - STRUT, FRONT - REPLACE

Note: REMOVE AND REPLACE FRONT SHOCK ABSORBERS OR STRUTS. UPON REMOVAL, INSPECT MOUNTS / BUSHINGS FOR WEAR, REPLACE AS NECESSARY. ROAD-TEST VEHICLE.
(INCLUDES TIME TO TRANSFER NECESSARY PARTS)

✕ Declined on 01/11/24 at 01:49 PM MST

Subtotal \$918.98 + est. Tax \$94.20

\$1,013.18

5 - STRUT, REAR - REPLACE

Note: REMOVE AND REPLACE REAR SHOCK ABSORBERS OR STRUTS. UPON REMOVAL, INSPECT MOUNTS/BUSHINGS FOR WEAR, REPLACE AS NECESSARY. ROAD-TEST VEHICLE.
(INCLUDES TIME TO TRANSFER NECESSARY PARTS)

✕ Declined on 01/11/24 at 01:49 PM MST

Subtotal \$829.72 + est. Tax \$85.05


\$914.77



34th Street Garage
2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

Invoice for RO #41613

Service Advisor: KAI BAERD
Posted Date: 04/05/24 at 04:14 PM MDT
Client: CARLA KOTILA
Vehicle: 1991 Honda CRX Base



1991 Honda CRX Base 1.5L 4Cyl GAS D15B2
Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 178341 / Out: 178341

RO # 41613
Time-In: 04/01/24 at 03:04 PM MDT
Save Parts: No

Client Concerns

OIL DYE FOLLOW UP

CHECK WIPERS

1 - OIL DYE FOLLOW-UP

Tech: G WALLACE

Note: LOCATE LEAK(S) WITH ULTRA VIOLET LIGHT AND GLASSES (PAID FOR ON PREVIOUS RO) CUST HAS NOW DRIVEN MIN 100 MILES TO HELP CIRCULATE OIL DYE

Labor: OIL DYE FOLLOW-UP

✓ Approved on 04/02/24 at 08:42 AM MDT

0

0

2 - OIL PAN GASKET - REPLACE

Tech: C HARDY

Note: REMOVE AND REPLACE ENGINE OIL PAN GASKET. CLEAN AREA OF RESIDUAL OIL AND RECHECK FOR FURTHER LEAKS.

Labor: OIL PAN GASKET - REPLACE
Parts: CLEANER
Oil Pan Gasket
5W30 MOTOR OIL
Exh. Man. to Pipe Gasket
Exh. Man. to Pipe Gasket

✓ Approved on 04/02/24 at 04:15 PM MDT

Subtotal \$415.07 + est. Tax \$42.54

\$457.61

3 - C/V AXLE SEAL - REPLACE - PASSENGER SIDE- PLUS DRAIN AND FILL TRANSMISSION FLUID

Tech: C HARDY

Labor: C/V AXLE SEAL - REPLACE
PLUS DRAIN AND FILL TRANSMISSION FLUID
Parts: BRAKE CLEANER
Drive Axle Seal
Motor Oil 10W-30 Group V - 1 Qt
CV Axle Shaft

✓ Approved on 04/02/24 at 04:15 PM MDT

Subtotal \$549.54 + est. Tax \$56.33

\$605.87

4 - VITAL FLUIDS INSPECTION

Tech: G WALLACE

Note: INCLUDES VISUAL INSPECTION OF ALL (UNDER HOOD) VITAL FLUID LEVELS AND CONDITION. AND VISUAL INSPECTION OF BELTS AND HOSES, INCLUDING STAGE 4-5 FLUID LEAKS.

Labor: VITAL FLUIDS INSPECTION - INCLUDES VISUAL INSPECTION OF ALL (UNDER HOOD) VITAL FLUID LEVELS AND CONDITION. AND VISUAL INSPECTION OF BELTS AND HOSES, INCLUDING STAGE 4-5 FLUID LEAKS.

✓ Approved on 04/02/24 at 08:44 AM MDT

0

0

5 - TIE-ROD END, INNER & OUTER- REPLACE

Tech: G WALLACE

Note: REMOVE AND REPLACE INNER TIE-ROD END(S). ROAD-TEST VEHICLE AND VERIFY REPAIR.

Labor: TIE-ROD END, INNER & OUTER- REPLACE
Parts: Tie Rod End
Tie Rod End
Steering Tie Rod End
Rack and Pinion Bellows

✓ Approved on 04/02/24 at 04:15 PM MDT

Subtotal \$714.92 + est. Tax \$73.28

\$788.20

6 - ALIGNMENT

Tech: C HARDY

Note: SET VEHICLE TO SPEC'S

Labor: ALIGNMENT

✓ Approved on 04/02/24 at 04:15 PM MDT

Subtotal \$179.95 + est. Tax \$18.44

\$198.39**7 - STRUT, REAR - REPLACE**

Tech: G WALLACE

Note: REMOVE AND REPLACE REAR SHOCK ABSORBERS OR STRUTS. UPON REMOVAL, INSPECT MOUNTS/BUSHINGS FOR WEAR, REPLACE AS NECESSARY. ROAD-TEST VEHICLE. (INCLUDES TIME TO TRANSFER NECESSARY PARTS)

Labor: STRUT, REAR - REPLACE

Parts: Excel-G
Mount Components

✓ Approved on 04/02/24 at 04:15 PM MDT

Subtotal \$847.14 + est. Tax \$86.83

\$933.97**8 - STRUT, FRONT - REPLACE**

Tech: G WALLACE

Note: REMOVE AND REPLACE FRONT SHOCK ABSORBERS OR STRUTS. UPON REMOVAL, INSPECT MOUNTS / BUSHINGS FOR WEAR, REPLACE AS NECESSARY. ROAD-TEST VEHICLE. (INCLUDES TIME TO TRANSFER NECESSARY PARTS)

Labor: SHOCK / STRUT, FRONT - REPLACE

Parts: Excel-G
Excel-G

✓ Approved on 04/02/24 at 04:15 PM MDT

Subtotal \$876.96 + est. Tax \$89.89

\$966.85**9 - CHECK WIPER BLADE(S) - REPLACE IF NECESSARY**

Tech: C HARDY

Note: INCLUDES REMOVE AND REPLACE WIPER BLADE(S) AS NEEDED. VERIFY PROPER OPERATION

Labor: WIPER BLADE(S) - REPLACE

Parts: Window Wiper Blade 20"
Window Wiper Blade 18"

✓ Approved on 04/04/24 at 09:31 AM MDT

0

0

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____
Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

Total Jobs: \$3,666.37
Total Fees: \$0.00
Discounts: -\$112.79
Subtotal: \$3,553.58
Taxes: \$364.24
Grand Total: \$3,917.82
BALANCE DUE: \$0.00

X

✓ PAID

Payment History					Payment Signature
04/05/24	CARLA KOTILA	\$3,917.82	Credit Card Payment	Mastercard****	Mastercard



34th Street Garage

2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

RO #43375

Service Advisor: Dylan Heckett

Posted Date: 09/13/24 at 06:10 PM MDT

Client: CARLA KOTILA

Vehicle: 1991 Honda CRX Base

1991 Honda CRX Base 1.5L 4Cyl GAS D15B2 Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 178568 / Out: 178568

RO # 43375
Save Parts: No

Client Concerns

IGNITION KILL SWITCH NEEDS TO BE REPAIRED OR REPLACED

Inspection Rating Key:

😊 Checked & Okay ⚠ Requires Attention Soon ✖ Requires Immediate Attention — Not Applicable

COURTESY INSPECTION

TECH: GABRIEL WALLACE


😊 ⚠ ✖ — COURTESY INSPECTION

☒ ☐ ☐ ☐ WARNING LIGHTS	Finding:
☐ ☒ ☐ ☐ LIGHTS - EXTERIOR	Finding: Reverse lights do not work. May need diag.
☒ ☐ ☐ ☐ NOTES:	Finding:
☒ ☐ ☐ ☐ ENGINE OIL	Finding:
☒ ☐ ☐ ☐ TRANSMISSION FLUID (IF EASILY ACCESSIBLE)	Finding:
☒ ☐ ☐ ☐ COOLANT / ANTIFREEZE	Finding:
☒ ☐ ☐ ☐ POWER STEERING FLUID	Finding:
☒ ☐ ☐ ☐ BRAKE FLUID	Finding:
☒ ☐ ☐ ☐ AIR FILTER	Finding:
☒ ☐ ☐ ☐ CABIN FILTER (IF EASILY ACCESSIBLE)	Finding:
☒ ☐ ☐ ☐ BELTS	Finding:
☒ ☐ ☐ ☐ HOSES	Finding:

☐ ☒ ☐ ☐ STEERING AND SUSPENSION

Finding: Front sway bar end links are cracking and rotting. Rear lower control arm bushings are cracking and ripping



☐ ☒ ☐ ☐ FUEL FILTER (IF APPLICABLE)	Finding: Fuel filter no history, visibly old. Rec replacement
	
☐ ☒ ☐ ☐ FLUID LEAKS	Finding: Transmission appears to be leaking. Rec oil dye. Possible case leak. need to identify location. Also possible coming from distributor which is also leaking, very hard to tell. Rec oil dye for trans and engine to determine where leaks are coming from.
	
☒ ☐ ☐ ☐ EXHAUST SYSTEM	Finding:
☒ ☐ ☐ ☐ TIRES	
☒ ☐ ☐ ☐ FRONT LEFT	Finding:
☒ ☐ ☐ ☐ FRONT RIGHT	Finding:
☒ ☐ ☐ ☐ REAR LEFT	Finding:
☒ ☐ ☐ ☐ REAR RIGHT	Finding:
☒ ☐ ☐ ☐ TECH NOTES	
☒ ☐ ☐ ☐ TECH NOTES	Finding:
☒ ☐ ☐ ☐ BRAKE INSPECTION	Finding:
☐ ☐ ☐ ☒ 4WD FLUID INSPECTION	Finding:
☐ ☒ ☐ ☐ TUNE UP INSPECTION	Finding: Evap canister vacuum lines are mold and rotting
	
☐ ☒ ☐ ☐ OTHER SERVICE / MAINTENANCE	Finding: Front lower engine mount ripping and cracking driver upper mount cracking and ripping as well
	



BODY DAMAGE


Finding:



34th Street Garage
2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

Invoice for RO #43375

Service Advisor: Dylan Heckett
Posted Date: 09/13/24 at 06:10 PM MDT
Client: CARLA KOTILA
Vehicle: 1991 Honda CRX Base

	1991 Honda CRX Base 1.5L 4Cyl GAS D15B2 Naturally Aspirated VIN: JHMED8354MS013987 License: 7601H Color: Red Odometer In: 178568 / Out: 178568	RO # 43375 Time-In: 09/11/24 at 06:29 PM MDT Save Parts: No

Client Concerns

IGNITION KILL SWITCH NEEDS TO BE REPAIRED OR REPLACED

1 - FIX ELECTRICAL

Tech: G WALLACE

Note: IGNITION CUTOFF SWITCH NEEDS TO BE REPLACED

Labor: ELECTRICAL
Part: Toggle Switch

✓ Approved on 09/12/24 at 09:14 AM MDT

Subtotal \$177.92 + est. Tax \$18.41

\$196.33

2 - COURTESY INSPECTION

Tech: G WALLACE

Note: See Report

Labor: COURTESY INSPECTION

✓ Approved on 09/12/24 at 09:14 AM MDT

0

0

3 - DIAGNOSE - OIL DYE TEST FOR ENGINE AND TRANSMISSION

Tech: G WALLACE

Note: INCLUDES ADDING TRACER OIL DYE TO AFFECTED SYSTEM AND INSPECTING WITH U.V. LIGHT TO PINPOINT SOURCE.

DOES NOT INCLUDE EXCESSIVE OIL CLEAN UP

Labor: DIAGNOSE - OIL DYE TEST
Parts: UV TRACER DYE
CLEANER

✓ Approved on 09/12/24 at 03:23 PM MDT

Subtotal \$131.90 + est. Tax \$13.65

\$145.55

4 - DIAGNOSE - BOTH REVERSE LIGHTS INOPERABLE

Tech: G WALLACE

Labor:

✓ Approved on 09/12/24 at 03:23 PM MDT

Subtotal \$247.50 + est. Tax \$25.62

\$273.12

5 - SWAY BAR BUSHINGS, FRONT - REPLACE

Tech: G WALLACE

Note: REMOVE AND REPLACE FRONT SWAY BAR BUSHINGS. ROAD-TEST VEHICLE/VERIFY REPAIRS.

Labor:
Part: Import Direct

✓ Approved on 09/12/24 at 03:23 PM MDT

Subtotal \$438.50 + est. Tax \$45.38

\$483.88

6 - REAR LOWER CONTROL ARMS - REMOVE AND REPLACE

Tech: G WALLACE

Note: DIS-ASSEMBLE AS NEEDED TO REMOVE AND REPLACE REAR CONTROL ARM(S). RE-ASSEMBLE AND ROAD-TEST VEHICLE / VERIFY REPAIR.

NOTE

THIS REPAIR MAY REQUIRE A WHEEL ALIGNMENT AND IS NOT INCLUDED IN THIS ESTIMATE.

Labor: CONTROL ARM, REAR - REPLACE
Parts: Control Arm
Control Arm

✓ Approved on 09/12/24 at 03:23 PM MDT

Subtotal \$752.48 + est. Tax \$77.88

\$830.36

7 - ENGINE MOUNTS - DRIVERS SIDE UPPER AND LOWER FORWARD MOUNT - REMOVE AND REPLACE - PARTS ARE 1 DAY OUT

Tech: G WALLACE

Note: REMOVE AND REPLACE _____ ENGINE MOUNT(S). ROAD-TEST VEHICLE AND VERIFY REPAIR.

Labor:

Parts:Engine Mount
Engine Mount

✓ Approved on 09/12/24 at 03:23 PM MDT

Subtotal \$436.69 + est. Tax \$45.20

\$481.89

8 - FUEL FILTER - REPLACE

Tech: G WALLACE

Note: INCLUDES REMOVE AND REPLACE FUEL FILTER, VERIFY OPERATION AND INSPECT FOR LEAKS

Labor:

Part:FUEL FILTER - REPLACE
Fuel Filter

✓ Approved on 09/12/24 at 03:23 PM MDT

Subtotal \$197.89 + est. Tax \$20.48

\$218.37

9 - VACUUM LINES - REMOVE AND REPLACE - CRACKED AND MOLDING

Tech: G WALLACE

Labor:

Part:VAC LINES

✓ Approved on 09/12/24 at 03:23 PM MDT

Subtotal \$103.26 + est. Tax \$10.69

\$113.95

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____

Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

Total Jobs: \$2,486.14

Total Fees: \$0.00

Subtotal: \$2,486.14

Taxes: \$257.32

Grand Total: \$2,743.46

BALANCE DUE: \$0.00

X

✓ PAID


Payment History					Payment Signature
09/19/24	CARLA KOTILA	\$2,743.46	Credit Card Payment	Mastercard****	Mastercard



34th Street Garage
2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

Invoice for RO #44262

Service Advisor: Dylan Heckett
Posted Date: 12/06/24 at 03:35 PM MST
Client: CARLA KOTILA
Vehicle: 1991 Honda CRX Base



1991 Honda CRX Base 1.5L 4Cyl GAS D15B2
Naturally Aspirated
VIN: JHMED8354MS013987
License: 7601H
Color: Red
Odometer In: 178813 / Out: 178813

RO # 44262
Time-In: 12/05/24 at 10:31 AM MST
Save Parts: No

1 - OIL DYE FOLLOW-UP

Tech: G WALLACE

Note: LOCATE LEAK(S) WITH ULTRA VIOLET LIGHT AND GLASSES (PAID FOR ON PREVIOUS RO) CUST HAS NOW DRIVEN MIN 100 MILES TO HELP CIRCULATE OIL DYE

Labor: OIL DYE FOLLOW-UP

✓ Approved on 12/05/24 at 10:33 AM MST

0

0

2 - VITAL FLUIDS INSPECTION

Tech: G WALLACE

Note: INCLUDES VISUAL INSPECTION OF ALL (UNDER HOOD) VITAL FLUID LEVELS AND CONDITION. AND VISUAL INSPECTION OF BELTS AND HOSES, INCLUDING STAGE 4-5 FLUID LEAKS.

Labor: VITAL FLUIDS INSPECTION - INCLUDES VISUAL INSPECTION OF ALL (UNDER HOOD) VITAL FLUID LEVELS AND CONDITION. AND VISUAL INSPECTION OF BELTS AND HOSES, INCLUDING STAGE 4-5 FLUID LEAKS.

✓ Approved on 12/05/24 at 10:38 AM MST

0

0

3 - DISTRIBUTOR CAP - REMOVE AND REPLACE (INCLUDES FRESH SEAL)

Tech: G WALLACE

Labor:
Parts: Distributor Cap
Distributor Cap Gasket
Dist. Housing Seal Kit

✓ Approved on 12/05/24 at 11:47 AM MST

Subtotal \$332.69 + est. Tax \$34.43

\$367.12

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____
Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

Total Jobs: \$332.69
Total Fees: \$0.00
Subtotal: \$332.69
Taxes: \$34.43
Grand Total: \$367.12
BALANCE DUE: \$0.00

X

✓ PAID

Payment History					Payment Signature
12/06/24	CARLA KOTILA	\$367.12	Credit Card Payment	Mastercard****	Mastercard



34th Street Garage
2410 34th Avenue West
Seattle, WA 98199
(206) 283-3448
info@34thstreetgarage.com
https://carrepairsseattle.com

Invoice for RO #47287

Service Advisor: LOGAN GALBRAITH
Posted Date: 10/10/25 at 04:44 PM PDT
Client: CARLA KOTILA
Vehicle: 1991 Honda CRX Base

	1991 Honda CRX Base 1.5L 4Cyl GAS D15B2 Naturally Aspirated VIN: JHMED8354MS013987 License: 7601H Color: Red Odometer In: 179255 / Out: 179256	RO # 47287 Time-In: 09/23/25 at 10:42 AM PDT Save Parts: No

Client Concerns

PREVIOUS RECS

CRX REPAIRS

1 - C/V AXLE - REPLACE

Tech: A HYATT

Note: DIS-ASSEMBLE AS NEEDED TO REMOVE ____ AXLE SHAFT, CLEAN OIL DEPOSITS. REPLACE AXLE AND RE-ASSEMBLE / ROAD-TEST VEHICLE AND VERIFY REPAIR.

Labor: C/V AXLE - REPLACE
Parts: CLEANER
CV Axle Shaft

✓ Approved on 10/09/25 at 06:45 AM PDT

Subtotal \$449.38 + est. Tax \$46.51

\$495.89

2 - BALL JOINT(S) LOWER - REPLACE

Tech: A HYATT

Note: REMOVE AND REPLACE FRONT LOWER BALL JOINT(S), ROAD TEST VEHICLE AND VERIFY PROPER OPERATION.

NOTE

THIS REPAIR MAY REQUIRE A WHEEL ALIGNMENT AND IS NOT INCLUDED IN THIS ESTIMATE.

Labor: BALL JOINT(S) LOWER - REPLACE
Parts: CLEANER
Suspension Ball Joint

✓ Approved on 10/09/25 at 06:45 AM PDT

Subtotal \$602.83 + est. Tax \$62.39

\$665.22

3 - SWAY BAR BUSHINGS, FRONT - REPLACE

Tech: A HYATT

Note: REMOVE AND REPLACE FRONT SWAY BAR BUSHINGS. ROAD-TEST VEHICLE/VERIFY REPAIRS.

Labor:
Part: Suspension Stabilizer Bar Link Kit

✓ Approved on 10/09/25 at 06:45 AM PDT

Subtotal \$246.04 + est. Tax \$25.47

\$271.51

4 - FRONT STRUT MOUNTS - REPLACE

Tech: A HYATT

Labor: FRONT STRUT MOUNTS - REPLACE
Part: Mount Components Suspension Strut Mount Kit

✓ Approved on 10/09/25 at 06:45 AM PDT

Subtotal \$247.34 + est. Tax \$25.60

\$272.94

5 - WHEEL ALIGNMENT SERVICE

Tech: A HYATT

Note: COMPUTERIZED FOUR WHEEL ALIGNMENT SERVICE - SET VEHICLE TO SPEC'S

Labor: ALIGNMENT

✓ Approved on 10/09/25 at 06:45 AM PDT

Subtotal \$189.95 + est. Tax \$19.66

\$209.61

6 - BRAKE LIGHT BULB(S) - REPLACE

Tech: A HYATT

Note: INCLUDES REMOVE AND REPLACE BURNED OUT BRAKE LIGHT BULB(S) AND VERIFY PROPER OPERATION

Labor: BRAKE LIGHT BULB(S) - REPLACE

Part: LIGHT BULB

✓ Approved on 10/09/25 at 06:45 AM PDT

Subtotal \$43.99 + est. Tax \$4.55

\$48.54

7 - BATTERY - REPLACE

Tech: A HYATT

Note: REMOVE AND REPLACE VEHICLE BATTERY. RE-TEST FOR PROPER OPERATION.

Labor: BATTERY - REPLACE

Part: Battery, CCA:500 RC:85 AH:47, Gold 42 Month Warranty

✓ Approved on 10/09/25 at 06:45 AM PDT

Subtotal \$252.45 + est. Tax \$26.13

\$278.58

34th Street Garage provides a limited warranty for repairs from 8.11.25 for 2 Years or 24,000 miles whichever comes first unless otherwise stated. The 3 Years or 36,000 miles limited warranty is valid for repairs between 4.23.24 thru 8.8.25 only. Towing is covered for the first 7 days after repairs. All warranty work must be performed at 34th Street Garage and cannot exceed the original cost of repair. We offer a Nationwide 12 Month/12,000 Mile warranty for vehicles outside of a 25-mile radius of 34th Street Garage. Please Call the Warranty Administrator prior to any warranty work performed at 1-888-411-9567.

Limited brake warranty covers brake pads, shoes, rotors, and drums for defects in materials or workmanship. The warranty does not cover regular wear on brake pads, brake shoes or any other issues unrelated to defects, including those resulting from abuse, accidents, or vandalism. Brake dust and noise are normal and not covered under this warranty unless proven to be caused by a defective part. Vibration or warpage in rotors and drums are not covered. Hotspots and cracks occurring after 90 days or 3,000 miles are also not covered, as these are due to excessive braking or misuse, not defects.

Your service today may have included the removal of your wheels. The lug nuts were torqued to specification by our technicians upon installation. To ensure safety, it is essential to return within 50-100 miles for a complimentary re-torque of the lug nuts. 34th Street Garage assumes no liability whatsoever should this re-torque not be performed.

WHEEL TORQUE DISCLAIMER

You must return to this shop with this paperwork in the next 50 - 100 miles to retorque the wheels.

Checked By: _____

Date: _____

There will be a \$75 storage charge per day for vehicles left 5 days after completion. Any vehicles left over 15 days may be impounded. You will be responsible for all impounding fees and costs. Except as otherwise stated herein, 34th Street Garage makes no other warranties and disclaims all other warranties to the maximum extent provided by law.

Work Authorization Signature:

X _____

Total Jobs: \$2,031.98

Total Fees: \$0.00

Subtotal: \$2,031.98

Taxes: \$210.31

Grand Total: \$2,242.29

BALANCE DUE: \$0.00

✓ PAID

Payment History					Payment Signature
10/10/25	CARLA KOTILA	\$2,242.29	Credit Card Payment	Mastercard****	Mastercard