



Classic Auto Restoration Specialist INC

17570 N Tamiami Trail Unit 2  
 North Fort Myers, FL 33903

# Statement

Date
------

12/9/2022



Due Date
12/9/2022

Date	Transaction	Amount	Balance
11/09/2022	Balance forward		-500.00
11/11/2022	3850 1940 Jeep Willy- INV #2022-7412. --- Assembly, 3 @ \$97.00 = 291.00 --- Tax: FL Sales Tax @ 6.5% = 18.92	309.92	-190.08
11/25/2022	INV #2022-7474. --- Parts \$2,076.24 --- Tax: FL Sales Tax @ 6.5% = 134.96	2,211.20	2,021.12
12/02/2022	INV #2022-7515. --- Assembly, 3 @ \$97.00 = 291.00 --- Assembly, 6.5 @ \$97.00 = 630.50 --- Assembly, 5.5 @ \$97.00 = 533.50 --- Parts \$51.70 --- Misc. Shop Supplies \$85.00 --- Tax: FL Sales Tax @ 6.5% = 103.46	1,695.16	3,716.28
12/09/2022	INV #2022-7530. --- Body/Paint Shop, 2 @ \$89.00 = 178.00 --- Assembly, 7 @ \$97.00 = 679.00 --- Assembly, 4.5 @ \$97.00 = 436.50 --- Misc. Shop Supplies \$63.75 --- Parts \$27.00 --- Tax: FL Sales Tax @ 6.5% = 89.98	1,474.23	5,190.51
12/09/2022	CREDMEM #2022-7537. --- Assembly, 4.5 @ \$97.00 = -436.50 --- Tax: FL Sales Tax @ 6.5% = -28.37	-464.87	4,725.64

CURRENT	1-30 DAYS PAST DUE	31-60 DAYS PAST DUE	61-90 DAYS PAST DUE	OVER 90 DAYS PAST DUE	Amount Due
1,009.36	3,716.28	0.00	0.00	0.00	\$4,725.64



# Classic Auto Restoration Specialist INC

17570 N Tamiami Trail Unit 2  
North Fort Myers, FL 33903


Phone # 239-543-0900

Fax # 239-731-9704

www.classicautorest.com

# Invoice

Date	Invoice #
12/9/2022	2022-7530



Account / Job
3850 1940 Jeep Willy

Serviced	Item	Quantity	Description	U/M	Rate	Amount
12/5/2022	Body/Paint ...	2	JD Sandblast hinge. Weld hinge.		89.00	178.00T
12/5/2022	Assembly	7	MM Finish front suspension springs, shackles and bushings. Grease suspension, driveshaft, slip yokes and pedals. Bleed brake system. Work on brake pedal assembly. Prime carburetor and fuel pump. Adjust park brake shoes. Road test and recheck.		97.00	679.00T
12/6/2022	Assembly	4.5	MM Check rear brake line leak at master cylinder. Tightened and removed line at master cylinder and inspect. Remove bad fitting and replace it. Road test brakes and rechecked. Seat in brake shoes. Remove and make new line from master cylinder to rear. Bled brake system. Loosen and adjust brake pedal, arm, bushing and worn and loose.		97.00	436.50T
	Misc. Shop ...		WARRANTY CM # 2022-7537		63.75	63.75T
	Parts		Misc. Shop Supplies		27.00	27.00T
			PARTS - 15 Hub nuts		6.50%	89.98
			Sales Tax			

3% Credit/Debit usage Fee on all transactions		\$1,474.23
		-\$464.87
		\$1,009.36




**Classic Auto Restoration Specialist INC**

17570 N Tamiami Trail Unit 2  
 North Fort Myers, FL 33903

Phone # 239-543-0900 carsinc2@gmail.com  
 Fax # 239-731-9704 www.classicautorest.com

**Credit Memo**

12/9/2022	2022-7537



Account #	
	3850 1940 Jeep ...

Description	Qty	U/M	Rate	Amount
MM Check rear brake line leak at master cylinder. Tightened and removed line at master cylinder and inspect. Remove bad fitting and replace it. Road test brakes and rechecked. Seat in brake shoes. INV 2022-7530	-4.5		97.00	-436.50T

	-436.50
	-\$28.37
	-\$464.87
	\$464.87
	\$0.00



**Classic Auto Restoration Specialist INC**

17570 N Tamiami Trail Unit 2  
North Fort Myers, FL 33903


Phone # 239-543-0900

Fax # 239-731-9704

www.classicautoresto.com

# Invoice

Date	Invoice #
12/2/2022	2022-7515

Bill To


Account / Job
3850 1940 Jeep Willy

Serviced	Item	Quantity	Description	U/M	Rate	Amount
11/30/2022	Assembly	3	MM Check over parts, Clean and paint shocks. Start removing brake lines.		97.00	291.00T
12/1/2022	Assembly	6.5	MM Install 3 front hoses and 2 steel lines on axle. Check bleeders and right front bleeder broke. Disassembled right front hub assembly. Remove wheel cylinder and remove broken bleeder screw. Make 3 steel lines to finish front.. Install bleeder and right front wheel cylinder, Installed hub assembly. Adjust front brakes. Remove 2 steel lines on rear axle.		97.00	630.50T
12/2/2022	Assembly	5.5	MM Make 2 rear brake lines. Loosen rear brake adjusters. Work on spring shackles. Remove rear shoe. Cut off V-bolts. Install new spring (modify front spring hangers) Press in spring and bushing. Install new V-bolts, new spring shackles. Trim rear shock mounts and install rear shocks. Unbolt left front spring and remove.		97.00	533.50T
	Parts		PARTS - 4 brake lines, 1 brake hose, 1 bleeder screw.		51.70	51.70T
	Misc. Shop ...		Misc. Shop Supplies		85.00	85.00T
			Sales Tax		6.50%	103.46

3% Credit/Debit usage Fee on all transactions	\$1,695.16
	\$0.00
	\$1,695.16



**Classic Auto Restoration Specialist INC**

17570 N Tamiami Trail Unit 2  
North Fort Myers, FL 33903

Phone # 239-543-0900

Fax # 239-731-9704

www.classicautorest.com

# Invoice

Date	Invoice #
11/25/2022	2022-7474

Bill To
[REDACTED]

Account / Job
3850 1940 Jeep Willy

Serviced	Item	Quantity	Description	U/M	Rate	Amount
11/21/2022	Parts		PARTS - 1 complete suspension overhaul kit, 16 Axle to leaf spring u-bolt clip nuts, 4 Front and rear leaf spring pivot eye bushings, 4 Front and rear left spring pivot eye bolts, 2 leaf spring shackle kit (left hand thread), 2 leaf spring shackle kit (right hand thread), 1 Front leaf spring u-bolt clips, 2 front leaf spring assembly (8 leaf), 2 rear leaf spring assembly (9 leaf), 4 rear leaf spring u-bolt clips, 3 front leaf spring u-bolt clips, 4 front and rear shock absorbers, 1 front and rear brake hose kit, 2 steel S-tubes front wheel cylinders, 2 front brake hose 7", 1 front brake hose 12-1/4", 1 rear brake hose 16", 3 cans of Olive drab green paint.		2,076.24	2,076.24T
			Sales Tax		6.50%	134.96

3% Credit/Debit usage Fee on all transactions		\$2,211.20
		-\$190.08
		\$2,021.12



# Classic Auto Restoration Specialist INC

17570 N Tamiami Trail Unit 2  
North Fort Myers, FL 33903

Phone # 239-543-0900


Fax # 239-731-9704

www.classicautorrest.com

# Invoice

Date	Invoice #
11/11/2022	2022-7412

Bill To



**PAID**  
**10/28/2022**

Account / Job
3850 1940 Jeep Willy

Serviced	Item	Quantity	Description	U/M	Rate	Amount
11/8/2022	Assembly	3	Full inspection of car Sales Tax		97.00 6.50%	291.00T 18.92

3% Credit/Debit usage Fee on all transactions	\$309.92
	-\$309.92
	\$0.00

# Kaiser Willys Auto Supply LLC

114 Bolton Ct.  
Aiken, SC 29803

**Toll Free: 888-648-4923**

Fax: 803-642-4197

Email: [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com)

Hours: Mon. - Fri., 9 - 5 (Eastern)



## INVOICE / PACKING SLIP

Order Number: 803978A


Invoice Date: 02/26/24

Page Number: 1

P.O. / Reference:

*We are the leading most complete supplier of 1941-72 Willys parts and accessories. See us online 24 hours a day at:*

[www.KaiserWillys.com](http://www.KaiserWillys.com)



SHIP TO

Customer #: 336303 Terms: \_\_\_\_\_

Ship Via: FPK Total Weight 1.0

Qty	B/O	Shipped	Item #	Description	Unit Price	Total Amount
1	0	1	670937	Tool Box Lid Weatherseal 64	8.99	8.54
1	1	0	7378876	NOS Tool Box Lid Catch Kit (1 required)	17.99	0.00
*WE EXPECT THE ABOVE ITEM ON OR BEFORE 03/07/24*						
1	0	1	932133	Turn Signal Flasher Holder Bracket	12.99	12.34
1	0	1	994139	Smaller Profile Black Steering Wheel (for 1-1/4	129.99	123.49

Merchandise Invoice Total:	\$	144.37
Sales Tax:	\$	0.00
Shipping & Handling:	\$	TOTAL \$
Invoice Total:	\$	144.37

**ATTN: State of California Consumers** Products in this package may be subject to California Prop. 65 Warning: Cancer and Reproductive Harm - [www.P65warnings.ca.gov](http://www.P65warnings.ca.gov)

**Return Policy:** Any unused parts in new condition may be returned any time of purchase with NO restocking fee. All returns must be accompanied by a number (Return Materials Authorization) - Call us toll free or email [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com). Please write it clearly on the outside of the box. Any return without this number on the packaging will be refused. Please note that sales or use tax may be due on certain purchases. Kaiser Willys does not collect sales tax on your purchase except for SC. Your state may require you to file a use tax return when sales tax is not paid at the time of purchase. Kaiser Willys may have to provide information to you and the your State Department of Revenue about the purchases you made where seals tax was not paid.

**Liability Disclaimer:** Liability of Kaiser Willys Auto Supply LLC is limited to the replacement of defective parts only and is not liable for any damages to property, loss of time, loss of profits, loss of income, or any other incidental damages arising from the purchase or use of items purchased. The Buyer assumes all Risk or Loss associated with parts purchased from Kaiser Willys Auto Supply LLC. JEEP®, WILLYS, CJ™ and other names used are registered trademarks or trademarks of Daimler Chrysler or their respective owners. Kaiser Willys, LLC is not affiliated with Daimler Chrysler or any other companies whose products or part numbers shown here as a reference. Part numbers used for reference purpose only. No implication is made that these are original car manufacturing parts or from sources whose part numbers used here as a reference or approved by them.

# Kaiser Willys Auto Supply LLC

114 Bolton Ct.  
Aiken, SC 29803

**Toll Free: 888-648-4923**

Fax: 803-642-4197

Email: [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com)

Hours: Mon. - Fri., 9 - 5 (Eastern)



## INVOICE / PACKING SLIP

Order Number: 803978B


Invoice Date: 03/11/24

Page Number: 1

P.O. / Reference:

*We are the leading most complete supplier of 1941-72 Willys parts and accessories. See us online 24 hours a day at:*

[www.KaiserWillys.com](http://www.KaiserWillys.com)



SHIP TO

Customer #: 336303 Terms: \_\_\_\_\_

Ship Via: FPK Total Weight 0.0

Qty	B/O	Shipped	Item #	Description	Unit Price	Total Amount
1	0	1	7378876	NOS Tool Box Lid Catch Kit (1 required)	17.99	17.09

Merchandise Invoice Total:	\$	17.09
Sales Tax:	\$	0.00
Shipping & Handling:	\$	THIS ORDER \$
Invoice Total:	\$	17.09

**ATTN: State of California Consumers** Products in this package may be subject to California Prop. 65  
Warning: Cancer and Reproductive Harm - [www.P65warnings.ca.gov](http://www.P65warnings.ca.gov)

**Return Policy:** Any unused parts in new condition may be returned any time of purchase with NO restocking fee. All returns must be accompanied by a number (Return Materials Authorization) - Call us toll free or email [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com). Please write it clearly on the outside of the box. Any return without this number on the packaging will be refused. Please note that sales or use tax may be due on certain purchases. Kaiser Willys does not collect sales tax on your purchase except for SC. Your state may require you to file a use tax return when sales tax is not paid at the time of purchase. Kaiser Willys may have to provide information to you and the your State Department of Revenue about the purchases you made where seals tax was not paid.

**Liability Disclaimer:** Liability of Kaiser Willys Auto Supply LLC is limited to the replacement of defective parts only and is not liable for any damages to property, loss of time, loss of profits, loss of income, or any other incidental damages arising from the purchase or use of items purchased. The Buyer assumes all Risk or Loss associated with parts purchased from Kaiser Willys Auto Supply LLC. JEEP®, WILLYS, CJ™ and other names used are registered trademarks or trademarks of Daimler Chrysler or their respective owners. Kaiser Willys, LLC is not affiliated with Daimler Chrysler or any other companies whose products or part numbers shown here as a reference. Part numbers used for reference purpose only. No implication is made that these are original car manufacturing parts or from sources whose part numbers used here as a reference or approved by them.

# Kaiser Willys Auto Supply LLC

114 Bolton Ct.  
Aiken, SC 29803

**Toll Free: 888-648-4923**

Fax: 803-642-4197

Email: [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com)

Hours: Mon. - Fri., 9 - 5 (Eastern)



## INVOICE / PACKING SLIP

Order Number: 807002A

Invoice Date: 03/11/24

Page Number: 1

P.O. / Reference:

*We are the leading most complete supplier of 1941-72 Willys parts and accessories. See us online 24 hours a day at:*

[www.KaiserWillys.com](http://www.KaiserWillys.com)

SHIP TO

Customer #: 336303 Terms: \_\_\_\_\_

Ship Via: UPS Total Weight 1.0

Qty	B/O	Shipped	Item #	Description	Unit Price	Total Amount
1	0	1	B0634-BKT	US Made Firewall Horn Bracket Mount	24.99	22.49
1	0	1	716100	TightSteer Sector Shaft Tensioner	89.99	80.99
1	0	1	A302B	Steering Column Horn Contact Bushing	11.44	10.30
1	0	1	A300	Original Reproduction Steering Column Horn	16.95	15.26
1	0	1	7673448	New Instrument Center Section Dash Panel	59.99	53.99
1	0	1	923418	Steering Connecting Rod Repair Kit (drag link)	17.74	15.97
1	0	1	641251	Outer Steering Column Tube	55.99	50.39
1	0	1	670554-2A	Steering Column to Floor Rubber Grommet	10.95	9.86
1	0	1	639190	Original Upper Steering Column Bearing	28.99	26.09
1	0	1	639191	US Made Upper Steering Column Bearing Spring	10.44	9.40
1	0	1	A6760	Steering Tube & Worm Gear Shim Pack	5.99	5.39
1	0	1	646084	Steering Worm Gear Bearing Kit	19.99	17.99
2	0	2	808591	Steering Worm Gear Bearing Retainer Ring (2	3.74	6.73
1	0	1	927645	Steering Gear Box Sector Shaft Oil Seal (7/8")	6.99	6.29
1	0	1	639091	Outer Steering Gear Box Sector Shaft Bushing	5.99	5.39
1	0	1	639090	Inner Steering Gear Box Sector Shaft Bushing	5.99	5.39
1	0	1	639119	Steering Gear Box Sector Shaft Gasket (7/8")	4.25	3.83

Merchandise Invoice Total:	\$	345.74
Sales Tax:	\$	0.00
Shipping & Handling:	\$	TOTAL \$
Invoice Total:	\$	345.74

**ATTN: State of California Consumers** - Products in this package may be subject to California Prop. 65 Warning: Cancer and Reproductive Harm - [www.P65warnings.ca.gov](http://www.P65warnings.ca.gov)

**Return Policy:** Any unused parts in new condition may be returned any time of purchase with NO restocking fee. All returns must be accompanied by a number (Return Materials Authorization) - Call us toll free or email [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com). Please write it clearly on the outside of the box. Any return without this number on the packaging will be refused. Please note that sales or use tax may be due on certain purchases. Kaiser Willys does not collect sales tax on your purchase except for SC. Your state may require you to file a use tax return when sales tax is not paid at the time of purchase. Kaiser Willys may have to provide information to you and the your State Department of Revenue about the purchases you made where seals tax was not paid.

Liability Disclaimer: Liability of Kaiser Willys Auto Supply LLC is limited to the replacement of defective parts only and is not liable for any damages to property, loss of time, loss of profits, loss of income, or any other incidental damages arising from the purchase or use of items purchased. They Buyer assumes all Risk or Loss associated with parts purchased from Kaiser Willys Auto Supply LLC. JEEP®, WILLYS, CJ™ and other names used are registered trademarks or trademarks of Daimler Chrysler or their respective owners. Kaiser Willys, LLC is not affiliated with Daimler Chrysler or any other companies whose products or part numbers shown here as a reference. Part numbers used for reference purpose only. No implication is made that these are original car manufacturing parts or from sources whose part numbers used here as a reference or approved by them.

# Kaiser Willys Auto Supply LLC

114 Bolton Ct.  
Aiken, SC 29803

**Toll Free: 888-648-4923**

Fax: 803-642-4197

Email: [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com)

Hours: Mon. - Fri., 9 - 5 (Eastern)



## INVOICE / PACKING SLIP

Order Number: 808393A


Invoice Date: 03/18/24

Page Number: 1

P.O. / Reference:

*We are the leading most complete supplier of 1941-72 Willys parts and accessories. See us online 24 hours a day at:*

[www.KaiserWillys.com](http://www.KaiserWillys.com)



SHIP TO

Customer #: 336303 Terms: \_\_\_\_\_

Ship Via: FPK Total Weight 1.0

Qty	B/O	Shipped	Item #	Description	Unit Price	Total Amount
1	0	1	A278	Master Cylinder Brass Outlet Fitting Plug	2.99	2.69
1	0	1	MGLOVE	Glove Box Weatherseal	15.99	14.39
2	0	2	663368	Replacement Windshield Wiper Arm for Original	15.74	28.33
2	0	2	663367	Replacement Windshield Wiper Blade for Original	9.99	17.98
1	0	1	A1912	Accelerator Linkage Cross Shaft	45.99	41.39

Merchandise Invoice Total:	\$	104.79
Sales Tax:	\$	0.00
Shipping & Handling:	\$	TOTAL \$
Invoice Total:	\$	104.79

**ATTN: State of California Consumers** Products in this package may be subject to California Prop. 65  
Warning: Cancer and Reproductive Harm - [www.P65warnings.ca.gov](http://www.P65warnings.ca.gov)

**Return Policy:** Any unused parts in new condition may be returned any time of purchase with NO restocking fee. All returns must be accompanied by a number (Return Materials Authorization) - Call us toll free or email [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com). Please write it clearly on the outside of the box. Any return without this number on the packaging will be refused. Please note that sales or use tax may be due on certain purchases. Kaiser Willys does not collect sales tax on your purchase except for SC. Your state may require you to file a use tax return when sales tax is not paid at the time of purchase.

Kaiser Willys may have to provide information to you and the your State Department of Revenue about the purchases you made where seals tax was not paid.

**Liability Disclaimer:** Liability of Kaiser Willys Auto Supply LLC is limited to the replacement of defective parts only and is not liable for any damages to property, loss of time, loss of profits, loss of income, or any other incidental damages arising from the purchase or use of items purchased. They Buyer assumes all Risk or Loss associated with parts purchased from Kaiser Willys Auto Supply LLC. JEEP®, WILLYS, CJ™ and other names used are registered trademarks or trademarks of Daimler Chrysler or their respective owners. Kaiser Willys, LLC is not affiliated with Daimler Chrysler or any other companies whose products or part numbers shown here as a reference. Part numbers used for reference purpose only. No implication is made that these are original car manufacturing parts or from sources whose part numbers used here as a reference or approved by them.

# Kaiser Willys Auto Supply LLC

114 Bolton Ct.  
Aiken, SC 29803



**Toll Free: 888-648-4923**

Fax: 803-642-4197

Email: [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com)

Hours: Mon. - Fri., 9 - 5 (Eastern)

## INVOICE / PACKING SLIP

Order Number: 812067A


Invoice Date: 04/04/24

Page Number: 1

P.O. / Reference:

*We are the leading most complete supplier of 1941-72 Willys parts and accessories. See us online 24 hours a day at:*

[www.KaiserWillys.com](http://www.KaiserWillys.com)



Customer #: 336303 Terms: \_\_\_\_\_

Ship Via: UP2 Total Weight 1.0

Qty	B/O	Shipped	Item #	Description	Unit Price	Total Amount
1	0	1	7372896	Replacement Door Hinge Socket for Drivers Side	15.49	13.94
1	0	1	A-1198-ST	US Made Steel Oil Pressure Line	27.99	25.19
1	0	1	647583	Oil Filter Outlet Hose 10 A1198	20.99	18.89
1	0	1	A215	Fuel Pump Inlet Fitting (90 degree port) C	4.99	4.49
1	1	0	643797	Speedometer Cable Assembly 60"	19.99	0.00
1	0	1	8126312	Inline Fuel Filter Kit	12.99	11.69
1	0	1	938899	Turn Signal Flasher 12 volt	12.99	11.69

Merchandise Invoice Total:	\$	85.90
Sales Tax:	\$	0.00
Shipping & Handling:	\$	TOTAL \$
Invoice Total:	\$	85.90

**ATTN: State of California Consumers** Products in this package may be subject to California Prop. 65  
Warning: Cancer and Reproductive Harm - [www.P65warnings.ca.gov](http://www.P65warnings.ca.gov)

**Return Policy:** Any unused parts in new condition may be returned any time of purchase with NO restocking fee. All returns must be accompanied by a number (Return Materials Authorization) - Call us toll free or email [mike@kaiserwillys.com](mailto:mike@kaiserwillys.com). Please write it clearly on the outside of the box. Any return without this number on the packaging will be refused. Please note that sales or use tax may be due on certain purchases. Kaiser Willys does not collect sales tax on your purchase except for SC. Your state may require you to file a use tax return when sales tax is not paid at the time of purchase. Kaiser Willys may have to provide information to you and the your State Department of Revenue about the purchases you made where seals tax was not paid.

**Liability Disclaimer:** Liability of Kaiser Willys Auto Supply LLC is limited to the replacement of defective parts only and is not liable for any damages to property, loss of time, loss of profits, loss of income, or any other incidental damages arising from the purchase or use of items purchased. They Buyer assumes all Risk or Loss associated with parts purchased from Kaiser Willys Auto Supply LLC. JEEP®, WILLYS, CJ™ and other names used are registered trademarks or trademarks of Daimler Chrysler or their respective owners. Kaiser Willys, LLC is not affiliated with Daimler Chrysler or any other companies whose products or part numbers shown here as a reference. Part numbers used for reference purpose only. No implication is made that these are original car manufacturing parts or from sources whose part numbers used here as a reference or approved by them.